Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

22471 Jonathan Burr Elementary School 2530 School: **Oracle Unit: Building ID:** Address: 1621 W. Wabansia Avenue Region: 02 Mail Room: Asbestos Surveyor: Arce, Hector X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Other Each child's backpack Notice printed in school's calendar HA No Material Description Material Material Location Asbestos Material Friable Damage Damage Change in Assessment Category Damage Quantity Units Type Category Type Quantity YES SF 0 X NO 1A **Boiler Jacket** 760 Boiler Room TSI Yes None 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

1B	Water Tank Insulation	140	SF	Boiler Room		TSI	Yes	Loc	20		YES	X NO
2016 - Fall:	No Change]							
Comments:]							
2017 - Fall:	No Change											
Comments:]							
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

5

Damage

Type

Damage

Quantity

Damage

Units

10	Airceil Pipe insulation	300	LF	Storage, NW Basement Hall (Pump Room)
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
	•	•		

366

HA No

1C

Material Description

Aircell Pipe Insulation

Material

Quantity

Material

Units

LF

Material Location

Boiler Room, Tank

Room, Engine Room, Fan Room, Kitchen Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1D	MJP E/F/V on Aircell Pipe Insulation	73	LF	Boiler Room, Tank Room, Engine Room, Fan Room, Kitchen Storage, NW Basement Hall (Pump Room)		TSI	Yes	Loc	5		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1E	Cardboard Pipe Insulation	554	LF	Boiler Room, Tank Room, Engine Room, NW Basement Hallway		TSI	Yes	Loc			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1F	MJP E/F/V on Cardboard Pipe Insulation	47	LF	Boiler Room, Tank Room, Engine Room, NW Basement Hallway (Pump Room)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1G	MJP E/F/V on Fiberglass Pipe Insulation	75	LF	Enginer Room, Pump Room, Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	_

03	12x12 Off White w/ Speckles VFT	0		002 Closet (Not Observed), Room 308 (Abated)							YES	X NO
2016 - Fall:	No Change	·		•	7							
Comments:	140 Orlange											
Comments.					-							
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

05	12x12 Off White w/ Speckles VFT Mastic	0	002 Closet (Not Observed), Room 308 (Abated)	3
0040 = 11				
2016 - Fall:	No Change			
Comments	:			
2017 - Fall:	No Change			
Comments				
2017 - Spri	ng: No Change			
Comments	• •			
2018 - Fall:	No Change			
Comments				

HA No

Material Description

Material

Quantity

Material

Units

Page 5

YES

X NO

06	Hard Coat Plaster	144000	SF	Throughout - 1st, 2nd, 3rd floors, basement		Surface	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

	Girl Tol.,(204T.O.)
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	_

3750

SF

HA No

07

Material Description

12x12 Beige w/ White & Dark Streaks VFT

Material

Quantity

Material

Units

Material Location

Aud., N&S Stair

Landings, Rms 200, 201, 207, 303, 201 washroom,

203, 301.,2nd FI Teach &

Page 6

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07A	12x12 Beige w/ White & Dark Streaks VFT Mastic	3750	SF	Aud., N&S Stair Landings, Rms 200, 201, 207, 303, 201 washroom, 203, 301.,2nd Fl Teach & Girl Tol.,(204T.O.)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						
Comments:					1						
2017 - Fall: N	lo Change										
Comments:					=						
2017 - Spring	g: No Change										
Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12x12 Light Brown w/ White & Brown Speckles VFT	4950	SF	Rm 006, 008, 009, Kitchen, 108, Main Office, Prin. Office(not observed), 206, 300, 307, (104&204 Tiled Over), 106, 302 closet, 101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
·	

2018 - Fall: No Change

Comments:

08A	12x12 Light Brown w/ White & Brown Spec VFT Mastic	4950	SF	Rm 006, 008, 009, Kitchen, 108, Main Office, Prin. Office(not observed), 206, 300, 307, (104&204 Tiled Over), 106, 302 closet, 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	•				1							
2017 - Fall:	No Change				-							
Comments:	•											
2017 - Sprii	ng: No Change											
Comments:					1							
2018 - Fall:	No Change											
Comments:	-				1							
					j							
HA No	Material Description	Material	Material	Material Location	Acheetoe	Material	Friable	Damage	Damage	Damage	Change in Accessme	ant Categor

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Units

YES

X NO

Damage

Units

			(104 Tiled Over)
2016 - Fall: No	Change		
Comments:			
2017 - Spring:	No Change		
Comments:			
2017 - Fall: No	Change		
Comments:			
2018 - Fall: No	Change		
Comments:			

Quantity

2600

Units

SF

HA No

09

Material Description

12x12 Brown w/ White &

Brown Speckles VFT

Material

Units

Material

Quantity

Material Location

Rm 006, 008, 009,

Prin. Office(not

Kitchen, 108, Main Office,

observed), 206, 300, 307,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09A	12x12 Brown w/ White & Brown Speckles VFT Mastic	2600	SF	Rm 006, 008, 009, Kitchen, 108, Main Office, Prin. Office (not observed), 206, 300, 307, (104 Tiled Over)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12x12 White w/ Dark Speckles VFT	180	SF	1st Floor Women's Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

10A	12x12 White w/ Dark Speckles VFT Mastic	180	SF	1st Floor Women's Toilet	Miscellaneous	No	None	0	YES	X NO
0040 Fall N	I. Oli									
2016 - Fall: N	io Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Material Location

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12x12 Dark Brown w/ White & Orange Speckles VFT	800	SF	Room 007, Break Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

11A	12x12 Dark Brown w/ Orange Speckles VFT Mastic	800	SF	Room 007, Break Room		Miscellaneous	No	None	0		YES	X NO
	•	•	•	•	7	•	•	•	•	•	•	
2016 - Fall:	No Change											
Comments:												
					1							
2017 - Fall:	No Change				1							
Comments:					1							
					1							
2017 - Sprin	g: No Change											
Comments:												
]							
2018 - Fall:	No Change											
Comments:					1							
]							
			•		=							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessr	ment Category

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12	12x12 Green w/ White Streaks VFT	1100	SF	Eng. Supply Rm (Store Room), Fan Room, Break Room, Sprinkler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

12A	12x12 Green w/ White Streaks VFT Mastic	1100	SF	Eng. Supply Rm (Store Room), Fan Room, Break Room, Sprinkler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1		·			·		
Comments:					1							
2017 - Fall:	No Change											
Comments:					1							
2017 - Sprin	g: No Change				_							
Comments:					1							
2018 - Fall:	No Change				_							
Comments:					-							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	12"X12" Coffee w Dark Streaks NOT OBSERVED	0		Room 002 Toilet NOT OBSERVED							YES	X NO
2016 - Fall: N	No Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

2018 - Fall: No Change Comments:

13A	12x12 Coffee w/ Dark Streaks VFT Mastic NOT OBSERVED	0		Room 002 Toilet NOT OBSERVED							YES	X NO
2016 - Fa	II: No Change	<u> </u>		•	7							
Comment					=							
2017 - Fa	II: No Change											
Comment	s:											
	ring: No Change											
Comment	s:											
					4							
	II: No Change											
Comment	s:											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

None

No

Damage

Quantity

Quantity

0

Damage

Units

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Quantity

1800

Units

SF

HA No

14

Material Description

12x12 Coffee w/ Dark

1'x1' White Ceiling Tile

Material

Units

Material

Quantity

Material Location

Auditorium Wall, main

office reception area

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
15	Multi Color Swirl Linoleum	325	SF	Room 204 Closet, 2nd fl. men's toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2040 Falls Na Obarras	
2018 - Fall: No Change	
Comments:	
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	Multi Color Swirl Linoleum Mastic	325	SF	Room 204 Closet, 2nd fl. men's toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

16	Orange Linoleum	0		1st Floor telephone booth (removed from school)							YES	X NO
2016 - Fall: I	No Change]							
Comments:	140 Change				-							
Comments.												
2017 - Sprin	g: No Change											
Comments:	 											
2017 - Fall: I	No Change											
Comments:												
2010 5 11												
2018 - Fall: I	No Change											
Comments:												
								_	_			
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
16A	Orange Linoleum Mastic	0		1st Floor telephone booth							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

(removed from school)

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
17	12"x12" Light Blue w/ Specks VFT	1600	SF	Room 204 (over HA's 7 & 8), 107 and office, 208		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	12"x12" Light Blue w/ Specks VFT Mastic	1600	SF	Room 204 (over HA's 7 & 8), 208, 107		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	/
18	12"x12" Peach w/ Specks VFT	650	SF	Room 104 (over HA's 8 & 9)		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	o Change											

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12"x12" Peach w/ Specks VFT Mastic	650	SF	Room 104 (over HA's 8 & 9)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	12 x 12 inch Blue w/Light Blue Streaks VFT	980	SF	Room 204 (Closet), 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12 x 12 inch Blue w/Light Blue Streaks VFT Mastic	980	SF	Room 204 (Closet), 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
20	12 x 12 inch Blue/Gray with Streaks VFT	1950	SF	Room 308, 302		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	12 x 12 inch Blue/Gray with Streaks VFT Mastic	1950	SF	Room 308, 302		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
21	12 x 12 inch Red w/Specks VFT	1600	SF	Room 202		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	12 x 12 inch Red w/Specks VFT Mastic	1600	SF	Room 202		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

23	Green Carpet Mastic	750	SF	Room 302 (Library) NOT OBSERVED	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments:										
2017 - Fall:	No Change									
Comments:										
2017 - Sprii	ng: No Change									
Comments:										
	No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Plum Floor Tile	1200	SF	Auditoriun		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
25	12" x 12" Plum Floor Tile Mastic	1200	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
0047 5 11 N 01	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	· <u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12" x 12" Lavander Floor Tile	800	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

		-										
7	12" x 12" Lavander Floor Tile Mastic	800	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
16 - Fall: N	o Change											
mments:	<u> </u>											
17 - Fall: N	o Change											
mments:												
17 - Spring	: No Change											
mments:												
18 - Fall: N	o Change											
	16 - Fall: Nomments: 17 - Fall: Nomments: 17 - Spring mments:	Tile Mastic 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change	Tile Mastic 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	Tile Mastic 800 SF 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	Tile Mastic 800 SF Auditorium 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	Tile Mastic 800 SF Auditorium 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	Tile Mastic 800 SF Auditorium Miscellaneous 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	Tile Mastic 800 SF Auditorium Miscellaneous No 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	12" x 12" Lavander Floor Tile Mastic 800 SF Auditorium Miscellaneous No None 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	12" x 12" Lavander Floor Tile Mastic 800 SF Auditorium Miscellaneous No None 0 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	12" x 12" Lavander Floor Tile Mastic 800 SF Auditorium Miscellaneous No None 0 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:	12" x 12" Lavander Floor Tile Mastic 800 SF Auditorium Miscellaneous No None 0 Tyes 1 16 - Fall: No Change mments: 17 - Fall: No Change mments: 17 - Spring: No Change mments:

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Carpet MASTIC - blue with multi-color specks	400	SF	Principal's office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29	12"x12 Dark blue w/ light blue streaks VFT	1200	SF	Rm 002		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Dark blue w/ light blue streaks VFT MASTIC	1200	SF	Rm 002		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 24

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
31	Incinerator Gasket/Insulation	1	SF	Boiler/coal room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change]							
Comments	S:				1							
2017 - Fall	l: No Change											
Comments	S:				=							
2017 - Spring: No Change												
Comments	S:											

2018 - Fall: No Change
Comments:

black specks

landing to 1st floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" White w/ green and black specks	100	SF	Bsmt corridor & stairwell landing to 1st floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	White w/ green & black specks VFT MASTIC	100	SF	Bsmt corridor & stairwell to 1st floor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						

[
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Black w/ green and black specks VFT	100	SF	Bsmt corridor & stairwell landing to 1st floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Black w/ green & black specks VFT MASTIC	100	SF	Bsmt corridor & stairwell landing to 1st floor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N Comments:	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Aqua w/ black & white specks VFT	2000	SF	Basement corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

37	Aqua w/ black & white specks VFT MASTIC	2000	SF	Basement Corridors		Miscellaneous	No	None	0	YES	X NO
0040 Fall N	I. Oli				1						
2016 - Fall: No Change											
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring: No Change											
Comments:	<u> </u>				1						
					1						
2018 - Fall: N	lo Change										
Comments:	<u>-</u>				1						
					1						
					•						
114 11	I Marit 1 Donat 1 d	1.0.4.1.1	T 8.4	I was a sile of			I = · · · ·	-	-	01 1 1	

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	38	9"x9" gray w/ white streaks VFT	2	SF	Auditorium at entry door to crawlspace under stairwell to balcony		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change													

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9"x9" gray w/ white streaks VFT MASTIC	2	SF	Auditorium at entry door to crawlspace under stairwell to balcony		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Jonathan Burr Elementary School
Date: <u>1/8/2019</u>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 22471

SCHOOL'S ASBESTOS MANAGEMENT PLAN.