Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

22511

Oracle Unit:

Building ID: Address: 8546 S. Cregier Region: Mail Room: Asbestos Surveyor: Walker, Esther X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/21/2018 Email Address: ewalker25@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 1937 bldg office storage YES 04 9x9 pale green floor tile 30 SF X NO Miscellaneous No None 0 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Charles P Caldwell Academy of Math & Science ES

School:

Oracle Unit: 22511

2580

HA No Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05 12x12 gray speck floor tile	2700	SF	Hallways 1st & 2nd Floors; Rooms 100, 110 and 206 - 1937 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change					•	•	•		•		
Comments:											
2017 - Fall: No Change											
Comments:				=							
2017 - Spring: No Change											
Comments:											
2018 - Spring : No Change											
Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	12"x12" maroon floor tile	7500	SF	Hallways on 1st & 2nd floors; Room 100 - 1937 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
06	9x9 red floor tile (under existing VFT)	1500	SF	1st & 2nd floor hallways (under existing VFT) - 1961 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change					•	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	9x9 gray floor tile (under existing VFT)	1500	SF	1st and 2nd floor hallways (under existing VFT) - 1961 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
06B	9x9 tan floor tile	1400	SF	Rooms 209, 207, and 107; Rm 109 (under HA's 63 & 64) -1961 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	•	•	•		•	•	•	•	•	•	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06C	9x9 dark green floor tile	750	SF	1961 bldg - Rooms 114 and 214		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

06D	9x9 brown floor tile	750	SF	1961 bldg - Rooms 114 and 214		Miscellaneous	No	None	0	YES	X NO
					1						
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	: No Change										
Comments:	<u> </u>										
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:	•										
2018 - Fall: N	o Change										
Comments:											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Mastic carpet blue /purple ABATED			Main office and admin room ABATED		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
09	9x9 pale green floor tile mastic	30	SF	1937 bldg - office storage room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:					1							
2017 - Sprin	g: No Change				1							
Comments:	<u> </u>											
2017 - Fall: N	No Change				-							

2018 - Spring : No Change Comments:

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12x12 gray w/specks floor tile mastic	2700	SF	Hallways 1st & 2nd Floors; Rooms 100, 110 and 206 - 1937 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
10A	12x12 Maroon floor tile mastic	7500	SF	Hallways on 1st & 2nd floors; Room 100 - 1937 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	•	•]	•	•	•		•	•	
Comments:	¥											
2017 - Sprir	ng: No Change]							
Comments:					_							
2017 - Fall:	<u> </u>											
Comments:					_							
2018 - Sprin	ng : No Change				†							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9x9 red floor tile mastic (under existing VFT)	1500	SF	1st & 2nd floor hallways (under existing VFT) - 1961 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categ	gory
12A	9x9 gray floor tile mastic (under existing VFT)	1500	SF	1st and 2nd floor hallways (under existing VFT) - 1961 bldg -		Miscellaneous	No	None	0		YES X NO	
					1		•			•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12B	9x9 tan floor tile mastic	1400	SF	Rooms 209, 207, and 107; Rm 109 (under HA's 63 & 64) - 1961 bldg -		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12C	9x9 dark green floor tile mastic	750	SF	1961 bldg - rooms 114 and 214		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12D	9x9 brown floor tile mastic	750	SF	1961 bldg - Rooms 114 and 214		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

15L	12 x 12 White w/Brown Speckles Floor Tile ABATED	Room 208, Main Office ABATED		Miscellaneous				YES	X NO
0040 5-11 1	I - Ol		1		•		•	•	
2016 - Fall: N	io Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:	-		1						
2017 - Spring	g: No Change								
Comments:									
			1						
2018 - Spring	g : No Change								
Comments:	<u> </u>								
2018 - Fall: N	lo Change								
Comments:									
			_						
1			_						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No Mat	aterial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	x 12 Black Edging Floor e HARDWOOD FLOOR			Room 212 HARDWOOD FLOOR		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
42	12x12 tan with brown and white floor tile	650	SF	Main office (under carpet) and storage room patch - 1937 Bldg		Miscellaneous	No	None	0		YES	X NO
	Fall: No Change			•]	,	•	•	•	•	•	
Comme	nts:											
	Spring: No Change											
C	m1a.											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43 - Duplicate	9x9 beige checkerboard floor tile			209, 207, 107, 109,		Miscellaneous					YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12x12 tan/brown/white floor tile mastic	800	SF	Main office (under carpet) and Storage - 1937 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
45	12x12 tan speckled floor tile	150	SF	Patches in rooms 207 & 209 - 1961 Bldg		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12x12 tan speckled floor tile mastic	150	SF	Patches in rooms 207 & 209 - 1961 Bldg		Miscellaneous	No	None	0		YES X NO
					1						_

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
47	Light brown carpet mastic	1000	SF	Room 200, Main Office - 1937 Bldg.		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
48	Pink carpet mastic	200	SF	Room 108 (Principal's Office) - 1937 Bldg		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
49	Green linoleum	700	SF	Room 112 - 1937 Bldg.		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
50	Green linoleum mastic	700	SF	Room 112 - 1937 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change				_							
Comments:]							
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	; No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51 - Not Used	12x12 green with streaks floor tile - "Green Linoleum in Classroom"			Patches in room 112 "Green Linoleum in Classroom"		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
52 - Not Used	12 x 12 green streaked floor tile mastic "Green Linoleum in Classroom"			Patches in room 112 "Green Linoleum in Classroom"		Miscellaneous					YES	X NO
2016 - Fall: N	2016 - Fall: No Change							•				

2016 - Fall: No Change	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53 - Not Used	12 x12 black floor tile "Green Linoleum in Classroom"			Patches in room 112 "Green Linoleum in Classroom"		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
54 - Not Used	12 x 12 black floor tile mastic "Green Linoleum in Classroom"			Patches in room 112 "Green Linoleum in Classroom"		Miscellaneous					YES	X NO
2016 - Fall:	No Change	•		•		•	•		•	•	•	
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Brown carpet mastic - NOT OBSERVED	80	SF	Engineer's office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12 x 12 white with specks floor tile	7000	SF	1972 bldg - Throughout classrooms 301, 302, 317, 315, 401, 402, 405, 409, 410, 411, 412, 413, 414, and 422		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12 x 12 white with specks floor tile mastic	7000	SF	1972 bldg - Throughout classrooms 301, 302, 317, 315, 401, 402, 405, 409, 410, 411, 412, 413, 414, 416, and 422		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Black baseboard	1200	LF	1972 bldg - Throughout classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

59	black baseboard mastic	1200	LF	1972 bldg - Throughout classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change]							
Comments												
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
2018 - Spr	ing : No Change											
Comments	S:											
	l: No Change											
Comments	S:											
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Units

Damage

Quantity

0

None

Change in Assessment Category

500

SF

HA No

60

Material Description

Light purple carpet mastic

Material

Units

Material

Quantity

Material Location

1972 bldg - Teacher's

lounge

Page 20

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
61	Plaster	50000	SF	Thoughout 1937 Bldg		Surface	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Plaster	2000	SF	Throughout 1972 Bldg		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
63	12 x 12 White Floor Tile	800	SF	Room 109 - 1961 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Spring	2017 - Spring: No Change											

Comments:

2017 - Fall: No Change
Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12 x 12 White Floor Tile Mastic	800	SF	Room 109 - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
65	Beige Terrazzo	3500	SF	1937 Bldg - Stairwells		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	j : No Change											
Comments:					-							
2018 - Fall: N	lo Change				<u> </u>							
Comments:					_							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66 - Duplicate	Brown Carpet Mastic			Room 200 (Included in HA #47)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67 - Duplicate HA	12 x 12 White Floor Tile (same as HA's #56 & 57)			1972 Bldg - Rooms 301, 302, 315, 317, 401, 405, 409, 410, 411, 412, 413, 414, and 422		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 22511

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68 - Duplicate HA	12 x 12 White Floor Tile Mastic (same as HA's #56 & 57)			1972 Bldg - Rooms 301, 302, 315, 317, 401, 405, 409, 410, 411, 412, 413, 414, and 422		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Terrazzo Flooring	1600	SF	Stairwells - 1972 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units	3.	
70	12' X 12' red VFT	1000	SF	Kitchen, Toilet and Office - 1972 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:					=							
	g : No Change											
Comments:					=							
2018 - Fall: N	lo Change											
Comments:		·	·		-							
					1							
LIA NI-	Material December Con-	NA - t 1	NA-test-1	Maradallasadas	A - I I	NA - t 2 - 1	Education .	D	D	D	Ol	

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70A	12X12 Red VFT Mastic	1000	SF	Kitchen, Toilet and Office - 1972 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12 x 12 White with Blue, Brown, & Gray Specks VFT	1800	SF	Gym/Lunch Room - 1972 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
Comments.
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71A	12 x 12 White with Blue, Brown, & Gray Specks VFT Mastic	1800	SF	Gym/Lunch Room - 1972 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12'X12" Green VFT	120	SF	Gym/Lunch Room - 1972 Bldg		Miscellaneous	No	None	0		YES X NO
					1						

		•							
2016 - Fall: No Change									
Comments:									
2017 - Spring: No Change									
Comments:									
2017 - Fall: No Change									
Comments:									
2018 - Spring : No Change									
Comments:									
2018 - Fall: No Change									
Comments:									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72A	12' X 12' Green VFT Mastic	120	SF	Gym/Lunch Room - 1972 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	9"x9" Floor Tile	800	SF	Rm 206 (under HA #05 and HA#10) - 1937 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change							
Comments:							
2017 - Spring: No Change							
Comments:							
2017 - Fall: No Change							
Comments:							
2018 - Spring : No Change							
Comments:							
2018 - Fall: No Change							
Comments:							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73A	9"x9" Floor Tile Mastic	800	SF	Rm 206 (under HA #05 and HA#10) - 1937 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	12' X 12' gray with specks VFT	600	SF	1st & 2nd Floor Corridors - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change										
Comments:										
2017 - Spring	: No Change									
Comments:	Comments:									
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	2018 - Fall: No Change									
Comments:	Comments:									
	·	·		·						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74A	12' X 12' gray with specks VFT Mastic	600	SF	1st & 2nd Floor Corridors - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
75	12x12 Maroon VFT	2800	SF	1st & 2nd Floor Corridors - 1961 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75A	12x12 Maroon VFT Mastic	2800	SF	1st & 2nd Floor Corridors - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	9x9 brown w/cream and dark maroon streaks VFT	3200	SF	Rooms 107, 207, and 209; Room 109 (under HA #63 & 64) - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76A	9x9 brown w/cream and dark maroon streaks VFT Mastic	3200	SF	Rooms 107, 207, and 209; Room 109 (under HA #63 & 64) - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Rough Plaster Ceiling	7500	SF	1st & 2nd Floor Corridors; Rooms 107, 109, 114, 207, 209 and 214; 2nd Floor Women's Toilet		Surface	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	2'x4' ceiling tile	21000	SF	Throughout 1971 bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
В	Mag tank insulation - ABATED			1939 bldg - Boiler room ABATED		TSI					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Fiberglass joints	800	LF	1937 bldg - Air tunnel		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
F	Fiberglass joints	240	LF	1961 bldg - Crawl Space		TSI	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
	: No Change											
Comments	: :											
2017 - Spri	ing: No Change											

Comments:

2018 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Cardboard pipe	1500	LF	1937 bldg - Crawl Space		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Н	Cardboard joints	265	LF	1937 bldg - Crawl Space		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change				_							
Comments:	J											
2018 - Fall:	No Change											
Comments:	J											
2018 - Sprin	g : No Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Aircell Pipe Insulation	1277	LF	1937 bldg - 1st Floor Hallway; Main Office; Rm 101, Crawlspaces		TSI	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
IA	Air cell Pipe covering	120	LF	1961 Addition - Crawl Space		TSI	Yes	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
0040 0 : N 01	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Aircell joints	150	LF	1937 bldg - Basement, Crawlspaces		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

		1	1							
K	Air cell duct wrap	600	SF	1937 Bldg - Basement	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Chango									
	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:	o onango									
2017 - Spring	: No Change									
Comments:										
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:	·			·						
		•	•							

Asbestos

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Mag block water main - ABATED			Boiler room ABATED		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	12x12 light brown floor tile	1050	SF	1971 bldg - 1st & 2nd floor corridors		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	2040. Caria a Na Channa
2018 - Fall: No Change	
· ·	Comments:
· ·	
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	12x12 light brown floor tile Mastic	1050	SF	1971 bldg - 1st & 2nd flr corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 39

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	12x12 beige floor tile	1050	SF	1971 bldg - 1st & 2nd floor corridor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	12x12 beige floor tile mastic	1050	SF	1971 bldg - 1st & 2nd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Q	Dark brown vinyl baseboard	75	LF	1971 bldg - Room 414		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Dark brown vinyl baseboard Mastic	75	LF	1971 bldg - Room 414		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
S	Red/Brown multicolor carpet mastic - ABATED			Rooms 410, 412 and 413 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•				1							
2017 - Spring: No Change												
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Т	Light brown/brown multicolor carpet -ABATED			1971 bldg - rooms 315 and 317 ABATED		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

U	Orange/brown multicolored carpet -ABATED			reachers founge area, rooms 411 and 414 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	o Change	•		•]							
Comments:	o onange											
Comments.					-							
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2019 Spring : No Chango												
2018 - Spring : No Change												
Comments:												
2010 Fall N	o Changa											
2018 - Fall: N	o Change											
Comments:												
					J							
	I a a a a a a a a a a a a a a a a a a a	1		T	T	T	1		T =			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
		<u> </u>		1972 bldg - public space,		<u> </u>		7.	•		 	
V	Mastic for Purple/blue multicolored carpet	4000	SF	office/corrridor, conference room,		Miscellaneous	No	None	0		YES	X NO
	manaosioroa darpot			counselors office								
004C F-II-N	- Oh				1							
∠∪16 - Fall: N	2016 - Fall: No Change											

Material

Category

Asbestos

Type

Friable

Damage

Type

Damage

Quantity

HA No

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

Damage

Units

		Quantity	Units		Type	Category	Type
Х	Mastic cream carpet - ABATED			1972 bldg - rooms 301 and 302 ABATED		Miscellaneous	
2016 - Fall:	: No Change				7		
Comments	:						
2017 - Spri	ing: No Change				_		
Comments	:						
2017 - Fall:	: No Change						
Comments	:						
2018 - Spri	ing : No Change						

Material Material Location

Asbestos

Material

Friable

Damage

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

HA No

Comments:

Comments:

2018 - Fall: No Change

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Υ	12x12 gray floor tile	1900	SF	1972 bldg - Rm. 416, all storage rooms, mechanical room, janitor closets & kitchen storage room, 2nd floor elec room/closet		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 22511

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Z	12x12 gray floor tile mastic	1900	SF	1972 bldg - Rm. 416, all storage rooms, mechanical room, janitor closets & kitchen storage room, 2nd floor elec room/closet		Miscellaneous	No	None	0		YES X NO
2016 - Fall: Comments:	No Change]						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 22511

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Charles P Caldwell Academy of Math & Science ES
Date: 12/21/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.