## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

Carroll-Rosenwald Specialty Elementary School 22571 2651 School: **Oracle Unit: Building ID:** Address: 2541 W 80th St. Region: 05 Mail Room: Asbestos Surveyor: Favela, David X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: dfavela5@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12x12 floor tile ABATED YES 01 SF X NO thoughout school SUMMER OF 1997 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
02	9x9 VAT ABATED IN SUMMER OF 1997										YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change											
Comments												
2017 - Fall	: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
05	linoleum univent tops ABATED IN SUMMER OF 1997			classrooms-1955							YES	X NO
2016 - Fall	: No Change			<u> </u>								
Comments												

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

06		9x9 VAT mastic ABATED IN SUMMER OF 1997	0		throughout school							YES	X NO
201	16 - Fall: N	o Change				7							
	mments:												
201	17 - Spring	: No Change				-							
	mments:												
201	17 - Fall: N	o Change				-							
	mments:												
201	18 - Fall: N	o Change				+							
Cor	mments:	•											
						_							
НА	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
07		12x12 VAT mastic ABATED IN SUMMER OF 1997	0		Throughout school							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

08	linoleum ABATED IN SUMMER OF 1997	0		classroom univents top 1962							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<b>3</b>				1							
2017 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09	hard coat plaster	1500	SF	Boys toilet ceiling; girls toilet ceiling; janitor		Surface	No	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

toilet ceiling; janitor closets; store rooms

Material

Quantity

Material

Units

HA No

Material Description

											II.
0010 5 1					٦						
	l: No Change										
Comments	s:										
2017 - Spi	ring: No Change										
Comments	3:										
2017 - Fal	I: No Change										
Comments	<b>3</b> :										
2018 - Fal	I: No Change										
Comments	3:										
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

0

Material

Quantity

0

Material

Units

Material Location

classroom univent top

classroom univent tops-

-1955

HA No

10

11

Material Description

IN SUMMER OF 1997

linoleum mastic ABATED

linoleum mastic ABATED

IN SUMMER OF 1997

Change in Assessment Category

X NO

X NO

YES

12	1'x1' acoustic tiles ABATED IN SUMMER OF 1997	0		1962 addition ceiling							YES	X NO
2016 - Fall: I	No Change				7							
Comments:	<u> </u>				]							
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	9x9 Vat mastic ABATED IN SUMMER OF 1997	0		1962 addition							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

1'x1' acoustic tiles ABATED

											<u> </u>
204C Fall N	la Changa				7						
2016 - Fall: N	io Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	Comments:										
2017 - Spring	j: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

600

SF

Material

Quantity

0

Material

Units

Material Location

1962 addition -Closets

1962 addition

HA No

14

15

Material Description

12x12 VAT ABATED IN

SUMMER OF 1997

Drywall

Change in Assessment Category

X NO

X NO

YES

2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Chango										
Comments:	NO Change										
	g: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

Material Location

Washroom

North Central Basement

1962 addition-closets

600

SF

Material

Quantity

0

Material

Units

HA No

15A

16

Material Description

9" x 9" Green Floor Tile

Mastic (ABATED)

Drywall Compound

Change in Assessment Category

X NO

X NO

YES

17	12x12 Beige VFT	13000	SF	Throughout School; Corridors, Offices and Classrooms		Miscellaneous	No	None	0		YES	X NO
0040 5-11	M. Ol	•	•	•	7	•	•	•	•	•	•	
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category	1	Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Material Location

Throughout School

Installed, No ACM		
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

13000

SF

Material

Quantity

Material

Units

HA No

18

Material Description

12x12 Beige Floor VAT Mastic; New Material

YES

X NO

2016 - Fal	: No Change										
Comments	5:										
2017 - Fal	l: No Change										
Comments	S:										
2017 - Spr	ing: No Change										
Comments	S:										
2018 - Fal	: No Change										
Comments											
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
11/4140	Waterial Description			Waterial Education			1 Habie				Change in Assessment Category
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

19

20

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

1'x1' Fissured Ceiling Tile

Transite Wall Panels

Material

Quantity

13000

Material

Units

SF

SF

360

Material Location

Throughout School

All 6 Classrooms

Change in Assessment Category

X NO

X NO

YES

В	aircell pipe insulation (Material was not Observed)	0	LF	boiler room		TSI	Yes				YES	X NO
0040 5-11 1		•	•	•	1	•	•	•	•	•	•	
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					•							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
1	1	Qualitity	Ullito	1	Type	Category		1 ype	Quantity	Office	1	

TSI

Asbestos

Type

Material

Category

Friable

No

Damage

Туре

Damage

Quantity

Damage

Units

D	(Material was not Observed)	0	SF	boiler room
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
				•

Material

Quantity

Material

Units

Material Location

HA No

Material Description

mag block boiler insulation

YES

X NO

Е	(Material was not Observed)	0	LF	boiler room		TSI	No				YES	X NO
0040 5 11 1		•	·		_ _					•		
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				1							
Comments:	-				1							
2017 - Fall: N	No Change				1							
Comments:												
2018 - Fall: N	No Change											
Comments:					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

TSI

Friable

No

Damage

Туре

Damage

Quantity

Damage

Units

F	cardboard fittings (Material was not Observed)	boiler room							
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	2017 - Spring: No Change								
Comments:									
2017 - Fall: N	o Change								
Comments:									
2018 - Fall: N	2018 - Fall: No Change								
Comments:		•	•						

Material

Quantity

Material

Units

Material Location

HA No

Material Description

cardboard pipe insulation

YES

Change in Assessment Category

X NO

G	pipe wrapping (Material Not Observed)	0	LF	inside univents	TSI	Yes		YES	X NO
2016 - Fall: N	lo Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
2018 - Fall: N	lo Change								
Comments:									

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Quantity	Units	Material Location	Asbestos Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
Н	vibration gaskets- fan on deck	10	LF	boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fa Comment	II: No Change s:											
2017 - Fa	II: No Change											

2017 - Fail: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

I	aircell insulation	0	LF	1962 addition No aircell insulation observed		TSI	Yes				YES	X NO
2016 - Fa	all: No Change				1							
Commen												
2017 - Sr	oring: No Change											
Commen												
2017 - Fa	all: No Change											
Commen	ts:											
2018 - Fa	all: No Change											
Commen	ts:											
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
J	cardboard insulation (No cardboard insulation	0	LF	1962 addition							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

observed)

Material

Quantity

Material

Units

Page 14

K	cardboard fittings (no cardboard fittings observed)	0		1962 addition							YES	X NO
2016 - Fall: I	No Change											
Comments:	J.											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
L	univent wrapping	0		1962 addition no wrapping univent lines observed							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

М	aircell fittings (abated)	0	LF	boiler room		TSI					YES	X NO
2016 - Fall: N	o Change				1							
Comments:												
2017 - Spring	: No Change				]							
Comments:					1							
2017 - Fall: N	o Change											
Comments:					_							
2018 - Fall: N	o Change				1							
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
N	aircell fittings	0		1962 addition no aircell fittings observed							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

fittings observed

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	boiler gasket	30	LF	boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 22571

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Carroll-Rosenwald Specialty Elementary School
Date: 1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 22571