

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2018 - Fall

**School:** Ira F Aldridge Elementary School  
**Address:** 630 E. 131st St.

**Oracle Unit:** 22641  
**Region:** 06

**Building ID:** 2710  
**Mail Room:** 48

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Nichols, Tijuana  
**Survey Date:** 1/7/2019  
**Email Address:** tnichols@cps.edu

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other

| HA No | Material Description   | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02    | 12" x 12" Ceiling Tile | 20000             | SF             | Throughout School 1960 and 1962 Buildings |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03    | 9" x 9" Gray Floor Tile | 3400              | SF             | Classrooms 101, 105, 110, 114, Special Ed Rooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04    | 12"x 12" Cream Floor Tile | 800               | SF             | 2nd Floor Corridor 1962 Building |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05    | 9"x9" Gray Floor Tile | 8140              | SF             | 2nd Floor Classrooms and Storage Room 1962 building |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description           | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06    | 9" x 9" Gray Floor Tile Mastic | 3400              | SF             | Classrooms 101, 105, 110,114, Special Ed Rooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07    | 12" x 12" Cream Floor Tile Mastic | 800               | SF             | 1962 Building: 2nd Floor Corrido |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description           | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08    | 9" x 9" Gray Floor Tile Mastic | 8140              | SF             | 2nd Floor Classrooms and Storage Room 1962 building |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09    | Hardcoat Plaster     | 15000             | SF             | 1960 Building: Classrooms, Offices and Miscellaneous Rooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | Hardcoat Plaster     | 12760             | SF             | 1962 Building: 1st and 2nd Floor Classrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | Insulation in Fire Rated Door | 32                | SF             | Boiler Room       |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | Vinyl Baseboard      | 200               | LF             | All Purpose Room  |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | Vinyl Baseboard Mastic | 200               | LF             | All Purpose Room  |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | Vinyl Baseboard      | 200               | LF             | 1962 Building: Southwest Section of South Corridor and Faculty Lounge I |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | Vinyl Baseboard Mastic | 200               | LF             | 1962 Building: Southwest Section of South Corridor and Faculty Lounge I |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | 9" x 9" Orange Floor Tile | 3965              | SF             | Classrooms 103, 107, 108, 111, 112, 116, Corridor Storage, Health Room, All Purpose Room Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | 9" x 9" Orange Floor Tile Mastic | 3965              | SF             | Classrooms 103, 107, 108, 111, 112, 116, Corridor Storage, Health Room, All Purpose Room Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | 9" x 9" Light Brown Floor Tile | 650               | SF             | All Purpose Room Vault and Principal's office( Under carpet) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | 9" x 9" Light Brown Floor Tile Mastic | 655               | SF             | All Purpose Room Vault and Principal's office( Under carpet) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | 9" x 9" Orange Floor Tile | 4066              | SF             | 1962 Building: Rooms: , 103, 104, 107, 108, 109, 111, 112, 116, All Purpose Room, Corridor Storage, and Health Room, Library |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | 9" x 9" Orange Floor Tile Mastic | 4066              | SF             | 1962 Building: Rooms: , 103, 104, 107, 108, 109, 111, 112, 116, All Purpose Room, Corridor Storage, and Health Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22    | 9" x 9" Light Brown Floor Tile | 650               | SF             | 1962 Building: Janitors Closet and Counselor's Office Storage Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | 9" x 9" Light Brown Floor Tile Mastic | 650               | SF             | 1962 Building: Janitors Closet and Counselor's Office Storage Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | 12" x 12" Cream Floor Tile | 720               | SF             | 1962 Building: 2nd Floor Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | 12" x 12" Cream Floor Tile Mastic | 120               | SF             | 1962 Building: 2nd Floor Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | 12" x 12" Black Floor Tile | 400               | SF             | 1962 Building: Faculty Lounge |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | 12" x 12" Black Floor Tile Mastic | 400               | SF             | 1962 Building: Faculty Lounge |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28    | 12" x 12" Green Floor Tile- NOT OBSERVED | 0                 | SF             | 1962 Building: Public Office |               | Miscellaneous     | No      | Unknown     | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29    | 12" x 12" Green Floor Tile Mastic(not observed) | 0                 | SF             | 1962 Building: Public Office |               | Miscellaneous     | No      | Unknown     | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30    | 12" x 12" Light Brown Floor Tile | 3320              | SF             | Room 102, All Purpose Room, Engineer's Office, Janitor's Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31    | 12" x 12" Light Brown Floor Tile Mastic | 3320              | SF             | Room 102, All Purpose Room, and Engineer's Office, Janitor's Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32    | 12" x 12" Cream Floor Tile | 1000              | SF             | 1960 Building: Pre-Kindergarten Room 100 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | 12" x 12" Cream Floor Tile Mastic | 1000              | SF             | 1960 Building: Pre-Kindergarten Room 100 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34    | 12" x 12" Brown Floor Tile | 1580              | SF             | All Purpose Room<br>Offices, Rooms<br>106&106A |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                 | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35    | 12" x 12" Brown Floor Tile<br>Mastic | 1580              | SF             | All Purpose Room<br>Offices, Rooms<br>106&106A |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36    | White Terrazo        | 15000             | SF             | Hallways and Stairwells |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37    | 12x12 Blue VFT       | 210               | SF             | Main Office Waiting Area,<br>All Purpose Room Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38    | 12x12 Blue VFT Mastic | 210               | SF             | Main Office Waiting Area,<br>All Purpose Room Office |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39    | Brown Carpet Mastic  | 150               | SF             | Principal's office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40    | 12x12 Blue w/ Gray Specs VFT | 1200              | SF             | Room 122, 123, 124, 125, 126, 127, & 128 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41    | 12x12 Blue w/ Gray Specs VFT Mastic | 1200              | SF             | Room 122, 123, 124, 125, 126, 127, & 128 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42    | Brown and Tan Ceramic tile Grout | 200               | LF             | Boys and Girl's Toilets<br>1st&2nd Floor, Principal's Office Toilet and Women's Toilet- 1962 Bldg |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | MJP E/F/V on Fiberglass Pipe Insulation | 10                | LF             | 1960 +1962 Building |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C     | Tank Insulation      | 180               | SF             | 1960 building     |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description         | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D     | Boiler Gasket (NOT OBSERVED) | 0                 | LF             | 1960 Building: Boiler Room |               | Miscellaneous     | No      |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description            | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E     | Boiler Breaching (NOT OBSERVED) | 0                 | LF             | 1960 Building: Boiler Room |               | TSI               | Yes     |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F     | Boiler#1 and Boiler#2: Insulation Under Steel Jacket | 320               | SF             | Boiler Room       |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | Caulk on Boiler      | 8                 | LF             | Boiler Room       |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H     | Trowled on Ceiling   | 2000              | SF             | Boiler Room       |               | Surface           | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I     | Thermal System Insulation in Tunnel | 120               | LF             | 1960 Building: Boiler Room |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J     | Drywall / Compound   | 207               | SF             | 110, 113, PRE-K (RM100) |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K     | Blue Carpet Mastic   | 500               | SF             | 1962 Building: Public Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L     | Black Baseboard      | 50                | LF             | Rooms 110, 113 and 100 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M     | Black Baseboard Mastic | 50                | LF             | Rm 110, 113, Pre-K (rm 100) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*



---

Robert Christlieb

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ira F Aldridge Elementary School  
Date: 1/7/2019

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.