## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

2018 - Fall

|           | School:<br>Address: | Horace Greeley Elementary School<br>832 W Sheridan Road |                           | Oracle Unit:<br>Region:       | 22661<br>01    | Building ID:<br>Mail Room: | 2730<br>32 |
|-----------|---------------------|---|---------------------------|-------------------------------|----------------|----------------------------|------------|
|           |                     |   | Asbestos Surveyor:        | McCarthy, Kevin               |                |                            |            |
| X CHECK F | IERE IF I           | NO CHANGE TO ASBESTOS                                   | Survey Date:              | 1/10/2019                     |                |                            |            |
|           |                     |   | Email Address:            | kmccarthy4@cps.edu            |                |                            |            |
|           |                     |   |                           |                               |                |                            |            |
|           | A copy of t         | he2016/2017 notice to parents and staff regard          | ding the asbestos managem | ent plan notifications was di | stributed via: |                            |            |

|                |                                     |                      |                   |   | -                | •                    |               |                |                    |                 |                |                 |
|----------------|-------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------------|----------------|--------------------|-----------------|----------------|-----------------|
|                | Each child's backp                  | ack                  | Notice            | printed in school's new                                 | vsletter         | Notice pr            | rinted in sch | ool's calenda  | ar X Ot            | her Email       |                |                 |
| HA No          | Material Description                | Material<br>Quantity | Material<br>Units | Material Location                                       | Asbestos<br>Type | Material<br>Category | Friable       | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Asse | ssment Category |
| 03             | 24"x24" Smooth Gray<br>Ceiling Tile | 0                    |                   | 1st, 2nd, & 3rd Floor<br>Classrooms, Office,<br>Library |                  |                      |               |                | 0                  |                 | YES            | XNO             |
| 2016 - Fall: N | lo Change                           |                      |                   |   |                  |                      |               |                |                    |                 |                |                 |
| Comments:      |                                     |                      |                   |   |                  |                      |               |                |                    |                 |                |                 |
| 2017 - Fall: N | lo Change                           |                      |                   |   |                  |                      |               |                |                    |                 |                |                 |
| Comments:      |                                     |                      |                   |   |                  |                      |               |                |                    |                 |                |                 |
| 2017 - Spring  | g: No Change                        |                      |                   |   |                  |                      |               |                |                    |                 |                |                 |
| Comments:      |                                     |                      |                   |   | _                |                      |               |                |                    |                 |                |                 |
| 2018 - Spring  | g : No Change                       |                      |                   |   |                  |                      |               |                |                    |                 |                |                 |
| Comments:      |                                     |                      |                   |   | _                |                      |               |                |                    |                 |                |                 |
| 2018 - Fall: N | lo Change                           |                      |                   |   |                  |                      |               |                |                    |                 |                |                 |
| Comments:      |                                     |                      |                   |   |                  |                      |               |                |                    |                 |                |                 |
| L              |                                     |                      |                   |   | ]                |                      |               |                |                    |                 |                |                 |

| HA No | Material Description               | Material<br>Quantity | Material<br>Units | Material Location                              | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|------------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 04    | 24"x24" Rough Gray<br>Ceiling Tile | 0                    |                   | 1st, 2nd, & 3rd Floor<br>Corridors, Lunch Room |                  |                      |         |                | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                | Material<br>Quantity | Material<br>Units | Material Location                          | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-------------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 05    | 24"x24" Smooth Dots<br>Ceiling Tile | 0                    |                   | Home Management<br>Room (215,216), Kitchen |                  |                      |         |                | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA N | lo | Material Description  | Material<br>Quantity | Material<br>Units | Material Location                | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|------|----|-----------------------|----------------------|-------------------|----------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 08   |    | Exterior Sink Coating | 100                  | SF                | Throughout(See<br>Hatching Maps) |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                  | Material<br>Quantity | Material<br>Units | Material Location                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---------------------------------------|----------------------|-------------------|-------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 09    | 12"x12" Beige w/ Brown<br>Streaks VFT | 19400                | SF                | Throughout ( See<br>Hatching Maps ) |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                         | Material<br>Quantity | Material<br>Units | Material Location                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 10    | 12"x12" Beige w/ Brown<br>Streaks VFT Mastic | 19400                | SF                | Throughout ( See<br>Hatching Maps ) |                  | Miscellaneous        | No      | None           | 2                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 11    | Vinyl Baseboard      | 0                    |                   | Throughout        |                  |                      | No      |                | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                              | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 13    | 12"x12" Cream w/ Beige<br>Wave VFT (Not Observed) | 0                    |                   | Rooms 218         |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description  | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 14    | 12"x12" Cream w/ Beige<br>Wave VFT Mastic (Not<br>Observed) | 0                    | SF                | Room 218          |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description   | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 15    | 12"x12" Royal Blue VFT | 1800                 | SF                | Lunchroom         |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description             | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 16    | 12"x12" Royal Blue VFT<br>Mastic | 1800                 | SF                | Lunchroom         |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2010 Fally No Change      |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2017 - Spring: No Change  |
|                           |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 17    | MJP on Fiberglass Pipe<br>Insulation | 0                    |                   | 2nd Floor Boys Toilet,<br>Penthouse, Boiler Room,<br>Gym, Pump Room,<br>Storage 117 (Behind<br>Engineers Office) |                  |                      |         |                | 0                  |                 |                               |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 18    | 12"x12" Beige w/ Grey<br>Streaks VFT | 40                   | SF                | Elevator          |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

*VFT* = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.*  Oracle Unit: 22661 Page 7

| HA No | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 19    | 12"x12" Beige w/ Grey<br>Streaks VFT Mastic | 40                   | SF                | Elevator          |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |  |
|---------------------------|--|--|
| Comments:                 |  |  |
|                           |  |  |
| 2017 - Fall: No Change    |  |  |
| Comments:                 |  |  |
|                           |  |  |
| 2017 - Spring: No Change  |  |  |
| Comments:                 |  |  |
|                           |  |  |
| 2018 - Fall: No Change    |  |  |
| Comments:                 |  |  |
|                           |  |  |
| 2018 - Spring : No Change |  |  |
| Comments:                 |  |  |
|                           |  |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 20    | Carpet mastic        | 15900                | SF                | Rooms (145, 147, 148,<br>151 (NOT OBSERVED));<br>217; 219; 220; (221,<br>221B (NOT<br>OBSERVED)); 215; 320;<br>316; 317; 318; 322; 323;<br>325; and 328 (Subtotal<br>144,000 SF).<br>Rooms 214, 314, KIVA,<br>and Library Main Office<br>(Subtotal 6900 SF) |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 21    | Black sink coating   | 84                   | SF                | Rooms 144, 145, 146,<br>147, 148, 151, 316, 317,<br>320, 321, 322, 325, 326,<br>328 |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location                          | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 22    | 12"X12" Brown VFT    | 5600                 | SF                | Rooms 140, 141, 144,<br>146, 321, 324, 326 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

*VFT* = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.* 

| ſ | HA No | Material Description     | Material<br>Quantity | Material<br>Units | Material Location                          | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|---|-------|--------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
|   | 23    | 12"X12" Brown VFT Mastic | 5600                 | SF                | Rooms 140, 141, 144,<br>146, 321, 324, 326 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 24    | White sink coating   | 40                   | SF                | Rooms 215, 216, 218,<br>and 2nd floor Teachers<br>Lounge |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 25    | Plaster ceiling      | 2800                 | SF                | Room 312, Stairwells,<br>Bathrooms 1st, 2nd and<br>3rd floors, Library,<br>Janitors Closet |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                     | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 26    | 12x12 Gray w/ gray and white streaks VFT | 2500                 | SF                | Rooms 147,145,151 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                            | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 27    | 12x12 Gray w/ gray and white streaks VFT Mastic | 2500                 | SF                | Rooms 147,145, 151 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description              | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-----------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 28    | 12x12 White w/Gray<br>Streaks VFT | 700                  | SF                | Room 218          |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                     | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 29    | 12x12 White w/Gray<br>Streaks VFT Mastic | 700                  | SF                | Room 218          |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

| School: | Horace Greeley Elementary School |
|---------|----------------------------------|
| Date:   | 1/10/2019                        |

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.


Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child



# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.