Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Marvin Camras Elementary School 22691 School: **Oracle Unit: Building ID:** Address: 3000 N. Mango Region: 02 Mail Room: Asbestos Surveyor: Cassaccio, Nicholas X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Other Each child's backpack Notice printed in school's calendar HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity Throughout 1938 Main YES 01 X NO Plaster None Building 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

0040 5 11					7						
	: No Change										
Comments:											
2017 - Fall:	: No Change										
Comments	•										
					_						
2017 - Spri	ng: No Change										
Comments	:										
2018 - Fall:	: No Change										
Comments	:	1									
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
1		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material

Quantity

5000

Material

Units

SF

Material Location

Hallways 19338 Main

Throughout 1938 Main

Building

Building

HA No

02

03

Material Description

2'x4' White Fissured Ceiling

1'x1' White w/ Holes Ceiling

Change in Assessment Category

X NO

X NO

YES

03A	1'x1' White w/ Holes Ceiling Tile Mastic	10000	SF	Throughout 1938 Building		Miscellaneous		None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:					-							
2017 - Fall:	No Change				_							
Comments:												
2017 - Sprir	ng: No Change											
Comments:					-							
2018 - Fall:	No Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04	Dry Wall System	2500	SF	Throughout 1938 Main		Miscellaneous		None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Building

Material

Units

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	12"x12" Beige & Brown VFT	5000	SF	3rd Floor Cafeteria- 1938 Building		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				-							
Comments:					1							

2018 - Fall	: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	12"x12" Beige & Brown VFT Mastic	5000	SF	3rd Floor Cafeteria -1938 Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

								l	
06	12"x12' White w/ Gray Streaks VFT	18000	SF	Throughout 1938 Main Building	Miscellaneous	None	0	YES	X NO
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:	<u> </u>								
2017 - Fall: N	o Change								
Comments:	<u> </u>								
Commonto.									
2018 - Fall: N	o Change								

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	12"x12' White w/ Gray Streaks VFT Mastic	18000	SF	Throughout 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
07	12"x12" Yellow Streaked VFT	5000	SF	Throughout 1938 Main Building		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07A	12"x12' Yellow Streaked VFT Mastic	5000	SF	Throughout 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
					_							
Comments.					1							
Comments:	-				1							
2018 - Fall: N	No Change											
Commenter												
Comments:												
2017 - Fall: N	No Change											
Comments.												
Comments:	g				1							
2017 - Spring	g: No Change											
Commenter												
Comments:	<u> </u>				1							
2016 - Fall: N	No Change											
				Building								
08	Beige Vinyl Baseboard	10000	SF	Throughout 1938 Main Building		Miscellaneous		None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

		Quantity	Units		Туре	Category	Туре	Quantity	Units	
08A	Beige Vinyl Baseboard Mastic	10000	SF	Throughout 1938 Main Building		Miscellaneous	None	0		YES
2016 - Fa	ıll: No Change]					
Commen	ts:				1					
2017 - Fa	ıll: No Change									
Commen	ts:				-					
2017 - Sp	oring: No Change				1					

Material Location

Throughout 1938 Main

Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
09	Air Cell Panel Insulation (Univents)	600	SF	3rd Floor Cafeteria- 1938 Building		TSI		None	0		YES	X NO
0040 F.II N	. 01			_								
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	·											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9"x9" Orange VFT	1500	SF	Throughout 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

10A	9"x 9" Orange VFT Mastic	1500	SF	Throughout 1938 Main Building	Miscellaneous	None	0	YES	X NO
2016 - Fall: N	lo Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:	<u> </u>								
2017 - Spring	ı: No Change								
Comments:									
2018 - Fall: N	lo Change								

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12'x12' Brown VFT	300	SF	SW and SE Stairwells- 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

11A	12"X12" Brown VF1 Mastic	300	SF	1938 Main Building		Miscellaneous		None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	140 Change											
2047 Falls	No Change											
2017 - Fall:	No Change				4							
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

12	Dark Brown Border VFT	600	SF	SW and SE Stairwells- 1938 Main Building	
2016 - Fall: N	lo Change				
Comments:					
2017 - Spring	: No Change				
Comments:					
2017 - Fall: N	lo Change				
Comments:					
2018 - Fall: N	lo Change				
Comments:					

Quantity

Units

Material

Units

SF

Material

Quantity

300

Material Location

SW and SE Stairwells-

SW and SE Stairwells-

HA No

11A

Material Description

12"x12" Brown VFT Mastic

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12A	Dark Brown Border VFT	600	SF	SW and SE Stairwells- 1938 Main Building		Miscellaneous		None	0		YES	X NO
2016 - Fall:	No Change]							
Comments	:				1							
2017 - Fall:	No Change				_							
Comments	:] -							
2017 - Spri	ng: No Change											
Comments	:				 							
2018 - Fall:	No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Beige Linoleum w/ Dark Waves	20	SF	Room 300G - 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

13A	Beige linoleum w/ Dark Waves Mastic	20	SF	Room 300G - 1938 Main Building	Miscellaneous	None	0	YES	X NO
2016 - Fall: I	No Change								
Comments:									
2017 - Fall: I	No Change								
Comments:									
2017 - Sprin	g: No Change								
Comments:									
2018 - Fall: I	No Change								
Comments:									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Terrazzo Floor	15000	SF	Throughout 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Oracle Unit: 22691

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	2'x2' White w/ Pinholes Ceiling Tile	10000	SF	Room 309- 1938 Main Building		Miscellaneous		None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" White w/ Blue Specs VFT	2000	SF	Rooms 312,314 - 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 13

16A	Specs VFT Mastic	2000	SF	Main Building		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

Change in Assessment Category

X NO

X NO

YES

YES

17	18"x18' White Textured Ceiling		Rooms 312,314 & 009- 1938 Main Building						
2016 - Fall: N	lo Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:									
2017 - Spring	g: No Change								
Comments:									
2018 - Fall: No Change									
Comments:	Comments:								

Material

Quantity

2000

Material

Units

SF

Material Location

Rooms 312,314 - 1938

HA No

16A

Material Description

12"x12" White w/Blue

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18	12"x12" Red w/ White Streaks VFT	5000	SF	Throughout-1938 Main Building		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
Confinents.
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12"x12" Red w/ White Streaks VFT Mastic	5000	SF	Throughout- 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
19	Back w/ White border VFT	300	SF	Rooms 317, 319, 217 - 1938 Main Building		Miscellaneous		None	0		YES X NO	
2016 - Fall: N	o Change											

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	Black w/ White Border VFT Mastic	300	SF	Rooms 317, 319, 217 - 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 16

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
20	12"x12" Gray w/ Dark Gray Streaks VFT	600	SF	Gym Balcony - 1938 Main Building		Miscellaneous		None	0		YES X NO	
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	12"x12" Gray w/ Dark Gray Streaks VFT Mastic	600	SF	Gym Balcony- 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

21	12"x12' Brown w/ Light & Dark Streaks VFT	100	SF	1st Floor SE and SW Stairwells - 1938 Main Building		Miscellaneous	None	0	YES	X NO
2016 - Fall: No	n Change	•		·	7					
Comments:	o Orlange				-					
Comments.					-					
2017 - Spring:	: No Change									
Comments:										
					4					
2017 - Fall: No	o Change									
Comments:					_					
2018 - Fall: No	o Change									
Comments:	<u> </u>									
					_					

Type

Asbestos

Type

Material

Material

Category

Miscellaneous

Category

Friable

Friable

Damage

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

21A	12"x12" Brown w/ Light & Dark Streaks VFT Mastic	100	SF	1st Floor SE and SW Stairwells - 1938 Main Building						
2016 - Fall: N	No Change									
Comments:	10 0ago									
2017 - Fall: No Change										
Comments:	NO Change									
2017 0	N. O.									
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	Jo Change									
Comments:	NO Change									
Commonto.										

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

1st Floor SE and SW

Material Location

1st Floor SE and SW

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

X NO

22	2'x2' Gray Ceiling Tile	4000	SF	Gym-1938 Main Building		Miscellaneous		None	0		YES	X NO
2016 - Fal	l: No Change											
Comments					1							
2017 - Fal	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fal	l: No Change											
Comments	S:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
				Rooms 211A, 213A,								

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

23	Black w/ Red Border VFT	500	SF	113A, 11A - 1938 Main Building
2016 Fall: N	o Chango			
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

Material

Quantity

Material

Units

Material Location

HA No

Material Description

YES

X NO

23A	Black w/ Red Border VFT Mastic	500	SF	Rooms 211A, 213A, 113A, 11A - 1938 Main Building		Miscellaneous	None	0	YES	X NO
2016 - Fall: N	lo Change]					
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	ı: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										
					J					

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	Carpet Mastic	200	SF	Rooms 114, 112, 112A, Basement Locker Room		Miscellaneous		None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	Category
25	1'x1' White Grooved Ceiling Tile	800	SF	Throughout 1938 Main Building		Miscellaneous		None	0		YES X	NO
2016 - Fall: N	lo Change	•	•	_]		•			•		

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	1'x1' White Grooved Ceiling Tile Mastic	800	SF	Throughout 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmer	nt Category
26	Air cell Pipe Insulation	2000	LF	Throughout 1938 Main Building		TSI		None	0		YES	K NO
2016 - Fall	No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2010 5 11 11 21
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	MJP on Air cell Pipe Insulation	138	EA	Throughout 1938 Main Building		TSI		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Green Streaked VFT	300	SF	Room 107-1938 Main Building		Miscellaneous		None	0		YES X NO
2010 5 11 1					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	12"x12" Green Streaked VFT Mastic	300	SF	Room 007-1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

29	9"x9" Gray VFT	100	SF	Mechanical Room 017- 1938 Main Building		Miscellaneous	None	0	YES	X NO
2016 - Fall: N	lo Change]					
Comments:	-]					
2017 - Spring	g: No Change									
Comments:					1					
2017 - Fall: N	lo Change									
Comments:					-					
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29A	9"x9" Gray VFT Mastic	100	SF	Mechanical Room 017- 1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

30	Vibration Damper Cloth	10	SF	Mechanical Room 017- 1938 Main Building		Miscellaneous	None	0	YES	X NO
					1					
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	r: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										
•	•			•						

Type

Material

Category

Material

Friable

Friable

Damage

Damage

Type

Damage

Quantity

Damage

Damage

Damage

Units

		Quantity	Units		Туре	Category	Туре	Quantity	Units	3.
31	Tank Insulation	120	SF	Mechanical Room 017- 1938 Main Building		TSI	None	0		YES
	all: No Change]					
Commer										
2017 - Fa	all: No Change									
Commer	nts:				-					
2017 - S	pring: No Change									

Asbestos

Comments: 2018 - Fall: No Change Comments:

HA No

HA No

Material Description

Material Description

Material

Material

Units

Material

Quantity

Material

Material Location

Material Location

Change in Assessment Category

Change in Assessment Category

X NO

32	Red Fire Stop Caulking	10	SF	Mechanical Room 017- 1938 Main Building	Miscellaneous	None	0	YES	X NO
2016 - Fall:	No Change								
Comments:									
2017 - Fall:	No Change								
Comments:	<u> </u>								
2017 - Sprir	ıg: No Change								
Comments:	<u> </u>								
2018 - Fall·	No Change								

Material

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" White w/Gray Streaks VFT	2700	SF	Throughout 1956 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
33A	12"x12" White w/ Gray Streaks VFT Mastic	2700	SF	Throughout 1956 Addition		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Yellow Streaked VFT	3500	SF	Throughout 1956 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
34A	12"x12" Yellow Streaked VFT Mastic	3500	SF	Throughout 1956 Addition		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	1'x1' White w/ Holes Ceiling Tile	4000	SF	Throughout 1956 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

35A	1'x1' White w/ holes Ceiling Tile Mastic	4000	SF	Throughout 1956 Addition		Miscellaneous	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	-									
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										
					l					

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Throughout 1956

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Terazzo Floor	4000	SF	Throughout 1956 Addition		Miscellaneous		None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

1'x1' White w/ holes Ceiling

Material

Quantity

Material

Units

37	Dry Wall System	2000	SF	Throughout 1956 Addition		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change				_							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	•											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material Location

Rooms 318D, 218C,

218E, 218F- 1956

Addition

2800

SF

HA No

38

Material Description

12"x12" Red w/ White

Streaked VFT

Material

Quantity

Material

Units

YES

X NO

38A	12"x12" Red w/ White Streaks VFT Mastic	2800	SF	Rooms 318D, 218C, 218E, 218F- 1956 Addition		Miscellaneous		None	0		YES	X NO
	•	*	•		7	•	•	•	•	•		
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	a consuming constraints											
Comments.					_							
2017 - Spring	ı. No Change				1							
	1. No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					1							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Black w/ White Border VFT	100	SF	Room 318D- 1956 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39A	Black w/ White Border VFT Mastic	100	SF	Rooms 318D- 1956 Addition		Miscellaneous		None	0		YES X NO
2016 - Fall: I	No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	1'x1' White w/ Grooves Ceiling Tile	2500	SF	Library 120 - 1956 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	y
40A	1'x1' White w/ Grooves Ceiling Tile Mastic	2500	SF	Library 120 - 1956 Addition		Miscellaneous		None	0		YES X NO	
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Light Green Streaked VFT	900	SF	Room 20 - 1956 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
<u> </u>	

41A	12"x12" Light Green Streaked VFT Mastic	900	SF	Room 20 - 1956 Addition		Miscellaneous		None	0		YES	X NO
0040 5-11	N. Olasas				1							
2016 - Fall:												
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					1							
					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

42	12"x12" Green Streaked VFT	900	SF	Room 20 - 1956 Addition							
2016 - Fall: No Change											
Comments:											
2017 - Spring: No Change											
Comments:											
2017 - Fall: No Change											
Comments:											
2018 - Fall: No Change											
Comments:		_									

Quantity

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

42A	VFT Mastic	900	SF	Room 20 - 1956 Addition		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

None

Damage

Quantity

0

Damage

Units

200

HA No

42A

43

Material Description

12"x12" Green Streaked

Air Cell Pipe Insulation

Material

Quantity

900

Material

Units

SF

LF

Material Location

Room 20 - 1956 Addition

Room 20 - 1956 Addition

Change in Assessment Category

X NO

X NO

YES

					7						
2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
					_						
2017 - Sprin	ng: No Change										
Comments:											
					1						
2018 - Fall:	No Change										
Comments:					1						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

TSI

Category

TSI

Category

Friable

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

44	Paper Wrap Pipe Insulation	400	LF	Room 20 - 1956 Addition							
	•										
2016 - Fall: No Change											
Comments:											
2017 - Spring: No Change											
Comments:											
2017 - Fall: No Change											
Comments:											
2018 - Fall: No Change											
Comments:				·							
			•								

Quantity

Material

Quantity

30

Material

Units

Units

LF

Material Location

Room 20 - 1956 Addition

HA No

43A

Material Description

MJP on Air cell Pipe

Insulation

Change in Assessment Category

X NO

X NO

YES

44A	MJP on Paperwork Pipe Insulation	70	EA	Room 20 - 1956 Addition		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	10 Onango				1							
0047 5-11 1	I. Ohana]							
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	<u> </u>											
<u> </u>					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ement Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	FIIable	Type	Quantity	Units	Change in Asses	Sment Category
		Quantity	Office		1,700	Outogory		1,700	Quantity	011113		
46	Plaster			Throughout 1956 Addition							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

47	Dry Wall System	2500	SF	Throughout 1962 Addition		Miscellaneous	None	0	YES	X NO
2016 - Fall: N	lo Change]					
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	lo Change				-					
Comments:	<u> </u>									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	1'x1' White w/ Holes Ceiling Tile	15000	SF	Throughout 1962 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
48A	1'x1' White w/ holes Ceiling Tile Mastic	15000	SF	Throughout 1962 Addition		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: No Change												

2017 - Spring: No Change

Comments:

2018 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	9"x9" Orange VFT	4500	SF	Rooms 323, 324, 325, 327, 225, 223 and 224		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
49A	9"x9" Orange VFT Mastic	1500	SF	Rooms 323, 324, 325, 327, 225, 223 and 224		Miscellaneous		None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N Comments:	lo Change	-										
2017 - Spring Comments:	g: No Change	-										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Terrazzo	5000	SF	Throughout 1962 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

51	Beige Vinyl Baseboard	240	LF	Throughout 1962 Addition		Miscellaneous	None	0	YES	X NO
0040 5 1	N. O.				1					
2016 - Fai	: No Change									
Comments	:									
2017 - Spr	ing: No Change									
Comments	S:									
2017 - Fal	: No Change									
Comments): :									
2018 - Fal	: No Change									
Comments										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51A	Beige Vinyl Baseboard Mastic	240	LF	Throughout 1962 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

		Quantity	Units		Type	Category	Туре	Quantity	Units		
52	12"x12" White w/ Gray Streaks VFT	5500	SF	Throughout 1962 Addition		Miscellaneous	None	0		YES	X NO
					7						
2016 - Fall: N	lo Change										
Comments:											
					1						
2017 - Spring	g: No Change										

Material

Friable

Damage

Damage

Asbestos

Comments:

2017 - Fall: No Change
Comments:

Material Material Location

2018 - Fall: No Change Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52A	12"x12" White w/ Gray Streaks VFT Mastic	5500	SF	Throughout 1962 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12"x12" Yellow Streaked VFT	1400	SF	Throughout 1962 Addition		Miscellaneous		None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2047 Caring No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53A	12"x12" Yellow Streaked VFT Mastic	1400	SF	Throughout 1962 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

H	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Ę	54	12"x12" Gray w/ Green Specks VFT	800	SF	Room 227 - 1962 Addition		Miscellaneous		None	0		YES X NO
2	2016 - Fall: No	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54A	12"x12" Gray w/Green Specks VFT Mastic	800	SF	Room 227-1962 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

55	Green Vinyl Baseboard	60	LF	Room 125-1962 Addition		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

0

Material

Units

SF

Material

Quantity

Material Location

Room 125-1962 Addition

HA No

55A

Material Description

Green Vinyl Baseboard

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	2'x2' White w/ Pinhole Ceiling Tile	400	SF	Room 129, 023 - 1962 Addition		Miscellaneous		None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"x12" White w/ Multicolor Streaks VFT	800	SF	Room 023-1962 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

57A	Strek	800	SF	Room 023-1962 Addition		Miscellaneous		None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:												
2017 - Fall: I	No Change											
Comments:					_							
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
58	Tank Insulation			Mechanical Room 022- 1962 Addition							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

12"x12' White w/ Multicolor

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

59	MJP on Fiberglass Pip Runs	244	EA	Mechanical Rooms 321,221,121,021 an 022 -1962 Addition		TSI	None	0	YES	X NO
2016 - Fal	II: No Change	<u> </u>	•	<u> </u>	1				·	
Comment]					
2017 - Fal	II: No Change				_					
Comment	S:									
2017 - Sp	ring: No Change				_					
Comment	S:									
2018 - Fal	II: No Change				1					
Comment	s:									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Mechanical Rooms

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Transite Table Tops	10	SF	Room 211-1962 Addition		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Paper wrap Pipe Insulation	2000	LF	Throughout 1938 Main Building		TSI		None	0		YES X NO
2016 - Fall: N	lo Change										

016 - Fall: No Change
comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61A	MJP on Paperwrap Pipe Insulation	124	EA	Throughout 1938 Main Building		TSI		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
62	Vibration Damper Cloth	40	SF	Mechanical Room 321- 1962 Addition		TSI		None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	_											
2017 - Fall: N	lo Change											
Comments:												

2017 - Spring: No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Duct Insulation	200	SF	Mechanical Room 321 -1962		TSI		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12"x12" Brown Streaked VFT	500	SF	Room 000B-1938 Main Building		Miscellaneous		None	0		YES X NO
2016 - Fall: N	lo Change										

016 - Fall: No Change
Comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64A	12"x12' Brown Streaked VFT Mastic	500	SF	Room 000B-1938 Main Building		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Marvin Camras Elementary School
Date:	1/8/2019
	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of
	os Management Plan is available at each school during school hours by appointment.
Requests to	o review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please	e be advised that CPS conducts asbestos inspections of all Schools every three years.
The last ins	spection was completed in 2016.
Asbestos s	urveillances are conducted every six months.
CHECK ON	<u>IE</u>
A co	ppy of this notice was sent home in each child's backpack.
A co	ppy of this notice was printed in the school's newsletter and sent home with each child
A co	ppy of this notice was printed in the school's calendar and sent home with each child
Othe	er.
A COPY	OF THIS NOTICE MUST BE PLACED IN THE
	OOL'S ASBESTOS MANAGEMENT PLAN.