Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Frederic Chopin Elementary School 22721 2770 School: **Oracle Unit:** Building ID: 2450 W. Rice Street Address: Region: 02 Mail Room: Asbestos Surveyor: Mallett, Glenda X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/11/2018 Email Address: gmallett@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type NW. NE. SE. & SW YES X NO 01 12x12 Green VFT SF 1500 Stairwells 1st to 2nd Miscellaneous No None 0 Floors 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 22721

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
1-C	MJP Elbow on Air Cell Pipe Insulation	10	LF	Fan Rooms, Bathrooms, Basement South Corridor		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	Pre-formed (Mag Block) Pipe Insulation	408	LF	Air Tunnels and Under Auditorium in Crawl Space		TSI	Yes	Loc	25		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03	Plaster	160000	SF	Throughout School		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	Ţ											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Blown In Insulation	10000	SF	Attic		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
05	1x1 Ceiling Tile	1500	SF	2nd Floor Gym		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change				=							
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	<u> </u>											
1					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Green Vinyl Floor Tile Mastic	1500	SF	NW, NE, SE, & SW Stairwells 1st to 2nd Floors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	Drywall	450	SF	Room #101, #112 bath.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	No Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	No Change											
Comments:	•				1							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	1x1 Ceiling Tile Brown Mastic	1500	SF	2nd Floor Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Red/Brown Vinyl Floor Tile	900	SF	Auditorium Stairwells, Engineers Office & Closet, Rooms 106, 105 - Not observed in Room 105, 106 and 104		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
14	12"x12" Red/Brown Vinyl Tile Mastic	900	SF	Auditorium Strairwell, Engineers Office & Closet, Rooms 106, 105, 104 - Not observed in ROOM 105, 106 and 104		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" White Vinyl Floor Tile	1700	SF	2nd Floor Main Offices, Rooms 106, 105, 104 (Lunch Rooms)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
16	12"x12" White Vinyl Floor Tile Mastic	1700	SF	2nd Floor Main Offices, Rooms 106, 105, 104 (Lunch Rooms)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12x12 Grey/Brown VFT	400	SF	Engineers Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12x12 Grey/Brown VFT Mastic	400	SF	Engineers Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
19	12x12 Light Brown/Yellow VFT	1200	SF	NW, NE, SE, SW Stairwells 2nd -3rd Flrs, NW & NE 3rd Flr Balcony Landings (Under Carpet) - Could not verify under cabinet		Miscellaneous	No	None	0		YES	x NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12x12 Light Brown/Yellow VFT Mastic	1200	SF	NW, NE, SE, SW Stairwells 2nd-3rd Flrs, NW & NE 3rd Flr Balcony Landings (Under Carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Tan VFT	800	SF	Room 104, 105		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
24	12"x12" Tan VFT Mastic	800	SF	Room 104, 105		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				\neg							
Comments	s:											
2017 - Spr	ring: No Change											
Comments	S:				_							
2017 - Fal	II: No Change											
Comments	s:			<u> </u>								
2018 - Fal	II: No Change											

					2.1			71			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
26	12"x12" Brown VFT Mastic	800	SF	Room 104, 105, 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring	g: No Change				-							
Comments:]							
2018 - Fall: N	No Change				-							
Comments:	•				1							
2018 - Spring	g : No Change				=							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Carpet Mastic (yellow and black mastic under red carpet), no VFT observed.	1800	SF	Room 20 and Library		Miscellaneous	No	None	0		YES X NO

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Air Cell Pipe Insulation	160	LF	Fan Rooms, Bathrooms, Basement South Corridor, Tunnel Entrance and 101 Bathroom		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	MJP E/F/V on Fiberglass Pipe Insulation	25	LF	Bathroom Pipe Chases and 211 Wardrobe		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

F	Incinerator - Fire Yellow Brick	35	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	Mortar (Associated with	20	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Incinerator - Fire Yellow

Incinerator Fire Brick)

2016 - Fall: No Change

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	12' x 12" VFT - Pink with White Streaks	15	SF	Room 112 - New Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Mastic Associated with New VFT Pink with White Streaks	15	SF	Room 112 - New Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	12" x 12" VFT - Green with Dark Green Streaks	24	SF	Room 112 - New Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	Mastic - Associated with HA #J - 12" x 12" Green with Dark Green Streaks	24	SF	Room 112 - New Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	2' x 2' White Ceiling Tile	48	SF	Room 112 - New Bathroom		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Frederic Chopin Elementary School
Date: 12/11/2018
·
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.