Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Grover Cleveland Elementary School 22741 2800 School: **Oracle Unit: Building ID:** Address: 3121 W Byron Avenue Region: 01 Mail Room: Asbestos Surveyor: Bailey, Jared X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Rooms 101 and 210: YES X NO 03 9"x9" Brown VFT SF 4300 203A & 203B (under Miscellaneous No None 0 existing flooring). 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

04	12"x12" Tan Spotted VFT	270	SF	203A , 203B , 103, Engineers Office.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments												
2017 - Spri	ng: No Change				-							
Comments					1							
2017 - Fall	: No Change											
Comments	:											
2018 - Spri	ing : No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	Green Linoleum	5000	SF	Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2018 - Spring : No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material Quantity Material Location

Auditorium Balcony,

Change in Assessment Category

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9"x9" Brown VFT Mastic	4300	SF	NOT OBSERVED in Rooms 101, 210 & Main Office; 203A & 203B (under exisitng flooring).		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N Comments:	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Tan Spotted VFT Mastic	270	SF	Auditorium Balcony, 203A, 203B, 103 & Engineers office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
08	Green Linoleum Mastic	5000	SF	Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fal	I: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	S:											
2018 - Fal	I: No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Drywall Joint Compound	200	LF	Room's 100, 203B, 203 A, 301		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

12	9"x9" Gray VFT	875	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J				1							
2017 - Spring	g: No Change				_							
Comments:					1							
2017 - Fall: N	lo Change				-							
Comments:					1							
2018 - Spring	g : No Change				_							
Comments:												
2018 - Fall: N	lo Change											
Comments:					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
13	9"x9" Gray VFT Mastic	875	SF	Room 106		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage Quantity Change in Assessment Category

HA No

Material Description

2016 - Fall: No Change

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	12"x12" Rust VFT	400	SF	Kitchen, Engineers Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	: No Change				=							
Comments	:											
2018 - Spri	ing : No Change				_							
Comments	:											
2018 - Fall:	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Rust VFT Mastic	400	SF	Kitchen, Engineers Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" White Streaked VFT	300	SF	Kitchen		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" White Streaked VFT Mastic	300	SF	Kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Exterior Window Caulk	9000	LF	Exterior Windows		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" x 12" White VFT	8000	SF	1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitors closets (under ceramic floor).		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" White VFT Mastic	8000	SF	1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitor's closets (under ceramic floor).		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

23 12" x 12" Grey VFT 2000 SF 1st thru 3rd Floor Corridors No None 0 TYES X NO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	23	12" x 12" Grey VFT	2000	SF			Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Grey VFT Mastic	2000	SF	1st thru 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
25	Drywall	1500	SF	Room's 100, 203B, 203 A, 301		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12 x 12 inch Brwn w/Wht Specks VFT	250	SF	Gym Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26 A	12 x 12 inch Brwn w/Wht Specks VFT Mastic	250	SF	Gym Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change]			_			

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
27	Fire Doors	3	EA	Boiler Room		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
28	12"x12" white & beige floor tile	2000	SF	throughout mobile unit		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	12"x12" white and beige floor tile (MASTIC)	2000	SF	throughout mobile unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		0 ,
29	2'x2' ceiling tile	1800	SF	corridor and classrooms in mobile unit		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fa	III: No Change				1							
Commen	ts:											
2017 - Sp	oring: No Change											
Commen	ts:											
2017 - Fa	III: No Change											
Commen	ts:				-							
2018 - Sp	oring : No Change											
Commen	ts:											
2018 - Fa	III: No Change											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	vinyl baseboard mastic	200	LF	throughout mobile unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
31	dry wall, tape & compound	3000	SF	throughout mobile unit		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change				_							
Comments:	•											
2017 - Fall: N	lo Change				_							
Comments:]							
2018 - Spring	g : No Change				_							
Comments:	g											
2018 - Fall: N	lo Change				_							
Comments:	10 Onlango				1							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Textured ceiling paint	300	SF	men's/women's toilet & mechanical room in mobile unit		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33	Fire Door	1	EA	mobile unit mechanical room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	•											
2017 - Sprir	ng: No Change				_							
Comments:												
2017 - Fall:	No Change				_							
Comments:												
2018 - Sprir	ng : No Change				-							
Comments:	-											
2018 - Fall:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	decorative plaster	2000	SF	auditorium main bldg.		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

35	2'x4' ceiling tile	1600	SF	Basement Room 500, 700, engineers office main bldg.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	10 Ondrigo				-							
2017 - Sprin	g: No Change											
Comments:	g											
2017 - Fall: I	No Change				-							
Comments:												
2018 - Sprin	g : No Change				-							
Comments:												
2018 - Fall: I	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
36	12"x12" Pink floor tile	200	SF	teachers toilets, slop sinks rooms, stair landing & room 700 closet in		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Basement Room 500,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	∍gory
36A	12"x12" pink floor tile & MASTIC	200	SF	teachers toilets, slop sinks rooms, stair landings & room 700 closet in main bldg.		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change											
2017 - Spring	ı: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" sand VFT	400	SF	Basement Room 350 main bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	
Comments: 2017 - Spring: No Change	
Comments: 2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
HA No Material Description Material Material Location Asbestos Material Friable Damage Damage Quantity Units Type Category Type Quantity Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Units

Damage

Quantity

0

None

Change in Assessment Category

800

HA No

38

Material Description

Vinyl Baseboard mastic

Material

Quantity

Material

Units

LF

Material Location

Basement Room 350

1st & 2nd floor corridors

main bldg.

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
39	Skim Coat and Hard Plaster			Throughout		Surface	Yes	Unknown			YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:	<u>-</u>											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
r-	1							1			1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Glazed Brick Mortar			Toilet Rooms		Miscellaneous	No	Unknown			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41	Ceramic Floor Tile Mortar			Toilet Rooms		Miscellaneous	No	Unknown			YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	<u> </u>											
Comments:												
	ng : No Change											
Comments:												
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cardboard Pipe Insulation	350	LF	Boiler, Pump, Engine, & Airhandling Rooms, Rm 100, Cold Deck, Rm 100		TSI	Yes	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Cardboard Pipe Insulation	15	LF	Kitchen, Boiler, Pump, Engine & room 100		TSI	Yes	None	4		YES X NO
204C Fall N	a Changa										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Aircell Duct Insulation	1940	SF	Boy's Playroom, Main Electrical room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Mag Block Insulation	80	SF	Feed Water Tank Pump Room		TSI	Yes	Loc	20		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Aircell Pipe Insulation	100	SF	Rooms 100, 200, 300 & 500		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	MJP E/F/V on Aircell Pipe Insulation	4	LF	Rooms 100, 200, 300 & 500		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Carpet Mastic	2380	SF	MDF, Assembly Hall, Balcony		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 25

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Fiber Glass pipes	150	EA	Boiler room, Janitor's closets, kitchen, water main room, room 500 toilet main bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Grover Cleveland Elementary School
Date: 1/9/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 22741

SCHOOL'S ASBESTOS MANAGEMENT PLAN.