Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Henry R Clissold Elementary School 22761 2820 School: **Oracle Unit: Building ID:** 2350 W. 110th Pl. Address: Region: Mail Room: Asbestos Surveyor: Walsh, Laura X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Auditorium, 2nd & 3rd YES 04A SF 0 X NO 9"x9" Red Floor Tile 3775 Miscellaneous No None Floor Corridors 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 22761

04B	9"x9" Black Floor Tile	3775	SF	Assembly Hall, 2nd & 3rd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
0040 5.11	N. Olasasa				1							
	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	-											
		•	•		-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

1175

HA No

04C

Material Description

9"x9" Beige w/Brown & Cream Streaks Floor Tile

Material

Units

SF

Material

Quantity

Material Location

Rooms 105 & 300

Assembly Hall, 2nd & 3rd

Change in Assessment Category

X NO

YES

				I .							
05A	12"x12" Cream w/Tan Specks Floor Tile	3950	SF	1st Floor Corridor, Copy Room 210, 214, 302 and 304		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change				1						
Comments											
2017 - Fall	: No Change				-						
Comments	:										
2017 - Spri	ing: No Change]						
Comments	:				-						
	: No Change										
Comments	:				1						
					_1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05B	12"x12" Cream w/Beige Streaks Floor Tile	1950	SF	Rm 102, 104 and 3rd Floor Teachers Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05C	12"x12" Cream w/Brown & Maroom Specks Floor Tile	1570	SF	Room 103, 303 and 3rd Floor NE Office		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05D	12"x12" Dark Multicolor Beige Floor Tile	1770	SF	Rm 109, 214, 302 and 304		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
05E	12"X12" Cream w/Brown Blotches Floor Tile	720	SF	Room 301		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	:											
2017 - Sprii	ng: No Change											
Comments:	· ·											
2017 - Fall:	No Change											
Comments:	•		•									

2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05F	12"x12" Light Multicolor Beige Floor Tile	50	SF	Teacher's Room (PKA Coat Room)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05G	12"x12" Cream w/Blue Streaks Floor Tile	720	SF	Room 202		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05H	12"x12" Green w/Cream Streaks Floor Tile	400	SF	Engineer Office and Lunch Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2016 Fall	: No Change				\neg						
Comments	:										
2017 - Spr	ing: No Change										
Comments											
2017 - Fall	: No Change										
Comments	:										
2018 - Fall	: No Change										
Comments											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:		•	

1155

Material

Quantity

400

Material

Units

SF

SF

Room 305

Material Location

Engineer Office and Lunch Lounge

HA No

05I

06

Material Description

Olive Green Carpet

Adhesive

Lab Table Top

Change in Assessment Category

X NO

X NO

YES

YES

07A	9"x9" Red Floor Tile Mastic	3775	SF	Auditorium, 2nd & 3rd Floor Corridors	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07B	9"x9" Black Floor Tile Mastic	3775	SF	Assembly Hall, 2nd & 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

Material

Quantity

Material

Units

HA No

Material Description

07C	9"x9" Beige w/Brown and Cream Streaks Floor Tile	1175	SF	Rooms 105 and 300		Miscellaneous	No	None	0		YES	X NO
					1							
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					<u>-</u>							
		1			1		•		1	1		

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08A	12"x12" Cream w/Tan Specks Floor Tile Mastic	3950	SF	1st Floor Corridor, Copy Room 210, Rooms 214, 302, 304, 209		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
08B	12"x12" Cream w/Beige Streaks Floor Tile Mastic	1950	SF	Rm 102, 104 and 3rd flr teachers lounge		Miscellaneous	No	None	0		YES	X NO
					Ì							
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08C	12"x12" Cream w/Brown & Maroon Specks Floor Tile Mastic	1570	SF	Room 103, 3rd Floor NE Office, Room 303		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08D	12"x12" Dark Multicolored Beige Floor Tile Mastic	1770	SF	Rm 109, 214, 302, 209 and 304		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 2 1 11 21	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
08E	12"x12" Cream w/Brown Blotches Floor Tile Mastic	720	SF	Room 301		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
08F	12"x12" Light Multicolor Beige Floor Tile Mastic	50	SF	Teachers Room (PKA Coat Room)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
08H	12"x12" Green w/Cream Streaks Floor Tile Mastic	400	SF	Engineer Office, Lunch Lounge		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

09	Gray Carpet Mastic	1800	SF	Library 205, 207		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	_											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11	Turqoise Carpet Mastic	650	SF	Main Office, Case Manager's Office, Principal's Office		Miscellaneous			0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

12	12"x12" Yellow Floor Tile	80	SF	Main Office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:	-									

Type

Material

Category

Friable

Damage

Туре

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Yellow Floor Tile Mastic	80	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

Change in Assessment Category

Damage

Quantity

Damage

Units

14	12"x12" Red Floor Tile	80	SF	Main Office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Red Floor Tile Mastic	80	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

16	Terrazzo	2000	SF	As a Border in All Corridors, Main Office, Stairwells and Foyers		Miscellaneous	No	None	0		YES	X NO
0040 5-11	NI- Ol-				_							
	: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	::											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Surface

Friable

Yes

Damage

Туре

None

Damage

Quantity

0

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

110000

Material

Quantity

Material

Units

SF

Material Location

As a Border in All

Throughout Facility

HA No

17

Material Description

Plaster Walls and Ceilings

YES

Change in Assessment Category

X NO

18	2'x4' Lay In Ceiling Tile with Pinholes and Fissures	1800	SF	Room 205/207		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments): 				1							
2017 - Fall	: No Change											
Comments	:				-							
2017 - Spr	ing: No Change											
Comments	S :				-							
2018 - Fall	: No Change											
Comments	:				 							
			-		1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Yes

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

2016 - Fall: No Change											
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Quantity

7500

Units

SF

Material

Units

Material

Quantity

Material Location

Assembly Hall

HA No

19

Material Description

12"x12" Ceiling Tile

Change in Assessment Category

X NO

YES

20	12"x12' White w/Blue Specks Floor Tile	2700	SF	Portable Classrooms		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	l: No Change										
Comments	5:										
	ing: No Change										
Comments	3:										
	l: No Change										
Comments	S:										
2018 - Fall	l: No Change										
Comments	S:										
					J						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20M	12"x12' White w/Blue Specks Floor Tile Mastic	2700	SF	Portable Classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change Comments:											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	·

Material

Quantity

Material

Units

HA No

Material Description

21	2x2 White w/ Pinholes Ceiling Tiles	1500	SF	Throughout Mobile Unit (except Bathrooms and Mechanical Rooms		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	-										
2017 - Spring	ı: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					I						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Beige Sheet Flooring	300	SF	Mobile Unit- Girl's and Boy's Restroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

23	Vinyl Baseboard Mastic	750	LF	Throughout Mobile Unit		Miscellaneous	No	None	0		YES	X NO
0040 F-II	NI OL TOTAL				1							
2016 - Fall:	No Change											
Comments												
2017 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
2018 - Fall:	No Change											
Comments												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

TSI

Friable

Yes

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

24	MJP on Fiberglass Pipe Runs	40	LF	Pump Room - Main bldg
2016 - Fall: N	lo Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2017 - Spring	g: No Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:				

Quantity

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

MJP on Fiberglass Pipe

25	Decorative Plaster	800	SF	Auditorium		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	-]							
2017 - Spring	j: No Change											
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Fall: N	lo Change				1							
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Type

Damage

Quantity

Damage

Units

HA No

Α

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Mag Block Insulation on Water Tanks - (ABATED)

Material

Quantity

Material

Units

Material Location

Store Room

YES

X NO

	C	Quantity	Units		Type	Category		Туре	Quantity	Units	
B Aircell P	Pipe Insulation 3	3300	LF	Throughout Basement 2nd Floor Corridor by Room 201 all toilet rooms and Under Auditorium		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cardboard Pipe Insulation	900	LF	Basement and Unexcavated Tunnel Area		TSI	Yes		0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

D	Preformed Pipe Insulation	600	LF	Basement Steam Lines and Tunnel	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	o onango									
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N	o Change									
Comments:		•								

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Aircell Duct Insulation	200	SF	unexcavated area south portion		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

G	MJP E/F/V on Aircell Pipe Insulation	200	LF	Basement Boiler Room, 2nd Foor Corridor by Room 201		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	lo Change			·	1	·					
Comments:]						
2017 - Spring	: No Change				1						
Comments:											
2017 - Fall: N	lo Change				_						
Comments:											
2018 - Fall: N	lo Change				1						
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	MJP E/F/V on Cardboard Pipe Insulation	150	FITTING	Basements, Tunnel Areas and Fan Rooms		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Page 24

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Boiler Gasket	130	LF	Boiler Room		TSI	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

the Asbest	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of tos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	se be advised that CPS conducts asbestos inspections of all Schools every three years aspection was completed in 2016. Surveillances are conducted every six months.
CHECK OF	<u>NE</u>
A c	opy of this notice was sent home in each child's backpack.
A c	opy of this notice was printed in the school's newsletter and sent home with each child
A c	opy of this notice was printed in the school's calendar and sent home with each child
Oth	ner.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.