Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Christopher Columbus Elementary School 22791 School: **Oracle Unit: Building ID:** Address: 1003 N. Leavitt Street Region: 02 Mail Room:

Asbestos Surveyor: Thompson, Cassandra X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/11/2018 Email Address: cthompson35@cps.edu

	A copy of the2016/20	17 notice to	parents and	d staff regarding the ask	oestos manag	jement plan not	ifications v	vas distribute	ed via:			
	Each child's backpa	,	_	printed in school's new				ool's calenda		her		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Catego
01	12"x12" Brown w/ White Speckles Vinyl Floor Tile	1000	SF	2nd Floor Teacher's Lounge & Toilet, Room 306		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: N	No Change				_							
Comments:												
2017 - Sprin	g: No Change				_							
Comments:												
2018 - Fall: I	No Change											
Comments:	_											
2018 - Sprin	g : No Change											
Comments:	-											

Page 1

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1A	MJP E/F/V on Cardboard Pipe Insulation	58	LF	Boiler Rm, Central Engine Rm, Pump Rm, Copy Rm, Janitor's Closet, Engineer's Off, & "H2O Mn" Hall		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1B	Cardboard Pipe Insulation	255	LF	Boiler Room, Engine Room, Pump Room, Copy Room, Janitor's Closet, Central Eng Rm & Engineer's Office		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

1C Aircell Pipe Insulation 192 LF Central Eng Rm, Eng Rm, Pump Room, Copy Room, Kitchen, & Engineer's Office TSI Yes None 0	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	1C	Aircell Pipe Insulation	192	LF	Rm, Pump Room, Copy Room, Kitchen, &		TSI	Yes	None	0		

2016 Falls No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1D	MJP E/F/V on Aircell Pipe Insulation	13	LF	Boiler Room, Engine Room, Pump Room, Copy Room, Kitchen, & Engineer's Office		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1E	MJP E/F/V on Fiberglass Pipe Insulation	60	LF	Copy Rm, Both Eng Rms, Pump Rm, Boiler Rm, Coal Rm, "H2O Main" Hall, Off W of C Eng Rm.		TSI	Yes	None	0		YES X NO

	rian, on it of o bing rain

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" Brown w/ White Speckles VFT Mastic	180	SF	2nd Floor Teacher's Lounge & Toilet, Room 306		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Dark Brown w/ Dark Speckles VFT	3600	SF	Rooms 301, 302, 303, 304, 305, 3rd Fl Girls Toilet Entry, 3rd Floor Corridor, E & W Stair Landings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Dark Brown w/ Dark Speckles VFT Mastic	3600	SF	Rooms 301, 302, 303, 304, 305, 3rd Fl Girls Toilet Entry, 3rd Floor Corridor, E & W Stair Landings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" light Brown w/ Light & Dark Speckles VFT	4440	SF	Rooms 201, 202, 203, 204, 205, 2nd Floor Corridor & Boy's Toilet Entrance, E & W Stair Landings, B-1		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Light Brown w/ Lt & Dk Speckles VFT Mastic	4440	SF	Rooms 201, 202, 203, 204, 205, 2nd Floor Corridor & Boy's Toilet Entrance, E & W Stair Landings, B-1		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments:
Comments: 2017 - Spring: No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Brown Speckled Vinyl Floor Tile Mastic	1480	SF	1st Floor Corridor & Room 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

11A	12"x12" Brown Speckled Vinyl Floor Tile	1600	SF	1st Floor Corridor & Room 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	J											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
12	12"x12" Green w/ White Speckled Vinyl Floor Tile	975	SF	Rm 101, 1st FI Girls Toilet, Kitchen & Toilet, Princ Off, Break Rm, Main Off., C.W. Room		Miscellaneous	No	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

		Main Off., C.W. Room
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		·
	·	 ·

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Green w/ White Speckled VFT Mastic	1000	SF	Rm 101, 1st FI Girls Toilet, Kitchen & Toilet, Princ Off, Break Rm, Main Off., C.W. Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change				1						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Linoleum Flooring	3200	SF	Lunch Room, Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

15	2'x2' Ceiling Tile	3000	SF	Lunch Room, Gym		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	1'x1' Ceiling Tile	550	SF	Stage		Miscellaneous	Yes	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16M	Mastic (Glue Pucks) Associated with HA #16 1' X 1' White Ceiling Tiles	1800	SF	Abovr Suspensed 2' x 2' Ceiling in Gym and Stage		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Hard Coat Plaster	120000	SF	Throughout		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12 x 12 Green with Dark Green Streaks Vinyl Floor Tile	25	SF	Main Office, Room 101, 1st Floor Girls Washroom, Entrance		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	12 x 12 Green with Dark Green Streaks Vinyl Floor Tile Mastic	25	SF	Main Office, Room 101, 1st Floor Girls Washroom, Entrance		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12 x 12 Brown with White and Light Brown Streaks Vinyl Floor Tile	60	SF	1st Floor Corridor, Rooms 201, 202, 203, 204, 205, 2nd Floor Boys Washroom, and 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	12 x 12 Brown with White and Light Brown Streaks Vinyl Floor Tile Mastic	60	SF	1st Floor Corridor, Rooms 201, 202, 203, 204, 205, 2nd Floor Boys Washroom, and 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12 x 12 Orangy Brown with Brown Streaks Vinyl Floor Tile	400	SF	East and West Stairwell Landing, Rooms 301, 302, 303, 304, 305, 3rd Floor Girls Washroom and 3rd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	12 x 12 Orangy Brown with Brown Streaks Vinyl Floor Tile Mastic	400	SF	East and West Stairwell Landing, Rooms 301, 302, 303, 304, 305, 3rd Floor Girls Washroom and 3rd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Black - Spray on under sink coating	6	LF	Room 102		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	Christopher Columbus Elementary School
Date: 12	2/10/2018
This is to noti	ify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of
the Asbestos	Management Plan is available at each school during school hours by appointment. review the Asbestos Management Plan must be made at least 24 hours in advance.
The last inspe	be advised that CPS conducts asbestos inspections of all Schools every three years. ection was completed in 2016. veillances are conducted every six months.
CHECK ONE	
A copy	y of this notice was sent home in each child's backpack.
A copy	y of this notice was printed in the school's newsletter and sent home with each child
A copy	y of this notice was printed in the school's calendar and sent home with each child
Other.	
A COPY C	OF THIS NOTICE MUST BE PLACED IN THE
SCHO	OL'S ASBESTOS MANAGEMENT PLAN.