Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

22871 **Everett McKinley Dirksen Elementary School** 2950 School: **Oracle Unit: Building ID:** Address: 8601 W Foster Avenue Region: 01 Mail Room: 30 Asbestos Surveyor: Flores, Genaro X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/27/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type 1st Floor Kitchen and YES X NO Throughout Building 80 Spray-on Fireproofing 4500 SF Surface Yes None 0 Above The Ceiling Tiles and Drywall - 1970 Bldg. 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12' Beige w/speckles VFT	7500	SF	Main Corridor - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Tan w/ Dark Brown Streaks VFT	2520	SF	Rooms 118, 120, 124, 126, 128 and 130 - 1971 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Beige w/ Specks VFT Mastic	7500	SF	Main Corridor - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Tan w/ Dark Brown Streaks VFT Mastic	2520	SF	Rooms 118, 120, 124, 126, 128 and 130 - 1971 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	MJP E/F/V on Fiberglass Pipe Insulation	150	LF	Throughout - 1970 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	2019 Caring : No Change
2018 - Fall: No Change	1 0 0
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	MJP E/F/V on Fiberglass Pipe Insulation	60	LF	1st Floor - Refuse Room - 1971 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Orange w/ Specks VFT	1200	SF	Main Corridor - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	12"x12" Orange w/ Specks VFT Mastic	1200	SF	Main Corridor - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Yellow w/ Specks VFT	900	SF	Room 104 - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
0040 Fall Na Obaras	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	12"x12" Yellow w/ Specks VFT Mastic	900	SF	Room 104 - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Light Brown VFT	400	SF	Vault - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	12"x12" Light Brown VFT Mastic	400	SF	Vault - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Light Orange VFT	90	SF	102 & 104 Storage - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 Fall N	o Chango	•	•							•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	12"x12" Light Orange VFT Mastic	90	SF	102 & 104 Storage - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Beige w/ Light Green VFT	1400	SF	Lunchroom and Room 102 - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
0040 Fall Na Obaras	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26A	12"x12" Beige w/ Light Green VFT Mastic	1400	SF	Lunchroom and Room 102 - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

27	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	27		2000	SF	and 107 and the Engineers Office - 1970		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	12"x12" Green w/ White VFT Mastic	2000	QE.	Lunchroom, Rooms 102 and 107 and the Engineers Office - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Grey w/ Specks VFT	220	SF	Lunchroom/Workroom and Teacher's Lounge - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	12"x12" Grey w/ Specks VFT Mastic	220	SF	Lunchroom/Workroom and Teacher's Lounge - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Beige (Marble) VFT	3500	SF	Gym, Assistant Principal's Office, Room 201 and 201 Washroom, Room 204, Engineer's Storage Room and the SW Corner of the Library - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring: No Change Comments:
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change
2017 - Spring: No Change Comments: 2018 - Spring : No Change
Comments: 2018 - Spring : No Change
Comments: 2018 - Spring : No Change
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29A	12"x12" Beige (Marble) VFT Mastic	3500	SF	Gym, Assistant Principal's Office, Room 201 and 201 Washroom, Room 204, Engineer's Storage Room and the SW Corner of the Library - 1970 Bldg.		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
30	12"x12" White VFT	1600	SF	Room 202 (Library), Engineer's Corridor and the Gym Stairwells - 1970 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments:	<u> </u>											
2017 - Fall:	: No Change											
Comments:	<u> </u>											
2017 - Sprii	ng: No Change											

Comments:
2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30A	12"x12" White VFT Mastic	1600	SF	Room 202 (Library), Engineer's Corridor and the Gym Stairwells - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Tan w/ Small Specks VFT	7500	SF	Rooms 101, 103, 105, 109, 110, 111, 112, 113, 114, 115 and 201, the Principal's Office and the Main Office - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	12"x12" Tan w/ Small Specks VFT Mastic	7500	SF	Rooms 101, 103, 105, 109, 110, 111, 112, 113, 114 and 115, the Principal's Office and the Main Office - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" White w/ Tan Streaks VFT Mastic	2520	SF	Corridor and Rooms 118, 120, 124, 126, 128 and 130 - 1971 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		0,
33	12"x12" White w/ Beige Speckles VFT	1440	SF	Rooms 119, 121, 122, 123 and 125 - 1971 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change											
Commen	ts:											
2017 - Fa	all: No Change											
Commen	ts:											
2017 - Sp	oring: No Change											
Commen	ts:											
2018 - Sp	oring : No Change											
Commen	ts:											
	all: No Change											
Commen	ts:											
					J							

Asbestos Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	12"x12" White w/ Beige Streaks VFT Mastic	1440	SF	Rooms 119, 121, 122, 123 and 125 - 1971 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Light Tan w/ Black & White Speckles VFT	1440	SF	Rooms 119, 121, 122, 123 and 125 - 1971 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34A	12"x12" Light Tan w/ Black & White Speckles VFT Mastic	1440	SF	Rooms 119, 121, 122, 123 and 125 - 1971 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Type	Quantity Quantity	Units	Change in Asses	ssment Category
35	2'x4' White w/ Grooved Ceiling Tile	9000	SF	Throughout - 1971 Bldg.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments	:											
2017 - Fall:	No Change											
Comments	:				1							
2017 - Spri	ng: No Change											
Comments	:				-							
2018 - Fall	No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" White w/ Tan Streaks VFT	2520	SF	Corridor and Rooms 118, 120, 124, 126, 128 and 130 - 1971 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
<u> </u>

Comments:

Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
37	2'x4' Ceiling Tile	7000	SF	Throughout - 1970 Bldg.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fall	: No Change											
Comments	S:											
2018 - Fall	: No Change											
Comments	S:											
2018 - Spr	ing : No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	2'x2' Ceiling Tile	3250	SF	Throughout - 1970 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
39	Fire Doors	16	EA	1st Floor Electrical Room, 1st Floor MDF Room and the Custodial Locker Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	l: No Change]								
Comments	•				1								
2017 - Spr	ing: No Change				_								
Comments	S:]								
2017 - Fall	l: No Change												
Comments	S:												
2018 - Spr	ing : No Change												
Comments	S:]								
2018 - Fall	l: No Change				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
40	Fire Doors	10	EA	Mobile Unit		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
41	Textured Plaster	270	SF	Men's and Women's Washroom Ceilings - Mobile Unit		Surface	No	None	0		YES	X NO
2016 - Fall: N	lo Change			<u> </u>								

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	12"x12" Crème w/ Brown Specks VFT	2500	SF	Throughout 99 Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

100A	12"x12" Crème w/ Brown Specks VFT Mastic	2500	SF	Throughout 99 Mobile		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	Vo Change]						
Comments:	10 Onango										
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:	ŭ										
2018 - Sprin	g : No Change										
Comments:	g · · · · · · · · · · · · · · · · · · ·										
]						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No N	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 101	2'x2' Ceiling Tile w/ Grooves			Throughout Mobile 99 (Except Washrooms and the Janitor's Closet)							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	Vinyl Baseboard			Throughout 99 Mobile							YES X NO
2016 - Fall: N	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:	<u> </u>										
2017 - Fall: N	No Change										
Comments:	J										
2018 - Fall: I	No Change										
Comments:	<u> </u>										
2018 - Sprin	g : No Change										
Comments:											
LIA NI-	Material Description	I Martania I	I Martardal	Market I Landon	A -11	I Markadal	Estable.	I D	I D	D	01

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102A	Vinyl Baseboard Mastic			Throughout 99 Mobile							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	12"x12" Cream w/Brown Specks VFT	120	SF	E Corridor-Class Doorways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	Comments: 2018 - Fall: No Change	
2018 - Fall: No Change	2018 - Fall: No Change	2018 - Spring : No Change
		Comments:
Commonto	Comments:	2018 - Fall: No Change
Comments:		Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103 A	12"x12" Cream w/Brown Specks VFT Mastic	120	SF	E-Corridor-Class Doorways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units	Туре	Category	Туре	Quantity	Units		
104	Not Used								YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:				-						
2017 - Fall: N	o Change									
Comments:				-						
2018 - Fall: N	o Change									
Comments:				-						
2018 - Spring	: No Change									
Comments:				-						
				_						

Material

Friable

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Terrazzo Flooring	400	SF	Both Stairwells leading to the 2nd Floor Library - 1970 Bldg.		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Drywall joint compound with tape	5000	SF	Throughout the Ceiling Tiles in Building 1970 Bldg.		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	lo Change	•			· ·		• •				

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Drywall Joint Compound with Tape	2000	SF	Above Ceiling Tiles Throughout - 1971 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
108	12X12 Off-white with tan specks VFT	4500	SF	2013 Mobile Unit: Rooms 401 & Storage; 402; Janitor Closet; 403 & Storage; 404; Electrical Room; Hallway; and N & S Entry Vestibules		Miscellaneous	No	None	0		YES [X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108A	12X12 Off-white with tan specks VFT Mastic	4500	SF	2013 Mobile Unit: Rooms 401 & Storage; 402; Janitor Closet; 403 & Storage; 404; Electrical Room; Hallway; and N & S Entry Vestibules		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 22871

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	2'X 2' Ceiling Tile	4900	SF	2013 Mobile Unit: Hallway N and S Entries; Rooms 401 & Storage; 402; 403 & Storage; 404; Boys, Girls and Unisex Toilets		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 22871

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
110	Drywall Systems	10000	SF	Throughout 2013 Mobile Unit		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:]							
2017 - Fall: N	No Change				1							
Comments:	<u> </u>											
2018 - Fall: N	No Change				1							
Comments:	Ţ.											
2018 - Sprine	g : No Change				-							
Comments:	J]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	Vinyl Baseboard Mastic	1000	LF	Rooms 401 and storage, 402, JC, 403 and storage, 404, Electrical Closet, Hallway - 2013 Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	Vinyl Flooring Mastic	400	SF	Boys and Girls toilet and Unisex toilet - 2013 Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 32

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: E	Everett McKinley Dirksen Elementary School
Date: 1	1/27/2018
the Asbestos	tify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of s Management Plan is available at each school during school hours by appointment. review the Asbestos Management Plan must be made at least 24 hours in advance.
The last insp	be advised that CPS conducts asbestos inspections of all Schools every three years. ection was completed in 2016. rveillances are conducted every six months.
CHECK ONE	
A cop	y of this notice was sent home in each child's backpack.
A cop	y of this notice was printed in the school's newsletter and sent home with each child
A cop	y of this notice was printed in the school's calendar and sent home with each child
Other	
A COPY (OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 22871

SCHOOL'S ASBESTOS MANAGEMENT PLAN.