Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Charles R Darwin Elementary School 22881 2960 School: **Oracle Unit: Building ID:** Address: 3116 W. Belden Avenue Region: 02 Mail Room: Asbestos Surveyor: Murphy, James X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: jmurphy37@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 01 SF X NO Plaster Walls and Ceilings 144908 No None 0 Throughout Building Surface 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12"x12" Tan w/ White Streaks Floor Tile	110000	SF	Rooms: 110, 112, 209, 212, 306, 313 - 1899 (Rooms: 002, 107, 108, 210, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	rnable	Type	Quantity	Units	Change in Asse	ssment Category
08	12"x12" Light Brown Floor Tile	4000	SF	Throughout Modular (See Hatching Maps)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: Repaired											
Comments:R	eplaced 3 square feet											
2017 - Fall: N	lo Change											
Comments:	io onango											

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	1'x1' Ceiling Tile - NOT OBSERVED	0		1st & 2nd Floor Corridor - 1919		Miscellaneous	Yes				YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Tan w/ White Streaks Floor Tile Mastic	7000	SF	Rooms: 110, 112, 209, 212, 306, 313 - 1899 (Rooms: 002, 107, 108, 210, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

14	1'x1' Ceiling Tile Mastic - NOT OBSERVED	1st & 2nd Floor Corridor - 1919				YES	X NO
2016 - Fall: N	o Change		1				
Comments:	_						
2017 - Spring Comments:	: No Change		-				
	o Change		=				
2017 - Fall: N Comments:	o Change		-				
2018 - Spring	: No Change						
Comments:			1				
2018 - Fall: N	o Change		_				
Comments:							
			1				

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Vinyl Baseboard Mastic			Throughout - 1899							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17	Wall Board			Throughout Classrooms - 1899							YES	X NO
2016 - Fall:	No Change]							
Comments:					1							
2017 - Sprir	ng: No Change											
Comments:					1							
2017 - Fall:	<u> </u>				-							
Comments:												
	ng : No Change											
Comments:					1							
2018 - Fall:	<u> </u>											
Comments:					-							
L					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Light Brown Floor Tile Mastic	4000	SF	Throughout Modular (See Hatching Maps)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
19	1'x1' Ceiling Tile Mastic			Throughout Modular						YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change				_						
Comments:	<u> </u>										
2018 - Spring	g : No Change										
Comments:	<u> </u>										
2018 - Fall: N	lo Change				-						
Comments:											
_											

Material

Damage

Friable

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Vinyl Baseboard Mastic			Throughout Modular							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
21	Wall Board			Throughout Modular						YES	X NO
2016 - Fall: N	lo Change]						
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change				1						
Comments:											
2018 - Spring	g : No Change				1						
Comments:	<u> </u>										
2018 - Fall: N	lo Change				1						
Comments:	Ü										
					_						
						•	,	,	•		

Material

Damage

Friable

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Vinyl Baseboard			Throughout - 1899							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
25	Wall Joint Compound			Throughout - 1899							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	, <u> </u>											
2017 - Fall: N	lo Change											
Comments:	-											
2018 - Spring	g : No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:	-											
	T			1		1		1	1		·	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Vinyl Baseboard			Throughout Modular							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
27	Wall Joint Compound			Throughout Modular							YES	X NO
2016 - Fall: N	No Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12'x12" Light Brown Floor Tile	2100	SF	304, & 304 Ward - 1919		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

31	12'x12" Light Brown Floor Tile Mastic	2100	SF	304, & 304 Ward - 1919		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change]						
Comments:	<u> </u>										
2017 - Sprin	g: No Change										
Comments:					<u> </u>						
2017 - Fall: I	No Change										
Comments:					1						
	g : No Change				-						
Comments:					-						
2018 - Fall: I	No Change										
Comments:					-						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Vinyl Baseboard			Throughout - 1919							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
33	Vinyl Baseboard Mastic			Throughout - 1919						YES	X NO
2016 - Fall: N	No Change										
Comments:	-										
	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Brown Floor Tile	300	SF	Rooms: 210 - 1899 (Rooms: 206, 305 Ward, 306 Ward NOT OBSERVED)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Brown Floor Tile Mastic	300	SF	Rooms: 210 - 1899 (Rooms: 206, 305 Ward, 306 Ward NOT OBSERVED)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego
36	12"x12" Off White Floor Tile	2000	SF	Rooms 107, 108, 206, 206 Ward, 208, 306, 308, 312 - 1899 (Rooms: 205 Ward NOT OBSERVED)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Off White Floor Tile Mastic	2000	SF	Rooms 107, 108, 206, 206 Ward, 208, 306, 308, 312 - 1899 (Rooms: 205 Ward NOT OBSERVED)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" Dark Brown Floor Tile	1200	SF	Rooms 308A, & 310A - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" Dark Brown Floor Tile Mastic	1200	SF	Rooms 308A, & 310A - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
40	12"x12" Beige Floor Tile	1100	SF	3rd Floor Corridor - 1899		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
2017 - Spring Comments:	g: No Change											
2017 - Fall: N	No Change											
2018 - Spring	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Beige Floor Tile Mastic	1100	SF	3rd Floor Corridor - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Orange Floor Tile _ NOT OBSERVED			Front of Room 003 - 1899							YES X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
	j : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					I						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Orange Floor Tile Mastic - NOT OBSERVED	10	SF	Front of Room 003 - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Black Floor Tile	70	SF	Bottom of Room 003 Stairs - 1899		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Black Floor Tile Mastic	70	SF	Bottom of Room 003 Stairs - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
46	Exterior Window Caulk			Modular							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: Deteriorated											
	plit and pulled away f	rom windov	ws									
2018 - Fall: N	lo Change											
Comments:	Ţ.											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Exterior Window Glaze			Modular							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:Split and pulled away from windows
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12"x12" White w/ Gray Streaks Floor Tile	1500	SF	Multipurpose Room (411) 412, 412A, 509 - Modular		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	lo Chango	•	•	•		•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12"x12" White w/ Gray Streaks Floor Tile Mastic	1500	SF	Multipurpose Room (411), 412, 412A, 509 - Modular		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	9"x9" Floor Tile (Painted Black)	95	SF	1899 Bldg: Corridor by Room 002		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50M	9"x9" Black Floor Tile Mastic	95	SF	1899 Bldg: Corridor by Room 002		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Carpet Adhesive	2100	SF	1899 Bldg: Room 003, Room 012 (Library) (Basement Corridor - NOT OBSERVED)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12"x12" Floor Tile (Painted Black)	75	SF	1899 Bldg: 1st Floor Women's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

53	12"x12" Black Floor Tile Mastic	75	SF	1899 Bldg: 1st Floor Women's Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	to onange				-							
2017 - Spring	g: No Change											
Comments:												
]							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
]							
2018 - Fall: N	lo Change											
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

700

SF

HA No

54

Material Description

Carpet Adhesive

Material

Units

Material

Quantity

Material Location

1919 Bldg: Room 104

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
55	Carpet Adhesive	1400	SF	1919 Bldg: Assembly Hall Balcony and Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Red Linoleum	500	SF	Room 410 (Pantry) - Modular		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Type	Quantity Quantity	Units	Change in Asses	ssment Category
56M	Red Linoleum Adhesive	500	SF	Room 410 (Pantry) - Modular		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:				_							
2017 - Spr	ring: No Change											
Comments	S:				4							
2017 - Fall	l: No Change											
Comments	S:											

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"x12" White w/Multi- colored Specks Floor Tile	300	SF	Office Room (416) - Modular		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12"x12" White w/Multi- colored Specks Floor Tile Mastic	300	SF	Office Room (416) - Modular		Miscellaneous	No	None	0		YES X NO
	•	•	•	-	•	•	•	•	•	=	•

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	12"x12" Grey w/Specks Floor Tile	25	SF	Room 501 ModularNOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	12"x12" Grey w/Specks Floor Tile Mastic	25	SF	Room 501 MODULAR NOT OBSERVED		Miscellaneous	No	None	0		YES X NO
204C Fall N	o Chango										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Sink Undercoating	3	SF	Room 501 MODULAR NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
62	Acoustical Plaster	2000	SF	Auditorium and Balcony		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:]							
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12x12 Gray w/ White Specs VFT	1200	SF	Mens Lounge210C, MDF. 2nd FI Unisex toilet, 112- 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
64	12x12 Gray w/ White Specs- Mastic	1200	SF	Mens loung 210c, MDF. 2nd fl unisex toilet, 112- 1899		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	ıll: No Change				7							
Comment	ts:											
2017 - Sp	oring: No Change				-							
Comment	ts:											
2017 - Fa	ill: No Change				-							
Comment	ts:											
2018 - Sp	oring : No Change				-							
Comment												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Carpet Mastic (Tile Carpet	2000	SF	Library- 1919		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12x12 White w/ black specs VFT	1800	SF	Basement corridor, 023, 002 1899		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12x12 White w/ Black specs Mastic	1800	SF	basement corridor, 023, 002 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12x12 Gray w/ white specs VFT	1600	SF	413, corridor oustise of 413, 510Modular		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Ÿ
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12x12 Gray W/ white specs Mastic	1600	SF	413, corridor outside of 413, 510Modular		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 32

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
70	Carpet Mastic	4700	SF	408, 502, 504-506, 508 Modular		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12x12 white w/ beige specs VFT	1200	SF	514modular		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12x12 White w/ Beige specs Mastic	1200	SF	514 - Modular		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12x12 White w/ gray specks VFT	1900	SF	Rooms 402, 502		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 34

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
74	12x12 White w/Gray Specs VFT Mastic	1900	SF	Rooms 402, 502		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change							•				
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	J											
2018 - Spring	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Boiler & Tank Mag Block Insulation (Abated 7/23/09)			Boiler Room - 1899		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP on Fiberglass Pipe Insulation	610	LF	Engineer's Office, Engineer's Hall, Teacher Lunch Area, Engine, Tank, Coal, & Boiler Rm's, 012A&B, 001, 003 - 1899		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
С	Cardboard Pipe Insulation			Engine Room, 003, Tank Room - 1899		TSI					YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	_											
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					I							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Aircell Pipe Insulation	600	LF	001-003, 012A&B, Eng. Work Area, Teacher Lunch Area, W.A.C., Engine, Tank, Boiler Rms - 1899		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP on Cardboard Pipe Insulation	0	LF	South Dressing Room		TSI	Yes		0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	MJP on Aircell Pipe Insulation	130	LF	001-003, 012A&B, Eng. Work Area, Teacher Lunch Area, W.A.C., Engine, Tank, Boiler Rms - 1899		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	MJP on Fiberglass Pipe Insulation			Basement Corridor, Lunch Room, 1st, 2nd, 3rd, & Basement Toliets - 1919							YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Cardboard Pipe Insulation			Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	MJP on Cardboard Pipe Insulation	30	LF	Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	Aircell Pipe Insulation	150	LF	Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	MJP on Aircell Pipe Insulation	25	LF	Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ch	narles R Darwin Elementary School
Date: <u>1/8</u>	3/2019
This is to notif	y you in accordance with Illinois and Federal Asbestos Regulations, that a copy of
the Asbestos	Management Plan is available at each school during school hours by appointment.
Requests to re	eview the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be	e advised that CPS conducts asbestos inspections of all Schools every three years.
•	ction was completed in 2016.
Asbestos surv	reillances are conducted every six months.
CHECK ONE	
<u>OHEOR ONE</u>	
А сору	of this notice was sent home in each child's backpack.
А сору	of this notice was printed in the school's newsletter and sent home with each child
А сору	of this notice was printed in the school's calendar and sent home with each child
Other.	
A COPY O	F THIS NOTICE MUST BE PLACED IN THE
	DL'S ASBESTOS MANAGEMENT PLAN.