## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Charles Gates Dawes Elementary School 22901 2980 School: **Oracle Unit: Building ID:** Address: 3810 W. 81st St. Region: 05 Mail Room: Asbestos Surveyor: Czerwinski, Thomas **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 1/9/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type orig. BLDG: 1/2 of rms. YES X NO 05A 9x9 tan w/rust streaks 16950 SF 101,103,106,107,108,116 Miscellaneous No None 0 .118.120.122.202-208.210 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05B	9x9 rust w/blk & wht streaks	16950	SF	orig. BLDG: 1/2 of rms. *100, 101,103,106,107,108,116 ,118,120,122,202- 208,210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05C	9x9 green VFT			2nd floor corridor between both additions & women teacher lounge		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: Abated
Comments:New tile in hallway
2018 - Spring : Abated
Comments:New Tile

05D	9 x 9 rust w/streaks ft			2nd floor corridor between both addition & wonem's teacher's lounge		Miscellaneous					YES	X NO
004C Falls	No Observe				7							
2016 - Fall:	No Change				4							
Comments:												
					4							
	ng: No Change											
Comments:												
					_							
2017 - Fall:	No Change											
Comments:												
					_							
2018 - Fall:												
Comments:	New tile in hallway											
2018 - Sprir												
Comments:	New Tile											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
05E	9x9 brown floor tile			1952 - 1st and 2nd floor corridor patches		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
05F	9x9 tan w/ brown floor tile			1954 &1958 - patches in hallways		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : Abated											
Comments:N	lew Tile											
2018 - Fall: A	Abated											
Comments:N	lew tile in hallway											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	12x12 gray w/dark streaks	400	SF	section of room 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06B	12x12 tan w/black streaks	9750	SF	rms: *109, 113,116,118,120,122,211 , 213,121,216,218,224,226		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 22901

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06C	12x12 white w/speck F.T.	6000	SF	basement passage, teachers lunchroom, kitchen lunchroom, modular classroom, book store room		Miscellaneous	No	None	0		YES X NO

	·-
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06D	12x12 white with tan specks floor tile	6048	SF	modular buildings* 220, carpet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: Other
Comments:modulars removed
2017 - Fall: No Change
Comments:
2018 - Fall: Abated
Comments:New Modular buildings
2018 - Spring : Abated
Comments:New Modular buildings

07A	gray swirl multicolor linoleum	840	SF	room 200, room 200-4		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12A	9x9 tan w/blk streaks mastic			1st & 2nd floor corridors		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

2016 - Fall: No Change

Material Description

Material

Units

Material

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13A	9x9 tan w/blk streaks matic			1st & 2nd floor corridors		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1		•		•			
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	<b>.</b>											
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : Abated											
Comments:N	lew Tile											
2018 - Fall: A	Abated											
Comments:N	lew tile in hallway											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	9x9 tan w/rust streaks mastic	16950	SF	orig. BLDG: 1/2 of rms. 100-108,202-208,210, public part of office		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

HA No

Change in Assessment Category

14B	9x9 rust w/blk & wht streaks mastic	13750	SF	orig. BLDG: 1/2 of rms. 100-108,202-208,210, public part of office		Miscellaneous	No	None	0		YES	X NO
004C Fall N	la Ohana	•	•	•	7	•	•	•	•	•	•	
2016 - Fall: N	io Cnange				1							
Comments:												
2017 - Spring	g: No Change											
Comments:	-				1							
					1							
2017 - Fall: N	lo Change				]							
Comments:					1							
					1							
2018 - Spring	g : No Change				1							
Comments:					1							
					1							
2018 - Fall: N	lo Change											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14C	9x9 green VFT mastic			2nd floor corridor between both additions & women teacher lounge		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: Abated
Comments:New tile in hallway
2018 - Spring : Abated
Comments:New Tile

HA No

Comments:

Material Description

Material

Quantity

Material

Units

14D	9x9 rust w/streaks mastic			2nd floor corridor between both addition & women's teaches longe		Miscellaneous					YES	X NO
		·			7						•	
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	Abated											
Comments:	New tile in hallway											
	•											
2018 - Sprin	ng : Abated											
Comments:	New Tile											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units	-	

Type

Asbestos

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Туре

Damage

Quantity

Damage

Units

YES

X NO

14E	9x9 brown floor tile mastic		corridor patches
004C Falls	No Observe		
2016 - Fall: I	No Change		
Comments:			
2017 - Fall: I	No Change		
Comments:			
2017 - Sprin	g: No Change		
Comments:			
2018 - Sprin	g : Abated		
Comments:N	New Tile		
2018 - Fall: A	Abated		
Comments:N	New tile in hallway		
	•	-	

HA No

14E

Material Description

9x9 brown floor tile mastic

Material

Units

Material

Quantity

Material Location

1952 - 1st and 2nd floor

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
14F	9x9 tan w/ brown floor tile mastic			1954 &1958 - patches in hallways		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	•											
2017 - Spring	ı: No Change				]							
Comments:					-							
2017 - Fall: N	lo Change				1							
Comments:					1							
2018 - Spring	: Abated				j							
Comments:N	ew Tile				1							
2018 - Fall: A												
Comments:N	ew tile in hallway				_							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	12x12 gray w/dark streaks mastic	400	SF	section of room 201		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15B	12x12 tan w/black streaks mastic	9750	SF	rms: 109,113,116,118,120,122 , 211,213,121,216,218,224 ,226		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15C	12x12 white w/speck F.T. mastic	6000	SF	basement passage, teachers lunchroom, kitchen lunchroom, modular classroom, book store room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15D	12x12 white with tan specks floor tile mastic	6048	SF	modular buildings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: Other	
Comments:modulars removed	
2017 - Fall: No Change	
Comments:	
2018 - Fall: Abated	
Comments:New Modular buildings	
2018 - Spring : No Change	
Comments:New Modular buildings	

18A	gray swirl multicolor linoleum mastic	840	SF	room 200		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comments												
2017 - Spi	ring: No Change											
Comments												
2017 - Fal	II: No Change											
Comments	S:											
2018 - Spi	ring : No Change											
Comments	s:				_							
2018 - Fal	II: No Change											
Comments	s:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
044	brown baseboard (some		1	rm. 122,120,118,114,			1	1				Tu hia

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

0

Damage

Units

Damage

Quantity

Change in Assessment Category

1370

LF

HA No

21A

Material Description

brown baseboard (some

painted yellow)

Material

Units

Material

Quantity

Material Location

restrm. Teachers lounge,

116

Page 14

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21B	green baseboard	119	LF	rm., 220 (1958)		Miscellaneous	No	None	0		YES X NO
2016 Fall N	2016 Falls No Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21C	black baseboard	419	LF	rooms 201, 109, 122, 113, 220		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
21D	cream baseboard	1000	LF	modular buildings		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change							•	•	•		
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: Other											
Comments:	modulars removed											
2018 - Fall:	Abated											
Comments:	New Modular buildings	6										
2018 - Sprii	ng : No Change											
Comments:	New Modular buildings	6										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21E	light brown baseboard	200	LF	basement, lunchroom, kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
22A	brown baseboard mastic	1370	LF	rm. 122,120,118,114, restrm. Teachers lounge, 116		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				•							
Comments.					1							
2017 - Spring: No Change												
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2019 Spring	ı : No Change				_							
Comments:	j . No Ghange				_							
Committeents.					1							

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22B	green baseboard mastic	119	LF	rm 220		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material

Material Location

Page 17

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domoso	Domoso	Domoso	Change in /	Assessment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
22C	black baseboard mastic	300	LF	rooms 201, 109, 122, 113		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change				]							
Comments												
2017 - Spr	ing: No Change											
Comments												
2017 - Fall	l: No Change											
Comments	S:											
2018 - Spr	ing : No Change											
Comments	S:											
2018 - Fall	l: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22D	cream baseboard mastic	1000	LF	modular buildings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: Other
Comments:modulars removed
2018 - Spring : Abated
Comments:New Modular buildings
2018 - Fall: Abated
Comments:New Modular buildings

	· ·	Quantity	Units		Type	Category		Туре	Quantity	Units		0 ,
22E	light brown baseboard mastic	200	LF	basement, lunchroom, kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:					]							
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:					_							
2018 - Spring	g : No Change				_							
Comments:	_											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Beige Floor Tile	4000	SF	First and Second Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material Material Location

Damage Change in Assessment Category

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
24	12"x12" Beige Floor Tile Adhesive	4000	SF	First and Second Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	ıll: No Change				1							
Comment	ts:				]							
2017 - Sp	oring: No Change				<u> </u>							
Comment	ts:				_							
2017 - Fa	ıll: No Change											
Comment	ts:				4							
2018 - Sp	oring : No Change				1							

Material

Friable

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
A	boiler (mag) insulation	700	SF	boiler room		TSI	Yes	None	0		YES X NO		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Comments:

Comments:

2018 - Fall: No Change

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	aircell pipe insulation	7000	LF	orig bldgbasement,1st & 2nd floors		TSI	Yes	Loc	10		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CM-1	brown carpet mastic	60	SF	room 102 Closet (1954)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	
CM-2	brown carpet mastic	3300	SF	(1958) 112,114,222		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments:												
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change				_							
Comments:												

2018 - Fall: Abated

2018 - Spring : Abated Comments:Tiled

Comments:not sure when changed to tile

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
CM-3	blue carpet mastic	3000	SF	principal's office,rm 111,209, library, 212, 221		Miscellaneous	No	None	0		YES X NO		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

		Quantity	Units		Type	Category	Туре	Quantity	Units		
CM-4	green carpet mastic			room 220, main office		Miscellaneous	None			YES	X NO
2016 - Fall: N	lo Change				7						
Comments:											
2017 - Fall: N	lo Change				1						
Comments:					]						
2017 - Spring	: No Change										
Comments:					_						
2018 - Fall: N	lo Change										
Comments:					_						
2018 - Spring	: No Change				_						
Comments:											
					J						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	*aircell duct wrap, (CLOTH WRAP)	250	LF	1958-crawlspace north and south sections, south wing - N & S areas		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	cardboard pipe insulation	3200	LF	(1958) basement,1st & 2nd floor		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-1	12x12 light blue tile	1125	SF	Room 102, 114, 222		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 24

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT-2	12x12 yellow floor tile	950	SF	Room 112, 1st floor storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	2017 - Spring: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	g : No Change				_							
Comments:	_		•									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-1	12x12 blue mastic	1125	SF	Room 102, 114, 222		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-2	12x12 yellow mastic	950	SF	Room 112, 1st floor storage		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2019 Spring : No Chango	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	fiberglass fittings	150	LF	basement (1954 BLDG.)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Н	aircell MJP	1000	LF	basement,1st & 2nd floors, *BOILER ROOM, LOCKER RM, ENGINEER'S OFF.Fan rms, crawl space, air tunnels		TSI	Yes	Loc	2		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
I	breeching insulation	75	SF	basement boiler room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					1							
2017 - Spring	: No Change											
Comments:					1							
2017 - Fall: N	lo Change				=							
Comments:												
2018 - Spring	: No Change				=							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	aircell pipe insulation	1300	LF	(1958) basement, 1st & 2nd floors, fan rooms, crawl spaces - 1958 bldg and south wing; air tunnels		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

K	cardboard pipe insulation	300	LF	2nd floor		TSI	Yes	Loc	5		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2247 2	N. O.											
	g: No Change											
Comments:												
2017 Falls N	lo Chongo				_							
2017 - Fall: N	io Change				_							
Comments:					_							
2018 - Spring	g : No Change											
	g . No Change				-							
Comments:					_							
2018 - Fall: N	lo Change											
Comments:	io onango				1							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
				1st and 2nf floor boys &				1				Ty.
L	fiberglass fittings & runs	20	FITTING	GIRL'S toilet; FAN ROOM*		TSI	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	cementitous pipe insulation (mag)	75	LF	basement, 1st & 2nd floors		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	PLASTER	1000	SF	BOILER ROOM		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	TRANSITE TYPE BOARDS	250	SF	RAMP OF MODULAR CLASSROOMS		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: Other
Comments:modulars removed
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: C	Charles Gates Dawes Elementary School
Date: 1	/9/2019
the Asbestos	ify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of Management Plan is available at each school during school hours by appointment. review the Asbestos Management Plan must be made at least 24 hours in advance.
·	·
	be advised that CPS conducts asbestos inspections of all Schools every three years. ection was completed in 2016.
•	rveillances are conducted every six months.
CHECK ONE	
<u>CITLOR ONL</u>	
A copy	y of this notice was sent home in each child's backpack.
A copy	y of this notice was printed in the school's newsletter and sent home with each child
A copy	y of this notice was printed in the school's calendar and sent home with each child
Other.	
A COPY O	OF THIS NOTICE MUST BE PLACED IN THE
SCHO	OL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 22901