## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

Thomas Drummond Elementary School 23021 3120 School: **Oracle Unit: Building ID:** 1845 W. Cortland Street Address: Region: 02 Mail Room: Asbestos Surveyor: Cano, Joseph X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Cafeteria Store Room 9"x9" Grey VFT - Not YES X NO 04 SF (1st Floor) - 1891 Bldg. Miscellaneous No None 0 Observed Not Observed 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

05	9"x9" Grey VFT Mastic - Not Observed	400	SF	(1st Floor) - 1891 Bldg. Not Observed		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change										
Comments:											
2017 - Fall: No Change											
Comments:											
	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
					J						

Type

Asbestos

Type

Material

Material

Category

Category

Friable

Friable

Damage

Damage Type

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

06	12"x12" White VFT	2050	SF	wardrobe) and 2nd Floor Hall, 106 Lunchrm, Room 207 - 1891 Bldg	Miscellaneous	No	None	0
2016 - Fa	all: No Change							
Commen	nts:							
2017 - S	pring: No Change							
Commen	nts:							
2017 - Fa	all: No Change							
Commen	nts:							

Material Location

Room 100 (and

HA No

HA No

2018 - Fall: No Change

Comments:

Material Description

9"x9" Grey VFT Mastic -

Material Description

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Cafeteria Store Room

Change in Assessment Category

Change in Assessment Category

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" White VFT Mastic	2000	SF	Rm 103 (and wardrobe), 100 (and wardrobe) and 2nd Floor Hall, 106 Lunchrm - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Blue Linoleum	600	SF	Rm 001 ("Home Mech Room") - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

09	Blue Linoleum Mastic	600	SF	Rm 001 ("Home Mech Room") - 1891 Bldg		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: No Change											
Comments:											
					J						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Brown Narrow Grain VFT Under HA-12 & HA-13 (2016)	650	SF	Rm 107 (and ward), Ward. between 201 and 203 - 1891 Bldg Under HA-12 & HA-13 (2016)		Miscellaneous	No	None	0		YES X NO
2016 - Fall	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11	12"x12" Brown Narrow Grain VFT Mastic Under HA-12 & HA-13 (2016)	650	SF	Rm 107 (and ward), Ward. between 201 and 203 and Hall between 201 and 202 Under HA-12 & HA-13 (2016)		Miscellaneous	No	None	0		YES	х мо
2016 - Fall: N	o Change				1							
Comments:												
2017 - Spring	: No Change				]							
Comments:					_							
2017 - Fall: N	o Change											
Comments:					_							
2018 - Fall: N	o Change											
Comments:					_							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Green VFT	4600	SF	2nd FI Hall, 2nd FI Teachers Lounge, Rms 200, 201, 204, 205, 206, and 303 - 1891 Bldg.		Miscellaneous	No	Dist	75		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Green VFT Mastic	4600	SF	2nd FI Hall, 2nd FI Teachers Lounge, Rms 200, 201, 204, 205, 206, and 303 - 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Beige VFT	36	SF	Room 104 (and wardrobe) - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

15	12"X12" Beige VFT Mastic	36	SF	wardrobe) - 1891 Bldg		Miscellaneous	NO	None	0	YES	<u>X</u> NO
2016 - Fall: N	No Change				1						
	10 Change				4						
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	No Change				]						
Comments:											
					1						
2018 - Fall: N	No Change				]						
Comments:											
					1						
					_						

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material Location

Room 104 (and

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	12"x12" Black VFT - REMOVED			1st Floor Principals office - 1891 Bldg REMOVED		Miscellaneous					YES	X NO
2016 - Comme	Fall: No Change ents:											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

Material

Quantity

36

Material

Units

SF

HA No

15

Material Description

12"x12" Beige VFT Mastic

Change in Assessment Category

X NO

YES

17	12"x12" Black VFT Mastic - REMOVED			- 1891 Bldg REMOVED		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:	110 Chango											
0047 On sin	an Na Ohanan											
	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	rto oriango				1							
Comments.					_							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
	12"x12" Brown WideGrain			1st Fl Hallway, Main								
18	VFT REMOVED			Office Common Area -		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

1891 Bldg. REMOVED

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

19	12"x12" Brown Wide Grain VFT Mastic REMOVED		1st Fl Hallway, Main Office Common Area - 1891 Bldg. REMOVED		Miscellaneous			YES	X NO
2016 - Fall: N	lo Change	·	<u> </u>	]	•	·			
Comments:									
2017 - Fall: N	lo Change			-					
Comments:				]					
2017 - Spring	g: No Change			}					
Comments:									
2018 - Fall: N	lo Change								
Comments:									
				J					

Type

Asbestos

Type

Material

Material

Category

Miscellaneous

Category

Friable

Friable

Damage

Damage

Type

Type

Damage

Quantity

Damage

Quantity

		•	
20	12"x12" Red/Brown VFT - REMOVED		Engineers, Room 107, and 103 Closet - 1891 Bldg REMOVED. NOT OBSERVED in Rms 107 & 103 (2016)
2016 - Fall: N	o Change		=
	o onunge		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			_

Material

Quantity

Material

Material

Units

Units

Material

Quantity

Material Location

Material Location

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

YES

X NO

Damage

Damage

Units

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21	12"x12" Red/Brown VFT Mastic - REMOVED			Engineers, Room 107, and 103 Closet - 1891 Bldg. REMOVED NOT OBSERVED in Rms 107 & 103 (2016)		Miscellaneous					YES	X NO
2016 - Fall: N	o Change	· · · · · · · · · · · · · · · · · · ·		·								

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Blue VFT	600	SF	Room 001 ("Home Mech Room") - 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
23	9"x9" Blue VFT Mastic	600	SF	Room 001 ("Home Mech Room") - 1891 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				]							
Comments	S:											
2017 - Fall	: No Change				_							
Comments	): 				]							
2017 - Spr	ing: No Change				-							
Comments	): 											
2018 - Fall	: No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Grey/Blue/Red VFT	900	SF	Basement: Speech room, Parents room, Rm 007 & Ward - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 11

27	12"x12" Grey/Blue/Red VFT Mastic	900	SF	Basement: Speech room, Parents room, Rm 007 & Ward - 1891 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change			<u> </u>	1					·	·	
Comments					- -							
2017 - Fall:	: No Change				-							
Comments	:				1							
2017 - Spri	ng: No Change											
Comments												
2018 - Fall:	: No Change											
Comments	:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Hard Coat Plaster	78000	SF	Throughout - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

29	12"x12" Ceiling Tile	3600	SF	Third Floor Gym - 1891 Bldg		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	- to onango											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

	Bldg	
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

6000

SF

HA No

30

Material Description

12"x12" Brown and White

VFT

Material

Quantity

Material

Units

Material Location

Room 101(and ward),

3rd Fl Corridor - 1891

Rooms 200, 206, 207, 300, 301, 305, 306, 307,

Change in Assessment Category

X NO

YES

HA No M	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 31	12"x12" Brown and White VFT Mastic	6000	SF	Room 101(and ward), Rooms 200, 206, 207, 300, 301, 305, 306, 307, 3rd Fl Corridor - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" Cream VFT	1500	SF	Room 306, Wardrobes on 3rd Floor Between: 300 and Gym, 301 and 303, 306 and Gym, 104 - 1891		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" Cream VFT Mastic	1500	SF	Room 306, Wardrobes on 3rd Floor Between: 300 and Gym, 301 and 303, 306 and Gym, 104 - 1891		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Off Grey and White VFT	640	SF	Room 305 - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
35	12"x12" Off Grey and White VFT Mastic	600	SF	Room 305 - 1891 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Brown VFT	600	SF	Room 305 and 307 - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

37	12"x12" Brown VFT Mastic	600	SF	Room 305 and 307 - 1891 Bldg		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change				]						
Comments	): :										
2017 - Fall	: No Change										
Comments	): 										
2017 - Spr	ing: No Change										
Comments	<b>:</b>										
2018 - Fall	: No Change										
Comments	S:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	White Troweled Plaster	500	SF	Basement Girl's Bathroom - 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

39	2'x4' White Ceiling Tile	900	SF	Room 204 - 1891 Bldg	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments:										
2017 - Fall:	No Change									
Comments:										
	g: No Change									
Comments:										
2018 - Fall:	No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

40 12" x 12" Green Floor Tile 1200 SF 1st Floor Hallway Miscellaneous No None 0 YES X NO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	40	12" x 12" Green Floor Tile	1200	SF	1st Floor Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

41	12" x 12" Green Floor Tile Mastic	1200	SF	1st Floor Hallway	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change									
Comments:										
2017 - Fall: N	No Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Gray with Black Specks Floor Tile	3600	SF	Lunch Room & Store Room; 1st Floor Corridor; Rms 100, 101 & 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

43	12" x 12" Gray with Black Specks Floor Tile Mastic	3600	SF	Lunch Room & Store Room; 1st Floor Corridor; Rms 100, 101 & 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change		•	•	1	•	•	•	•	•	•	
Comment					-							
2017 - Fal	II: No Change				_							
Comment	S:				1							
2017 - Sp	ring: No Change											
Comment	S:											
2018 - Fal	II: No Change											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Off-white with Brown Specs Floor Tile	1200	SF	2nd Floor Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

45	12" x 12" Off-white with Brown Specs Floor Tile Mastic	1200	SF	2nd Floor Hallway		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	II: No Change				]						
Comment	S:										
2017 - Fa	II: No Change										
Comment	s:				 						
	ring: No Change				-						
Comment	S:				1						
	II: No Change										
Comment	s:				<u> </u>						
					j						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
46	12" X 12" Yellow VFT	50	SF	1st Floor Main Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Fall: N	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

HA No

Material Description

12" x 12" Off-white with

Material

Quantity

Material

Units

2018 - Fall: No Change Comments:

47	12" X 12" Yellow VFT Mastic	50	SF	1st Floor Main Hallway	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	J									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" X 12" Red VFT	25	SF	1st Floor Main Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

49	12" X 12" Red VFT Mastic	25	SF	1st Floor Main Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
	io Change				+							
Comments:					1							
0047	I. Oli				-							
2017 - Fall: N	io Change											
Comments:												
2017 - Spring	j: No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:					1							
Commenter					1							
L					1							
HA No	Material Description	Material	Motorial	Material Location	Achostos	Material	Friable	Damaga	Damago	Damaga	Change in Assess	mant Catagomi

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
50	12" X 12" Gray w/ Dark Gray Streaks VFT	1400	SF	#101 Closet & #106 Lunchroom; #107 Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

51												
Comments:  2017 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  2018 - Fall: No Change	51	12" X 12" Gray w/ Dark Gray Streaks VFT Mastic	1400	SF	Lunchroom; #107 Main		Miscellaneous	No	None	0	YES	X NO
Comments:  2017 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  2018 - Fall: No Change	2016 - Fall	l: No Change		<u> </u>	<u> </u>	]						
Comments:  2017 - Spring: No Change  Comments:  2018 - Fall: No Change												
2017 - Spring: No Change Comments: 2018 - Fall: No Change	2017 - Fall	I: No Change										
Comments:  2018 - Fall: No Change	Comments	S:										
2018 - Fall: No Change												
	Comments	S:				_						
Comments:		<u> </u>										
	Comments	S:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" X 12" White w/ Blue Streaks VFT	1150	SF	#106 Lucnhroom and #103 Classroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" X 12" White w/ Blue Streaks VFT Mastic	1150	SF	#106 Lunchroom and #103 Classroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Fire Brick - Kiln Oven	15	SF	Engineers Storage Closet Next to Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
9	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

55	Duct Vent Insulation	4	LF	Basement corridor next to entrance to warm air chamber		Miscellaneous	No	None	0		YES	X NO
0040 Fall	l. Na Obasasa	<u> </u>	•	·	1							
	l: No Change											
Comments	S:											
2017 - Fal	l: No Change				]							
Comments	3:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fal	l: No Change											
Comments	S:											
	_		•	_	=							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

			סס
2016 - Fall: N	lo Change		
Comments:			
2017 - Fall: N	lo Change		
Comments:			
2017 - Spring	j: No Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:			·
		•	

HA No

56

Material Description

Fire Rated Metal Clad Door

Material

Quantity

Material

Units

EΑ

Material Location

Basement corridor next to

Basement Play Room

(#107 Formerly) - Exit

Change in Assessment Category

X NO

YES

2016 - Fall: N	o Change										
Comments:	o change										
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	· No Change										
Comments:	. No Change										
2018 - Fall: No Change											
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

57

58

Comments:

Comments:

Comments:

Comments:

Material Description

Boiler Rope Insulation

Carpet Mastic

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

64

Material

Units

LF

SF

1400

Material Location

Boiler #1 & #2 in Boiler

Library (Room 203)

room

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
59	12" X 12" Yellow w Blue Specks VFT	1000	SF	Rm 207		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	12" X 12" Yellow w Blue Specks VFT Mastic	1000	SF	Rm 207		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _Thomas Drummond Elementary School
Date:
<del></del>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.