Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Esmond Elementary School 23131 3250 School: **Oracle Unit: Building ID:** Address: 1865 W. Montvale Region: 06 Mail Room: Asbestos Surveyor: Collins, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 1891 bldg - 107 Ward, 12x12 VFT Tan w/ brown YES X NO 03A SF 1825 205, 207, & 208, and Miscellaneous No None 0 and white specks **Associated Wardrobes** 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

03B	12x12 Pink VFT			1891 building - room 206 and 107		Miscellaneous					YES	X NO
2016 - Fall	l: No Change]							
Comments					1							
2017 - Spr	ing: No Change											
Comments	S:				-							
2017 - Fall	l: No Change											
Comments	S:				-							
	l: No Change											
Comments	S:				-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
03C	12X12 Carmel VFT	500	SF	1891 bldg - 2nd floor Corridor by West Stairwell, Half of		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

03D	12x12 White w/Tan Specks VFT	2325	SF	1891 Bldg - Rooms 106, 107, 108, and Assoc. Closets, 105		Miscellaneous	No	Loc	150	YES	X NO
2016 - Fall: N	o Change]						
Comments:					1						
2017 - Fall: N	o Change										
Comments:					-						
2017 - Spring	: No Change										
Comments:					-						
2018 - Fall: N	o Change				-						
Comments:											
					J						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03E	12x12 White w/gray and orange specks VFT	3500	SF	1891 - basement, 102, classroom 8, classroom 108, 105, 106, Lunchroom, Engineer's office, boy Playroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cateo	ory
04A	9x9 Tan w/ Orange Specks VFT	10	SF	1891 bldg Basement Closet by Custodial		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04B	9x9 Blue VFT CHECKERBOARD	50	SF	1891 Building - 1 1/2 Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

04C	9x9 Gray VFT	50	SF	1891 bldg - 1 1/2 office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	j: No Change											
Comments:					 							
2017 - Fall: N	lo Change				-							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

1825

SF

HA No

05A

Material Description

12x12 VAT Mastic, Tan

w/brown and white specks

Material

Quantity

Material

Units

Material Location

1891 bldg - rooms 205,

Wardrobes

207, 208 and Associated

YES

Change in Assessment Category

X NO

05B	12x12 Pink VFT Mastic			1891 building - Room 206 and 107		Miscellaneous					YES	X NO
2016 - Fall:	: No Change]							
Comments]							
2017 - Spri	ing: No Change											
Comments	:				<u> </u>							
2017 - Fall:	: No Change											
Comments	:				1							
2018 - Fall:	: No Change											
Comments	:				<u> </u>							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
05C	12x12 Carmel VFT Mastic	500	SF	1891 bldg - 2nd floor Corridor by West Stairwell, Half of		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05D	12x12 White w/Tan Specks Floor Tile Mastic	2325	SF	1891 bldg - rooms 105, 107, 108, and assoc. closets, Eng's Office, Boys Playroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05E	12x12 White w/gray and orange specks Floor Tile and Mastic	3500	SF	1891 Basement Classroom 8, 102, and Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 7

06A	9x9 Tan w/ orange specks VAT Mastic (NOT OBSERVED)			1st & 2nd Floor Corridors - 1891 Building (NOT OBSERVED)		Miscellaneous					YES	X NO
0040 5 1		•	•	•	7	•	•	•	•	•	•	
	I: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	3:											
2017 - Fal	l: No Change											
Comments	3:											
2018 - Fal	l: No Change											
Comments	3:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Asbestos

Type

Material

Category

Category

Friable

No

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

06B	9x9 Blue Floor Tile Mastic	50	SF	1891 Building, 1 1/2 office	Miscellaneous
2016 - Fall: No Comments:	o Change				
2017 - Fall: No Comments:	o Change				
2017 - Spring Comments:	: No Change				
2018 - Fall: No	o Change				

Quantity

Material

Units

Units

Material

Quantity

Material Location

HA No

Material Description

Change in Assessment Category

X NO

2016 - Fall: N	o Chango				1						
	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:	_										
2017 - Fall: N	o Change										
Comments:											
2018 - Fall: N	o Change										
Comments:	-										
	_				_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material

Quantity

50

Material

Units

SF

Material Location

1891 Building - 1 1/2

1937 Addition - 1st floor

Corridor

office

HA No

06C

07A

Material Description

9x9 Gray Floor Tile Mastic

12x12 Lt. Brown Floor Tile

Change in Assessment Category

X NO

X NO

YES

07B	12x12 Beige w/ White Specks Floor Tile			Room 104		Miscellaneous					YES	X NO
2016 - Fall: I	Vo Change				1							
Comments:	NO Onlange											
Comments.					-							
2017 - Fall: I	No Change				-							
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2010 5 11 1					1							
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

HA No

07C

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

12x12 Off White w/ Tan

Specks Floor Tile

Material

Units

Material Quantity

960

SF

Material Location

Room 102

Change in Assessment Category

X NO

07D	12x12 Tan w/ Brown & White Specks Floor Tile	2760	SF	204, Storage Office of S/E Landing		Miscellaneous	No	None	0		YES	X NO
2016 Fo	II: No Change				7							
Comment	S:											
2017 - Sp	ring: No Change											
Comment	s:											
2017 - Fa	II: No Change											
Comment	S:											
2018 - Fa	II: No Change											
Comment	s:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

A80

Material Description

12x12 Tan w/ Brown &

9x9 Black Floor Tile - NOT

OBSERVED

Material

Units

Material

Quantity

Material Location

Rooms 201, 202, 203,

1937 Addition - 1st & 2nd

Change in Assessment Category

X NO

YES

08B	9x9 Red Floor Tile - NOT OBSERVED			1937 Addition - 1st & 2nd Floor Corridor (NOT OBSERVED)		Miscellaneous					YES	X NO
0040 Falls	No Observe	•		•	7							
2016 - Fall:												
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change				1							
Comments:					1							
					1							
2018 - Fall:	No Change				1							
Comments:	<u>~</u>											
COMMITTORIO.					1							
					_							
	Tata da sa d	1	1	I a		T	1	T =	T =		1 0	
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
	9x9 Black w/ white streaks			1937 Addition - North								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

08C

Material Description

Floor Tile - NOT

OBSERVED

Material

Units

Material Quantity Material Location

Entrance (NOT

OBSERVED)

Change in Assessment Category

X NO

08D	9x9 Gray w/ White Specks Floor Tile - NO LONGER PRESENT			Building 1937 - Storage by Attic Hatch NO LONGER PRESENT		Miscellaneous					YES	X NO
204C Fall N	la Change	•	•	•	1	•	*	•	•	•	•	
2016 - Fall: N	io Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:	-											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

08E

Material Description

9" Wide Black Border Tile -

NOT OBSERVED

Material

Units

Material

Quantity

Material Location

1937 Addition - 1st & 2nd

flr corridor NOT OBSERVED

Change in Assessment Category

X NO

08F	9x9 Gray VFT NOT OBSERVED			Room 104 NOT OBSERVED		Miscellaneous					YES	X NO
2016 - Fall	: No Change]							
Comments												
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	: No Change											
Comments												
2018 - Fall:	: No Change											
Comments	<u> </u>											
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Туре

Type

None

Damage

Quantity

Quantity

0

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Quantity

775

Units

SF

Material

Units

Material

Quantity

Material Location

1937 Addition - 1st Floor

HA No

09A

Material Description

12x12 Lt. Brown Floor Tile

Mastic

Change in Assessment Category

X NO

YES

Damage

Units

Units

											· I
2016 - Fall:	No Change										
Comments:	140 Orlango										
Commonto:											
2017 - Fall:	No Change										
Comments:											
0047 0	. N. Observe				_						
2017 - Sprin	g: No Change										
Comments:											
2212 5 11	N. O.										
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

960

SF

HA No

09B

09C

Material Description

12x12 Beige w/ White

Specks Floor Tile Mastic

12x12 Off White w/ tan

Specks Floor Tile Mastic

Material

Units

Material

Quantity

Material Location

Hatch by Attic

room 102

Building 1937 - Storage

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

09D	white specks Floor Tile Mastic	2760	SF	204, Storage office of S/E Landing		Miscellaneous	No	None	0		YES	X NO
		•	· ·	•	- 	•	•	•	•	•	•	
2016 - Fal	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments												
2017 - Fal	l: No Change											
Comments	S:											
2018 - Fal	l: No Change											
Comments	S:											
	-											
					<u>=</u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

10A	9x9 Black Floor Tile Mastic (NOT OBSERVED)	floor Corridor (NOT OBSERVED)
2016 Fall	No Change	
	: No Change	
Comments	:	
2017 - Fall	: No Change	
Comments	:	
2017 - Spri	ing: No Change	
Comments	:	
2018 - Fall	: No Change	
Comments	:	

HA No

Material Description

12x12 Tan w/ brown &

9x9 Black Floor Tile Mastic

Material

Units

Material

Quantity

Material Location

Rooms 201, 202, 203,

1937 Addition - 1st & 2nd

Change in Assessment Category

X NO

10B	9x9 Red floor tile Mastic - NOT OBSERVED			1937 Addition - 1st & 2nd flr Corridor (NOT OBSERVED)		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
					4							
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
Committee					1							
2017 - Fall:	No Change				1							
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

10C	9x9 Black w/white streaks Tile Mastic - NOT OBSERVED	1937 Addition - North Entrance (NOT OBSERVED)
2016 - Fal	I: No Change	
Comments	S:	
2017 - Spi	ring: No Change	
Comments	s:	
2017 - Fal	I: No Change	
Comments	s:	
2018 - Fal	I: No Change	
Comments	s:	·
	_	_

Material

Quantity

Material

Units

Material Location

HA No

Material Description

YES

X NO

10D	9x9 Gray w/ White Specks floor tile Mastic - NOT OBSERVED	32	SF	Room 104 Closet		Miscellaneous	No	None	0		YES	X NO
0040 5 11 1		•	•	•	1	•	•	•	•	•	•	
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	յ։ No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
			•		-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
1	1	L CJUANTITY	LITHIS	1	IVDE	Lalecory	1	I I VDE	LUDIANTITY	I UIIIIS		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

10E	9" Wide Black Border Tile Mastic (NOT OBSERVED)		Floor Corridors (NOT OBSERVED)
0040 = 11 14			
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:	·		
		•	

HA No

Material Description

9" Wide Black Border Tile

Material

Quantity

Material

Units

Material Location

1937 Addition 1st & 2nd

YES

X NO

10F	9x9 Gray FT Mastic - Not Observed			Room 104 (NOT OBSERVED)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	to onango											
2017 - Spring	a: No Change											
Comments:	<u>, , , , , , , , , , , , , , , , , , , </u>											
2017 - Fall: N	lo Change											
Comments:	ŭ											
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
13A	12x12 White w/ Gray Speckles VFT			1971 Modular - 1st & 2nd Floor Corridors, Gym, Rooms 110 and 113		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

2016 - Fall: N	lo Change				\neg						
Comments:	io change										
Comments.					-						
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	J										
2018 - Fall: N	lo Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
TIA NO	Material Description	Quantity	Units	Ivialeriai LOCALIOTI	Type	Category	Filable	Type	Quantity	Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

13B

13C

Material Description

12x12 Gray Floor Tile

12x12 Beige Floor Tile

Material

Quantity

450

Material

Units

SF

Material Location

1971 Mod - Gym Office and Storage Rooms

1971 Mod - Kitchen and

Lunchroom

Change in Assessment Category

X NO

X NO

YES

13D	12x12 Tan Floor Tile with Streaks VFT	660	SF	1971 Mod - 2nd floor, Janitor's and Book Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				1							
Comment]							
2017 - Sn	ring: No Change				1							
Comment												
2017 - Fa	II: No Change				-							
Comment	<u> </u>											
2018 - Fa	II: No Change				-							
Comment	<u> </u>											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
125	12x12 Off White w/	1000	SE.	1971 Mod-Janitor Closet, Rm 319, 316, Store Rms,		Missellaneous	No	None			YES	X NO

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

1000

SF

HA No

13E

Material Description

Multicolor Streaks Floor Tile

Material

Quantity

Material

Units

Material Location

main off. stock rms, 1st &

2nd Floors

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessi	ment Category
13F	12 x 12 Gray w/white streaks VFT	3175	SF	1971 Mod Gym, Rooms 110 and 113		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change]								
Comments													
2017 - Spri	ng: No Change												
Comments	:												
2017 - Fall:	No Change				-								
Comments													
2018 - Fall:	No Change												
Comments	:				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	12x12 White w/ Gray Speckles VFT Mastic	8000	SF	1971 Modular - 1st & 2nd floor Corridors, Gym, Rooms 110 and 113		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

2016 - Fall:	No Changa										
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
	T			T		T					1 -
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

14B

14C

2016 - Fall: No Change

Material Description

12x12 Gray Floor Tile

12x12 Beige Floor Tile

Mastic

Material

Units

SF

Material

Quantity

450

Material Location

and Storage

1971 Mod - Gym Office

1971 Mod - Kitchen and

Lunchroom

Change in Assessment Category

YES

YES

X NO

X NO

14D	12x12 Tan Floor Tile Mastic w/ Streaks	660	SF	1971 Mod - Second Floor Janitor's and Book Closets		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprii	ng: No Change										
Comments:											
	No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

14E	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	14E		80	SF			Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

15	Brown Vinyl Baseboard			Throughout Modular Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:	go											
2017 - Fall:	No Change				-							
Comments:					1							
2017 - Sprin	g: No Change				-							
Comments:												
2018 - Fall:	No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	Brown Vinyl Baseboard Mastic			Throughout Modular Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

17	Expansion Joints			Throughout Modular Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18	Metal Clad Drywall			1971 Mod Building - Throughout		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

19	2'x4' Acoustic Celing Tile			1971 Mod - Throughout Classrooms and Corridors		Miscellaneous					YES	X NO
2016 - Fall: N	o Chango		•	•			•	•	•	•		
	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	-											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
12.110	material Besonption	Quantity	Units	material Ecoditori	Type	Category	- Habio	Type	Quantity	Units	Change in 7 toocot	Smort Catogory
		-				- •						
20	Linoleum - NOT OBSERVED			1891 Building 1 1/2 office NOT OBSERVED		Miscellaneous					YES	X NO
	ODOLIVED	1		NOT OBSERVED		1	I		I	1		

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

1971 Mod - Throughout

HA No

Material Description

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
21	Linoleum Mastic - NOT OBSERVED			1891 Bldg. 1 1/2 office NOT OBSERVED		Miscellaneous					YES	X NO
2016 - Fall	: No Change]							
Comments	<u> </u>											
2017 - Fall	: No Change											
Comments												
2017 - Spri	ing: No Change				1							
Comments	:											
2018 - Fall	: No Change											
Comments	:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22	Brown Carpet Mastic - NOT OBSERVED			3rd Floor Hall and Classrooms, Rooms 115, 116 and 114 NOT OBSERVED		Miscellaneous					YES	X NO
2016 - Fall	: No Change	·		·]							

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Beige Streaked VFT	10000	SF	1st, 2nd and 3rd floor hallways - 1937 bldg		Miscellaneous	No	None	0		YES X NO
0040 5-11					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Beige Streaked VFT Mastic	10000	SF	1st, 2nd and 3rd floor hallways - 1937 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

25	Blue carpet mastic	600	SF	Room 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change]							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Type

Material

Category

Category

Surface

Friable

Yes

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

26	Plaster - Wall and Ceiling	30000	SF	1891 Building - Attic, \Throughout								
2016 - Fall: No Change												
Comments:												
2017 - Fall: N	2017 - Fall: No Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: No Change												
Comments:	Comments:											

Quantity

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	Vapor Barrier Felt Paper Under Wood Floor	1500	SF	1891 Building - Attic		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Plaster Ceiling Patch	100	SF	1891 Building - 2nd Floor Corridor		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 31

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
29	Black Baseboard	200	SF	1971 Modular - Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2010 5 11 11 21	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Fire Door Insulation - no longer present	1	LF	1937 Building - Air Tunnel		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

31	Black Baseboard Mastic	200	SF	1971 Modular - Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	-											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Yes

Damage

Type

None

Damage

Quantity

0

Damage

Units

32	2X4 Dotted Ceiling Tile	6700	SF	106, 107, 108, 205, 206, 207, 208
0040 Fall	Na Ohana			
2016 - Fall:	No Change			
Comments:				
2017 - Fall:	No Change			
Comments:				
2017 - Sprii	ng: No Change			
Comments:				
2018 - Fall:	No Change			
Comments:				

HA No

Material Description

Material

Quantity

Material

Units

Material Location

1891 Bldg - Rooms 105,

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
33	12x12 Off-White with Grey Specs Floor Tile	970	SF	1891 Bldg - 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							

016 - Fall: No Change
Comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33M	12x12 Off-White with Grey Specs Floor Tile Mastic	970	SF	1891 Bldg - 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

34	Green Carpet Adhesive	720	SF	Bldg 1891 - Basement Room 007	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring	ı: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Metal Pan Ceiling (Felt Paper)	1090	SF	Bldg 1891 - Basement, Boiler Room and Pump Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
36	Red Carpet Adhesive	660	SF	Bldg 1937 - Main office, Principal's office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Plaster - Ceiling and upper walls	50000	SF	Bldg 1937 - Throughout 1st and 2nd Floors		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 36

А	Mag Boiler Insulation - ABATED			Boiler Room		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:	go											
2017 - Spring	r. No Change											
Comments:	g. No Onlange											
2017 - Fall: N	lo Change											
Comments:	io chango											
2018 - Fall: N	lo Change											
Comments:	io change				_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	o a gr	,
В	Mag Blockinsulation on Hot Water Tank - no longer			Boiler room (no longer		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

present

2016 - Fall: No Change

Material

Quantity

Material

Units

Material Location

present)

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Type

Asbestos

Type

Material

Category

Material

Category

Friable

Friable

Damage

Damage

Туре

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

BBM-1	Black Baseboard Mastic	100	LF	1891 building - Half of the floor of foyer		Miscellaneous	No	None	0
2016 - Fall: N	No Change]				
Comments:]				
2017 - Sprin	g: No Change				-				
Comments:									
2017 - Fall: N	No Change				-				
Comments:	•								
2018 - Fall: I	No Change								

Material Location

HA No

HA No

Comments:

Material Description

Material Description

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Change in Assessment Category

Change in Assessment Category

X NO

С	Mag Block Insulation on Water Tank - NOT OBSERVED			Pump room NOT OBSERVED		TSI					YES	X NO
2016 Falls	No Changa		<u> </u>									
	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:	•											
Commission												
2017 - Fall:	No Change											
Comments:	·											
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Material

Units

Material

Quantity

Material Location

throughout 1971 building (NOT OBSERVED)

HA No

CM-1

Material Description

Mag Block Insulation on Water Tank - NOT

Light Blue Green Carpet Mastic (NOT OBSERVED)

CM-2	Dark Blue Carpet Mastic (NOT OBSERVED)			1971 Building - Teacher's Lounge & Main Office (NOT OBSERVED)		Miscellaneous					YES	X NO
2016 Fall	: No Change				7							
					4							
Comments	:											
2017 - Spr	ing: No Change											
Comments	::											
2017 - Fall	: No Change											
Comments	::				1							
					1							
2018 - Fall	: No Change				1							
Comments	::				1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

400

SF

HA No

CTG-1

Material Description

Ceramic Tile Grout

Material

Units

Material Quantity Material Location

1937 building -

Bathrooms

1971 Building - Teacher's Lounge & Main Office

Change in Assessment Category

X NO

CTG-2	Ceramic Tile Grout	400	SF	1937 Building - Bathrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	<u> </u>											
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

8

Damage

Type

Damage

Quantity

Damage

YES

X NO

Units

Change in Assessment Category

D	Airceil Pipe Insulation	1100	LF	Room, Engineer's Office, Lunchroom, 105-108
0040 = 11.11				
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
	·			<u>-</u>

1100

HA No

D

Material Description

Aircell Pipe Insulation

Material

Quantity

Material

Units

LF

Material Location

1891 Building - Pump

Room, Boiler Room,

Basement Storage

E	Cardboard Pipe Insulation			1891 Bldg Boiler room		TSI					YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprir	ng: No Change				1							
Comments:]							
2017 - Fall:	No Change											
Comments:					-							
2018 - Fall:	No Change				<u> </u>							
Comments:					-							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA NO	Material Description	Quantity	Units	Iviaterial Location	Type	Category	Filable	Type	Quantity	Units	Change in Asses	SSITIETH Category
F	Aircell Joints and Elbows	100	LF	1891 bldg - pump room and boiler room, Basement Hallway, Basement Storage, Lunchrooms, Rooms 105, 106, 107, 108		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

HA No

Material Description

Material

Quantity

Material

Units

Material Location

FB-1	Fire Brick in Incinerator	100	SF	boiler room	TSI	No	None	0	YES	L	X NO
2016 - Fall: N	o Chango										
	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-1	12x12 Green with Specks Floor Tile	150	SF	Custodial Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

FTM-1	12x12 Green with Specks Floor Tile Mastic	150	SF	Custodial Room		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	: No Change				1						
Comments											
2017 - Fall:	: No Change										
Comments	:										
2017 - Spri	ing: No Change										
Comments	:										
2018 - Fall:	: No Change										
Comments	:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Aircell Duct Cover	100	LF	1937 Building - Crawl Space		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

I	Cementitious Duct Cover	50	SF	Attic - 1937 Building		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments]							
2017 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change				-							
Comments	<u> </u>]							
2018 - Fall:	No Change				-							
Comments	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
	Aircell Pine Insulation	1300	I.E.	1937 - Building Crawlspaces, Basement		TSI	Vec	Loc	20		YES	X NO

TSI

Asbestos

Type

Material

Category

Friable

Yes

Loc

29

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Fan Room, Air Tunnel and Hall to Air Tunnel

1300

LF

HA No

Material Description

Aircell Pipe Insulation

2016 - Fall: No Change

Comments:

Material

Quantity

Material

Units

K	Cardboard Pipe Insulation (NOT OBSERVED)			1937 Building NOT OBSERVED		TSI					YES	X NO
2016 Fo	II: No Change				7							
	· · · · · · · · · · · · · · · · · · ·											
Comment	S:											
					_							
	II: No Change											
Comment	s:											
2017 - Sp	ring: No Change											
Comment	s:											
2018 - Fa	II: No Change											
Comment	s:											
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

L	Aircell Pipe Fittings	37	LF	1937 Building Crawlspces	TSI	No	None	0
2016 - Fall: N	o Change							
Comments:	-							
2017 - Spring	: No Change							
Comments:	.							
2017 - Fall: N	o Change							
Comments:								
2018 - Fall: N	o Change							

Material Location

Material

Units

Units

Material

Quantity

Quantity

HA No

Comments:

K

Material Description

Change in Assessment Category

X NO

М	Aircell Pipe Fittings (NOT OBSERVED)			1891 Bldg Lunchroom NOT OBSERVED		TSI					YES	X NO
2016 - Fa	II: No Change]							
Comment												
2017 - Fa	II: No Change											
Comment	S:											
	ring: No Change											
Comment	S:											
	II: No Change											
Comment	S:											
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
N	Cardboard Pipe Fittings (NOT OBSERVED)			1937 Bldg NOT OBSERVED		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material Quantity Material Location

HA No

Material Description

Change in Assessment Category

0	Boiler Gaskets	18	LF	Boiler Room	TSI	No	None	0	YES	X NO
0040 Fall N	- Ob									
2016 - Fall: N	o Cnange									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Р	Joints on Fiberglass Lines	115	SF	1891 Building		TSI	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring	ı: No Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Q	Felt Paper Under Wood Floor	1500	SF	1891 Building - Auditorium (Attic)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	¥											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Felt Paper under Wood Floor	1500	SF	1937 Building - Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Joints on Fiberglass Lines	115	SF	1971 Building		TSI	No	None	0		YES X NO
2016 - Fall: N	lo Change										

016 - Fall: No Change
Comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T-1	Terrazzo	400	SF	1891 building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:	ı i										
2017 - Sprii	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

34

Material

Quantity

500

Material

Units

SF

LF

Material Location

1937 Building

Attic & Gym

HA No

T-2

VC-1

Material Description

Terrazzo

Vibration Collars

Page 51

Change in Assessment Category

X NO

X NO

YES

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Esmond Elementary School	
Date: 1/10/2019	
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy the Asbestos Management Plan is available at each school during school hours by appointme Requests to review the Asbestos Management Plan must be made at least 24 hours in advan	nt.
Also please be advised that CPS conducts asbestos inspections of all Schools every three ye. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.	ars.
CHECK ONE	
A copy of this notice was sent home in each child's backpack.	
A copy of this notice was printed in the school's newsletter and sent home with each child	
A copy of this notice was printed in the school's calendar and sent home with each child	
Other.	
A COPY OF THIS NOTICE MUST BE PLACED IN THE	

VFT = Vinyl Floor Tile
Oracle Unit: 23131

SCHOOL'S ASBESTOS MANAGEMENT PLAN.