Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

23161

Oracle Unit:

Address: 5414 N Linder Avenue Region: 01 Mail Room: 30 Asbestos Surveyor: Sanchez, Alexander X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/17/2018 Email Address: sanchezalexander@aramark. com A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Notice printed in school's calendar Other Each child's backpack HA No **Material Description** Material Material Material Location Asbestos Material Friable Damage Damage Change in Assessment Category Damage Quantity Units Type Category Type Quantity Units 1st & 2nd Flr Corr., Rm X NO YES 110, 110 Storage, Main 12"x12" White w/ Brown 03 11180 SF Ofc, Storage Under Rm Miscellaneous No None 0 Specks VFT 109(Lunchroom Mngr), Rm 112 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

James B Farnsworth Elementary School

School:

2018 - Fall: No Change

Comments:

3280

Building ID:

04	9"x9" Beige w/ White Streaks VFT (has carpet with blue specks)	800	SF	Room 101 (has carpet with blue specks)		Miscellaneous	No	None	0	YES	X NO
	•	•	•	•	1	•	•	•	•		
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
					1						
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:	-]						
2018 - Fall: N	o Change	•									
Comments:	-										
					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" White w/ Brown Specks VFT Mastic	11180	SF	1st & 2nd Flr Corr., Rm 110, 110 Storage, Main Ofc, Storage Under Rm 109(Lunchroom Mngr), Rm 112		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

06	9"x9" Beige w/ White Streaks VFT Mastic (has carpet with blue specks)	800	SF	Room 101 (has carpet with blue specks)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change]							
Comments					1							
2017 - Sp	ring: No Change				-							
Comments	s:]							
2017 - Fal	II: No Change				_							
Comments	s:]							
2018 - Sp	oring : No Change				_							
Comments	s:]							
2018 - Fal	II: No Change				_							
Comments	s:]							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Asbestos

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

Damage

Units

Damage Quantity

Quantity

Units

YES

Change in Assessment Category

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
	•	_

Quantity

Units

Throughout

HA No

07

Material Description

Vinyl Baseboard

Material

Quantity

Material

Units

Material Location

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	Vinyl Baseboard Mastic			Throughout (See Hatching Maps)		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change				-							
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" Brown w/ White Specks VFT	1400	SF	Room 207, 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Brown w/ White Specks VFT Mastic	1600	SF	Room 207, 109		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Cream w/ Brown Specks VFT	1800	SF	Room 207, 109, & 112		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Cream w/ Brown Specks VFT Mastic	1800	SF	Room 207, 109, & 112		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Light Green w/ Brown Specks VFT	160	SF	Main Office Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
14	12"x12" Light Green w/ Brown Specks VFT Mastic	160	SF	Main Office Storage		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Beige VFT (Has Blue Carpet)	1400	SF	Room 103 Kindergarten (Has Blue Carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

16	12"x12" Beige VFT Mastic (Has Blue Carpet)	1400	SF	Room 103 Kindergarten (Has Blue Carpet)	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Chango									
	io Change									
Comments:										
2017 - Spring	j: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Spring	j : No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	<u> </u>									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9x9 Orange w/Brown Speckles VFT (ABATED)			Engineer's Office & Toilet		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18	9x9 Orange w/Brown Speckles VFT Mastic (ABATED)			Engineer's Office & Toilet		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change		•]		•					
Comments:					1							
2017 - Spring	g: No Change				_							
Comments:]							
2017 - Fall: N	lo Change											
Comments:					-							
	g : No Change											
Comments:					=							
2018 - Fall: N	No Change											
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Red w/ White Streaks VFT	300	SF	2nd Floor Teacher's Lounge		Miscellaneous	No	Loc	25		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Red w/ White Streaks VFT Mastic	300	SF	2nd Floor Teacher's Lounge		Miscellaneous	No	Loc	25		YES X NO

	•	
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12 x 12 inch White w/Tan Streaks VFT	160	SF	Engineer's Office and Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21 A	12 x 12 inch White w/Tan Streaks VFT Mastic	160	SF	Engineer's Office and Toilet		Miscellaneous	No	None	0		YES X NO
•											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	2'x4' Ceiling Tiles	3000	SF	Throughout 2nd floor		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

		Quantity	Units		Type	Category		Type	Quantity	Units		
23	Terrazzo	10000	SF	1st and 2nd floor corridors, 2nd fl teachers lunchroom, all stairwells, and vestibules		Miscellaneous	No	None	0		YES	X NO
2016 - F	all: No Change											
Comme												
2017 - S	Spring: No Change											
Comme	nts:											
	all: No Change											
Comme	nts:				1							
	Spring : No Change											
Comme	nts:											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	drywall system	3000	SF	rooms 201, 202, 203, 204, 205, 207, 114, 104, 115, 116, 107, 106		Miscellaneous	Yes	None	0		YES X NO

		110, 110, 101, 100
•		
	•	

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	2x4 Ceiling tile	1700	SF	1st fl corridor, 2nd fl corridor, rooms 208, 207, 206, 209, 210, 211, 212, 205, 203, 201, 214, 202, 204		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
26	Carpet Mastic	2400	SF	Rooms 120, 107, 103, 106 Assembly hall between aisles,		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change	<u> </u>	<u> </u>	<u> </u>	7							
Comment												
2017 - Sp	ring: No Change											
Comment	s:											
2017 - Fa	II: No Change											
Comment	S:											
2018 - Sp	ring : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Brown w/White Specks VFT	700	SF	room 103		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	12"x12" Brown w/White Specks VFT Mastic	700	SF	Room 103		Miscellaneous	No	None	0		YES X NO
204C Falls N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Decorative Plaster	1200	SF	Assembly Hall		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
29	Spray-on Insulation, gray			Boiler Room		Surface					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	: No Change]							
Comments:					-							
2018 - Fall: N	lo Change]							
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12x12 Beige VFT	120	SF	Engineers office and toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	ry
31	12x12 Beige VFT Mastic	120	SF	Engineers office and toilet		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	12" x 12" Woodgrain VFT (NOT OBSERVED)	100	SF	Storage Room #103 Kindergarden		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

В	MJP E/F/V on Fiberglass Pipe Insulation	Boys Bathroom Pipe Chases, 2nd Floor Janitors Closet Chase	Miscellaneous		YES	X NO
2016 - Fall: N	No Change					
Comments:	10 Change					
Commonto.						
2017 - Fall: I	No Change					
Comments:						
	g: No Change					
Comments:						
2018 - Fall: N	No Change					
Comments:						
2019 Cprin	a . No Chongo					
	g : No Change					
Comments:						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
С	Cardboard Pipe Insulation			Boiler Room, Unexcavated Areas, & Main Engine Room		Miscellaneous					YES	X NO
2016 - Fall: N Comments:	lo Change									•		

Comments:

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

2018 - Spring: No Change
Comments:

2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

D	MJP E/F/V on Cardboard Pipe Insulation			Unexcavated Areas, & Main Engine Room		TSI					YES	X NO
2016 - Fall: I	No Change				٦							
Comments:	go											
2017 - Sprin	g: No Change				_							
Comments:	g. No Change											
Comments.												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change				-							
Comments:	<u> </u>											
0040 5-11	N. Observe											
2018 - Fall: I	No Change				_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Е	Mag Block Tank Insulation			Boiler Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

2016 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
F	Mag Block Boiler Insulation			Boiler Room		TSI					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	ı: No Change]							
Comments:					_							
2017 - Fall: N	lo Change]							
Comments:					_							
2018 - Spring	: No Change											
Comments:					1							
2018 - Fall: N	lo Change]							
Comments:					_							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Mag Block Pipe Insulation			Boiler Room & Main Engine Room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Н	MJP E/F/V on Mag Block Pipe Insulation			Boiler Room & Main Engine Room		TSI					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				1							
Comments:												
2017 - Fall: N	lo Change				1							
Comments:	<u> </u>]							
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change				-							
Comments:	y i i to onango]							
]							
		Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
HA No	Material Description				Turno	Category		Type	Quantity	Units		
HA No	Material Description	Quantity	Units	D.1. D. M.	Туре	Catogory		**	, ,	Offics		
HA No	Material Description Aircell Pipe Insulation			Boiler Room, Main Engine Room, Unexcavated Areas, North & South Basement	туре	TSI				Offits	YES	X NO
ı	Aircell Pipe Insulation			Engine Room, Unexcavated Areas,	Туре					Units	YES	X NO
I 2016 - Fall: N	Aircell Pipe Insulation			Engine Room, Unexcavated Areas, North & South Basement	Туре					Units	YES	X NO
I 2016 - Fall: N Comments:	Aircell Pipe Insulation No Change			Engine Room, Unexcavated Areas, North & South Basement	Туре					Units	YES	X NO
I 2016 - Fall: N Comments: 2017 - Spring	Aircell Pipe Insulation			Engine Room, Unexcavated Areas, North & South Basement	Туре					Units	YES	X NO
I 2016 - Fall: N Comments: 2017 - Spring Comments:	Aircell Pipe Insulation No Change g: No Change			Engine Room, Unexcavated Areas, North & South Basement	Туре					Units	YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2017 - Fall: N	Aircell Pipe Insulation No Change g: No Change			Engine Room, Unexcavated Areas, North & South Basement	Туре					Units	YES	X NO
I 2016 - Fall: N Comments: 2017 - Spring Comments:	Aircell Pipe Insulation No Change g: No Change			Engine Room, Unexcavated Areas, North & South Basement	Туре					Units	YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2017 - Fall: N Comments:	Aircell Pipe Insulation No Change g: No Change			Engine Room, Unexcavated Areas, North & South Basement	Туре					Units	YES	X NO

HA No

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	MJP E/F/V on Aircell Pipe Insulation			Boiler Room, Main Engine Room, Unexcavated Areas, North & South Basement Stairs		TSI					YES X NO

Oracle Unit: 23161

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
К	Blown-In Insulation NOT OBSERVED	1100	SF	Attic NOT OBSERVED		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	-											
2017 - Spring	g: No Change											
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					1							
2018 - Spring	g : No Change											
Comments:	.				1							
2018 - Fall: N	lo Change				-							
Comments:	J											
1												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Air Cell Duct Cover Insulation			Main, North & South Unexcavated Areas		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 23

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Boiler Gaskets			Boiler Room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 23161

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: James B Farnsworth Elementary School
Date:1/7/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23161

SCHOOL'S ASBESTOS MANAGEMENT PLAN.