## **Chicago Public Schools**

## 6 Month Asbestos Surveillance

2018 - Fall

| School:  | Frederick Funston Elementary School |  | Oracle Unit:                                    | 23291 | Building ID: | 3460 |
|----------|-------------------------------------|--|---|-------|--------------|------|
| Address: | 2010 N. Central Park Avenue         |  | Region:   | 02    | Mail Room:   | 35   |
|          | NO CHANGE TO ASBESTOS               | Asbestos Surveyor:<br>Survey Date:<br>Email Address: | Wernsing, Dale<br>1/8/2019<br>dwernsing@cps.edu |       |              |      |

|  | A copy of the2016/20 | 17 notice to         | parents and       | staff regarding the asb  | estos manag      | ement plan no        | otifications w | as distribute  | ed via:            |                 |                |                 |
|--|----------------------|----------------------|-------------------|--------------------------|------------------|----------------------|----------------|----------------|--------------------|-----------------|----------------|-----------------|
|  | Each child's backp   | ack                  | X Notice          | printed in school's news | sletter          | Notice pi            | rinted in scho | ool's calenda  | nr Ot              | her             |                |                 |
| HA No  | Material Description | Material<br>Quantity | Material<br>Units | Material Location        | Asbestos<br>Type | Material<br>Category | Friable        | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Asse | ssment Category |
| 01   | Hard Coat Plaster    | 100000               | SF                | Throughout - 1895 Bldg.  |                  | Surface              | Yes            | Dist           | 350                |                 | YES            | XNO             |
| 2016 - Fall: N<br>Comments:<br>2017 - Fall: N<br>Comments:<br>2017 - Spring<br>Comments: |                      |                      |                   |                          |                  |                      |                |                |                    |                 |                |                 |
| 2018 - Spring<br>Comments:   | g : No Change        |                      |                   |                          | -                |                      |                |                |                    |                 |                |                 |
| 2018 - Fall: N<br>Comments:  | lo Change            |                      |                   |                          | -                |                      |                |                |                    |                 |                |                 |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location                 | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-----------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 01A   | Textured Plaster     | 7500                 | SF                | Auditorium Balcony -<br>1928 Bldg |                  | Surface              | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2010 Crains : No Change   |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description              | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-----------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 02    | 9"x9" Tan w/ Brown Streaks<br>VFT | 1000                 | SF                | Room 506, 301,<br>Basement Teachers<br>Toilet (N) - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Abated       |
| Comments:rm 301 replaced  |
|                           |

| HA N | lo | Material Description                         | Material<br>Quantity | Material<br>Units | Material Location                         | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|------|----|--|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 03   |    | 12"x12" Coffee w/ Black & White Speckles VFT | 1500                 | SF                | 2nd & 3rd Floor Corridors<br>- 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change             |
|------------------------------------|
|                                    |
| Comments:                          |
| 0017 0 i N 0                       |
| 2017 - Spring: No Change           |
| Comments:                          |
|                                    |
| 2017 - Fall: No Change             |
| Comments:                          |
|                                    |
| 2018 - Spring : No Change          |
| Comments:                          |
|                                    |
| 2018 - Fall: Damaged               |
| Comments: 2nd floor outside office |
|                                    |

| HA No | Material Description                                  | Material<br>Quantity | Material<br>Units | Material Location                         | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 08    | 12"x12" Coffee w/ Black &<br>White Speckls VFT Mastic | 1500                 | SF                | 2nd & 3rd Floor Corridors<br>- 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change             |  |
|------------------------------------|--|
| Comments:                          |  |
|                                    |  |
| 2017 - Spring: No Change           |  |
| Comments:                          |  |
|                                    |  |
| 2017 - Fall: No Change             |  |
| Comments:                          |  |
|                                    |  |
| 2018 - Spring : No Change          |  |
| Comments:                          |  |
|                                    |  |
| 2018 - Fall: Damaged               |  |
| Comments: 2nd floor outside office |  |
|                                    |  |

| HA No | Material Description                     | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 12    | 9"x9" Tan w/ Brown Streaks<br>VFT Mastic | 1000                 | SF                | Room 506, 301,<br>Basement Teachers<br>Toilet (N) - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: Abated       |  |
| Comments:rm 301 replaced  |  |
|                           |  |

| HA No | Material Description             | Material<br>Quantity | Material<br>Units | Material Location     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------------------|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 14    | 12"x12" White w/ Speckles<br>VFT | 1000                 | SF                | Room 311 - 1928 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                    | Material<br>Quantity | Material<br>Units | Material Location     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 15    | 12"x12" White w/ Speckles<br>VFT Mastic | 1000                 | SF                | Room 311 - 1928 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description          | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 16    | 12"x12" Brown Speckled<br>VFT | 2500                 | SF                | Room 501, Kitchen (109),<br>Kitchen Toilet - 1895<br>Blda. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
| Comments.                 |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 Spring : No Change   |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
| 2018 - Fall: Damaged      |  |
| Comments:broken tiles     |  |
|                           |  |

| HA No | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 17    | 12"x12" Brown Speckled<br>VFT Mastic | 2500                 | SF                | Room 501, 507, Kitchen<br>(109), Kitchen Toilet -<br>1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: Abated       |  |
| Comments:room 507         |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                   | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 18    | 12"x12" White w/ Brown<br>Speckles VFT | 1000                 | SF                | Room 501, Kitchen (109),<br>Kitchen Toilet - 1895<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: Damaged      |  |
| Comments:broken tiles     |  |
|                           |  |

| HA No | Material Description                          | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 19    | 12"x12" White w/ Brown<br>Speckles VFT Mastic | 1000                 | SF                | Room 501, Kitchen (109),<br>Kitchen Toilet - 1895<br>Blda |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description             | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 20    | 12"x12" White w/ Speckles<br>VFT | 5500                 | SF                | Rooms 508, 502, 408,<br>407, 406, 405, 403, 302,<br>301, Principal Toilet, 308<br>Closet - 1928 Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change              |
|-------------------------------------|
|                                     |
| Comments:                           |
|                                     |
| 2017 - Spring: No Change            |
| Comments:                           |
|                                     |
| 2017 - Fall: No Change              |
| Comments:                           |
|                                     |
| 2018 - Spring : No Change           |
| Comments:                           |
|                                     |
| 2018 - Fall: Abated                 |
| Comments:RM 408,406, replaced tiles |
|                                     |

| HA No | Material Description                    | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 21    | 12"x12" White w/ Speckles<br>VFT Mastic | 5500                 | SF                | Rooms 508, 502, 408,<br>407, 406, 405, 403, 302,<br>301, Principal Toilet, 308<br>Closet - 1928 Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change              |
|-------------------------------------|
| Comments:                           |
|                                     |
| 2017 - Spring: No Change            |
| Comments:                           |
|                                     |
| 2017 - Fall: No Change              |
| Comments:                           |
| 2018 - Spring : No Change           |
| Comments:                           |
|                                     |
| 2018 - Fall: Abated                 |
| Comments:RM 408,406, replaced tiles |
|                                     |

| HA No | Material Description            | Material<br>Quantity | Material<br>Units | Material Location     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---------------------------------|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 22    | 12"x12" Rust w/ Speckles<br>VFT | 750                  | SF                | Room 503 - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: Damaged      |  |
| Comments:broken tiles     |  |
|                           |  |

| HA No | Material Description                   | Material<br>Quantity | Material<br>Units | Material Location     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 23    | 12"x12" Rust w/ Speckled<br>VFT Mastic | 750                  | SF                | Room 503 - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |  |  |
|---------------------------|--|--|
| Comments:                 |  |  |
|                           |  |  |
| 2017 - Spring: No Change  |  |  |
| Comments:                 |  |  |
|                           |  |  |
| 2017 - Fall: No Change    |  |  |
| Comments:                 |  |  |
| 2018 - Spring : No Change |  |  |
| Comments:                 |  |  |
|                           |  |  |
| 2018 - Fall: No Change    |  |  |
| Comments:                 |  |  |
|                           |  |  |

| HA | A No | Material Description                       | Material<br>Quantity | Material<br>Units | Material Location     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|----|------|--|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 24 | 1    | 12"x12" Light Blue w/ White<br>Streaks VFT | 750                  | SF                | Room 504 - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: Abated       |  |
| Comments:replaced tiles   |  |
|                           |  |

| HA No | Material Description                              | Material<br>Quantity | Material<br>Units | Material Location     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 25    | 12"x12" Light Blue w/ White<br>Streaks VFT Mastic | 750                  | SF                | Room 504 - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Abated       |
| Comments:replaced tiles   |
|                           |

| HA No | Material Description                  | Material<br>Quantity | Material<br>Units | Material Location                              | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---------------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 26    | 12"x12" White w/ Brown<br>Streaks VFT | 2000                 | SF                | 1st Floor Corridor, 505<br>Closet - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: Damaged      |  |
| Comments:broken tiles     |  |
|                           |  |

| HA No | Material Description                         | Material<br>Quantity | Material<br>Units | Material Location                              | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 27    | 12"x12" White w/ Brown<br>Streaks VFT Mastic | 2000                 | SF                | 1st Floor Corridor, 505<br>Closet - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 28    | 9"x9" Brown w/ White<br>Streaks VFT | 200                  | SF                | Room 506, Conference<br>Rm- 1895 Bldg.<br>(Main Office, Principal<br>Office NOT OBSERVED) |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:broken tiles     |
|                           |

| HA No | Material Description                       | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 29    | 9"x9" Brown w/ White<br>Streaks VFT Mastic | 200                  | SF                | Room 506, Main Office,<br>Principal Office,<br>Conference - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2018 - Spring : No Change |
| Comments:                 |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-----------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 30    | 12"x12" Off White VFT | 450                  | SF                | 1st Floor Ladies Toilet,<br>2nd Floor Teachers Toilet<br>- 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description            | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 31    | 12"x12" Off White VFT<br>Mastic | 450                  | SF                | 1st Floor Ladies Toilet,<br>2nd Floor Teachers Toilet<br>- 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 32    | 9"x9" White w/ Yellow<br>Streaks VFT | 750                  | SF                | Room 401 (Under Other<br>Tile) - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:broken tiles     |
|                           |

| HA No | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 33    | 9"x9" White w/ Yellow<br>Streaks VFT Mastic | 750                  | SF                | Room 401 (Under Other<br>Tile) - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                  | Material<br>Quantity | Material<br>Units | Material Location    | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---------------------------------------|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 34    | 12"x12" Brown & White<br>Speckled VFT | 750                  | SF                | Room 305 - 1895 Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Abated       |
| Comments:replaced tile    |
|                           |

| HA No | Material Description                         | Material<br>Quantity | Material<br>Units | Material Location    | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 35    | 12"x12" Brown & White<br>Speckled VFT Mastic | 750                  | SF                | Room 305 - 1895 Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Abated       |
| Comments:replaced tile    |
|                           |

| HA No | Material Description                | Material<br>Quantity | Material<br>Units | Material Location     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-------------------------------------|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 36    | 9"x9" Green w/ White<br>Streaks VFT | 250                  | SF                | Room 308 - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:broken tiles     |
|                           |

| HA No | Material Description                       | Material<br>Quantity | Material<br>Units | Material Location     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 37    | 9"x9" Green w/ White<br>Streaks VFT Mastic | 250                  | SF                | Room 308 - 1895 Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA | A No | Material Description                          | Material<br>Quantity | Material<br>Units | Material Location                             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|----|------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 38 | 3    | White Checkered Linoleum (Not Observed, 2016) | 250                  | SF                | Room 308 - 1895 Bldg.<br>(Not Observed, 2016) |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:broken tiles     |
|                           |

| HA No | Material Description                                       | Material<br>Quantity | Material<br>Units | Material Location                             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 39    | White Checkered Linoleum<br>Mastic (Not Observed,<br>2016) | 250                  | SF                | Room 308 - 1895 Bldg.<br>(Not Observed, 2016) |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 40    | 9"x9" Black w/ White<br>Streaks VFT (Not<br>Observed, 2016) | 200                  | SF                | Break Room (N) of<br>Kitchen - 1895 Bldg<br>(Not Observed, 2016) |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 0040 Opring No Oberge     |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description   | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 41    | 9"x9" Black w/ White<br>Streaks VFT Mastic NOT<br>OBSERVED, 2016 | 200                  | SF                | Break Room (N) of<br>Kitchen - 1895 NOT<br>OBSERVED, 201695<br>Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
|                           |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2018 - Spring : No Change |
| Comments:                 |
| oommonto.                 |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                                      | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 42    | 9"x9" White w/ Black<br>Streaks VFT NOT<br>OBSERVED, 2016 | 200                  | SF                | Break Room (N) of<br>Kitchen - 1895 Bldg<br>NOT OBSERVED, 2016 |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description   | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 43    | 9"x9" White w/ Black<br>Streaks VFT Mastic NOT<br>OBSERVED, 2016 | 200                  | SF                | Break Room (N) of<br>Kitchen - 1895 Bldg<br>NOT OBSERVED, 2016 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location                  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 44    | Brown Linoleum       | 400                  | SF                | Basement Store Room -<br>1895 Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

Oracle Unit: 23291 Page 19

| HA No | Material Description  | Material<br>Quantity | Material<br>Units | Material Location                  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-----------------------|----------------------|-------------------|------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 45    | Brown Linoleum Mastic | 400                  | SF                | Basement Store Room -<br>1895 Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                            | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 46    | 2'x4' White Textured<br>Dot/Groove Ceiling Tile | 2000                 | SF                | Room 503, 506 - 1895<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                         | Material<br>Quantity | Material<br>Units | Material Location                  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 47    | 2'x4' White Textured<br>Horizontal Groove CT | 2000                 | SF                | Room 503, 505, 506 -<br>1895 Bldg. |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| ſ | HA No | Material Description                                    | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|---|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
|   | 48    | 2'x4' White Textured<br>Speckled Groove Ceiling<br>Tile | 900                  | SF                | Room 503, 1st Floor and<br>2nd Floor Ladies<br>Bathrooms - 1895 Bldg. |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| Н | HA No | Material Description                                | Material<br>Quantity | Material<br>Units | Material Location              | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|---|-------|---|----------------------|-------------------|--------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 4 | 19    | 2'x4' White Textured Dot<br>1/2 Groove Ceiling Tile | 100                  | SF                | Kitchen Toilet - 1895<br>Bldg. |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 50    | 9"x9" Maroon VFT     | 2000                 | SF                | Assembly Hall, 1st, 2nd,<br>& 3rd Fl Corridors - 1928<br>Blda. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description    | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 51    | 9"x9" Maroon VFT Mastic | 2000                 | SF                | Assembly Hall, 1st, 2nd,<br>& 3rd Fl Corridors - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 52    | 9"x9" Black VFT      | 2000                 | SF                | Assembly Hall, 1st, 2nd,<br>& 3rd Fl Corridors - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description   | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 53    | 9"x9" Black VFT Mastic | 2000                 | SF                | Assembly Hall, 1st, 2nd,<br>& 3rd Fl Corridors - 1928<br>Bldo |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| · · · ·                   |  |
|---------------------------|--|
| 2016 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| H  | A No | Material Description                | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|----|------|-------------------------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 54 | 4    | 9"x9" Black w/ White<br>Streaks VFT | 500                  | SF                | Assembly Hall - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:broken tiles     |
|                           |

| HA No | Material Description                       | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 55    | 9"x9" Black w/ White<br>Streaks VFT Mastic | 500                  | SF                | Assembly Hall - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-----------------------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 56    | 9"x9" Red w/ White Streaks<br>VFT | 500                  | SF                | Assembly Hall - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: Damaged      |  |
| Comments:broken tiles     |  |
|                           |  |

| HA No | Material Description             | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 57    | 9"x9" Red w/ White VFT<br>Mastic | 500                  | SF                | Assembly Hall - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2018 - Spring : No Change |
|                           |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 58    | 12"x12" Black VFT    | 500                  | SF                | Assembly Hall - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:broken tiles     |
|                           |

| HA No | Material Description     | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 59    | 12"x12" Black VFT Mastic | 500                  | SF                | Assembly Hall - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 60    | 12"x12" Brown VFT    | 500                  | SF                | Assembly Hall - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:broken tiles     |
|                           |

| HA No | Material Description     | Material<br>Quantity | Material<br>Units | Material Location             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 61    | 12"x12" Brown VFT Mastic | 500                  | SF                | Assembly Hall - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                   | Material<br>Quantity | Material<br>Units | Material Location                                    | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 62    | 12"x12" Brown w/ White<br>Speckles VFT | 200                  | SF                | South Assembly Hall<br>Dressing Room - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:broken tiles     |
|                           |

| HA No | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location                                    | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 63    | 9"x9" Brown w/ White<br>Speckles VFT Mastic | 200                  | SF                | South Assembly Hall<br>Dressing Room - 1928<br>Bldg. |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 64    | 12"x12" White w/ Multi<br>Specks VFT | 1200                 | SF                | Principal Office, Main<br>Office, Room 401, 1895<br>Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 65    | 12"x12" White w/ Multi<br>Specks VFT Mastic | 1200                 | SF                | Principal Office, Main<br>Office, Room 401, 1895<br>Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

|                           | · · | · · |  |
|---------------------------|-----|-----|--|
| 2016 - Fall: No Change    |     |     |  |
| Comments:                 |     |     |  |
|                           |     |     |  |
| 2017 - Fall: No Change    |     |     |  |
| Comments:                 |     |     |  |
|                           |     |     |  |
| 2017 - Spring: No Change  |     |     |  |
| Comments:                 |     |     |  |
| 2018 - Spring : No Change |     |     |  |
| Comments:                 |     |     |  |
|                           |     |     |  |
| 2018 - Fall: No Change    |     |     |  |
| Comments:                 |     |     |  |
|                           |     |     |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location                  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 66    | Spray-On Insulation  | 1500                 | SF                | Boiler Room, Engine<br>Room - 1897 |                  | Surface              | Yes     | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: Damaged      |  |
| Comments:broken tiles     |  |
|                           |  |

| HA No | Material Description      | Material<br>Quantity | Material<br>Units | Material Location                             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 67    | 12"x12" White w/ Dots VFT | 3500                 | SF                | Elevator, 1st & 2nd Floor<br>Corridors - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                | Material<br>Quantity | Material<br>Units | Material Location                             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 68    | 12"x12" White w/ Dots VFT<br>Mastic | 3500                 | SF                | Elevator, 1st & 2nd Floor<br>Corridors - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description   | Material<br>Quantity | Material<br>Units | Material Location                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|------------------------|----------------------|-------------------|-------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 69    | 12"x12" Gray w/ Dots ∖ | FT 3500              | SF                | 1st & 2nd Floor Corridors<br>- 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description               | Material<br>Quantity | Material<br>Units | Material Location                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|------------------------------------|----------------------|-------------------|-------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 70    | 12"x12" Gray w/ Dots VFT<br>Mastic | 3500                 | SF                | 1st & 2nd Floor Corridors<br>- 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
|                           |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA | No | Material Description                | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|----|----|-------------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 71 |    | 12"x12" White w/ Gray<br>Swirls VFT | 3500                 | SF                | Throughout - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HAN | No | Material Description                       | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-----|----|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 72  |    | 12"x12" White w/ Gray<br>Swirls VFT Mastic | 3500                 | SF                | Throughout - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 73    | 2'x2' Groved CT      | 3500                 | SF                | Throughout - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

|   | HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|---|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| ſ | 74    | Vinyl Baseboards     | 5000                 | LF                | Throughout - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description    | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 75    | Vinyl Baseboards Mastic | 5000                 | LF                | Throughout - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA | A No | Material Description | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|----|------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 76 | 6    | Drywall              | 18000                | SF                | Throughout - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

|                           | 1 |
|---------------------------|---|
| 2016 - Fall: No Change    |   |
| Comments:                 |   |
|                           |   |
| 2017 - Spring: No Change  |   |
| Comments:                 |   |
|                           |   |
| 2017 - Fall: No Change    |   |
| Comments:                 |   |
| 2018 - Spring : No Change |   |
| Comments:                 |   |
| Comments.                 |   |
| 2018 - Fall: No Change    |   |
| Comments:                 |   |
|                           |   |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 77    | Drywall Compound     | 3500                 | LF                | Throughout - 1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location                               | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 78    | Spray-On Insulation  | 2500                 | LF                | Throughout Above<br>Ceilings On Beams -<br>1994 |                  | Surface              | Yes     | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 79    | Carpet Mastic        | 5000                 | SF                | Main Office, Offices 1, 2,<br>3, & 4, Library, & 201 -<br>1994 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
| Comments.                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 80    | 12"x12" Gray w/ Black<br>streaks VFT | 1400                 | SF                | Room 200(Teacher<br>Lounge) & 320 (old boy's<br>playroom) - 1985 bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Fall: Damaged      |  |
| Comments:broken tiles     |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 81    | 12"x12" Gray w/ Black<br>streaks VFT Mastic | 1400                 | SF                | Room 200(Teacher<br>Lounge) & 320 (old's<br>boy's playroom) - 1985<br>bldg |                  | Miscellaneous        | No      | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                      | Material<br>Quantity | Material<br>Units | Material Location         | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 82    | 2'X4' White w/ dot waves<br>ceiling tiles | 750                  | SF                | Main Office in 1895 Bldg. |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description | Material<br>Quantity | Material<br>Units | Material Location                                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 83    | Terrazzo             | 2000                 | SF                | All floors, entry ways and corridors - 1928 addtion |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change         |
|--------------------------------|
| Comments:                      |
|                                |
| 2017 - Fall: No Change         |
| Comments:                      |
|                                |
| 2017 - Spring: No Change       |
| Comments:                      |
|                                |
| 2018 - Fall: Damaged           |
| Comments:damaged pits in floor |
|                                |
| 2018 - Spring : No Change      |
| Comments:                      |
|                                |

| HA No | Material Description     | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 84    | 12x12 Cream speckled VFT | 550                  | SF                | Rm 306            |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description               | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|------------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 84A   | 12x12 Cream speckled VFT<br>Mastic | 550                  | SF                |                   |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| I | HA No | Material Description    | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|---|-------|-------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
|   | В     | MJP E/F/V on Fiberglass | 15                   | SF                | Basement Boys Toilet,<br>Girls Toilet in Pipe<br>Chasre - 1897 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |  |  |  |  |  |  |  |
|---------------------------|--|--|--|--|--|--|--|--|
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |
| 2017 - Spring: No Change  |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
| 2017 - Fall: No Change    |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
| 2018 - Spring : No Change |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
| 2018 - Fall: Damaged      |  |  |  |  |  |  |  |  |
| Comments:missing tiles    |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |

| HA No | Material Description     | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| С     | Air Cell Pipe Insulation | 200                  | LF                | Basement Girls<br>Playroom, Lunch Room,<br>Kitchen, Room 109,<br>Basement Janitors Closet<br>- 1895 Bldn |                  | TSI                  | Yes     | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |  |  |  |  |  |  |  |
|---------------------------|--|--|--|--|--|--|--|--|
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |
| 2017 - Spring: No Change  |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |
| 2017 - Fall: No Change    |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
| 2040 Fally No Change      |  |  |  |  |  |  |  |  |
| 2018 - Fall: No Change    |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |
| 2018 - Spring : No Change |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |

| HA No | Material Description                       | Material<br>Quantity | Material<br>Units | Material Location               | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|---------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| D     | MJP E/F/V on Fiberglass<br>Pipe Insulation | 50                   | SF                | Attic above Gym - 1928<br>Bldg. |                  | TSI                  | Yes     | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |  |  |  |  |  |  |  |
|---------------------------|--|--|--|--|--|--|--|--|
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |
| 2017 - Spring: No Change  |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |
| 2017 - Fall: No Change    |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
| 2018 - Spring : No Change |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |
| 2018 - Fall: No Change    |  |  |  |  |  |  |  |  |
| Comments:                 |  |  |  |  |  |  |  |  |
|                           |  |  |  |  |  |  |  |  |

*VFT* = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.*  Oracle Unit: 23291 Page 41

| HA No | Material Description    | Material<br>Quantity | Material<br>Units | Material Location                  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|-------------------------|----------------------|-------------------|------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| E     | Aircell Pipe Insulation | 69                   | LF                | Auditorium Fan Room -<br>1928 Bldg |                  | TSI                  | Yes     | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                    | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| F     | MJP E/F/V on Aircell Pipe<br>Insulation | 40                   | LF                | Basement Girls<br>Playroom, Lunch Room,<br>Kitchen, Room 109,<br>Basement Janitors Closet<br>- 1895 Bldg. |                  | TSI                  | Yes     | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description      | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| G     | Cardboard Pipe Insulation | 200                  | LF                | Bsmt. Girls Playroom,<br>Basement Hall, Room<br>109 & Toilet, Boys Toilet,<br>Store Rm & JC - 1895<br>Bldg. |                  | TSI                  | Yes     | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description                      | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| н     | MJP E/F/V on Cardboard<br>Pipe Insulation | 40                   | LF                | Lunch Room, Bsmt. Girls<br>Playroom, Room 109 &<br>Toilet, Boys Toilet, Store<br>Rm & JC - 1895 Bldg. |                  | TSI                  | Yes     | None           | 0                  |                 |                               |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |

| HA No | Material Description      | Material<br>Quantity | Material<br>Units | Material Location                             | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 1     | Cardboard Pipe Insulation | 100                  | LF                | Auditorium Tunnel Crawl<br>Space - 1928 Bldg. |                  | TSI                  | Yes     | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
|                           |  |

*VFT* = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.* 

| HA No | Material Description                    | Material<br>Quantity | Material<br>Units | Material Location                 | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-----------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| J     | 12" X 12" black with white streaks, VFT | 35                   | SF                | 3rd floor corridor - 1928<br>Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES XNO                       |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Damaged      |
| Comments:outside office   |
|                           |

| HA No | Material Description                       | Material<br>Quantity | Material<br>Units | Material Location                 | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-----------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| к     | 12" X 12" black with white streaks, Mastic | 35                   | SF                | 3rd floor corridor - 1928<br>Bldg |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |
|---------------------------|
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
| 2017 - Spring: No Change  |
| Comments:                 |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description   | Material<br>Quantity | Material<br>Units | Material Location                       | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |
|-------|------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| L     | Fire-proofed draperies | 600                  | SF                | Auditorium Stage, 1928<br>Bldg Addition |                  | Miscellaneous        | No      | None           | 0                  |                 | YES X NO                      |

| 2016 - Fall: No Change    |  |
|---------------------------|--|
| Comments:                 |  |
|                           |  |
| 2017 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |
| 2017 - Spring: No Change  |  |
| Comments:                 |  |
| 2018 - Spring : No Change |  |
| Comments:                 |  |
| 2018 - Fall: No Change    |  |
| Comments:                 |  |
|                           |  |

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

| School: | Frederick Funston Elementary School |
|---------|-------------------------------------|
| Date:   | 1/8/2019                            |

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

## CHECK ONE

X A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

## A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.