## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

Joseph E Gary Elementary School 23311 3520 School: **Oracle Unit: Building ID:** Address: 3740 W. 31st St. Region: Mail Room: Asbestos Surveyor: Vargas, Armando **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 1/9/2019 Email Address: avargas139@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other Material Description HA No Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity YES SF 0 X NO Plaster 60000 Throughout 1909 Building Surface Yes None 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

											1
004C F-II	No Observe										
2016 - Fall:	: No Change										
Comments	:										
2017 Falls	: No Change				_						
Comments	:										
2017 - Spri	ng: No Change										
Comments											
2018 - Fall:	: No Change										
Comments	:										
		·									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

800

SF

Material

Quantity

Material

Units

Material Location

100 of 1909 Building

104

HA No

2 D

2A

Material Description

9" x 9" Beige Floor Tile

9"x9" Tan w/Yellow, Blue,

and White Floor Tile

Page 2

Change in Assessment Category

X NO

X NO

YES

			1							
2B	9"x9" Tan Floor Tile w/Brown and White	800	SF	100 and Room 208 of 1909 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:	•									
2018 - Fall: N	o Change									

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2C	9"x9" Brown Floor Tile w/White and Red	800	SF	208 and Faculty Washroom of 1909 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
2E	9" x 9" Black Floor Tile	50	SF	Faculty Washroom of 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

016 - Fall: No Change
comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2F	9" x 9" Maroon Floor Tile	20	SF	Faculty Washroom of 1909 Building		Miscellaneous	No	None	0		YES X NO

0040 5 11 N1 O1	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

		-				• •			-		
2G	9" x 9" Brown Floor Tile	750	SF	208 of 1909 Building		Miscellaneous	No	Loc	5	YES	X NO
2016 - Fall: N	lo Change				]						
Comments:											
2017 - Spring	: No Change				_						
Comments:											
2017 - Fall: N	lo Change										
Comments:					-						
2018 - Fall: N	lo Change										

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2H	9"x9" Green Floor Tile w/White Streaks	400	SF	204 of 1909 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Aqua Floor Tiles w/White Streaks	415	SF	Room 204 of 1909 Building		Miscellaneous	No	None	0		YES X NO
2016 Falls N	2016 Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2J	9"x9" Aqua Floor Tile w/Black and White Specks	40	SF	301 of 1909 Building		Miscellaneous	No	Loc	8		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 6

2016 Falls	No Changa										
2016 - Fall:											
Comments:	Comments:										
2017 - Spring: No Change											
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
	_		•	_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

Loc

Damage

Quantity

8

Damage

Units

Change in Assessment Category

X NO

X NO

YES

YES

2L	9"x9" Gray Floor Tile w/White Streaks		Gym of 1909 Building
	•	-	
2016 - Fall: N	lo Change		
Comments:			
2017 - Fall: N	No Change		
Comments:			
2017 - Spring	g: No Change		
Comments:			
2018 - Fall: N	No Change		
Comments:			

Material

Quantity

50

Material

Units

SF

Material Location

301 of 1909 Building

HA No

2K

Material Description

9"x9" Yellow Floor Tile

w/White Streaks

2M	9"x9" Light Brown Floor Tile w/White Swirls			Gym of 1909 Building		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring: No Change												
Comments:	•											
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No Material Description Material Material Location Quantity Units						Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

700

SF

HA No

ЗА

Material Description

12"x12" Beige Floor Tile w/Brown Streaks

Material

Quantity

Material

Units

Material Location

005 of 1909 Building

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
3B	12"x12"Beige Floor Tile w/Brown and White Specks	750	SF	101 of 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3C	12"x12" Beige Floor Tile w/Brown and White Streaks	750	SF	206 of 1909 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 9

	3D	12"x12" White Floor Tile	700	SF	301of 1909 Building		Miscellaneous	No	Loc	7		YES	X NO
ĺ	2016 - Fall: No	o Change				]							
	Comments:	-											
	2017 - Spring:	: No Change											
	Comments:												
	2017 - Fall: No	o Change											
	Comments:												
	2018 - Fall: No	o Change											
	Comments:												
						I							
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
	4	12"x12" Ceiling Tile			Throughout Annex		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
5A	12"x12" Multi-Gray Floor Tile	1900	SF	Hallways of 1972 Annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5B	12"x12" Gray Floor Tile w/White Streaks	600	SF	Book Room and Storage in 1972 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

6	Brown Linoleum	400	SF	Basement Room D of 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments					-							
Comments	•											
2017 - Fall:	No Change				=							
Comments												
2017 - Spri	ng: No Change				1							
Comments												
2018 - Fall:	No Change				1							
Comments	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
7	Transite Panels	,		Basement (Abated)	7.	3 7		None	,		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
8A	9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic	800	SF	Room 100 in 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	_											
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	lo Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
8B	9"x9" Tan Floor Tile w/Brown and White Mastic	800	SF	Faculty Washroom by Room 100 and Room 208 of 1909 Building		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

8C	9"x9" Brown Floor Tile w/White and Red Mastic	800	SF	Faculty Washroom and Room 208 of 1909 Building		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change			<u> </u>	1						
Comments											
2017 - Spr	ing: No Change				1						
Comments	S:				]						
2017 - Fall	: No Change										
Comments	S:				_						
	: No Change				]						
Comments	3:				1						
1					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8D	9" x 9" Beige Floor Tile Mastic	250	SF	Room 104 of 1909 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmer	nt Category
8E	9" x 9" Black Floor Tile Mastic	50	SF	Faculty Washroom of 1909 Building		Miscellaneous	No	None	0		YES	NO
2016 - Fall: N	No Change				]							

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8F	9" x 9" Maroon Floor Tile Mastic	20	SF	Faculty Washroom of 1909 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	ry
8G	9" x 9" Brown Floor Tile Mastic	750	SF	Room 208 of 1909 Building		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: I	No Change			_	1							

016 - Fall: No Change
comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8H	9" x 9" Green Floor Tile Mastic	400	SF	Room 204 0f 1909 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	9" x 9" Aqua Floor Tile Mastic	415	SF	Room 301 of 1909 Building		Miscellaneous	No	None	0		YES X NO
0040 5 11 14	01				1						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8J	9" x 9" Aqua Floor Tile Mastic	40	SF	Room 301 of 1909 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

											II.
0010 5 1					٦						
	l: No Change										
Comments:											
2017 - Spi	ring: No Change										
Comments	3:										
2017 - Fal	I: No Change										
Comments	<b>3</b> :										
2018 - Fal	I: No Change										
Comments	3:										
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material

Quantity

40

Material

Units

SF

Material Location

Room 301 of 1909

Gym of 1909 Building

Building

HA No

8K

8L

Material Description

9" x 9" Yellow Floor Tile

9" x 9" Gray Floor Tile

Mastic

Change in Assessment Category

X NO

X NO

YES

8M	9" x 9" Light Brown Floor Tile Mastic			Gym of 1909 Building		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	to Change				-							
2017 - Spring	g: No Change				_							
Comments:					1							
2017 - Fall: N	No Change				_							
Comments:												
2018 - Fall: N	No Change											
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

750

HA No

9A

Material Description

9" x 9" Light Brown Floor

12" x 12" Beige Floor Tile w/ Brown Streaks Mastic

Material

Units

SF

Material

Quantity

Material Location

Room 005 of 1909

Building

Page 19

Change in Assessment Category

X NO

VES

YES

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	ıry
9B	12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic	750	SF	101		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change				1							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic	700	SF	206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

9D	12" x 12" White Floor Tile Mastic	700	SF	301		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	o Orlange											
2017 - Spring	: No Change											
Comments:												
0047 5 11 11	01											
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
10	Number Skipped										YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

11	Tan Linoleum	576	SF	Kitchen of 1909 Building		Miscellaneous	No	Dist	25		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>				1							
2017 - Fall: N	lo Change				}							
Comments:												
2017 - Spring	g: No Change											
Comments:					 							
2018 - Fall: N	lo Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:			•	

720

Material

Quantity

Material

Units

SF

Material Location

Lunchroom, 008, and 009

of 1909 Building

HA No

13

Material Description

Beige Linoleum

YES

X NO

15A	4" Black Vinyl Baseboards	1800	LF	Annex		Miscellaneous	NO	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	· ·				-							
2018 - Fall:	No Change				-							
Comments:	· ·											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
15B	6" Black Vinyl Baseboard	480	LF	Hallways of 1972 Annex		Miscellaneous	No	None	0		YES	X NO
	: No Change				]							
Comments	<u>:</u>				-							
2017 - Fall:	: No Change											
Comments	:				-							
					4							

2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No

15A

Material Description

4" Black Vinyl Baseboards

Material

Units

LF

Material

Quantity

1800

Material Location

Classrooms in 1972

Change in Assessment Category

X NO

	I .									<u> </u>	
16A	4" Black Vinyl Baseboard Mastic	1800	LF	Classrooms of 1972 Annex		Miscellaneous	No	None	0	YES	X NO
					1						
2016 - Fall: I	No Change										
Comments:											
					1						
2017 - Sprin	g: No Change				1						
Comments:											
					1						
2017 - Fall: I	No Change										
Comments:					1						
					1						
2018 - Fall:	No Change										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16B	6" Black Vinyl Baseboard Mastic	480	LF	Hallways of 1972 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

19	Exterior Brick - Not AHERA			1909 Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	j: No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
20	Exterior Brick Mortar	14000	SF	1909 Building		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

21	Exterior Door Caulk	120	LF	1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	Ü											
2017 - Fall: N	lo Change				-							
Comments:	J											
2017 - Spring	g: No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

22	Drywall	1440	SF	Lunchroom, 008, 009 of 1909 Building						
2016 - Fa	II: No Change									
Comment	S:									
2017 - Fall: No Change										
Comment	s:									
2017 - Sp	ring: No Change									
Comment	s:									
2018 - Fa	II: No Change									
Comment	s:	·		·						
	·			·						

Material

Quantity

Material

Units

Material Location

Teacher's Room,

HA No

Material Description

YES

X NO

23	Black Cementitious Flooring	1760	SF	First Floor Corridor and Stair Landings of 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 Falls	No Change			•	1				•			
Comments:	ı											
2017 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
,					_							
LIA NI-	Markedal December	NA-t-d-	NA-t-d-	I Maradallandon	A -11	Maria da	Establis	D	D	D	Observa la Assers	

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

First Floor Corridor and

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Green Terrazzo	40	SF	Women's Washroom of 1909 Building		Miscellaneous	No	None	0		YES X NO
0040 5 11 1	. 0				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

25	Brown Terrazzo Wall Panels	40	SF	Men's and Women's Washrooms of 1909 Building		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change	•	<u> </u>	•				·			
Comments:					4						
2017 - Fall: N	o Change										
Comments:					4						
2017 - Spring	: No Change				1						
Comments:											
2018 - Fall: N	o Change				1						
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Men's and Women's

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
26	2'x2' Ceiling Panels	800	SF	Lunchroom of 1909 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Fall: No Change												

Comments: 2017 - Spring: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

2018 - Fall: No Change Comments:

27	Terrazzo Basin	20	SF	Kitchen and Sink Closet of 1909 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	o Griango									
2017 - Fall: N	lo Change									
Comments:	o Griango									
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:	J									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Yellow Baseboard	200	SF	Lunchroom of 1909 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

29	Yellow Baseboard Mastic	200	SF	Lunchroom of 1909 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
2017 - Fall: N	lo Change									
Comments: 2017 - Spring	g: No Change									
Comments:	la Changa									
2018 - Fall: N Comments:	io Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Blue Baseboard	108	SF	1st Room West of E Entrance of 1909 Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

				1				- 1			
2016 - Fall:	: No Change										
Comments											
2017 - Fall:	: No Change										
Comments											
2017 - Spri	ing: No Change										
Comments											
2018 - Fall:	: No Change										
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

HA No

31

32

Comments:

Comments:

Comments:

Comments:

Material Description

Blue Baseboard Mastic

Interior Brick

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Units

SF

SF

80000

Material

Quantity

100

Material Location

1st Room West of E

Entrance of 1909 Building

Throughout 1909 Building

Change in Assessment Category

X NO

X NO

YES

33	Interior Brick Mortar	80000	SF	Throughout 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

34

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Terrazzo Baseboard

Material

Quantity

Material

Units

SF

300

Material Location

Throughout 1909 Building

Change in Assessment Category

YES

X NO

2016 - Fall: N	No Change										
	10 Change										
Comments:											
2017 - Fall: N	No Change										
Comments:	10 Ondrigo										
2017 - Spring	g: No Change										
Comments:											
0040 5 11 1											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Units	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

35

36

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Ceramic Tile Grout

Glazed Brick Mortar

Material

Quantity

70

400

Material

Units

SF

SF

Material Location

1909 Building

Throughout Entrances of

Throughout 1909 Building

Change in Assessment Category

X NO

X NO

YES

37	Interior Door Caulk	200	LF	Throughout 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	_											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
		1	1		1			i e	i e			

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

HA No

38

Comments:

Comments:

Comments:

Comments:

Material Description

Block Mortar

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

10

SF

Auditorium

Material

Units

Material Location

YES

X NO

39	Blue/Green/Gray/White Ceramic Tile Grout	500	SF	Girl's Washrooms of 1909 Building		Miscellaneous	No	None	0		YES	X NO
2242 = "	N. O.				1							
2016 - Fall:	: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments												
Comments												
2017 - Spri	ng: No Change											
Comments												
2019 Falls	· No Changa											
	: No Change											
Comments	•											
HA No	Material Description	Material	Materia	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
40	Gray Carpet Mastic	1500	SF	Office, 105, and 106 of 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments: 2017 - Fall: N	o Change											
2011 Tall: 14	o onango				1							

Comments: 2017 - Spring: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Throughout Boy's and Girl's Washrooms of 1909

2018 - Fall: No Change Comments:

Change in Assessment Category

41	Cinder Block Mortar	1300	SF	Throughout 1909 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

200

HA No

42

Material Description

Black Border Tile

Material

Quantity

Material

Units

SF

Material Location

204 of 1909 Building

YES

X NO

004C Fall	Na Ohana				<del></del>						
	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprii	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Yes

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

HA No

43

44

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Black Border Tile Mastic

2'x4' Ceiling Panels

Material

Units

SF

SF

Material Quantity

50

200

Material Location

204 of 1909 Building

Kitchen of 1909 Building

Change in Assessment Category

X NO

X NO

YES

0040 5 11											
	l: No Change										
Comments	S:										
2017 - Fall	l: No Change										
Comments	S:										
2017 - Spr	ing: No Change										
Comments	S:										
2018 - Fall	l: No Change										
Comments	S:										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category	1	Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

150

Material

Quantity

150

Material

Units

SF

SF

Material Location

1909 Building

Washroom in Room D of

D Room of 1909 Building

HA No

45

46

Material Description

Terrazzo

12"x12" Terrazzo

Change in Assessment Category

X NO

X NO

YES

47	Boiler Wrap #1	500	SF	Boiler Room of 1909 Building		Miscellaneous	Yes	Loc	50	YES	X NO
2016 - Fa	all: No Change										
Commen											
2017 - Fa	all: No Change										
Commen											
2017 - Sp	oring: No Change				-						
Commen	ts:										
2018 - Fa	all: Repaired				}						
Commen	ts:Cheese cloth repair	ed y Andee	Boiler								
					J						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Boiler Room of 1909

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
48	Boiler Wrap #2	500	SF	Boiler Room of 1909 Building		Miscellaneous	Yes	Loc	50		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Change in Assessment Category

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
	49	Insulation Over Fiberglass	140	LF	Maintenance Room of 1909 Building		TSI	Yes	None	0		YES	X NO
-	2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Mag Block Insulation	100	LF	Boiler Room of 1909 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	tegory
51	Duct Insulation	300	SF	Boiler Room of 1909 Building		TSI	Yes	None	0		YES X NO	)
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Refractory Cement in Doors of #1 Boiler	20	SF	Boiler Room of 1909 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Refractory Cement in Doors of #2 Boiler	20	SF	Boiler Room of 1909 Building		TSI	Yes	None	0		YES X NO
2010 = 11 11		1									

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Firebrick in Boiler #1	200	SF	Boiler Room of 1909 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

				J							
2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprin	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
			1							_	<u></u>
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
		Qualitity	Office		туре	Category		Турс	Quantity	Office	

Type

Material

TSI

Category

Miscellaneous

Friable

Yes

Damage

Туре

None

Damage

Quantity

0

Damage

Units

Material Location

Boiler Room of 1909

004 of 1909 Building

Building

Material

Quantity

200

Material

Units

SF

HA No

55

56

Material Description

Firebrick in Boiler #2

4" Black Vinyl Baseboard

Change in Assessment Category

X NO

X NO

YES

	Madie										
2016 - Fall: N	No Change										
Comments:	<u> </u>										
0045 5 11 1											
2017 - Fall: N	No Change										
Comments:											
2017 - Spring: No Change											
Comments:											
2018 - Fall: N	No Change										
Comments:	J										
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
					71	5-7	ļ	71			

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

10

SF

HA No

57

60

Material Description

4" Black Vinyl Baseboard

Green Ceramic Tile Grout

Mastic

Material

Quantity

Material

Units

Material Location

004 of 1909 Building

Entrances of 1972 Annex

Change in Assessment Category

X NO

X NO

YES

				1972 Annex							
	· · · · · · · · · · · · · · · · · · ·	-	•	•	7	•	*	•	•	•	•
2016 - Fall:											
Comments:											
2017 - Fall: No Change											
Comments:											
0047 0	an Na Ohanan										
	ng: No Change										
Comments:											
2018 - Fall:	No Change				1						
Comments:	<u> </u>				-						
Comments.					+						
					J						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

HA No

61

65

Material Description

Gray Carpet Mastic

**Exterior Door Caulk** 

Material

Units

SF

LF

Material

Quantity

600

Material Location

Classrooms, Teacher's

Throughout 1972 Annex

Lounge and Office of

Change in Assessment Category

X NO

X NO

YES

									<u> </u>	
66	12"x12" Multi-Gray Floor Tile Mastic	1900	SF	Hallways of 1972 Annex	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	·			·						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12"x12" Gray Floor Tile w/White Streaks Mastic	600	SF	Book Room and Storage in 1972 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		 

Material

Quantity

Material

Units

Material Location

HA No

Material Description

				*							
2016 - Fall: N	lo Change										
Comments:	to onange										
2017 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

TSI

Category

Friable

Yes

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material

Quantity

Material

Units

LF

Material Location

Electric Room (Behind

Electric Room of 1972

Annex

Wall) in 1972 Annex

HA No

68

70

Material Description

Cementitious Pipe Joint

Fiberglass Insulation

Insulation

Change in Assessment Category

X NO

X NO

YES

71	Vault Door Liner	15	SF	2nd Floor Landing N/E Stairwell		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments	<u> </u>				-							
Comments	).				-							
2017 - Fall	: No Change											
Comments	): :											
2017 Spr	ing: No Change				-							
	· ·											
Comments	S:				4							
2018 - Fall	: No Change				-							
Comments	<u> </u>				1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Type	Quantity	Units		
70	12" x 12" Tan w/ lt. Brown			F : 100								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

Engineer's Office

HA No

72

Material Description

Page 48

YES

X NO

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
	g: No Change										
Comments:					_						
2018 - Fall:	No Change										
Comments:					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

HA No

73

74

Material Description

It. brown floor tile

Mastic w/ 12" x 12" tan w/

12 x 12 Grey w/ Dk. Grey & White Floor Tile Material

Units

SF

Material

Quantity

Material Location

Engineer's Office

Engineer's Washroom

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

75	mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile	60	SF	Engineer's Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	V				1							
2017 - Fall: N	lo Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
76	purple carpet adhesive			Principal's Office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	Mastic w/ 12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
79	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile	2300	SF	Café		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	•											
2017 - Fall: I	No Change											
Comments:												
					1							

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

2017 - Spring: No Change Comments:

Material

Material

Material Location

2018 - Fall: No Change

Material Description

HA No

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile	2300	SF	Café		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
81	12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile	100	SF	Café		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile	100	SF	Café		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

83	Tan Linoleum	600	SF	Basement Art Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Sprin	g: No Change											
Comments:					-							
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
					1		1	1	1	1		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

600

HA No

84

Material Description

Adhesive w/ Tan Linoleum

Material

Quantity

Material

Units

SF

Material Location

Basement Art Room

YES

X NO

2016 - Fall:	No Change										
Comments:											
2017 - Fall:											
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

85

86

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Brown Carpet Adhesive

12" x 12" Beige Floor Tile

Material

Quantity

3000

700

Material

Units

SF

SF

Room 104

Material Location

1972 Annex Classrooms

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
87	Mastic Associated w/ 12" x 12" Beige Floor Tile	700	SF	Room 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	Vinyl Sheeting Glued on Plywood	3000	SF	Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

89	2' x 4' Ceiling Tile	7500	SF	N, S, E, W Corridor Entrances, Rooms 401- 412		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments					-							
2017 - Fall	: No Change											
Comments	<b>:</b>				-							
	ing: No Change											
Comments	<b>:</b>				4							
2018 - Fall												
Comments	:New tiles installed				_							
HA No	Material Description	Material	Material	Material Location	Achaetae	Material	Friable	Damage	Damage	Damage	Change in Access	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
A2	Cementitious Insulation on Joints off Fiberglass	350	LF	Throughout 1909 Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

B1	Cardboard Pipe Insulation	1300	LF	Throughout 1909 Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change				]							
	NO Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
					1							
2017 - Sprin	g: No Change				]							
Comments:	-				1							
					1							
2018 - Fall: 1	No Change				]							
Comments:												
					<b>-</b> '							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

TSI

Friable

Damage

Type

Type

None

Yes

Damage

Quantity

Quantity

0

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:		•	
		•	

Quantity

100

Units

LF

HA No

B2

Material Description

Cementitious Insulation off

Paper Wrap Pipe Runs

Material

Units

Material

Quantity

Material Location

Throughout 1909 Building

Change in Assessment Category

X NO

Damage

Units

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D1	Aircell Pipe Insulation	300	LF	Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Joseph E Gary Elementary School	
Date:1/10/2019	
This is to notify you in accordance with Illinois and Federal Asbestos Regulation the Asbestos Management Plan is available at each school during school house Requests to review the Asbestos Management Plan must be made at least 24	rs by appointment.
Also please be advised that CPS conducts asbestos inspections of all School The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.	s every three years.
CHECK ONE	
A copy of this notice was sent home in each child's backpack.	
X A copy of this notice was printed in the school's newsletter and sent home with	h each child
A copy of this notice was printed in the school's calendar and sent home with	each child
Other.	
A COPY OF THIS NOTICE MUST BE PLACED IN THE	

VFT = Vinyl Floor Tile
Oracle Unit: 23311

SCHOOL'S ASBESTOS MANAGEMENT PLAN.