Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Johann W von Goethe Elementary School 23341 3560 School: **Oracle Unit: Building ID:** Address: 2236 N. Rockwell Avenue Region: 02 Mail Room: Asbestos Surveyor: Mcardle, James **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 1/9/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Throughout - 1885 YES 01 Hard Coat Plaster SF X NO 60000 Miscellaneous No None 0 Building 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 23341

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	2'x4' Ceiling Tile	500	SF	Room 106 - 1885 Building		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12"x12" Brown VFT	16700	SF	Throughout - 1885 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

04	12"x12" Beige w/ Brown Spots VFT	2500	SF	2nd floor corridors. 1885 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	-											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:					 							
	g : No Change											
Comments:					 							
2018 - Fall:	No Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	12"x12" White VFT	1500	SF	First and Second Floor Hallways, Lunchroom Managers office, Kitchen, Room 001- 1885 Building		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Material Description

12"x12" Beige w/ Brown

Material

Units

Material

Quantity

Material Location

Rooms 106 & 206 - 1st,

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Brown w/ White Spots VFT	1500	SF	First and Second Floor Hallways, Lunchroom Managers office, Kitchen - 1885 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Air Cell Pipe Insulation	180	LF	Rooms 001, 002, 003, 004, Boiler Room, Coal Room- 1885 Building		TSI	Yes	Loc	1		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Repaired
Comments:vendor out in nov

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	MJP E/F/V on Aircell Pipe Insulation	35	LF	Rooms 001, 002, 003, 004, Boiler Room, Coal Room, Basement corridor's- 1885 Building		TSI	Yes	None	3		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Repaired
Comments:vendor out

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Cardboard Pipe Insulation	320	LF	Coal Room, Room 003, Room 004 and 004 Storage Room, Basement Corridor, South Fan Room, Boys + Girls Toilet, Basement- 1885 Building		TSI	Yes	Loc	5		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Repaired
Comments:vendor out

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
10	MJP E/F/V on Cardboard Pipe Insulation	21	LF	Coal Room, Room 003, Room 004 and 004 Storage Room, Basement Corridor, South Fan Room, Boys+Girls Toilet, Bastment- 1885 Building		TSI	Yes	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Repaired
Comments:vendor out

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	MJP E/F/V on Fiberglass Pipe Insulation	124	LF	Basement Girls Toilet, Rooms 001, 003, 004, 104 wardrobe, Basement Corridor, Pump Room, N. Fan Room- 1885 Building		TSI	Yes	None	17		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Repaired
Comments:vendor out

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Aircell Duct Insulation	480	SF	Basement Corridor- 1885 Building		TSI	Yes	Dist	2		X YES NO

2016 - Fall: Damaged
Comments:LOOSE INSULATION
2017 - Spring: Damaged
Comments:Loose duct insulation
2017 - Fall: Deteriorated
Comments:still loose insulation
2018 - Spring : Damaged
Comments:loose air cell insulation still
2018 - Fall: Repaired
Comments:vendor out

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
13	12"x12" Brown VFT Mastic	18450	SF	Throughout - 1885 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change				-							
Comments:	•]							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:					1							
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Beige w/ Brown Spots VFT Mastic	1350	SF	Rooms 106 & 206- 1885 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 9

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	ategory
15	12"x12" White VFT Mastic	2500	SF	First and Second Floor Hallways, Lunchroom, Managers office, Kitchen, RM 001 - 1885 Building		Miscellaneous	No	None	0		YES XN	0

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2047 5 11 N O	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
0040 5 11 N 01	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12" x12" Brown w/ White Spots VFT Mastic	2500	SF	First and Second Floor Corridors, Lunchroom Managers office, Kitchen, - 1885 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

11/(140	Waterial Description	Quantity	Units	Waterial Education	Туре	Category	Thable	Type	Quantity	Units	Change in 7,55cc	oment outegory
17	9" x 9" Brown w/ Streaks VFT	180	SF	Room 308 Wardrobe- 1885 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	:											
	: No Change											
Comments	:											
	ng : No Change											
Comments	:											
	: No Change											
Comments	:											
					_							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9" x 9" Brown w/ Streaks VFT Mastic	180	SF	Room 308 Wardrobe- 1885 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12" x 12" White w/ Brown Specks VFT (NOT OBSERVED)	0		Room # 500 through # 503 - 1987 Annex		Miscellaneous	No	None	0		YES X NO
•	•			•	1	•	•	-	-	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12" x 12" White w/ Brown Specks VFT Mastic (NOT OBSERVED)	0		Room # 500 through # 503 - 1987 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

21	12" x 12" Brown w/ Wht. & Black Specks VFT(NOT OBSERVED)	0	Throughout - 1987 Annex		Miscellaneous	No	None	0	YES	X NO
				1	•				•	
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
				1						
2017 - Fall: N	lo Change									
Comments:										
				1						
2018 - Spring	j : No Change]						
Comments:				1						
2018 - Fall: N	lo Change									
Comments:				1						
				1						
1										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" Brown w/ Wht. & Black Specks VFT Mastic (ABATED)			Throughout (See Hatching Maps) - 1987 Annex							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

23	12" x 12" Beige w/ Brown Specks VFT (ABATED)			Room 400, AP Room - 1987 Annex				YES	X NO
2016 - Fall: N	o Change				1				
Comments:									
2017 - Spring: No Change					1				
Comments:	. No Griango								
2017 - Fall: N	o Change				-				
Comments:	Ü				- -				
2018 - Spring	: No Change				_				
Comments:					1				
2018 - Fall: N	lo Change								
Comments:					1				
					J				

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Beige w/ Brown Specks VFT Mastic (ABATED)			Room 400, AP Room - 1987 Annex							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

25	12" x 12" White w/ Blue Specks VFT (NOT OBSERVED)		Room # 401 - 1987 Annex					YES	X NO
204C Fall N	o Change	•	 ·	1		•	•		
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
				1					
2017 - Fall: N	o Change								
Comments:									
2018 - Spring	: No Change								
Comments:				1					
2018 - Fall: N	o Change								
Comments:									
Commonto.									
				1					

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
26	12" x 12" White w/ Blue Specks VFT Mastic (NOT OBSERVED)			Room # 401 - 1987 Annex							YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27	1' x 1' White w/ Grooves Ceiling Tile	20000	SF	Throughout - 1987 Annex		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				_							
Comments:					-							
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	: No Change				=							
Comments:	-											
2018 - Fall: N	lo Change				1							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	1' x 1' White w/ Grooves Ceiling Tile Mastic	20000	SF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	1' x 1' White w/ Dots and Grooves Ceiling Tile	1200	SF	Room 400 - 1987 Annex		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	lo Change		_								

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	1' x 1' White w/ Dots & Grooves Clng. Tile Mastic	1200	SF	Room 400 - 1987 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
31	Vinyl Baseboard	3500	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change				-							
Comments:	, <u> </u>											
2018 - Fall: N	lo Change				<u> </u>							
Comments:]							
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Vinyl Baseboard Mastic	3500	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 18

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33	Drywall	50000	SF	Throughout - 1987 Annex		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	g: Damaged				1							
Comments:H	IALL WALL CRACKIN	NG,BY 502,	AND 403									
2017 - Fall: N	lo Change				1							
Comments:	Ŭ]							
2018 - Spring	g : No Change				_							
Comments:	grito Griange											
2018 - Fall: N	lo Chango				-							
Comments:	NO Change				-							
					<u> </u>							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Drywall Joint Compound	5000	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

35	and Brown Specs Floor Tile (ABATED)	LunchroomREMOVED	Miscella	eous			YES	X NO
2016 - Fa	II: No Change]					
Commen								
2017 - Sp	oring: No Change							
Commen								
	II: No Change							
Commen	ts:							
	oring : No Change							
Commen	ts:							
	II: No Change							
Commen	ts:	·						
]					
					1	1	1	

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12 x 12 White with Gray and Brown Specs Floor Tile (ABATED)			LunchroomREMOVED		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12x12 White w/ Tan Specs VFT	14000	SF	1st fl classrooms (400 thru 405) + staff rooms #06-#09; 2nd fl classrooms(500 thru 507) 1987 annex bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37M	12x12 White w/ tan specs VFT Mastic	14000	SF	1st fl classrooms (400 thru 405) + staff rooms #06-#09; 2nd fl classrooms(500 thru 507) 1987 annex bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12x12 Green with Gray + Dark Green specs VFT	7800	SF	1st fl corridor (4000 SF); 2nd fl corridor (3800 SF) 1987 annex bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
	•
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No Ma	laterial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38M Da	2x12 Green w/ gray + ark green specs VFT lastic	7800	SF	1st fl corridor (4000 SF); 2nd fl corridor (3800 SF)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	White Spray-On Under sink coating	3	SF	under sink in cabinet room #4021987 annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
40	1x1 White Ceiling Tile	2800	SF	3rd Floor Gym		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	1x1 White Ceiling Tile Matic	2800	SF	3rd Floor Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Tank Insulation	40	SF	Boiler Room		TSI	Yes	None	0		X YES NO

2016 - Fall: Damaged
Comments:VALVE ELBOWS, LOOSE
2017 - Spring: Damaged
Comments:VALVE ELBOWS , EXPOSED
2017 - Fall: Damaged
Comments:valve elbows, loose and damaged
2018 - Spring : Damaged
Comments:minor damage on elbows
2018 - Fall: Repaired
Comments:vendor out

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Johann W von Goethe Elementary School
Date: 1/11/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23341

SCHOOL'S ASBESTOS MANAGEMENT PLAN.