Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Jesse Owens Elementary Community Academy 23351 3570 School: **Oracle Unit: Building ID:** Address: 12302 S State Street Region: Mail Room: Asbestos Surveyor: Jackson, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/24/2018 Email Address: majackson35@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's calendar Notice printed in school's newsletter Each child's backpack Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 9x9 Green w/White Streaks YES 03 140 SF X NO Library Store Room Miscellaneous No Dist 50 Floor Tile 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04A	12x12 Tan w/Brown and White Specks Floor Tile	10193	SF	1st and 2nd Floor Corridors, Auditorium		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change Comments: 2017 - Spring: No Change
Comments:
2017 - Spring: No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2019 Falls No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04B	12x12 White w/Brown Specks Floor Tile	3700	SF	Rooms 112, 117, 218, 222, 224 and 110		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04C	12x12 Tan w/Brown & White Streaks Floor Tile	915	SF	Rm 108, 121, 110		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04D	12 x 12 Gray Floor Tile- Beneath Carpet	810	SF	Rm 114 (library)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
04E	12x12 White Floor Tile	1890	SF	Rm 121, 120, 123 and library 114 (under the carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change							·	·			·

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04F	12x12 Beige w/Brown & White Streaks Floor Tile	240	SF	Main office engineers office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
04G	12x12 Lilac Colored Floor Tile	1030	SF	Rm 120, 121, 123		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	g : No Change											
Comments:												

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
05	Green Carpet Mastic	810	SF	Room 114 (Library)		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
07	1'x1' Acoustical Ceiling Tile	120	SF	Engineers Office in Boiler Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:	_												
2017 - Spring	g: No Change												
Comments:	.												
2017 - Fall: N	lo Change												
Comments:	Ţ.												
2018 - Spring	g : No Change												
Comments:	, 5-												
2018 - Fall: N	lo Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
08	9x9 Green w/White Streaks Floor Tile Mastic	140	SF	Library Store Room		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09A	12x12 Tan w/Brown and White Specks Floor Tile Mastic	10450	SF	1st and 2nd Floor Corridors, Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change										•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09B	12x12 White w/Brown Specks Floor Tile Mastic	3700	SF	Rm 110, 112, 117, 218, 222 and 224		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 7

		Quantity	Units		Type	Category		Type	Quantity	Units		
09C	12x12 Tan w/Brown & White Streaks Floor Tile Mastic	915	SF	Rm 108, 121, 110		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change											
Commen	ts:											
2017 - Sp	oring: No Change											
Commen	ts:											
2017 - Fa	all: No Change											
Commen	ts:											

Material

Damage

Damage

Damage

Friable

					ı						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09D	12"x12" Gray Floor Tile Mastic	810	SF	room 114 (library)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Material Location

Material

HA No

Material Description

2018 - Spring: No Change

Mastic

2018 - Fall: No Change

Comments:

Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
09E	12x12 White Floor Tile Mastic	1890	SF	Rm 121, 120, 123 and Library 114		Miscellaneous	No	None	0		YES	X NO
0040 = 11 11	01				1							
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												

Material

Damage

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09F	12x12 Beige w/Brown & White Streaks Floor Tile Mastic	240	SF	Main office, engineers office		Miscellaneous	No	None	0		YES X NO

Material

Material Description

Material

Material Location

HA No

2018 - Fall: No Change

Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units		
09G	12x12 Lilac Colored Floor Tile Mastic	130	SF	Rooms 120, 121, 123		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change				+							
Comments:												

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	Green Carpet Adhesive	840	SF	Main Office (NOT OBSERVED); 2nd Floor Teachers Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Location

Page 10

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11B	Blue Carpet Adhesive	720	SF	Rm 122		Miscellaneous	No	None	0		YES	X NO
	No Change											
Comments:												
2017 - Sprii Comments:	ng: No Change											
Comments.												
2017 - Fall:	No Change											
Comments:												

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11C	Brown Carpet Adhesive	912	SF	Rm 124 & 206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Brown Baseboard	20	LF	2nd Floor Teachers Lounge		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	Brown Basebord Mastic	20	LF	2nd Floor Teachers Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12x12 Blue Floor Tile	523	SF	1994 - Lunchroom and Kitchen Office		Miscellaneous	No	Dist	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	12x12 Blue Floor Tile Mastic	523	SF	1994 - Lunchroom and Kitchen Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
14	12x12 White Floor Tile	2968	SF	1994 - lunchroom and kitchen office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments): :]							
2017 - Spri	ing: No Change											
Comments	:				_							
2017 - Fall	: No Change											
Comments): 											
2018 - Fall: No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Smooth Plaster	125000	SF	Throughout and Projection Room		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

2018 - Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Asse	essment Category
16	Textured Plaster	10500	SF	Auditorium		Surface	Yes	None	0		YES	X NO
2016 - Fall	l: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fall	l: No Change											
Comments	S:				_							
1					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12x12 Blue with White Specked Floor Tile	450	SF	Room 114		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Spring : No Change

Comments:

Page 15

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17M	12x12 Blue with White Specked Floor Tile Mastic	450	SF	Room 114		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	4" Brown Base Board	100	LF	Room 114		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
18M	4" Brown Base Board Mastic	100	LF	Room 114		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				1								
Comments:													
2017 - Fall: N	lo Change												
Comments:	•												
2017 - Spring	g: No Change												
Comments:													
2018 - Fall: N	lo Change												
Comments:	•												
2018 - Spring	g : No Change				_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Terrazo Flooring - Gray, White and Black Speckled	5500	SF	Stairs, Auditorium, Entrance and Washrooms		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	Carpet Mastic - Green dot pattern	500	SF	Teacher's Lounge in 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments:					1							
2017 - Spri	ing: No Change											
Comments:												
2017 - Fall: No Change												
Comments	Comments:											

2018 - Spring : No Change Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	2 x 4 White Worm Holed Ceiling Tiles	86000	SF	Throughout		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22	White Mosaic Ceramic Tile Grout	2500	SF	Washrooms thoughout		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	: No Change]										
Comments	Comments:											
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	2017 - Spring: No Change											
Comments	Comments:											

2018 - Spring : No Change Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22M	White Mosaic Ceramic Tile - Mastic	2500	SF	Washrooms throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asse	essment Category
23	Incinerator	250	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments	:											
	ng: No Change											
Comments	:											

2018 - Spring : No Change Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Α	Aircell pipe insulation	150	LF	tunnel between boiler house and engine room		TSI	Yes	Loc	10		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
В	Cardboard hard joints	100	Fittings	1st floor , basement, boiler room		TSI	Yes	None	0		YES	X NO
2016 Falls N	la Changa				1							
2016 - Fall: N	io Change				4							
Comments:												
					1							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:			•									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Boiler insulation mag block - ABATED			boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessi	ment Category
F	Preform insulation	250	LF	Basement boiler room and Tunnels		Surface	Yes	None	0		YES		X NO
2016 - Fall: I	No Change				1								
Comments:	•												
2017 - Sprin	g: No Change				1								
Comments:													
2017 - Fall: I	No Change				1								
Comments:	J												
2018 - Fall: I	No Change				1								
Comments:]								
2018 - Sprin	g : No Change				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Spray on duct insulation	2000	SF	Attic		Surface	No		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
1	Insulation rope	100	LF	Fan room		TSI	No	None	0		YES	X NO
2016 - Fall: N	2016 - Fall: No Change											
Comments:	<u> </u>											
2017 - Spring	2017 - Spring: No Change											
Comments:	, <u> </u>											
2017 - Fall: N	lo Change				1							
Comments:												
2018 - Spring	g : No Change				-							
Comments:	, ,											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Aircell hard fittings	150	LF	1st floor, basement		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Fall: No Change

Comments:

Page 23

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
K	cardboard pipe insulation	460	LF	1st floor, basement, boiler room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	Ü											
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Preform hard fitting - ABATED			Basement, boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance. Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance. Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance. Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
X A copy of this notice was printed in the school's calendar and sent home with each child
Other.

VFT = Vinyl Floor Tile
Oracle Unit: 23351

SCHOOL'S ASBESTOS MANAGEMENT PLAN.