## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Robert L Grimes Elementary School 23461 3680 School: **Oracle Unit: Building ID:** Address: 5450 W. 64th Pl. Region: 05 Mail Room: Asbestos Surveyor: Walsh, Laura X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Room 100, 102, main YES X NO 01 8" black vinyl baseboard office, principal office & Miscellaneous restroom, 104 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 23461

01A	mastic beneath 8" vinyl baseboard			room 100, 102, main office, principal office & restroom, 104		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change			·								
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	, ,											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
02	gray 8" Vinyl Baseboard			Throught 1996 Addition		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

room 100, 102, main

02A	Mastic Beneath Vinyl Baseboard			Througout 1996 Addition		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:	140 Change				-							
					1							
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
	110 Change				1							
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
137710	Material Bosonption	Quantity	Units	Material Ecoation	Туре	Category	THOSE	Type	Quantity	Units	Change in Access	oment dategory
				104, 100, main off,							Dvrc	X NO
1	12v12 vft top with white	1	1	principal office, safe, 105,	1	1	1			1	YES	X NO

Type

Material

Category

Damage

Quantity

0

None

Damage

Units

Change in Assessment Category

Damage

Type

Friable

No

Miscellaneous

21	and brown specs	7010	Oi	lounge, 106, 101, 102, library
0040 5-11	N. Olassa			
2016 - Fall:	No Change			
Comments:	•			
2017 - Spri	ng: No Change			
Comments:	•			
2017 - Fall:	No Change			
Comments	• •			
2018 - Fall:	No Change			
Comments				

7515

SF

HA No

21

Material Description

12x12 vft, tan with white

and brown specs

Material

Quantity

Material

Units

Material Location

main corridor, teach

21A	12x12 vft beige with brown and white streaks	1310	SF	south entrance, south vestibule, room 106, room 103		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	la Changa				1			•	·	•	
	lo Change										
Comments:											
					]						
2017 - Spring	ı: No Change										
Comments:	-										
					1						
2017 - Fall: N	lo Change				1						
Comments:					1						
					1						
2018 - Fall: N	lo Change				1						
Comments:					1						
					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21B	12x12 vinyl floor tile, white with gray specs	2330	SF	gymnasium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	mstic beneath 12x12 vft, tan with wh and brn specs	7515	SF	104, 100, 106, 101, 102, 105, lib, princip office, safe, main corridor, teach lounge, main office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	mastic beneath 12x12vft	1310	SF	south entrance, south vestibule, room 106 and 103		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

22B	mastic beneath 12x12 vft white with gray specs	2330	SF	gymnasium		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				1							
					4							
Comments	S:											
2017 - Fal	I: No Change											
Comments												
-												
2017 - Spr	ring: No Change											
	· ·											
Comments	S.											
2212 = 1												
2018 - Fal	l: No Change											
Comments	3:											
					_							
110.01-	Material Description	I Maradal	NA-1-2-1	I Maradall and a	A -11	Maria dal	I market	I B		D	01	
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
				south vestibule, above all								

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Material Location

ceiling tile throughout

handicap restroom, kitchen office and storage

HA No

25

Comments:

Comments:

Comments:

Comments:

Drywall

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

11000

SF

Material

Units

Change in Assessment Category

X NO

26	Hard Plaster	800	SF	Engineers office and boiler room		Surface	No	None	0		YES	X NO
2016 - Fal	I: No Change				1							
Comments					= =							
2017 - Spr	ring: No Change											
Comments					=							
2017 - Fal	I: No Change				-							
Comments	3:				1							
2018 - Fal	I: No Change											
Comments	3:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material Category	Friable	Damage	Damage Quantity	Damage Units	Change in Assess	sment Category
		Quantity	UtillS	south vestibule, above all	Туре	Category		Туре	Quartity	UTILS		
27	drywall joint compound	3000	LF	celing tile throughout handicap restroom,		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

kitchen office and storage

2016 - Fall: N	lo Change	]									
Comments:	10 Onlange				-						
Comments.					1						
2017 - Spring	g: No Change										
Comments:											
0045 5 11 1											
2017 - Fall: N	No Change										
Comments:											
0040 5.11 1	1. 01										
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	
	1	1	1	1	1	1	1	1	1	1	1

Type

Material

Category

Miscellaneous

Miscellaneous

Yes

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

2564

SF

Material

Quantity

Material

Units

Material Location

throught building

gymnasium

HA No

28

29

Material Description

2x4 lay in celing tile

(fissure)

2x4 ceiling tile

Change in Assessment Category

X NO

X NO

YES

2016 Fall	. No Change										
	: No Change										
Comments	:										
2017 - Spri	ing: No Change										
Comments	•										
2017 - Fall	: No Change										
Comments	:										
2018 - Fall	: No Change										
Comments											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: No	o Change				
Comments:					
2017 - Fall: No	o Change				
Comments:					
2017 - Spring:	: No Change				
Comments:					
2018 - Fall: No	o Change				
Comments:		•	•	•	

828

HA No

30

31

Material Description

2x2 ceiling tile

linoleum flooring

Material

Quantity

848

Material

Units

SF

SF

Material Location

office

kitchen

kitchen, west foyer, gym

Change in Assessment Category

X NO

X NO

YES

2016 - Fall: I	No Change										
Comments:	<u> </u>										
2017 - Fall: I	No Change										
Comments:					_						
2017 - Sprin	g: No Change										
Comments:					_						
2018 - Fall: I	No Change										
Comments:					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

350

Material

Units

SF

SF

Material Quantity

828

Material Location

kitchen

rm 104A, office

HA No

32

33

Material Description

linoleum flooring mastic

gray carpet mastic

Change in Assessment Category

X NO

X NO

YES

2016 - Fall:	No Change										
Comments:											
2017 - Sprin	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:	-										
					<u> </u>						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change	 	
Comments:			
2017 - Fall: N	o Change	 	
Comments:			
2018 - Fall: N	o Change		
Comments:			

Material

Quantity

60

Material

Units

LF

LF

Material Location

West Foyer

east foyer

HA No

34

35

Material Description

8" Brown Basebaord

8" Brown Baseboard mastic

Page 11

Change in Assessment Category

X NO

X NO

YES

	L	Boiler Gaskets			Boiler Room		TSI					YES	X NO
I	2016 - Fall: No	o Change				]							
	Comments:	<u> </u>				1							
	2017 - Fall: No	o Change				-							
	Comments:					-							
	2017 - Spring:	No Change											
	Comments:												
	2018 - Fall: No	o Change											
	Comments:					] =							
						]							
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	М	incinerator insulation-NOT OBSERVED, SEE NOTES			Boiler room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

N	cardboard insulation	20	LF	bathroom pipe chase		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:					]							
2017 - Sprii	ng: No Change											
Comments:												
	No Change				_							
Comments:					_							
	No Change											
Comments:					_							
					<b>_</b>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	cardboard elbows-										<u> </u>	

Type

Material

TSI

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

bathroom pipe chase

HA No

0

Material Description

**ABATED** 

YES

X NO

W-1	Window Caulk			Throughout 1955		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	lo Change				1							
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
W-2	Window Caulk			Throught 1996 Addition		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Robert L Grimes Elementary School
Date: 1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23461

SCHOOL'S ASBESTOS MANAGEMENT PLAN.