Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Nathan Hale Elementary School 23491 3710 School: **Oracle Unit: Building ID:** Address: 6140 S. Melvina Region: 05 Mail Room: Asbestos Surveyor: Doyle, Robert X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: rdoyle2@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Mastic 9x9 flr tile gray YES 32A SF X NO 515 Rms 202 and 204 Miscellaneous No None 0 w/black & white 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32B	Mastic 9x9 tan w/brown and white flr tile			Rms 202 & 204		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2018 - Fall: N	lo Change											
Comments:	Ü											
2018 - Spring	ı : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32C	Mastic 9x9 flr tile tan	1700	SF	Auditorium aisles, engineers office		Miscellaneous	No	Dist	30		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
33A	Mastic 12x12 offwhite speckled flr tile	3500	SF	Lunchroom, basement classroom, coat check room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change							•	•		•		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33B	Mastic 12x12 gray w/black& white flr tile	10300	SF	Main and principal's office,rms 200-213, 102-113		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33C	Mastic 12x12 tan w/brown and white flr tile	12000	SF	Library,2nd floor teachers restrm,rooms 100,102- 106,108,110- 113,200,201,203,205- 213, prncp		Miscellaneous	No	None	0		YES X NO

/ / /
2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33D	Mastic 12x12 beige speckled floor tile - Abated			1st flr corridor in front of fountains and at north end		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units	ŭ	
33E	12x12 beige flr tile mastic-	130	SF	Patches in auditorum		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Spring	: No Change											
Comments:					-							
2017 - Fall: N	o Change]							
Comments:					_							
2018 - Spring	: No Change											
Comments:					1							
2018 - Fall: N	o Change											
Comments:					1							
					J							

Type

Material

Category

Miscellaneous

Asbestos

Material

Friable

Friable

No

Damage

Type

None

Damage

Damage

Damage

Quantity

0

Damage

Damage

Units

34	w'black	1620	SF	closet, janitors room
2016 - Fall: I	No Change			
Comments:				
2017 - Sprin	g: No Change			
Comments:				
2017 - Fall: I	No Change			
Comments:				
2018 - Sprin	g : No Change			
Comments:				
2018 - Fall: I	No Change			
Comments:				

Material

Quantity

1620

HA No

HA No

34

Material Description

Material Description

12x12 flr tile mastic grn

Material

Material

Material

Units

SF

Material Location

Material Location

Stockroom, storage

Page 5

Change in Assessment Category

Change in Assessment Category

X NO

YES

35A	12x12 offwhite speckled flr tile	3500	SF	Lunchroom basement classroom, auditorium coatcheck		Miscellaneous	No	None	0	YES	X NO
					7						
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	-										
2017 - Spring	j: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
2018 - Spring	j : No Change										
Comments:											
1											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35B	12x12 gray w/black and white floor tile	10300	SF	1st/2nd floor corridors, library, main and principal's office,rms 200,201,203-213, 102- 113		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35C	12x12 tan w/brown and white	12000	SF	Libr.,2nd flr teach restrm, rms 100,102- 106,108,110- 113,200,201,203,205- 213, prncp		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 23491

35D	12x12 beige speckled floor tile - Abated	1st fir corridor in front of fountains and at north end	Miscellaneous			YES	X NO
2016 - Fall:	No Change	·	·]				
Comments:							
Comments.							
2017 - Fall:	No Change						
Comments:							
	ng: No Change						
Comments:							
2018 - Fall:	No Change						
Comments:							
2018 - Sprir	ng : No Change						
Comments:							

Type

Material

Category

Material Location

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35E	12x12 beige flr tile	130	SF	Patches in auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36A	9x9 flr tile gray w/black/white	515	SF	Rms 202 & 204		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:					4							
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	: No Change											
Comments:	•											
2018 - Spring	: No Change				1							
Comments:	Ŭ											
2018 - Fall: N	o Change				=							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36B	9x9 tan w/brown and white floor tile			Rms 202 and 204		Miscellaneous		None			YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
36C	9x9 tan floor tile	1700	SF	Auditorium aisles, engineers office		Miscellaneous	No	Dist	50		YES	X NO
2016 - Fal	II: No Change											
Comment	s:											
2017 - Spi	ring: No Change											
Comments	s:											
2017 - Fal	II: No Change											
Comments	S:											
2018 - Spi	ring : No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12x12 ft grn w/black	600	SF	storeroom, storage closet. Janitors room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
39A	Brown mopboard	450	LF	Rm 202, 204, lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:]							
2017 - Fall: I	No Change											
Comments:					-							
	g: No Change											
Comments:					-							
	g : No Change											
Comments:					=							
2018 - Fall: I	No Change											
Comments:		<u> </u>										
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39B	Black mopboard	1200	LF	Throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
40A	Mastic under brn mopboard	450	LF	Rm 202, 204, lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Fall: No Change												
Comments:					_							
	g: No Change]							
Comments:					_							
	g : No Change]							
Comments:					_							
2018 - Fall: N	lo Change]							
Comments:					-							
L					_							

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40B	Black mopboard mastic	1200	LF	Throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Page 12

41	Window glaze throughout 1st and 2nd flr windows - Non AHERA		Throughout		Miscellaneous		None			YES	X NO
2016 - Fa	II: No Change										
Comment											
Comment											
2017 - Sp	oring: No Change										
Comment	ts:										
2017 - Fa	II: No Change										
Comment	<u> </u>										
2018 - Sp	oring : No Change										
Comment	ts:										
2018 - Fa	II: No Change										
Comment											
HA No	Material Description	Material I	Material Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	amont Cotogon
	i iviatetiai Deschollon	i iviaienal i l	Marenar i Marenari Ocanon	ASOESIOS	I IVIAIENAI		I Damade	i Damade	Daniage	Chance in Assess	smem caledony

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Fire brick			Boiler room		Miscellaneous					YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" VFT Red w/ Streaks	3000	SF	1st and 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43A	12"x12" VFT Red w/ Streaks Mastic	3000	SF	1st and 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Light Brown w/ Streaks	1500	SF	1st and 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO
2016 Falls No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	12"x12" Light Brown w/ Streaks Mastic	1500	SF	1st and 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 15

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
45	Grey Multicolor Carpet Mastic	600	SF	Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

2018 - Spring : No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Brown w/ Streaks	55	SF	Room 202, 204		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46A	12"x12" Brown w/ Streaks Mastic	55	SF	Room 202, 204		Miscellaneous	No	None	0		YES X NO
0040 = 11.11	01				ĺ						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	9x9 Blueish Green w/ Black Specks	10	SF	Room 202, 204		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
47A	9x9 Blueish Green w/ Black Specks	10	SF	Room 202, 204		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				\neg							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	•											
2018 - Fall: I	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Aircell pipe covering	4292	LF	Fan room, driving room, throughout basement, airtunnels, art room		TSI	Yes	None	0		YES X NO

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Aircell pipe joints	310	LF	Unfinished pipe space, fan room, art room		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Felt covering	2580	LF	Fan rooms, unfinished pipe space, gym		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
D	Felt pipe packing-ABATED			Boiler room		TSI					YES	X NO
2016 - Fall: N	o Change]							
Comments:	•				1							
2017 - Spring	: No Change				-							
Comments:	•				1							
2017 - Fall: N	o Change				-							
Comments:					1							
2018 - Spring	: No Change											
Comments:					1							
2018 - Fall: N	o Change				1							
Comments:	J											
					J							
2018 - Spring Comments: 2018 - Fall: N	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	fiberglass pipe packing- ABATED			Boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
F	Tank insulation	180	SF	Boiler room		TSI	Yes	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:													
2017 - Spring	ı: No Change												
Comments:	<u> </u>												
2017 - Fall: N	lo Change												
Comments:	J												
2018 - Fall: N	lo Change												
Comments:	go												
2018 - Spring	ı : No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-1	12x12 white w/grey specks	3500	SF	Modular classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
FTM-1	12x12 white mastic	3500	SF	Modular classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Tank packing-ABATED			Boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Н	Boiler insulation-ABATED			Boiler room		TSI					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
2018 - Spring	: No Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Boiler packing-ABATED			Boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
J	Mag block elbows-ABATED			Boiler room		TSI					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	: No Change				_							
Comments:]							
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	: No Change				<u> </u>							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Mag pipe insulation- ABATED			Boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
L	Troweled appplied plaster material	3200	SF	Auditorium ceiling		Surface	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:	<u> </u>]							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring: No Change												
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	: No Change											
Comments:					-							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Boiler gasket			Boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	mag block elbows			asst. principal washroom		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 23491

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Nathan Hale Elementary School
Date:1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23491

SCHOOL'S ASBESTOS MANAGEMENT PLAN.