## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Helge A Haugan Elementary School 23591 3810 School: **Oracle Unit: Building ID:** 4540 N Hamlin Avenue Address: Region: 01 Mail Room: Asbestos Surveyor: Huggins, Mike **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 1/8/2019 Email Address: mhuggins2@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type YES 03 50 SF X NO 2'x4' Ceiling Tile Engineer's Office, 1911 Miscellaneous Yes None 0 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Dark Brown VFT	24435	SF	Throughout (See Hatching Maps)- 1911		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Orange & Brown Spotted VFT	400	SF	Room 301 (Under HA # 34), 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Dark Brown VFT Mastic	25435	SF	Throughout (See Hatching Maps)- 1911		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Orange & Brown Spotted VFT Mastic	400	SF	Room 301 (Under HA # 34), 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Dark Brown VFT	16080	SF	Throughout (See Hatching Maps)- 1920		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" Dark Brown VFT Mastic	16080	SF	Throughout (See Hatching Maps)- 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
10	Green Linoleum	600	SF	3rd Fl Boy's Toilet & 2nd Fl Girl's Toilet - 1920 (Under HA#13)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change			*		•	•	•	•	•		
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:	·			<u> </u>								
2018 - Fall: I	No Change				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Green Linoleum Mastic	600	SF	3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet, 1920 (Under HA#13)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
12	12"x12" Beige w/ Tan Streaks VFT	600	SF	3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet, 1920		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change		•	•		•		•	•	•	•	

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Beige w/ Tan Streaks VFT Mastic	600	SF	3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet, 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Beige w/ Tan Streaks VFT	380	SF	2nd and 3rd Floor Girls Bathrooms, 1911		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
15	12"x12" Beige w/ Tan Streaks VFT Mastic	380	SF	2nd and 3rd Floor Girls Bathrooms, 1911		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
16	12"x12" White VFT	1650	SF	Room 112, 114 & 2nd Floor Teacher's Toilet, 1911		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change		•	~	]	•		•	•	•	•	
Comments	<b>~</b>											
2017 - Spr	ring: No Change											
Comments	S:				_							
	II: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	s:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" White VFT Mastic	1650	SF	Room 112 & 2nd Floor Teacher's Toilet, 1911		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Green Linoleum	300	SF	Girl's Toilet (Under HA # 14 & 15), Behind Engineer's Office, 1911		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change			<u> </u>	]						
Comments:											
2017 - Spring	g: No Change				_						
Comments:											

2017 - Fall: No Change
Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Green Linoleum Mastic	300	SF	Girl's Toilet Behind (under HA # 14 & 15), Engineer's Office, 1911		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	12"x12" Pink VFT	100	SF	Main Office, 1920		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change Comments:											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Pink VFT Mastic	100	SF	Main Office, 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Tan VFT	2350	SF	Room 106 & 107 (Under Carpet), 1920		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Tan VFT Mastic	2350	SF	Principals Office (Under Carpet), Room 106 & 107 (Under Carpet), 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
24	12"x12" Cream VFT	300	SF	Room 105, 1920		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Cream VFT Mastic	300	SF	Room 105, 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Taupe VFT	300	SF	Room 105, 1920		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Taupe VFT Mastic	300	SF	Room 105, 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" White VFT	875	SF	Room 116, 1920		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" White VFT Mastic	875	SF	Room 116, 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
30	12"x12" Cream VFT	100	SF	Engineer's Office, 1911		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Cream VFT Mastic	100	SF	Engineer's Office, 1911		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" Taupe VFT	100	SF	Engineer's Office, 1911		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" Taupe VFT Mastic	100	SF	Engineer's Office, 1911		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" White w/ Gray Spots VFT	875	SF	Room 301, 1920		Miscellaneous	No	None	0		YES X NO
					-						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34A	12" x 12" White w/ Gray Spots VFT Mastic	875	SF	Room 301, 1920		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" White w/ Creme Spots VFT	1750	SF	Room 114 & 112, 1911 (9x9 Tile under 12x12)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
36A	12" x 12" White w/ Creme Spots VFT Mastic	1750	SF	Room 114 & 112, 1911 (9x9 Tile under 12x12)		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

38	Off-White Linoleum	600	SF	Kitchen Office, Lockeroom Bathroom,		Miscellaneous	No	None	0	YES	X NO
				1994						<u> </u>	
					7						
2016 - Fall: N	lo Change										
Comments:											
					1						
2017 - Spring	j: No Change										
Comments:	-										
					1						
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	j : No Change										
Comments:	-										
2018 - Fall: N	lo Change										
Comments:	<u> </u>										
					1						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Off-White Linoleum Mastic	600	SF	Kitchen Office, Lockeroom Bathroom, 1994		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
40	Pink Linoleum	600	SF	Lockeroom, Food Storage, South Kitchen Entrance, 1994		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change	*			- ]	•	•	•	•	•	•		
Comments													
2017 - Spri	ng: No Change				-								
Comments					1								
2017 - Fall:	: No Change												
Comments					1								
2018 - Spri	ng : No Change												
Comments					1								
2018 - Fall:	: No Change				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Pink Linoleum Mastic	1200	SF	Lockeroom, Food Storage, South Kitchen Entrance, 1994		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
42	Textured Tan Linoleum	800	SF	Kitchen, Serving Area, 1994		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					]							
2017 - Spring	g: No Change				]							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Textured Tan Linoleum Mastic	800	SF	Kitchen, Serving Area, 1994		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Co	ategory
44	2' x 2' Yellow w/ Grooves Ceiling Tile	600	SF	Lunchroom, South Kitchen Entrance, 1994		Miscellaneous	Yes	None	0		YES XN	0
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	2' x 2' Pink w/ Grooves Ceiling Tile	600	SF	Lunchroom, 1994		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	2' x 4' White Smooth Ceiling Tile	600	SF	Kitchen, Serving Area, 1994		Miscellaneous	Yes	None	0		YES X NO
204C Fall N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	2' x 2' White w/ Grooves Ceiling Tile	600	SF	Teachers Lounge, 1994		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
48	2' x 4' White w/ Grooves Ceiling Tile	900	SF	Kitchen Office, Lockeroom, Lockeroom Bathroom, 1994		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change	•	•	•		•	•	•	•	•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Drywall	6000	SF	Throughout, 1994		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
50	Drywall Joint Compound	2000	SF	Throughout, 1994		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	-											
2018 - Fall: I	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Tan Vinyl Baseboard	200	LF	Throughout, 1994		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
52	Tan Vinyl Baseboard Mastic	200	LF	Throughout, 1994		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12"X 12" White w/black specks Floor Tile	1000	SF	Room 311 (1911 Bldg)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12"X 12" White w/ black specks floor tile MASTIC	1000	SF	Room 311 (1911 Bldg)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
	<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12"X12" Off-white w/Tan Specks VFT	800	SF	Rm 321 (1920 Bldg)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
55A	12"X12" Off-white w/Tan Specks VFT Mastic	800	SF	Rm 321 (1920 Bldg)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	V											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	ј : No Change											
Comments:					=							
2018 - Fall: N	lo Change											
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Terrazzo	3000	SF	1st, 2nd, and 3rd Floor Corridors, Janitor's Closets and Stairwells (1920 Bldg)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"X12" Light-Beige VFT	600	SF	Faculty Lounge (1994 Bldg)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57A	12"X12" Light-Beige VFT Mastic	600	SF	Faculty Lounge (1994 Bldg)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
58	12"X12" Tan Speckled VFT	2500	SF	Lunch Rm (1994 Bldg)		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	ıll: No Change				7					•		
Comment												
2017 - Fa	ıll: No Change				-							
Comment	ts:											
2017 - Sp	oring: No Change											
Comment	ts:											
2018 - Fa	III: No Change											
Comment	ts:											
2018 - Sp	oring : No Change											
Comment	ts:											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58A	12"X12" Tan Speckled VFT Mastic	2500	SF	Lunch Rm (1994 Bldg)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
59	9"x9" peach VFT	46	SF	Boiler room bathroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I Comments:	No Change	•			]							
2017 - Fall: I	No Change											
Comments:	a. No Chango				_							
Comments:	g: No Change				-							
2018 - Fall: I Comments:	No Change				-							
	g : No Change											
Comments:	<u> </u>				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59A	9"x9" peach VFT MASTIC	46	SF	boiler room bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
60	12"x12" tan w/ brown streaks and white streaks VFT (over HA 59&59A)	46	SF	Boiler room bathroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments					=							
2017 - Fal	I: No Change				-							
Comments	3:											
2017 - Spr	ring: No Change				-							
Comments	3:											
2018 - Fal	I: No Change				-							
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60A	12"x12 tan w/brown streaks and white streaks VFT MASTIC (over HA 59&59A)	46	SF	Boiler room bathroom		Miscellaneous	No	None	0		YES X NO

2018 - Spring : No Change

Comments:

Page 32

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12"x12 offwhite w/ beige specks VFT	3500	SF	Rms 304, 306, 303,, 307, 308, 309 - 1911		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
	<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61A	12"x12 offwhite w/ beige specks VFT MASTIC	3500	SF	Rms 304, 306, 303,, 307, 308, 309 - 1911		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	offwhite w/ beige specks VFT	3500	SF	Rm 317, 312, 300, 320 - 1920 addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62A	offwhite w/ beige specks VFT MASTIC	3500	SF	Rm 317, 312, 300, 320 - 1920 addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
63	12"x12" offwhite w/ gray shadows VFT	450	SF	Rm 109- principal's office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change				_							
Comments:	-				]							
2017 - Spring	g: No Change				1							
Comments:												
2018 - Fall: N	No Change				1							
Comments:	<u> </u>											
2018 - Sprine	g : No Change				1							
Comments:	<i>,</i>				]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63A	12"x12" offwhite w/ gray shadows VFT MASTIC	450	SF	Rm 109- principal's office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12"x12" beige w/ tan streaks VFT	875	SF	Rm 116		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64A	12"x12" beige w/ tan streaks VFT MASTIC	875	SF	Rm 116		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12"x12" white w/ blue specks VFT	400	SF	Rm 103		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65A	12"x12" white w/ blue specks VFT MASTIC	400	SF	Rm 103		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Hard Coat Plaster	80000	SF	Throughout 1911 Main building		Surface	Yes	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Hard Coat Plaster	80000	SF	Throughout 1920 Additions		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

68	Carpet Masitc	4600	SF	2nd Floor Teachers lounge, Rooms 106, 107, 108, Auditorium		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Changa				1						
	NO Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
					1						
2017 - Fall: N	No Change										
Comments:	-										
0040 5 11 1											
2018 - Fall: I	No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:	<u> </u>										
					1						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Aircell Pipe Insulation	1500	LF	Throughout (See Hatching Maps) -1911		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Aircell Pipe Insulation	300	LF	Throughout (See Hatching Maps) -1911		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Preform Pipe Insulation	50	LF	Engine Room/Tank Room- 1911		TSI	Yes		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Preform Pipe Insulation	7	LF	Engine Room/Tank Room- 1911		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Aircell Pipe Insulation	1000	LF	Main Office, Counselor's Office, Pipe Tunnels, rm 105, 1920		TSI	Yes	Dist	20		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No Ma	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 H	MJP E/F/V on Aircell Pipe nsulation	75	LF	Main Office, Counselor's Office, Pipe Tunnels, 1920		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	MJP E/F/V on Fiberglass Pipe Insulation	124	LF	Girl's Toilet Chases & Boy's Toilet Chases, 1920		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Boiler Gaskets	80	LF	Boiler Room, 1911		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Cardboard Pipe Insulation	100	LF	Throughout (See Hatching Maps) - 1911		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Abated
Comments:Pipes in basement abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	MJP E/F/V on Cardboard Pipe Insulation	8	LF	Throughout (See Hatching Maps) - 1911		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:Pipes in basement abated under capital projects
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Cardboard Pipe Insulation	70	LF	Main Office, Air Tunnels, 1920		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Abated
Comments:Pipes abated under capital project

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	MJP E/F/V on Cardboard Pipe Insulation	20	LF	Main Office, Air Tunnels, 1920		TSI	Yes	None	0		YES X NO

2016 - Fall: No	o Change							
Comments:								
2017 - Spring: No Change								
Comments:								
2017 - Fall: No	o Change							
Comments:	Comments:							
2018 - Fall: Ab	oated							
Comments:Pip	pes abated under capi	tal project	S					
2018 - Spring	: No Change							
Comments:								
	<u> </u>			·				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	MJP E/F/V on Fiberglass Pipe Insulation	100	LF	Throughout (See Hatching Maps) - 1911		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: Abated
Comments:Pipes abated under capaital project this summer
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Helge A Haugan Elementary School
Date:
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23591

SCHOOL'S ASBESTOS MANAGEMENT PLAN.