Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

23621

Oracle Unit:

Address: 1518 W Granville Avenue Region: 01 Mail Room: Asbestos Surveyor: Liddell, William X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: bill.lidd.cps@gmail.com A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity YES 11 Hard Coat Plaster 0 SF X NO Throughout - 1905 Bldg. Surface No None 0 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Stephen K Hayt Elementary School

School:

3850

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Beige w/Brown Vinyl Floor Tile	200	SF	Rm 002 1/2 - 1905 Bldg NOT OBSERVED		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Orange w/Brown Vinyl Floor Tile	1130	SF	Assembly Hall - 1905 BldgNOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9'x9' Beige w/Brown Vinyl Floor Tile Mastic	200	SF	Rm 002 1/2 - 1905 Bldg NOT OBSERVED		Miscellaneous	No	None	0		YES X NO
					1						_

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Orange w/Brown Vinyl Floor Tile Mastic	1130	SF	Assembly Hall - 1905 BldgNOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"X12" Sand w/Brown Vinyl Floor Tile	400	SF	Engineers office, Room 305 wardrobe - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO
•	-				1	•	•	•		•	•

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"X12" Sand w/Brown Vinyl Floor Tile Mastic	400	SF	Engineers office, Room 305 wardrobe - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
28	12"x12" White Vinyl Floor Tile	480	SF	Public Space, 2nd Flr. Teacher Toilet - 1905 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" White Vinyl Floor Tile Mastic	480	SF	Public Space, 2nd Flr. Teacher's Toilet- 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	9"x9" Maroon Vinyl Floor Tile	700	SF	Room 100, 102 closet, 102 Toilet, clerks space (Under Carpet) 200B - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	9"x9" Maroon Vinyl Floor Tile Mastic	700	SF	Room 100, 102 closet, 102 Toilet, (Private office not observed), clerks space (Under Carpet) Public Space (Under HA 28) 200B - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	9"x9" Black Vinyl Floor Tile	25	SF	2nd Floor Boys Toliet Vestibule - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	9"x9" Black Vinyl Floor Tile Mastic	25	SF	2nd Floor Boys Toliet Vestibule - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Gray Vinyl Floor Tile	500	SF	Room 305 - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	2019 Caring : No Change
2018 - Fall: No Change	1 0 0
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Gray Vinyl Floor Tile Mastic	500	SF	Room 305 - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Tan Vinyl Floor Tile	500	SF	Room 305 - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Tan Vinyl Floor Tile Mastic	500	SF	Room 305 - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	9"x9" Brown Vinyl Floor Tile	700	SF	Room 300, 3rd Fl Teachers Toilet - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	o Chango	•	•	•]	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9"x9" Brown Vinyl Floor Tile Mastic	700	SF	Room 300, 3rd Fl Teachers Toilet - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
41	Yellow Marble Linoleum			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Yellow Marble Linoleum Mastic			Throughout - 1992		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
43	Gray Marble Linoleum			Throughout - 1992		Miscellaneous				YES	X NO
2016 - Fall: N	o Change										
Comments:	<u> </u>										
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					I						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Gray Marble Linoleum Mastic			Throughout - 1992		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
45	Beige Linoleum			Throughout - 1992		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	J										
2018 - Spring	g : No Change										
Comments:	<i>y</i>										
2018 - Fall: N	lo Change										
Comments:	to orialigo										
]						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Beige Linoleum Mastic			Throughout - 1992		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
47	Drywall			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>				1							
2017 - Spring	ı: No Change				-							
Comments:					1							
2017 - Fall: N	lo Change				-							
Comments:]							
2018 - Spring	ı : No Change				-							
Comments:					1							
2018 - Fall: N	lo Change				-							
Comments:	J]							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Drywall Compound			Throughout - 1992		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
49	2'x2' Yellow Ceiling Tile			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:	.											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change				\dashv							
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	2'x2' Blue Ceiling Tile			Throughout - 1992		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
51	2'x4' Smooth Ceiling Tile			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	ı : No Change											
Comments:	J											
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	2'x4' Textured Ceiling Tile			Throughout - 1992		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
53	Black Vinyl Baseboards	1500	LF	Throughout - 1992		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	Ţ.											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Black Vinyl Baseboard Mastic			Throughout - 1992		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Quantity Units Type Category Type Quantity	Units	Change in Assessment Category
60 12"x12" Blue VFT Throughout - 1997 Miscellaneous		YES X NO
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12"x12" Blue VFT Mastic			Throughout - 1997		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
62	12"x12" Yellow VFT			1st Floor Corridor, 2nd Floor Corridor - 1997		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:					1							
2017 - Fall: N	lo Change				-							
Comments:					-							
	g : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					 							
L					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12"x12" Yellow VFT Mastic			1st Floor Corridor, 2nd Floor Corridor - 1997		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
64	2'x2' Textured CT			Throughout - 1997		Miscellaneous					YES	X NO
2016 - Fall:	No Change						•					
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	-											
	1					1			1			

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Drywall			Throughout - 1997		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Page 21

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
66	Drywall Compound			Throughout - 1997		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:	Ü											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Carpet Mastic			Room 210 (Library), Main Office Area - 1997		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
68	Vinyl Baseboards			Throughout - 1997		Miscellaneous	None			YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	: No Change										
Comments:	<u> </u>										
2047 Fall N	la Changa										
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	lo Change										
	lo Change										
Comments:											
]						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Vinyl Baseboard Mastic			Throughout - 1997		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
70	12"x12" Red VFT	1500	SF	1st floor Corridor & SE & SW 1st floor stairwell landings and basement - Bldg. 1905		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70A	12"x12" Red VFT (MASTIC)	1500	SF	1st floor Corridor & SE & SW 1st floor stairwell landings and basement - Bldg. 1905		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12"x12" Lt. Gold VFT	1500	SF	1st floor Corridor & SE & SW 1st floor stairwell landings and basement - Bldg. 1905		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
71A	12"x12" Lt. Gold VFT	1500	SF	1st floor Corridor & SE & SW 1st floor stairwell landings and basement - Bldg. 1905		Miscellaneous	No	None	0		YES X	NO
2016 - Fall:	No Change]							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12"x12" tan w/ black dots VFT	400	SF	auditorium aisles		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72A	12"x12" tan w/ black dots VFT MASTIC	400	SF	auditorium aisles		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Carpet MASTIC	200	SF	private office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 27

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
74	12"x12" gold VFT	2000	SF	Room 002, auditorium, teacher's lounge 2nd fl, rm 223, 3rd floor elevator lobby		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	io Change											
2017 - Spring	ı: No Change											
Comments:	,											
2018 - Fall: N	lo Change											
Comments:	·	·		·								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74A	12"x12" gold VFT MASTIC	2000	SF	room 002, auditorium, teacher's lounge 2nd fl, room 223, 3rd floor elevator lobby		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
		,
2018 - Spring : No Change		
Comments:		·

2018 - Spring : No Change

Comments:

75 ^	12"×12" rod \/ET MASTIC	700	05	teacher's lounge 2nd fl,		Minnellanassa	N-	N			□ I	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
					_							
Comments	S:											
	ing : No Change											
Comments	Ţ											
2018 - Fal	I: No Change				-							
Comments	S:				_							
	ing: No Change											
Comments	o.				1							
Comments												
2017 - Fal	I: No Change				-							
Comments	3:											
	l: No Change											
_				auuit011u111, 1111 223							<u> </u>	
75	12"x12" red VFT	700	SF	teacher's lounge 2nd fl, auditorium, rm 223		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

700

SF

Material Description

12"x12" red VFT MASTIC

Material

Quantity

Material

Units

Material Location

teacher's lounge 2nd fl,

auditorium, rm 223

HA No

75A

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
А	Boiler Gasket #1	7	SF	Boiler Room - 1905		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fal	II: No Change												
Comments	<u> </u>												
2017 - Fal	II: No Change												
Comments													
2017 - Spi	ring: No Change				1								
Comments	S:												
2018 - Fal	II: No Change				1								
Comments	S:												
2018 - Spi	ring : No Change				-								
Comments	s [.]												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Boiler Gasket #2	7	SF	Boiler Room - 1905		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 30

Q Aircell Pipe Insulation 40 LF Engine Room, W Basement Corridor, 002 Vestibule, 002 1/2 - 1905 TSI Yes None 0	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego
Bidg.	Q	Aircell Pipe Insulation	40	LF	Basement Corridor, 002		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
·
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Cardboard Pipe Insulation	100	LF	Pump Room, Boiler Toliet, 002 Vestibule, Boiler Room, Electric Room - 1905 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

H	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	3	Pre-Formed Pipe Insulation	1000	LF	Engine Room, Boiler Toliet, Boiler Room - 1905 Bldg.		TSI	Yes	None	0		YES X NO
_						1						

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	MJP E/F/V on Aircell Pipe Insulation	10	LF	Engine Room, W Basement Corridor, 002 Vestibule, 002 1/2 - 1905 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

V	MJP on Fiberglass Pipe Insulation	120	LF	Throughout - 1905		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]										
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring : No Change												
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
W	MJP on Mag Block Pipe Insulation	75	LF	Engine Room, Boiler Toliet, Boiler Room - 1905 Bldg.		TSI	Yes	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
	•	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Stephen K Hayt Elementary School
Date:	5/14/2018
the Asbesto	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of os Management Plan is available at each school during school hours by appointment. o review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2016. surveillances are conducted every six months.
CHECK ON	<u>JE</u>
A co	opy of this notice was sent home in each child's backpack.
A co	opy of this notice was printed in the school's newsletter and sent home with each child
A co	opy of this notice was printed in the school's calendar and sent home with each child
Othe	er.
	OF THIS NOTICE MUST BE PLACED IN THE IOOL'S ASBESTOS MANAGEMENT PLAN.