## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Robert Healy Elementary School 23651 3880 School: **Oracle Unit: Building ID:** Address: 3010 S. Parnell Region: Mail Room: Asbestos Surveyor: Lagiglia, Brian X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12"x12" Brown VFT Engineer's Office, Room YES 001 SF X NO 1475 Miscellaneous No None 0 w/Brown & White Streaks 101,209B 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 23651

001 A	12"x12" Brown VFT w/Brown & White Streaks Mastic	1475	SF	Engineer's Office, Room 101, 209B		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change			<u> </u>	]						
Comments											
2017 - Fall:	No Change										
Comments	:										
	ng: No Change										
Comments											
	No Change										
Comments	:										
					J						

Type

Material

Category

Friable

Friable

Damage

Type

Damage

Damage

Quantity

Damage

Damage

Units

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
002	9"x9" Gray Fllor Tile w/ White Streaks	445	SF	Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Sprii	ng: No Change				_							

Material

Asbestos

Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

HA No

Material Description

12"x12" Brown VFT

Material Description

Material

Units

Material

Quantity

Material

Material Location

Material Material Location

Oracle Unit: 23651

Change in Assessment Category

Damage Change in Assessment Category

				Type	Category		Type	Quantity	Units	1	
9" Gray Fllor Tile w/ te Streaks Mastic	445	SF	Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003	9"x9" Beige Floor Tile w/White & Blue Streaks	200	SF	Security Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

003 A	9"x9" Beige Floor Tile w/White & Blue Strks Mastic	200	SF	Security Office		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change				]						
Comments:					-						
2017 - Fall:	No Change				<u>.</u>						
Comments:	•				-						
2017 - Sprin	ng: No Change				-						
Comments:											
2018 - Fall:	No Change				-						
Comments:											
					]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
004	9"x9" Tan Floor Tile w/White & Brown Streaks	9000	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
004 A	9"x9" Tan Floor Tile w/White & Brn Streaks Mastic	9000	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005	9"X9" Green Floor Tile w/White & Black Streaks	300	SF	1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

005 A	9"X9" Green Floor Tile w/White & Blk Strks Mastic	300	SF	1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change				]		·				
Comments:					1 -						
2017 - Fall: No Change					_						
Comments:	•										
2017 - Spring	g: No Change				-						
Comments:					1						
2018 - Fall: N	lo Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006	12"x12" Lt. Brown VFT w/ Dk Brown & White Marbling	4100	SF	Kitchen and Rooms 101, 204, and 218		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

006A	12"x12" Lt. Brn VFT w/Dk Brn & Wht. Marble Mastic	4100	SF	Kitchen and Rooms 101,204, and 218		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments												
Comment	3.											
2017 - Fal	I: No Change											
Comments	S:											
2017 - Spi	ring: No Change											
Comments	S:											
0040 5-1	I No Observe											
	I: No Change											
Comments	S:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		
				Kitchen, Teacher's							l — ,	

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

4100

SF

HA No

007

2016 - Fall: No Change

Material Description

12"x12" Lt. Brn VFT w/Dk

12"x12" Cream Floor Tile

w/Tan & Brown Marbling

Material

Quantity

Material

Units

Material Location

Kitchen and Rooms

Lounge, Rooms 209,

215, 218 and the Far Room on the 1st Floor Change in Assessment Category

X NO

VES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
007 A	12"x12" Cream VFT w/Tan & Brown Marbling Mastic	4100	SF	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
008	9"x9" White Floor Tile w/Black & Gray Streaks	2500	SF	North Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

008 A	9"x9" White VFT w/Black & Gray Streaks Mastic	2500	SF	North Gym		Miscellaneous	No	None	0		YES	X NO
204C Falls	No Change				1							
2016 - Fall:												
Comments:												
2017 - Fall:	No Change											
Comments:												
					1							
2017 - Sprir	ng: No Change				1							
Comments:					1							
					1							
2018 - Fall:	No Change											
Comments:												
		•	•		_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Asses	sment Category
009	9"x9" Red Floor Tile w/White Streaks	200	SF	North & South Gym Storage Areas and South Gym Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

9"x9" White VFT w/Black &

Material

Quantity

Material

Units

009 A	9"x9" Red Floor Tile w/White Streaks Mastic	200	SF	North & South Gym Storage Areas and South Gym Office		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change			·	]						
	o Change										
Comments:											
2017 - Fall: No Change											
Comments:											
2017 - Spring	: No Change										
Comments:	•										
					1						
2018 - Fall: N	o Change										
Comments:	-										
					]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
010	12"x12" White VFT w/Black & Gray Streaks	2500	SF	South Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

010 A	12"x12" White VFT w/Black & Gray Streaks Mastic	2500	SF	South Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Fall:	No Change				-							
Comments												
2017 - Spri	ng: No Change											
Comments	:				_							
2018 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
011	9"x9" Blue VFT w/White &			Auditorium		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Black Streaks

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

011 A	Black Streaks Mastic			Auditorium		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:					_							
	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

HA No

011 A

012

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

9"x9" Cream Floor Tile

w/Red & Black Streaks

9"x9" Blue VFT w/White &

Material

Units

SF

4000

Material

Quantity

Material Location

Rooms 103, 105, 106

Auditorium

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

012 A	9"x9" Cream Floor Tile w/Red & Black Strks Mastic	4000	SF	Rooms 103, 105, 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
					-							
Comments:												
2017 - Fall:	No Change											
Comments:	-											
					1							
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	•											
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units	3	,
				Engineer's Office, Main								
035	Mastic Associated With			Office, Teachers Lounge,		Miscellaneous					YES	X NO
033	Carpeting			& Various areas		wiscenarieous					· ·	
			1	Throughout				1	1			

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

036	Brown Mop Board	100	SF	Throughout Bldg, Rms 001, 003, 005, 116 & 208	Miscellaneous	No	None	0	YES	X NO
2016 - Fal	l: No Change									
Comments										
2017 - Spi	ring: No Change									
Comments	S:									
2017 - Fal	l: No Change									
Comments	S:									
2018 - Fal	l: No Change									
Comments	S:									

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
036 A	Brown Mop Board Mastic	100	SF	Throughout Bldg, Rms 001, 003, 005, 116 & 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
037	Black Mop Board	100	SF	Rms 007 through 102 Auditorium & rm. 100		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
					_							
2017 - Fall	I: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											
2018 - Fall	I: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
037 A	Black Mop Board Mastic	100	SF	Rms 007 through 102 Auditorium & rm. 100		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

038	Exterior Window Caulk - Non AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
2016 - Fall:	: No Change				]							
Comments					]							
2017 - Fall:	: No Change											
Comments	:				_							
	ing: No Change											
Comments	:				_							
	: No Change				]							
Comments	:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
039	Exterior Expansion Joint - Non AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
2016 - Fall:	: No Change											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

040	Dark Brown Exterior Brick - Not AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
2016 Fall	: No Change				7							
					4							
Comments					4							
2017 - Fall	: No Change				-							
Comments					]							
2017 - Spri	ing: No Change				-							
					-							
Comments	-				4							
2018 - Fall	: No Change				=							
Comments	<u> </u>				=							
Comments	•				-							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units		0 ,
041	Brown Exterior Brick - Not AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
	1				<u></u>	1	1				<u> </u>	
2016 - Fall	: No Change	•			1							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

042	Tan Exterior Brick - Not AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
2016 - Fal	I: No Change											
Comment	s:											
2017 - Fal	I: No Change											
Comment	s:											
	ring: No Change											
Comment	S:											
	I: No Change											
Comment	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
043	Cream Brick w/Black Speckles - Not AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
2016 - Fal	I: No Change	<u> </u>			7							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
044	Brick Mortar - Not AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
2016 - Fall:	: No Change				$\neg$							
Comments												
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2018 - Fall:	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
045	Chimney Flashing - Not AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
2016 - Fall:	: No Change											
Comments												

Material

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

046	Exterior Window Glaze - Not AHERA			Exterior of Bldg.		Miscellaneous					YES	X NO
2016 - Fall: N	Jo Change				7							
Comments:	10 Onlange				-							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	r: No Chango				_							
	g. No Change				4							
Comments:					4							
2018 - Fall: N	lo Change				_							
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
047	Plaster	3000	SF	Gym and Auditorium		Surface	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

048	Transite Ceiling Panels			by Main Office, Engineer's Corridor Door		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	10 0.1a.1.go				]							
2017 - Fall: N	No Change				_							
Comments:					]							
2017 - Spring	g: No Change				1							
Comments:												
2018 - Fall: N	No Change				1							
Comments:	J				]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

	A,107B
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

1850

SF

HA No

049

Material Description

12" x 12" White w/Gray Specks Floor Tile Material

Quantity

Material

Units

Material Location

North Doors, West Doors

Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
050	12" x 12" White w/Gray Specks Floor Tile Mastic	1300	SF	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107 A,107B		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
051	12" x 12" Burnt Orange Floor Tile	2500	SF	North Stairwell		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

	052	12" x 12" Burnt Orange Floor Tile Mastic	2500	SF	North Stairwell		Miscellaneous	No	None	0		YES	X NO
_ [3	2016 - Fall: N	n Change											
_	Comments:	o onango				-							
-	2017 - Spring	No Chango											
	Comments:	. No Change				-							
		o Changa				1							
_	2017 - Fall: N Comments:	o Change				-							
_	2018 - Fall: N	o Change											
(	Comments:												
_						J							
Г	HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
			Quantity	Units		Туре	Category		Type	Quantity	Units		
	053	Dark Gray Carpet Adhesive			Engineer's Office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
054	12" x 12" Blue Floor Tile	5600	SF	109 A and 1st Floor Hallway		Miscellaneous	No	None			YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:					_							
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change				+							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
055	12" x 12" Blue Floor Tile Mastic	5600	SF	109 A and 1st Floor Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
056	12" x 12" Yellow Floor Tile	5000	SF	2nd Floor Hallway and Janitor's Utility Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
057	12" x 12" Yellow Floor Tile Mastic	5000	SF	2nd Floor Hallway and Janitor's Utility Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
58	Insulation inside of Vault Door	32	SF	Main Office		TSI	Yes	None	0		YES X NO	
2016 - Fall: No Change												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
059	12"x12" Gray Mabling Mix Floor Tile	1150	SF	Room 107 (Library)		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

060	12"x12" Gray Mabling Mix Floor Tile Mastic	1150	SF	Room 107 (Library)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Chango				1							
	<u> </u>				_							
Comments:												
2017 - Sprin	ng: No Change											
Comments:	•											
Commente												
2017 - Fall:	No Change											
Comments:	rto oriango				_							
Comments.												
2212 5 11												
2018 - Fall:	No Change											
Comments:												
					-							
	1			Tara and a	1	T	1			1 -		
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

		Quantity	Units		Type	Category		Туре	Quantity	Units		
061	12"x12" Peach Floor Tile	300	SF	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				7							
	Comments:				_							
2017 - Sp	oring: No Change											
Comment	ts:	7										

2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

062	12"x12" Peach Floor Tile Mastic	300	SF	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change			<u> </u>	1		·				
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
063	12"x12" White w/Gray Floor Tile	3050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Page 28

064	12"x12" White w/Gray Floor Tile Mastic	3050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change				]						
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					J						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
06	5	12"x12" Grey w/Grey Speckles Floor Tile	1100	SF	First Floor Men's Room, Washroom and Room 211		Miscellaneous	No	None	0		YES	X NO
	16 - Fall: No mments:	o Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

066	12"x12" Grey w/Grey Speckles Floor Tile Mastic	1100	SF	First Floor Men's Room, Washroom and Room 211		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change		<u> </u>	·							
Comments:	<u> </u>										
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:											
L					J						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
067	12"x12" Brown w/White Floor Tile	270	SF	Family Room and Restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change

Material

Quantity

Material

Units

HA No

Material Description

068	12"x12" Brown w/White Floor Tile Mastic	270	SF	Family Room and Restroom		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	l: No Change				]						
Comments	S:				-						
2017 - Fall	l: No Change				_						
Comments	S:										
2017 - Spr	ing: No Change										
Comments	S:				_						
2018 - Fall	l: No Change										
Comments	S:		•								

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
069	Grey Baseboard	1500	LF	First Floor Hall and Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
·	-

Material

Quantity

Material

Units

Material Location

HA No

Material Description

	070	Grey Baseboard Adhesive	1500	LF	First Floor Hall and Main Office		Miscellaneous	No	None	0		YES	X NO
I	2016 - Fall: N	o Change				1							
	Comments:					1							
	2017 - Spring	: No Change				-							
	Comments:	<b>3</b>											
	2017 - Fall: N	o Change				-							
	Comments:	<u> </u>											
	2018 - Fall: N	o Change				-							
	Comments:	<u> </u>											
						J							
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	071	Brown Baseboard	6500	LF	First & Second Floor Classrooms and Second		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Floor Hall

072	Brown Baseboard Adhesive	6500	LF	First & Second Floor Classrooms and Second Floor Hall		Miscellaneous	No	None	0		YES	X NO
0040 5-	II NI OL TOTAL	•			7							
	II: No Change											
Comment	S:											
2215 5					_							
2017 - Fa	II: No Change											
Comment	s:											
22.17					_							
	ring: No Change											
Comment	S:											
2018 - Fa	II: No Change				_							
Comment					1							
					]							
HA No	Material Description	Material	Material	Material Location	Achaetae	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

None

No

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

073	9"x9" White w/Brown Floor Tile	8	SF	Room 203 (Patch)
2016 - Fall: N	o Chango			
	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:	·			·
	·			

Quantity

Units

Material

Units

Material

Quantity

Material Location

First & Second Floor

HA No

Material Description

074	9"x9" White w/Brown Floor Tile Mastic	8	SF	Room 203 (Patch)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:					= - -							
2017 - Fall:	No Change				1							
Comments:	<u> </u>				1							
2017 - Sprii	ng: No Change											
Comments:					=							
2018 - Fall:	No Change											
Comments:					=							
L					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

7200

Material

Quantity

Material

Units

SF

Material Location

Room

,216

200,201,202,206,208,214

HA No

75

Material Description

12"x12" Light Brown VFT

Change in Assessment Category

X NO

YES

76	12"x12" Light Brown VFT Mastic	7200	SF	Room 200,201,202,206,208,214 ,216	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
2017 - Fall: N	lo Change									
2017 - Spring Comments:	g: No Change									
2018 - Fall: N Comments:	lo Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Room

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
77	12"x12" White w/Multicolored Speckle VFT	1000	SF	Auditorium Rows		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change hts:											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

HA No

Material Description

12"x12" Light Brown VFT

Material

Quantity

Material

Units

2018 - Fall: No Change Comments:

78	12"x12" White w/Multicolored Speckle VFT Mastic	1000	SF	Auditorium Rows	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			·						
Comments:										
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
79	12"x12" White w/Blue Speckles VFT	900	SF	Room 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
0047 Cmrin	N. Observe											

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
80	12"x12" White w/Blue Speckles VFT Mastic	900	SF	Room 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:				-							
2017 - Spri	ing: No Change											
Comments	:											
2017 - Fall:	: No Change											

Comments: 2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Vibration Damper	10	SF	2nd Floor Fan Room Above Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

82	Duct Cornering	25	SF	Above Auditorium		Miscellaneous	No	None	U		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change				_							
Comments:												
2017 - Fall:	No Change											
Comments:	_											
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Yes

Damage

Type

None

Dist

Damage

Quantity

0

560

Damage

Units

1120

Material

Quantity

25

Material

Units

SF

LF

Material Location

2nd Floor Fan Room

101 and Washroom,

System

Crawl Space - Heating

HA No

82

Н

Material Description

**Duct Cornering** 

Pipe Insulation

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Pipe Insulation Assoc. Elbows			Crawl Space		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Robert Healy Elementary School
Date: 1/8/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23651

SCHOOL'S ASBESTOS MANAGEMENT PLAN.