## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Helen M Hefferan Elementary School 23711 3910 School: **Oracle Unit: Building ID:** Address: 4409 W. Wilcox Region: 03 Mail Room: Asbestos Surveyor: Thompson, Darren X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2018 Email Address: dthompson72@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Category Quantity Type Type Throughout Classrooms YES X NO 1' x 1' Ceiling Tile & Corridors of 1st & 2nd 001 50000 SF Miscellaneous No None 0 (Interlocking Smooth) Floors, 111, teachers Lounge 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: Abated Comments:Removed in Parent U Room 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 23711

		Quantity	Units		Type	Category		Туре	Quantity	Units		
002	12" x 12" Tan w/Brown Streaks Floor Tile	9000	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:												
2017 - Fall: I	No Change				1							
Comments:	•											
2017 - Sprin	g: No Change				1							
Comments:					]							
2018 - Sprin	g : No Change				1							
Comments:					]							
2018 - Fall: I	No Change				1							
Comments:	-											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
002M	12" x 12" Tan w/Brown Streaks Floor Tile Mastic	9000	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003	12" x 12" Brown w/Tan Streaks Floor Tile	3000	SF	Throughout 1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003M	12" x 12" Brown w/Tan Streaks Floor Tile Mastic	3000	SF	Throughout 1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
004	12" x 12" Light Tan w/Light Streaks Floor Tile	100	SF	1st Floor Office, Foyer & Teacher's Lounge		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
004M	12"x12"Light Tan w/Light Streaks Floor Tile Mastic	1000	SF	1st Floor Office, Foyer & Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

005	1' x 1' Acoustic Tile (Interlocking Fissured)	800	SF	Auditorium		Miscellaneous	Yes	None	0	YES	X NO
					Ī						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:	-										
2018 - Fall: N	o Change										
Comments:	-										
					•						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006	Spray-on Ceiling Material			Throughout 1st & 2nd Floor Corridors		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:Removed
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
007	Hard Ceiling Plaster	3500	SF	Fan Room, Pump Room, Library, 2nd Floor Fan & Pump Rooms, Janitor's Closets & Assembly Hall		Surface	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments												
2017 - Spr	ring: No Change				-							
Comments	s:											
2017 - Fall	I: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	S:											
2018 - Fall	I: No Change											
Comments	s:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
008	Vibration Damper	25	SF	2nd Floor Fan Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
009	Cementitious Pipe Insulation	50	LF	2nd Floor Auditorium Fan Room		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
010	Cementitious Pipe Fitting Insulation	25	LF	2nd Floor Auditorium Fan Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
011	9" x 9" Tan Floor Tile	228	SF	2nd Floor Reading Special Ed Room, Math Resource room		Miscellaneous	No	None	0		YES	X NO
0040 5-1	L NI - Ol	•	•	•	7	•	•	•	•	•	•	
	I: No Change											
Comments	s:											
2017 - Spi	ring: No Change											
Comments	S:											
					]							
2017 - Fal	I: No Change											
Comments	S:											

Material

Friable

Damage

Damage

Asbestos

2018 - Fall: No Change Comments:

Material Description

Material

Material Location

2018 - Spring : No Change

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11M	9" x 9" Tan Floor Tile Mastic	228	SF	Reading Special Ed Room and Math Resource Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

012	Spray-on Insulation (Brown)	1500	SF	Boiler Room		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: No Change											
Comments:	J										
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
2018 - Spring	: No Change										
Comments:											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
013	Wallboard Remnant			Incinerator Room - North Wall		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
014	Boiler Refactory Brick	100	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015	9" x 9" Red Floor Tile - Abated 2004			Rooms 104		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Type	Damage Quantity	Units Units	Change in Assessm	ent Category
015M	9" x 9" Red Floor Tile mastic - Abated 2004			Rooms 104, 203 & 208		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:		•										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
016	Fittings on Fiberglass Pipe Insulation	140	LF	Boiler Room , Crawl Space		TSI	Yes	Loc	4		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
017	Duct Insulation	60	SF	2nd Floor Mechanical Room		TSI	Yes	None	0		YES		X NO
2016 - Fall: N	No Change				]								
Comments:	_												
2017 - Fall: N	No Change				1								
Comments:	<u> </u>												
2017 - Spring	g: No Change				1								
Comments:													
2018 - Fall: N	No Change				1								
Comments:	Ţ.												
2018 - Spring	2018 - Spring : No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
018	Woven Boiler Gasket	100	SF	Boiler Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
019	9" x 9" Brown Floor Tile - Abated 2004			Rooms 104, 203, 204, 208, 211, 223 & 225		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
2017 - Fall: N	No Change				_							
Comments:					<del>-</del>							
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	-											
	g : No Change											
Comments:					4							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
019M	9" x 9" Brown Floor Tile Mastic - Abated 1999/2004			Rooms 104, 204, 223 & 225		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
020	12" x 12" Brown Streaked Floor Tile	10000	SF	Room 111/Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2017 - Spri	ing: No Change											
Comments	:				4							
2018 - Fall	: No Change											
Comments	:			·								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
020M	12" x 12" Brown Streaked Floor Tile Mastic	10000	SF	Room 111/Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
021	2' x 2' Ceiling Tile (Fissured)			Rooms 100, 101, 201, 1st Floor Corridor & Stage		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	J				]							
2017 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	g: No Change											
Comments:	_											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					J							
	T			1	1		1	1	1	1	·	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
022	Interior Incinerator Brick			Incinerator Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Catego
023	Fire Doors	255	SF	Room100,Boiler Room, Stage Door Entrance Way & Tool Shed, Auditorium Entrance Way, Gym and Fan Rooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change s:											
	I: No Change											

2017 - Spring: No Change

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
024	Roof Flashing - Not AHERA			Roof		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
	j : No Change											
Comments:												
					_							
								_	_	_	01 1 1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
025	Exterior Brick - Not AHERA			Exterior of Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
026	Exterior Brick Mortar - Not AHERA			Exterior of Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change				1							
Comments:	•											
2018 - Fall: N	lo Change				1							
Comments:	<b>.</b>											
2018 - Spring	ı : No Change				1							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
027	4" Black Vinyl Baseboard			Assembly Hall and Room 201		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
028	4" Black Vinyl Baseboard Mastic			Assembly Hall		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
029	12"x12"Cream w/Brown Specks Floor Tile-(Top Layer)	710	SF	Assembly Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

030	12"x12"Cream w/Brown Specks FT Mastic-(Top Layer)	Assembly Hall	Miscellaneous			YES	X NO
2016 Fo	II: No Change		٦				
			4				
Comment	S:						
2017 - Fa	II: No Change						
Comments:			7				
			7				
2017 - Sp	ring: No Change						
Comment							
2018 - Fa	II: No Change						
Comment	S:						
2018 - Sp	ring : No Change		_				
Comment							

Type

Material

Category

Material Location

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
031	12" x 12" Gray Floor Tile - (Bottom Layer)	710	SF	Assembly Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
032	12" x 12" Gray Floor Tile Mastic - (Bottom Layer)	710	SF	Assembly Hall		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
033	9" x 9" Gray w/Black & White Streaks Floor Tile	316	SF	Gym Office and Book Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
034	9" x 9" Gray w/Black & White Streaks FT Mastic	316	SF	Gym Office and Book Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change				_							

Comments:

2017 - Spring: No Change
Comments:

2018 - Fall: No Change Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
035	9"x9" Gray w/Red/Blk/Blue/Wht. Streaks Floor Tile	100	SF	Gym Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

036	9" x 9" Gray w/Red/Blk/Blue/Wht. Streaks FT Mastic	100	SF	Gym Office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	<u> </u>									
2017 - Fall: N	lo Change									
Comments:	io Ondrigo									
0047 Caria	No Observe									
2017 - Spring	j: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										
2018 - Spring	ı : No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
037	Interior Door Caulk			Throughout Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
038	2' x 2' Ceiling Tile			Room 101		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:	-											
2018 - Fall: N	lo Change				1							
Comments:	-											
2018 - Spring	g : No Change				=							
Comments:												
	1			1					1		1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
039	Spray-on Ceiling			East North/South Corridor Outside Boy's Washroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:Removed
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
040	Aircell Pipe Insulation	50	LF	1st Floor Boy's Washroom		TSI	Yes	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
041	Fittings on Aircell Pipe Insulation	12	LF	1st Floor Boys Washroom		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
042	12"x12" Brown, Beige & Cream Speckled Floor Tile	2100	SF	Rooms 203, 208 & 211		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2019 Falls No Change	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
043	12"x12" Brown, Beige & Cream Speckled FT Mastic	2300	SF	Rooms 203, 208 & 211		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
044	4" Brown Vinyl Baseboard	100	LF	Room 211 and 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change				_							
Comments:												
2018 - Fall:	No Change											
Comments:	•											
2018 - Sprin	ng : No Change											

HA	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	15	4" Brown Vinyl Baseboard Mastic	100	LF	Room 211		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

Page 27

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
046	1' x 1' Ceiling Tile	1220	SF	Library		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2019 Fall: No Change	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
047	12" x 12" Lt. Beige Floor Tile Same as HA 42	2225	SF	Rooms 203, 208 and 211, gym office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
048	12" x 12" Lt Beige Floor Tile Mastic Same as HA 43	2100	SF	Rooms 203, 208 and 211		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	•				1							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	9" x 9" Beige w/Brown & White Floor Tile (Patch) -			Room 223 - Abated 2004		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
50	9" x 9" Beige w/Brown & White FT (Patch) Mastic			Room 223 - Abated 2004		Miscellaneous					YES X	NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Sink Undercoat	100	SF	Room 103 ,Faculty Lounge, Main Office and Assist Principals Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Fire Door - Same As See HA# 23	255	SF	Room 100		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change	•						•			

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Lab Counter	60	SF	Room 200		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
54	Lab Tables	168	SF	Room 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	g: No Change											
Comments:					-							
2018 - Spring	j : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12" x 12" Dark Brown Mix Floor Tile	7232	SF	Room 111/Library, 101,102,103,104, 105, 107, 109, 200, 202, 204, 223, 225		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
56	12" x 12" Dark Brown Mix Floor Tile Mastic	7232	SF	Room 111/Library, 101,102,103,104, 105, 107, 109, 200, 202, 204, 223, 225		Miscellaneous	No	None	0		YES X NO		

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12" x 12" Beige w/Brown Floor Tile	170	SF	2nd Floor Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:	•	
	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12" x 12" Beige w/Brown Floor Tile Mastic	170	SF	2nd Floor Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

Comments:  2017 - Spring: No Change Comments:  2018 - Fall: No Change Comments:	
Comments:  2017 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  2018 - Fall: No Change Comments:	
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	2016 - Fall: No Change
Comments:  2017 - Spring: No Change Comments:  2018 - Fall: No Change Comments:	Comments:
Comments:  2017 - Spring: No Change Comments:  2018 - Fall: No Change Comments:	
2017 - Spring: No Change Comments:  2018 - Fall: No Change Comments:	2017 - Fall: No Change
Comments:  2018 - Fall: No Change  Comments:	Comments:
Comments:  2018 - Fall: No Change  Comments:	
2018 - Fall: No Change Comments:	2017 - Spring: No Change
Comments:	Comments:
Comments:	2040. Falls No Charage
	2018 - Fail: No Change
2018 - Spring : No Change	Comments:
2018 - Spring · No Change	
2010 Opining : 110 Onlango	2018 - Spring : No Change
Comments:	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
59	12" x 12" Gray w/White Mix Floor Tile	784	SF	Room 213		Miscellaneous	No	None	0		YES X NO		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Change in Assessment Ca	
60	12" x 12" Gray w/White Mix Floor Tile Mastic	784	SF	Room 213		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change							•	•				
Comments:													
2017 - Fall: N	No Change												
Comments:													
	g: No Change												
Comments:													
2018 - Fall: N	No Change												
Comments:					_								
2018 - Spring	g : No Change												
Comments:	·		·	·									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Peg Board	1200	SF	Rooms 223, 109, 107, 106, 104, 105, 102, 103, 100, 200, Copy Room, 1st floor foyer near phone booth		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Blue Ceramic Floor Tile Grout	160	SF	Main Office, Kitchen, 1st and 2nd Floor Teachers Lounge Washrooms		Miscellaneous	No	None	0		YES X NO
0040 F.II N	01				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Blue Ceramic Baseboard Grout	70	LF	Main Office, Kitchen, 1st and 2nd Floor Teachers Lounge Washrooms		Miscellaneous	No	None	0		YES X NO

	_cange rracine
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
64	Blue Ceramic Baseboard Grout Adhesive	70	LF	Main Office, Kitchen, 1st and 2nd Floor Teachers Lounge Washrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				1							
Comments					-							
Comment	S.				-							
2017 - Spi	ring: No Change				-							
Comments	s:											
2017 - Fal	II: No Change											
Comments	s:				1							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Blue Carpet Mastic	200	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
66	Light Brown Carpet Mastic	120	SF	1st Floor Foyer		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	· ·											
2017 - Fall: N	lo Change				-							
Comments:	•				1							
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	j : No Change				=							
Comments:					1							
2018 - Fall: N	lo Change				=							
Comments:	•				1							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Orange Ceramic Wall Tile Grout	120	SF	1st Floor Outside Engineers Office, 2nd Floor Hall across from rooms 211 and 223		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No M	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
i hx	Orange Ceramic Wall Tile Grout Adhesive	120	SF	1st Floor Outside Engineers Office, 2nd Floor Hall across from rooms 211 and 223		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Н	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	69	Blue Ceramic Wall Tile Grout	80	SF	1st Floor Foyer outside Boiler Room, 2nd Floor Hall across from rooms 211 and 223.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
2016 - Fall: No Change
2010 Tail: 140 Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 39

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	Blue Ceramic Wall Tile Grout Adhesive	80	SF	1st Floor Foyer outside Boiler Room, 2nd Floor Hall across from rooms 211 and 223.		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	- Oh										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Gray Ceramic Floor Tile Grout	1000	SF	1st and 2nd Floors Girl's and Boy's Washrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	·	Quantity	Units		Type	Category		Туре	Quantity	Units	· ·	,
72	Brown Ceramic Baseboard Grout	160	LF	1st and 2nd Floors Girl's and Boy's Washrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					]							
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Brown Ceramic Baseboard Grout Adhesive	160	LF	1st and 2nd Floors Girl's and Boy's Washrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego
74	Wht,Yllw, Grn, Brn Multi Color Ceramic Tile Grout	250	SF	1st Floor Mens Washroom and Boiler Room Washroom		Miscellaneous	No	None	0		YES X NO
	-	·•	·•	•	7	•	•	•	•	•	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Brick Baseboard Grout	65	LF	1st Floor Mens Washroom and Boiler Room Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Beige Baseboard Adhesive	65	LF	1st Floor Mens Washroom and Boiler Room Washroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change				]						
Comments:											
2017 - Fall: N	lo Change										
Comments:											

2047 0 : N 01
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Green Ceramic tile Floor Grout- Bathrooms	32	SF	Rooms 100 and 101		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
78	Green Ceramic tile Baseboard Grout - Bathrooms	32	LF	Rooms 100 and 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change			·	]					·		
Comments:					]							
2017 - Fall:	No Change											
Comments:					_							
2017 - Sprin	g: No Change											
Comments:					_							
2018 - Fall:	No Change											

2018 - Spring : No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Green Ceramic tile Baseboard Adhesive	32	LF	Rooms 100 and 101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Pink/Gray Multi Color Ceramic Tile Floor Grout	400	SF	1st and 2nd floor Girls Washrooms		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Gray Baseboard Grout	100	LF	2nd Floor Boy's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
82	Gray Baseboard Adhesive	100	LF	2nd Floor Boy's Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
	: No Change											
Comments	S:											
2017 - Spr	ing: No Change											

2018 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	4" Black Vinyl Baseboard	24	LF	1st Floor Elevator Equipment Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
84	4" Black Vinyl Baseboard Adhesive	24	LF	1st Floor Elevator Equipment Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	White Wall Caulk	18	LF	1st Floor Elevator Equipment Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
86	Drywall Wall	72	SF	1st Floor Elevator Equipment Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fa	II: No Change												
Comment	s:												
2017 - Fa	II: No Change												
Comment													
2017 - Sp	ring: No Change												
Comment													
2018 - Fa	II: No Change												
Comment	<u> </u>												
2018 - Sp	ring : No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Drywall Ceiling	32	SF	1st Floor Elevator Equipment Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
88	Drywall Joint Compound	50	LF	1st Floor Elevator Equipment Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments												
2017 - Spri	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	<u> </u>											
2018 - Spri	ing : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	Drywall Tape	50	LF	1st Floor Elevator Equipment Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
90	White Wall Caulk	30	LF	1st Floor Elevator Equipment Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	-											
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	2'X4' White Fissured Ceiling Tile	654	SF	Reading Specialist Room and South Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	Brown/White multi color Ceramic Floor tile Grout	200	SF	2nd Floor Boy's Washroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2010 0 1 11 01	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	Vibration Collar On Duct	4	SF	Boiler Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	12x12 Grey Floor Tile	9000	SF	Rms. 206,207,209,210,212, 213,215,217,219,221		Miscellaneous	No	Dist	500		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12x12 Grey Floor Tile Mastic	9000	SF	Rms. 206,207,209,210,212,213 ,215,217,219,221		Miscellaneous	No	Dist	500		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	12x12 Tan with Brown Streaks Floor Tile	9800	SF	Lunch Room, Lunch Room Office, 100,101,102,104,105,106 , parents center		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Chango										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12x12 Tan with Brown Streaks Floor Tile Mastic	9800	SF	Lunch Room, Lunch Room Office, 100,101,102,104,105,106 , parents center		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	·

98	12"X12" Lite Green W/Streaks Floor Tile	800	SF	Bookstore 2nd floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: No Change					-							
Comments:	J											
2017 - Spring	g: No Change				-							
Comments:	, J											
2018 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:	, ,											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
99	12"X12" Lite Green W/Streaks Floor Tile Mastic	800	SF	Bookstore 2nd floor		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

2016 - Fall: No Change

Comments:

Material Description

12"X12" Lite Green

Material

Units

Material

Quantity

Material Location

HA No Material Description Material Material Location Quantity Units				Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category	
100	Boiler Jacket	300	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Mag Block Pipe Insulation	40	LF	1st Floor Tool Shed and 2nd Floor Fan Rooms		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Hard Joints Associated With Mag Block Insulation	15	LF	1st Floor Tool Shed and 2nd Floor Fan Rooms		TSI	No	None	0		YES X NO

2016 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change Comments:	
2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	2016 - Fall: No Change
Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:
Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:
Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	
2018 - Fall: No Change	2018 - Spring : No Change
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

Oracle Unit: 23711

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Helen M Hefferan Elementary School
Date: 12/18/2018
·
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.