## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

South Loop Elementary School 23751 3960 School: **Oracle Unit: Building ID:** 1212 S. Plymouth Ct. Address: Region: 03 Mail Room: Asbestos Surveyor: Bulvan, William X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other email blast Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 12"x12"Dark Tan Floor Tile Throughout Classrooms, YES 12200 SF X NO Miscellaneous No None 0 w/Brown & White Streaks Library 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 23751

2	12"x12" Dark Tan FT w/Brown & White Streaks Mastic	12200	SF	Throughout Classrooms. Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change		•	*	]	•	•	•	•	•		
Comments:	to onango											
2017 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Change in Assessment Category

Oracle Unit: 23751

Page 2

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	12"x12" Light Tan Floor Tile w/Brown & White Strks	10500	SF	Corridors and Classrooms, stairwells, Engineer's Office, Men's Locker room		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

4	12"x12"Light Tan FT w/Brown & White Streaks Mastic	10000	SF	Corridors and Classrooms	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change			•	•					
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Spray on Fireproofing	22000	SF	On Roof Panels, Storage 2nd Floor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

6	2' x 4' Fissured Lay In Ceiling Panels	20200	SF	Classrooms and Corridors, Storage 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change											
Comment												
	II: No Change											
Comment	S:											
2017 Cn	ring, No Changa											
	ring: No Change											
Comment	S:											
2018 - Fa	II: No Change											
Comment	S:											
				<u>-</u>								
	1	1		Tarin in		T	1					
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
7	Counter Caulk	1200	LF	Throughout Classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Material

Quantity

Material

Units

Material Location

Classrooms and

HA No

Material Description

Change in Assessment Category

											<u> </u>
2016 - Fall: No Ch	ange				7						
Comments:	<u> </u>				=						
2017 - Fall: No Ch	ange										
Comments:					4						
2017 - Spring: No	Change										
Comments:					4						
2018 - Fall: No Ch	ange										
Comments:					4						
					_						
HA No Mate	erial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

8000

LF

Material

Quantity

10000

Material

Units

LF

Material Location

Throughout Facility

Throughout Facility

HA No

8

9

Material Description

4" Brown Vinyl Baseboard

4" Brown Vinyl Baseboard

Change in Assessment Category

X NO

X NO

YES

10	Cinderblock	40000	SF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	· ·				1							
2017 - Fall: N	lo Change				-							
Comments:	•				1							
2017 - Spring	g: No Change											
Comments:	•				1							
2018 - Fall: N	lo Change											
Comments:	•				1							
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11	Cinderblock Mortar	40000	SF	Throughout Facility		Miscellaneous	No		0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

2016 - Fall: No Change

Material

Quantity

Material

Units

2016 - Fall	: No Change										
Comments											
2017 - Fall	: No Change										
Comments	:										
	ing: No Change										
Comments	:										
2018 - Fall	: No Change										
Comments	:										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Surface

Category

Surface

Friable

No

No

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

Quantity

10000

Units

SF

Material

Quantity

400

Material

Units

SF

Material Location

Throughout Facility

Classrooms

HA No

12

13

Material Description

of Sinks

Soundproofing on Bottom

Drywall and Compound

Change in Assessment Category

X NO

X NO

YES

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:					_						
2017 - Sprin	g: No Change										
Comments:					_						
2018 - Fall:	No Change			-							
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Surface

Miscellaneous

Category

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:	_		

20000

LF

Material

Quantity

1000

Material

Units

SF

Material Location

213 & Library

Classrooms

HA No

14

15

Material Description

Adhesive Behind Wall

Panels

Window Caulk

Change in Assessment Category

X NO

X NO

YES

	. 4.10.0										<u> </u>
2016 - Fall: I	No Change				7						
Comments:					1						
2017 - Fall:	No Change		-		_						
Comments:					]						
2017 - Sprin	ng: No Change				_						
Comments:					]						
2018 - Fall:	No Change				_						
Comments:											
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Quantity

5000

Units

LF

Material

Quantity

1000

Material

Units

SF

Material Location

Throughout Facility

Kitchen

HA No

16

17

Material Description

2' x 4' Smooth Ceiling

Panels

Wall Caulk

Change in Assessment Category

X NO

X NO

YES

2016 - Fall: N	No Change										
	10 Change										
Comments:											
2017 - Fall: N	No Change										
Comments:	10 Ondrigo										
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
1		Quantity	Units		Type	Category	1	Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

18

19

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Blue Carpet Mastic

**Duct Caulk** 

Material

Quantity

100

400

Material

Units

LF

SF

Material Location

Engineer's Office and

Custodian Locker Rooms

Boiler Room

Change in Assessment Category

X NO

X NO

YES

20	Window Glazing	10000	LF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:	<u> </u>				1							
2017 - Fall:	No Change				_							
Comments:					-							
	ng: No Change											
Comments:					-							
2018 - Fall:	No Change											
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

Damage

Quantity

0

None

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

30

Material

Quantity

Material

Units

LF

Material Location

2nd Floor Mechanical

Room

HA No

21

Material Description

Vibration Collars

YES

X NO

22	Brown Carpet Mastic	1000	SF	Room 213		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					I						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Lab Tables	200	SF	Room 229		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change				]						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

24	Formica Adhesive	100	SF	Room 229		Miscellaneous	No	None	0		YES	X NO
	o Change											
Comments:												
	o Change											
Comments:												
2017 - Spring	: Abated											
Comments:re	moned											
2018 - Fall: N	o Change											
Comments:	·			·								
(2 ()	2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring Comments:re	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments:remoned 2018 - Fall: No Change	2016 - Fall: No Change Comments:  2017 - Fall: No Change Comments:  2017 - Spring: Abated Comments:remoned  2018 - Fall: No Change

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Lab Counter & Sink	150	SF	Room 229		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall	: No Change										
Comments											
2017 - Fall	: No Change										
Comments	<b>:</b>										
2017 - Spri	ing: No Change										
Comments	S:										
2018 - Fall	: No Change										
Comments	<b>:</b>				_						
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

500

Material

Units

SF

LF

Material Quantity

1200

Material Location

Room 228

Stairways

HA No

26

27

Material Description

Purple Carpet Mastic

Stair Treads

Change in Assessment Category

X NO

X NO

YES

		Quantity	Units		Туре	Category		Type	Quantity	Units		
28	Rolled Flooring	6500	SF	Auditorium, Gym, Room 149		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: Abated											
Comments:re	moved			·								

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

2018 - Fall: No Change	
Comments:	

Material

Material

Material Location

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Rolled Flooring Adhesive	2800	SF	Auditorium, Gym, Room 149		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed
2018 - Fall: No Change
Comments:

30	Blue Carpet Mastic	200	SF	Auditorium, Women's Locker room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
					+							
Comments	<u> </u>				4							
0047 5 11	N. O.				-							
	: No Change				_							
Comments	S:											
2017 - Spr	ing: No Change											
Comments	<b>5</b> :											
					1							
2018 - Fall	: No Change											
Comments	··				1							
	<del></del>											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	smont Catagory
TIA NO	Waterial Description	Quantity	Units	Waterial Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	Sillerit Category
		Quantity	Office		1,700	Calogory		1,700	Quality	Office		
0.4	DI /O O			Rooms 137. Conference							l	F

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

31

Material Description

Blue/Green Carpet Mastic

Material

Quantity

Material

Units

Material Location

Room, Rm 136

YES

X NO

32	Blue/Orange Mix Carpet Mastic			Office		Miscellaneous					YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Fal	I: No Change											
Comments	S:											
	ring: Abated											
Comments	s:removed											
	l: No Change											
Comments	3:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33	Liner in Vault Door			Office		TSI					YES	X NO
2016 - Fal	I: No Change											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

34	Mirror Mastic	400	SF	Washrooms, Rm 149	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										
<u> </u>										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
35	12" x 12" Brown Mix Floor Tile	700	SF	Room 109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

2017 - Fall: No Change
Comments:

2017 - Spring: No Change
Comments:

2018 - Fall: No Change

HA No

Comments:

Material Description

Material

Quantity

Material

Units

										1	
36	12" x 12" Brown Mix Floor Tile Mastic	700	SF	Room 109		Miscellaneous	No	None	0	YES	X NO
0040 5 11	NI OI				1						
2016 - Fall:	No Change										
Comments:											
2017 Fall:	No Change										
2017 - Fall.	No Change										
Comments:											
2017 - Sprin	ng: No Change										
	<u> </u>										
Comments:											
2018 - Fall:	No Change										
					1						

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Acoustical Panel Mastic	200	SF	North Wall of Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall: N	No Change										
Comments:	J.										
2017 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

2000

Material

Quantity

7500

Material

Units

SF

SF

Material Location

Gym and Auditorium

Rooms 124 and 127

HA No

38

39

Material Description

New 2' x 4' Ceiling Tile

2' x 4' Ceiling Tile

Change in Assessment Category

X NO

X NO

YES

2016 - Fall:	: No Change										
Comments	): 										
	: No Change										
Comments	S:										
2017 - Spri	ing: No Change										
Comments	S:										
2018 - Fall:	: No Change										
Comments	): 										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:	_	•	

150

LF

Material

Quantity

150

Material

Units

LF

Material Location

Auditorium

Auditorium

HA No

40

41

Material Description

4' Grey Vinyl Baseboard

4" Grey Vinyl Baseboard

Adhesive

Change in Assessment Category

X NO

X NO

YES

42	Brown with Blue and white carpet adhesive	1750	SF	Auditorium	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	4' Black Vinyl Baseboard	300	LF	Library Room 228, Stairways, Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

44	4' Black Vinyl Baseboard adhesive	300	LF	Library, Room 228. Stairways, Corridors		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:	io onango										
2017 - Fall: N	lo Change										
Comments:	<u>g</u>										
2017 - Spring	g: No Change										
Comments:	_										
2018 - Fall: N	lo Change										
Comments:											
					_						
	T	T	T					_	_	 	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
45	Green Ceramic Flooring and Grout	1200	SF	East & West Bldg 1st and 2nd Floor Boys and Girls Bathrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

Change in Assessment Category

46	Green Ceramic Flooring Mastic	1200	SF	East & West Bldg. 1st, and 2nd Floor Boys and Girls Bathrooms		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change	·	·	<u>·</u>	1						
Comments											
2017 - Fall	: No Change										
Comments	<b>:</b>				_						
	ing: No Change										
Comments	<b>5</b> :				-						
	: No Change				]						
Comments	): 										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Red Ceramic Flooring & Grout	1350	SF	Kitchen, Dishwash Area & Main Entrance		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

48	Red Ceramic Flooring Mastic	1350	SF	Kitchen, Dishwash Area, & Main Entrance		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	I: No Change				]						
Comments:											
2017 - Fal	I: No Change										
Comment	s:										
2017 - Spring: No Change											
Comment	S:										
2018 - Fal	I: No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12' x 12' Gray Floor Tile	15000	SF	Main Office, Conference Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12" x 12" Gray Floor Tile Mastic	1500	SF	Main Office, Conference Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: South Loop Elementary School
Date: 1/14/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. email blast
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23751

SCHOOL'S ASBESTOS MANAGEMENT PLAN.