Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

School:William G Hibbard Elementary SchoolOracle Unit:23801Building ID:4000Address:3244 W Ainslie AvenueRegion:01Mail Room:31

X CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Sanchez, Alexander
Survey Date: 12/13/2018
Email Address: sanchez-

alexander@aramark.

com

	A copy of the2016/201	7 notice to	parents and	I staff regarding the asl	bestos manag	ement plan noti	fications w	as distribute	d via:				
	Each child's backpack				X Notice prin								
HA No						Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category	
05	12"x12" Dark Brown VFT	23100	SF	Throughout Building - 1916		Miscellaneous	No	Loc	30		YES	X NO	
2016 - Fall:	No Change												
Comments:													
2017 - Sprii	ng: No Change												
Comments:													
2017 - Fall:	No Change												
Comments:	<u> </u>												
2018 - Sprii	ng : No Change												
Comments:													
2018 - Fall [.]	No Change												
Comments:													

06	12"x12" Dark Brown VFT Mastic	23100	SF	Throughout Building - 1916		Miscellaneous	No	Loc	30	YES	X NO
2016 - Fall: N	lo Change				1						
Comments:	to onango										
2017 Spring	g: No Change				1						
Comments:	g. No Change				1						
	la Changa				1						
2017 - Fall: N	io Change										
Comments:					_						
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	lo Change				1						
Comments:	<u> </u>										
					J						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage Units Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Brown VFT	100	SF	1st Floor Corridor outside Lunchroom & Kitchen Entrance (106-104-102) - 1916		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

08	9"x9" Brown VFT Mastic	100	SF	1st Floor Corridor outside Lunchroom & Kitchen Entrance (106-104-102) - 1916		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	: No Change				1						
Comments											
2017 - Spri	ng: No Change				-						
Comments	· · · · · · · · · · · · · · · · · · ·				1						
2017 - Fall:	: No Change										
Comments	:				 						
2018 - Spri	ng : No Change										
Comments	:				-						
	: No Change				1						
Comments	:				=						
<u> </u>					1						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12' Brown Replacement Tile	500	SF	1st Floor Mezzanine Office Hallway, Vice Principal's Office - 1916		Miscellaneous	No	None	0		YES X NO

			,			
2016 - Fall: No	o Change					
Comments:						
2017 - Spring:	No Change					
Comments:						
2017 - Fall: No	o Change					
Comments:						
2018 - Spring	: No Change					
Comments:						
2018 - Fall: No	o Change					
Comments:		•		•		
		•		•	•	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12' Brown Replacement Tile Mastic	500	SF	1st Floor Mezzanine Office Hallway, Vice Principal's Office - 1916		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2040 0 : N 0	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
11	Blue Linoleum	1600	SF	Room 104/106 Lunchroom - 1916		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
12	Orange Linoleum-NOT OBSERVED			1st Floor Mezzanine Telephone Booth - 1916		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				_							
Comments:	-											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Gray Linoleum	180	SF	Room 104/106 Lunchroom - 1916		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
14	Hard Coat Plaster	150000	SF	Throughout Building - 1916		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:					_							
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change				-							
Comments:	Ţ.											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Black VFT	3000	SF	Throughout - 1998		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
16	12"x12" Black VFT Mastic	3000	SF	Throughout - 1998		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:	-												
2017 - Spring	g: No Change				1								
Comments:	, <u> </u>												
2017 - Fall: N	lo Change				1								
Comments:	Ŭ												
2018 - Spring	g : No Change				_								
Comments:	,]								
2018 - Fall: N	lo Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" White VFT	15000	SF	Throughout - 1998		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
18	12"x12" White VFT Mastic	15000	SF	Throughout - 1998		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments): 											
2017 - Spri	ing: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	S :											
2018 - Spri	ing : No Change											
Comments	S :				_							
2018 - Fall	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Light Blue VFT	3000	SF	Throughout - 1998		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Light Blue VFT Mastic	3000	SF	Throughout - 1998		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Black VFT	300	SF	2nd Floor Link to 1998 Annex - 1916		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Black VFT Mastic	300	SF	2nd Floor Link to 1998 Annex - 1916		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Vinyl Baseboard	4000	LF	Throughout - 1998		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
24	Vinyl Baseboard Mastic	4000	LF	Throughout - 1998		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change				-							
Comments:	.				1							
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>											
2018 - Spring	g : No Change				-							
Comments:	, G											
2018 - Fall: N	lo Change				-							
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Red HVAC Caulk	200	LF	Mechanical Room - 1998		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 11

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Decorative Plaster	1500	SF	Assembly Hall - 1916 Bldg.		Surface	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Drywall	2000	SF	Assembly Hall balcony - 1916 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	drywall joint compound & tape	200	SF	Assembly hall balcony - 1916 Bldg.		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Carpet Mastic	1500	SF	Assembly hall & balcony - 1916 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Terrazzo	20000	SF	1st, 2nd, 3rd, floor corridors & stairwells all levels		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change					•					

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Firedoors	2	EA	Dividing Doors Between Lecture Room 1&2		Miscellaneous	No	Loc	1		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
32	Carpet Mastic	4600	SF	Room 302, Lecture Room A&B		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	: No Change											
2017 - Fall: N	lo Change											
Comments:	-											
	: No Change											
Comments:												
2018 - Fall: N	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Firedoors	8	EA	3rd and 2nd Floor Balcony Entrance and Projector Room		Miscellaneous	No	Loc	1		YES X NO

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
34	2x2 Ceiling Tile	2100	SF	Room 103&105		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	: No Change											
Comments	:											
2018 - Fall:	: No Change											
Comments	•											
2018 - Spri	ng : No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
35	12x12 Green VFT	300	SF	Room 103&105		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
35A	12x12 Green VFT Mastic	300	SF	Room 103&105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]				•			
Comments:					_							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2018 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	ı : No Change											
Comments:	,											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Drywall System	10000	SF	Room 103&105		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
37	12x12 Beige w/ White Specs VFT	1800	SF	Room 103&105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37A	12x12 Beige w/ White Specs VFT & Mastic	1800	SF	Room 103&105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
А	Aircell Pipe Insulation	25	LF	2nd Floor Teacher's Lunchroom (Room 214) - 1916		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Comments:	o Change	•	•					•	•	•		
					1							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Aircell Pipe Insulation	3	LF	2nd Floor Teacher's Lunchroom (Room 214) - 1916		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	MJP E/F/V on Fiberglass Pipe Insulation	48	LF	1st FI:Girl's Toilet,SFan Rm; 2nd FI:Social Rm, Boy's Toilet; 3rd FI:Boy's Toilet, Rm 314 - 1916		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Mag Block Pipe Insulation	114	LF	N Mech Area: S Fan Rm, W & E Cold Decks, S Fan Housing Chamber (W & E) - 1916		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	MJP E/F/V on Mag Block Pipe Insulation	49	LF	1st FI N Mech Area: S Fan Rm, S Cold Deck, S Fan Housing Chamber (W & E) - 1916		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Cardboard Pipe Insulation	55	LF	1st Floor: South Fresh Air Intake, Room 101 (Kindergarten) Toilet - 1916		TSI	Yes	None	0		YES X NO
2016 Fall N	a Change				Ī						

2016 - Fall: No Change Comments:
Commonto
Confinents.
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	MJP E/F/V on Cardboard Pipe Insulation	8	LF	1st Floor: South Fresh Air Intake, Room 101 (Kindergarten) Toilet - 1916		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Н	Spray-On Duct Insulation	2000	SF	Attic Space: Hatch (NW, Center, SW) - 1916		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>]							
2017 - Spring	g: No Change				1							
Comments:	,											
2017 - Fall: N	lo Change				1							
Comments:	<u> </u>]							
2018 - Spring	g : No Change				1							
Comments:												
2018 - Fall: N	lo Change											
Comments:]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
I	Blow-In Insulation	1000	SF	Attic Space: Hatch (NW & SW) - 1916		Miscellaneous	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

Material

Units

Material

Quantity

Material Location

Attic Space: Hatch (NW,

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Canvas Wall Covering	432	SF	Room 214 (behind sink) - 1916		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change				1						
Comments:	- Criming										
2017 - Fall: N	lo Change				1						
Comments:											
2017 - Spring	g: No Change				-						
Comments:											
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:]						
					1						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	2'x4' Lay-In Ceiling Tile			1st Floor: Men's Toilet, Room 101 Toilet; 2nd Floor: Balcony Room - 1916		Miscellaneous					YES X NO
2016 - Fall: I	Vo Change			<u> </u>	1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	2'x2' Lay-In Ceiling Tile	1600	SF	Room 104/106 Lunchroom - 1916		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	2'x4' White w/ Grooves CT	30000	SF	Throughout - 1998		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
N	2'x2' White Smooth CT			Kitchen Area - 1998		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•]							
2017 - Fall: N	lo Change				-							
Comments:	-]							
2017 - Spring	ı: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Drywall	10000	SF	Throughout - 1998		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
Р	Drywall Compound	5000	SF	Throughout - 1998		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fal	II: No Change											
Comments												
2017 - Spr	ring: No Change											
Comments	s:											
2017 - Fal	II: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	s:											
2018 - Fal	II: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Brown and Tan carpet Mastic	1100	SF	Room 111		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William G Hibbard Elementary School	
Date:	
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy the Asbestos Management Plan is available at each school during school hours by appointm Requests to review the Asbestos Management Plan must be made at least 24 hours in advan	ent.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years through the last inspection was completed in 2016. Asbestos surveillances are conducted every six months.	ears.
CHECK ONE	
A copy of this notice was sent home in each child's backpack.	
A copy of this notice was printed in the school's newsletter and sent home with each child	
X A copy of this notice was printed in the school's calendar and sent home with each child	
Other.	
A COPY OF THIS NOTICE MUST BE PLACED IN THE	

VFT = Vinyl Floor Tile
Oracle Unit: 23801

SCHOOL'S ASBESTOS MANAGEMENT PLAN.