## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

23811

**Oracle Unit:** 

Address: 5625 N McVicker Avenue Region: 01 Mail Room: 30 Asbestos Surveyor: BALLEN24 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/17/2018 Email Address: ballen@learncharter.org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 9"x9" Light Green w/ Black YES 02 6000 SF X NO 1st Floor Corridor Miscellaneous No None 0 & White Streaks VFT 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: Abated Comments: Abated 4/15 and new tile installed 2018 - Fall: No Change Comments:

Rufus M Hitch Elementary School

School:

4010

**Building ID:** 

03	9"x9" Brown w/ White Speckles VFT	0	SF	Room 209 (Under Carpet) (Under HA 24 & 25)		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change		<u> </u>	<u> </u>	]		·				
Comments:											
2017 - Fall: N	lo Change				1						
Comments:											
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	-										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Brown w/ Speckles VFT -NOT OBSERVED	600	SF	Room 206 (under the carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Type	Category		Туре	Quantity	Units	_	
05	9"x9" Green Vinyl Floor Tile -NOT OBSERVED	750	SF	Room 106 (under the carpet) and Room 113		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					]							
2017 - Fall: N	lo Change											

Material

Friable

Damage

Damage

Comments:

2017 - Spring: No Change
Comments:

Material Material Location

2018 - Fall: No Change Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9"x9" Lt Green w/ Blk & White Streaks VFT Mastic	6000	SF	1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

07	9"x9" Brown w/ White Speckles VFT Mastic -NOT OBSERVED	0	SF	Room 209 (Under Carpet)		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change		<u> </u>	·	]	·	·			•	
Comments:											
2017 - Fall:	No Change										
Comments:	<u> </u>										
2017 - Sprin	g: No Change				_						
Comments:											
2018 - Fall:	No Change										
Comments:											
					]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
08	12"X12" Brown w/ Speckles VFT Mastic -NOT OBSERVED	600	SF	Room 206 (under the carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

09	9"x9" Green Vinyl Floor Tile Mastic -NOT OBSERVED	750	SF	Room 113 and 106 (under carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	vo onange				-							
2017 - Fall: N	lo Change											
Comments:												
2017 Carin	v. No Change				1							
	g: No Change				1							
Comments:					_							
2018 - Fall: N	lo Change				-							
Comments:												
	·			·	]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

None

Damage

Quantity

Damage

Units

HA No

10

Material Description

12"x12" White w/ Dark

Speckles VFT - NOT OBSERVED

Material

Units

Material

Quantity

Material Location

2nd Floor Men's Room -

NOT OBSERVED

Change in Assessment Category

X NO

10A	Speckles VFT Mastic -NOT OBSERVED			2nd Floor Men's Room		Miscellaneous		None			YES	X NO
004C F-II	No Observe	•	•	•	_ _							
	: No Change											
Comments												
2017 - Fall:	: No Change											
Comments	:				1							
2017 - Spri	ng: No Change											
Comments												
2018 - Fall:	: No Change				1							
Comments	· ·				1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

		-			 0 ,		· ·	-	
11	12"x12" White w/ Speckles VFT -NOT OBSERVED	600	SF	Room 206 (under carpet)	Miscellaneous	No	None	0	YES
2016 - Fal	II: No Change								
Comments	s:								
	ring: No Change								
Comments	s:								
2017 - Fal	II: No Change								

2017 - Fail: No Change Comments:

2018 - Fall: No Change Comments:

Material Description

12"x12" White w/ Dark

Material

Units

Material

Quantity

Material Location

HA No

Change in Assessment Category

X NO

11A	12"x12' White w/ Speckles VFT Mastic -NOT OBSERVED	0	SF	Room 206 (under carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change		<u> </u>								•	
Comments:												
2017 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					I							
LIA No	Material Description	Motorial	Motorial	Motorial Logation	Achootoo	Motorial	Erioblo	Domogo	Domogo	Domogo	Change in Assess	mont Cotogony

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
12	12"x12" White w/ Brown Speckles VFT	500	SF	Main Office Copy Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

12A	12"x12" White w/ Brown Speckles VFT Mastic	500	SF	Main Office Copy Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				1							
					-							
Comments	S:											
2017 - Fal	l: No Change											
Comments	3:											
2017 - Spr	ing: No Change											
Comments												
					1							
2018 - Fal	l: No Change											
Comments	<u> </u>											
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

13	Speckles VFT	1000	SF	the MDF Room, Engineers office	Miscellaneous	No
2016 - F	all: No Change					
Comme	nts:					
2017 - S	Spring: No Change					
Comme	nts:					
2017 - F	all: No Change					
Comme	nts:					
2018 - F	all: No Change					

Units

HA No

Comments:

Material Description

12"x12" Light Tan w/ White

Material

Quantity

Quantity

Material

Units

Material Location

Rooms 109 and 110 and

Change in Assessment Category

X NO

13A	12"x12" Light Tan w/ White Speckles VFT Mastic	1000	SF	Room 109 and 100 and the MDF Room, engineers office		Miscellaneous	No	None	0		YES	X NO
		•	· ·		1	•	•	•	•	•		
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	3											
Comments.												
2017 - Spring	· No Change											
	. No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:					1							
Committee in the												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Tan w/ Gray Streaks Vinyl Floor Tile	500	SF	1st Floor Faculty Room		Miscellaneous	No	None	0		YES X NO
204C Fall N	o Change	1									

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
14A	12"x12' Tan w/ Gray Streaks VFT Mastic	500	SF	1st Floor Faculty Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				]							
Comments:												
2017 - Fal	II: No Change											
Comments	s:				-							
2017 - Spr	ring: No Change											
Comments	s:				-							
2018 - Fal	II: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	9"x9" Tan w/ White & Black Streaks VFT	6000	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 10

		Quantity	Units		Type	Category		Туре	Quantity	Units		
16A	9"x9" Tan w/ White & Black Streaks VFT Mastic	6000	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
					7							
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: No Change					1							

Material

Friable

Damage

Damage

Comments:

2017 - Pail: No Change

2017 - Spring: No Change

Comments:

Material Material Location

2018 - Fall: No Change Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Beige w/tan streaks VFT	6000	SF	2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
·	-

Damage Change in Assessment Category

		-							-		
23	12"x12 Beige w/ Tan Streaks VFT Mastic	6000	SF	2nd Floor Corridor		Miscellaneous	No	None	0	YES	X NO
					1						
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Gray w/White Streaks VFT	1000	SF	Room 209		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Gray w/White Streaks VFT Mastic	1000	SF	Room 209		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Carpet Mastic	5000	SF	Rooms 106, 113, 206 and the Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	Wire Insulation Associated With All Heaters	1000	LF	1st & 2nd floors boys & girls restrooms, room 214, 206, gym office, 1st floor teachers lounge, janitor's closet in boiler room		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	ig. No Change											
2040 Falls	No Change											
2018 - Fall: Comments:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Wire Insulation Associated With Gym Lights At Ceiling -NOT OBSERVED	1000	LF	Gym		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	Category
29	Terrazzo	2500	SF	Vestibules, All Stairwells, 1st and 2nd Floor Corridors Borders, Auditorium Vestibule & Stairs, Room 110 Back Entry & Room 213		Miscellaneous	No	None	0		YES X	NO
2016 - Fall: N	lo Change				]							
Comments:	Ğ											
2017 - Fall: N	lo Change				_							
Comments:	to enange											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Drywall, Tape and Compound	500	SF	Wall Between 109 and 110, 1st Floor MDF Room		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

31	Fire doors	3	EA	Off Of 2nd Floor Hall Leading to Teacher's Restroom		Miscellaneous	No	None	0		YES	X NO
			•	•								
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	-											
2018 - Fall: I	No Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Off Of 2nd Floor Hall

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	rnable	Type	Quantity	Units	Change in Asses	sment Category
32	Fire Doors	52	EA	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				-							
2017 - Fall: N	No Change				-							

Comments: 2017 - Spring: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

2018 - Fall: No Change Comments:

33	Fire Doors	10	EA	Boiler Room, Fan Room and Air Tunnel		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change				7							
Commen					- -							
2017 - Fa	all: No Change				-							
Commen	ts:											
2017 - Sp	oring: No Change											
Commen	ts:				-							
2018 - Fa	all: No Change											
Commen	ts:				_							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Surface

Friable

No

Damage

Туре

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
		-

Quantity

800

Units

SF

Material

Quantity

Material

Units

Material Location

Assembly Hall

HA No

34

Material Description

Ornamental Plaster

Change in Assessment Category

X NO

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
35	12"x12" Off-White w/orange and brown speckles VFT	200	SF	2nd Floor Room Annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Spring Comments:	: No Change											

Material

Damage

Friable

Damage

Damage

Comments:
2018 - Fall: No Change

Material

Material

Material Location

Comments:

Material Description

HA No

2017 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35A	12"x12" Off-White w/orange and brown specs Mastic	200	SF	2nd Floor Room Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 18

004C Falls	Na Ohana										
2016 - Fall:											
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Surface

Miscellaneous

Category

Friable

Yes

Yes

Damage

Туре

None

None

Damage

Quantity

0

Damage

Units

2016 - Fall: No Change			
Comments:			
2017 - Spring: No Change			
Comments:			
2017 - Fall: No Change			
Comments:			
2018 - Fall: No Change			
Comments:		•	

150

Material

Quantity

2400

Material

Units

SF

SF

Material Location

Library (room 106)

Attic

HA No

36

37

Material Description

Pink Insulation -NOT

OBSERVED

4x4 Ceiling Tile

Change in Assessment Category

X NO

X NO

YES

38	Vinyl Baseboard			Annex Building		Miscellaneous	No	None			YES	X NO
2016 - Fall:	No Change				7							
Comments:					-							
2017 - Sprii	ng: No Change											
Comments:					4							
	No Change											
Comments:					4							
2018 - Fall:	No Change											
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
39	2x2 Ceiling Tile	2000	SF	Annex Building		Miscellaneous	Yes	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

(throughout)

40	Blue/Green Linoleum	400	SF	Annex Building Mens/Womens Washrooms		Miscellaneous	No	None			YES	X NO
004C F-II	l. Na Obasasa											
	: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	<u> </u>											
	-											
2017 - Fall	l: No Change											
Comments	S:											
2018 - Fall	l: No Change											
Comments	S:											
	_		•	_								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

Damage

Quantity

Damage

Units

			, ,	
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				•

2000

HA No

41

Material Description

12x12 Beige Streak VFT

Material

Quantity

Material

Units

SF

Material Location

Annex Building

Annex Building

(throughout)

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
В	Mudded Joint Packing on Fiberglass Pipe Insulation	100	LF	Boiler Room and 1st and 2nd Floor North & South Janitors Closets Pipe Chases		TSI	Yes	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Aircell Pipe Insulation	370	LF	Tunnel, Shower Room (BR) and Girl's Former Locker Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 22

D	Mudded Joint Packing on Aircell Pipe Insulation	28	LF	Tunnel and Girl's Former Locker Room		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:	0											
2017 - Fall:	0				_							
Comments:					_							
2017 - Sprin	ng: No Change				1							
Comments:												
2018 - Fall:	No Change				_							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Type

Damage

Quantity

Damage

Units

	Pipe Chase
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

590

LF

HA No

Ε

Material Description

Cardboard Pipe Insulation

Material

Quantity

Material

Units

Material Location

Shower Room--NOT

OBSERVED, Boiler

Room Bathroom and

North Janitor's Closet

YES

X NO

F	Mudded Joint Packing on Cardboard Pipe Insulation	70	LF	Pipe Chases and Girl's Locker Room		TSI	Yes	None	0		YES	X NO
		•		•	7				•	•		
2016 - Fall: N	No Change											
Comments:												
					1							
2017 - Fall: N	No Change											
Comments:												
					1							
2017 - Spring	g: No Change											
Comments:	-											
					1							
2018 - Fall: N	lo Change											
Comments:												
					1							
					=							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

Н	Tank Insulation - REMOVED		Boiler Room - REMOVED
-	•		
2016 - Fall: N	lo Change		
Comments:			
2017 - Fall: N	lo Change		
Comments:			
2017 - Spring	g: No Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:			

Material

Quantity

Material

Units

Material Location

Tunnel, Janitor's Closets

HA No

Material Description

I	Spray-On White and Pink Duct InsulationNOT OBSERVED			Attic Space							YES	X NO
2016 - Fall: I	No Change				7							
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Friable

Yes

Miscellaneous

None

0

Damage

Туре

Damage

Quantity

Damage

Units

J	Boiler Gasket(s) on New Boiler	20	LF	Boiler Room
2016 - Fall: No Change				
Comments:				
2017 - Spring: No Change				
Comments:				
2017 - Fall: No Change				
Comments:				
_				
2018 - Fall: No Change				
Comments:				

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

X NO

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Rufus M Hitch Elementary School
Date: 12/17/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 23811