Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Julia Ward Howe Elementary School of Excellence 23851 4060 School: **Oracle Unit: Building ID:** Address: 720 N. Lorel Avenue Region: 02 Mail Room: Asbestos Surveyor: Acevedo, Andres X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/11/2018 Email Address: aacevedo22@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 9"x9" Green Floor Tile Room 208, Deck Over YES 02 X NO Miscellaneous (Abated 2008) Vestibule - 1896 Bldg. 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
03	12"x12" Beige Floor Tile (Abated 2008)			South Dressing Room - 1910 Bldg.		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>]							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					1							
2018 - Spring	: No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	9'x9" Green Floor Tile Mastic (Abated 2008)			Room 208 - 1896 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		
05	12"x12" Beige Floor Tile Mastic (Abated 2008)			South Dressing Room - 1910							YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprin	g: No Change				_							
Comments:					_							
2017 - Fall:	No Change											
Comments:					4							
	g : No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:					-							
					_							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Material

Friable

Damage

Damage

Damage

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
08	12"x12" Off White Floor Tile (ABATED 2010)			Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.		Miscellaneous				YES	X NO
2016 - Fa	ıll: No Change]						
Commen	ts:										
2017 - Sp	oring: No Change										
Commen	ts:										

2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments:

HA No

Material Description

Material

Material

Material Location

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
09	12"x12" Off White Floor Tile Mastic(ABATED 2010)			Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.							YES	X NO
2016 - Fall	: No Change				1							
Comments					_							
2017 - Spri	ing: No Change											
Comments												
2017 - Fall	: No Change											
Comments	S:											
2018 - Spri	ing : No Change											
Comments): -											
2018 - Fall	: No Change											
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" White Floor Tile (ABATED 2010)			Room 303 - 1910 Bldg.		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" White Floor Tile Mastic (ABATED 2010)			Room 303 - 1910 Bldg.		Miscellaneous					YES X NO
2016 - Fall: I	No Change										
Comments:	J										
2017 - Sprin	g: No Change										
Comments:	<u>g </u>										
2017 - Fall: I	No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:	<u> </u>										
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Off-White Floor Tile (ABATED 2010)			NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

13	12"x12" Off-White Floor Tile Mastic (ABATED 2010)	between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.				YES	X NO
2016 - Fa	ıll: No Change]				
Commen							
2017 - Sp	oring: No Change						
Commen	ts:						
2017 - Fa	ıll: No Change						
Commen	ts:						
2018 - Sp	oring : No Change						
Commen	ts:						
2018 - Fa	ıll: No Change						
Commen	ts:						
			I				

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
14	Red Linoleum			Auditorium Stairs - 1910 Bldg.							YES	X NO
2016 - Fall: N Comments:	lo Change											

HA No

Material Description

Material

Quantity

Material

Units

Material Location

NW Stairwell Landing

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
15	9"x9" Brown Floor Tile (Abated 2008)			Small Room North of Boiler Room - 1910 Bldg.		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Spring	g: No Change]							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					_							
	g : No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					1							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	9"x9" Brown Floor Tile Mastic (Abated 2008)			Small Room North of Boiler Room - 1910 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

17	12"x12" Off-White w/Tan Streaks Floor Tile (Not Observed) ABATED 2010			Room 306 - 1910 Bldg.		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprin	ıg: No Change				-							
Comments:												
2017 - Fall:	No Change				=							
Comments:	.											
2018 - Sprin	ıg : No Change				=							
Comments:					<u> </u>							
2018 - Fall:	No Change				1							
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18	12"x12" Off-White w/Tan Streaks Floor Tile Mastic (Not Observed) ABATED 2010			Room 306 - 1910 Bldg.							YES	X NO
2016 - Fall:	No Change				7							
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2017 - Spring: No Change

2018 - Spring : No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Green w/White & Black Streaks Floor Tile (Not Observed) ABATED 2010			Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Green w/White & Black Streaks Floor Tile Mastic (Not Observed) ABATED 2010			Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Off White Floor Tile (ABATED 2010)			Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room		Miscellaneous		None			YES X NO
2016 - Fall: I Comments:	No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
38	12"x12" Off White Floor Tile Adhesive Abated in 2010.			Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room		Miscellaneous					YES	X NO
2016 - Fal	II: No Change s:											
2017 - Spi	ring: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 23851

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" Khaki Colored w/Streaks VFT	24	SF	Electric Room in Gym		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

0040 5 11 11 01
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Khaki Colored w/Streaks Mastic	24	SF	Electric Room in Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 13

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41	Black Trip Vinyl	200	SF	Stair Landings & Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											_
Comments:												
2017 - Spring	g: No Change				1							
Comments:												

2017 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Black Trip Vinyl Adhesive	200	SF	Stair Landings & Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
43	12 x 12 Tan with Brown Streaks VFT	12000	SF	1896 & 1910 Bldg Addition - 1st, 2nd, 3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

1896 & 1910 Bldg Addition - 1st, 2nd, 3rd			
43M	No None	0	YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 23851

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12 x 12 Off White with Tan Streaks VFT	8500	SF	1910 Bldg-New 4th Floor Offices and Classrooms 401, 402, 403, 404, Closets& Coatrooms, 406 Teachers Lounge, Corridors & Top or Stairwells, 3rd Floor 303, 304, 305, 2nd Floor 208; 1896 Bldg-1st Floor 104, 105		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44M	12 x 12 Off White with Tan Streaks Mastic	8500	SF	1910 Bldg-New 4th Floor Offices and Classrooms 401, 402, 403, 404, Closets& Coatrooms, 406 Teachers Lounge, Corridors & Top or Stairwells, 3rd Floor 303, 304, 305, 2nd Floor 208; 1896 Bldg-1st Floor 104, 105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
45	Drywall System	15000	SF	1910- Throughout 1st, 2nd, 3rd Floors, New 4th Floor Classrooms & Offices Bathrooms; 1896 Classrooms, Storage Offices		Miscellaneous	No	None	0		YES	NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

46	2 x 2 White Ceiling Tile	3500	SF	Throughout New 4th Floor Corridors		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: N	lo Change				_						
Comments:	io Change										
Comments.											
2017 - Spring	g: No Change										
Comments:	9										
2017 - Fall: N	lo Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	•										
2018 - Spring	g : No Change										
Comments:	, ,										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Cardboard Pipe Insulation	65	LF	1st Floor Corridor, Storeroom by Gymnasium, Storeroom (#100 Pre-K Classroom now) 1896 - 1910 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Fiberglass Pipe Insulation	80	LF	Boiler Rm Toilet, Aud Storerm, NW Boy's Toilet & Corr, Jan's Closet next to Rm 304 - 1910 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
G	MJP E/F/V on Cardboard Pipe Insulation	5	LF	1st Floor Corridor, Store Room by Gymnasium - 1910 Bldg. #100 Pre-K Classroom - 1896 Bldg & Room#202 Wardrobe - 1910		TSI	Yes	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _Julia Ward Howe Elementary School of Excellence
Date: 12/14/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 23851