## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

23901

**Oracle Unit:** 

Building ID: Address: 4247 W. 15th St. Region: 03 Mail Room: Asbestos Surveyor: Greason, Daron X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/11/2018 Email Address: dgreason@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 01 12" x 12" Beige Floor Tile SF X NO 500 Lunchroom Miscellaneous No None 0 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Charles Evans Hughes Elementary School

School:

4110

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02.1	9" x 9" Grey Vinyl Floor Tile	28832	SF	See Comments For Locations		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02.2	9" x 9" Blue Floor Tile	4320	SF	Throughout 2nd Floor Corridor		Miscellaneous	Yes	Loc	5		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
03	1' x 1' Ceiling Tile	30000	SF	1st Floor Corridor, 2nd Floor West half of Building, Rooms 110- 116, 104-108, 201-209		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fal	II: No Change											
Comment	<u> </u>											
2017 - Sp	ring: No Change				-							
Comment	<u> </u>											
2017 - Fal	II: No Change				-							
Comment												
2018 - Sp	ring : No Change				_							
Comment	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Plaster	2500	SF	Washroom Ceiling & Stairway, Kitchen		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05	12" x 12" Beige Floor Tile Mastic	800	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change				-							
Comments:	Comments:											

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9" x 9" Gray Vinyl Floor Tile Mastic	28832	SF	See Comments For Locations		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
06.2	9"x9" Blue VFT Mastic	4320	SF	2nd floor corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments	:											
2018 - Spri	ing : No Change											
Comments	:											
2018 - Fall:	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	4" Vinyl Mop Board	324	LF	Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
08	4" Vinyl Mop Board Mastic	324	LF	Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]		•		•			
Comments:												
2017 - Spring	g: No Change											
Comments:	,g				1							
2017 - Fall: N	lo Change				]							
Comments:												
2018 - Spring	g : No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:	<del>-</del>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Fire Doors	21	SF	Throughout Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

10 Incinerator Door Boiler Room Miscellaneous TyES X NO 2016 - Fall: No Change	
Commonto	
Comments:	
2017 - Spring: No Change	
Comments:	
2047 Fall, Na Change	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Incinerator Fire Brick			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
12	Exterior Glazed Brown Brick - Non AHERA			Exterior of Building		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:					]							
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	o Change				_							
Comments:												
2018 - Spring	: No Change				_							
Comments:												
2018 - Fall: N	o Change				_							
Comments:					]							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Exterior Glazed Brown Brick Mortar - Non AHERA			Exterior of Building		Miscellaneous					YES X NO
004C Fall N	In Ohama				1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 8

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
14	Exterior Window Glaze - Non AHERA			Exterior of Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	: No Change				1							
Comments:	J											
2017 - Fall: N	lo Change				1							
Comments:	•											
2018 - Spring	: No Change				1							
Comments:	•											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Exterior Window/Door Caulk - Non AHERA			Exterior of Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 9

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
16	Drywall	10000	SF	Above the 1' x 1' Ceiling Tile Throughout the Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				7							
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fal	II: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	S:											
2018 - Fal	II: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" yellow floor tile w/cream specks	520	SF	Auditorium Stage area		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" yellow floor tile w/cream specks mastic	520	SF	Auditorium Stage area		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

0040 5 11 11 01
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	4" Cream Vinyl Baseboard	800	LF	Auditorium Stage area		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

20	4" Cream Vinyl Baseboard Adhesive	800	LF	Auditorium Stage area		Miscellaneous	No	None	0	YES	X NO
0040 = " 1					1						•
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	j: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	j : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Cream floor tile w/gray streaks			Gym-Multi purpose room		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
22	9"x9" Cream floor tile w/gray streaks mastic			Gym-Multi purpose room		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	ı: No Change											
Comments:					 							
2017 - Fall: N	lo Change											
Comments:					 							
2018 - Spring	: No Change											
Comments:					 							
2018 - Fall: N	lo Change											
Comments:					=							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	1'x1' Ceiling Tile adhesive	24000	SF	1st Floor Corridor, 112, 114, 117, Gym, Office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

24	12"X12" Lt. Blue floor tile w/blue specks	1800	SF	2nd floor corridor		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:	io onango										
2017 - Spring	r. No Change										
Comments:	y. 110 Chango										
2017 - Fall: N	lo Change										
Comments:	ge										
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					J						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"X12" Lt. Blue floor tile w/blue specks mastic			2nd floor corridor							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"X12" Lt. Blue flr tile w/gray & wht. spks	110	SF	2nd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12X12 Lt. Blue flr tile w/gray & wht. Spks mastic	225	SF	2nd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Brown Speckled floor tile	44	SF	Meeting Room, Rms 214 & 217		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring: No Change Comments:  2018 - Fall: No Change	Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring: No Change Comments:	
Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring: No Change Comments:  2018 - Fall: No Change	Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring: No Change Comments:  2018 - Fall: No Change	
2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	2016 - Fall: No Change
Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:
Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	2017 - Spring: No Change
Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:
Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	Comments: 2018 - Fall: No Change	
2018 - Fall: No Change	2018 - Fall: No Change	2018 - Spring : No Change
		Comments:
Commonto	Comments:	2018 - Fall: No Change
Comments:		Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Brown Speckled floor tile mastic	44	SF	Meeting Room, Rms 214 & 217 replacement tile		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 16

30	12"x12" Cream floor tile w/gray & wht. Specks	1500	SF	Main Office, Room 106	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	o onango									
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										
0040 5-11 N	01									
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Cream flr tile w/gray & wht. Specks mastic			Main Office, Room 106							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

32	Interior Door Caulk	1530	LF	interior side of door frames		Miscellaneous	No	None	0	YES	X NO
			•	<u> </u>	7	•	•				
2016 - Fall: I	No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:	-										
					1						
2018 - Sprin	g : No Change		•								
Comments:	-										
					1						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	1"x1" White Pinhole ceiling tile			Now HA 03		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
34	1"x1" White ceiling tile			Now HA 03		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:	_											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9" x 9" Green w/White & Black FT	95	SF	Rooms 102 and 103 replacement tiles		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	9" x 9" Green w/White & Black FT Mastic	95	SF	Rooms 102 and 103 replacement		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" Gray Mix Floor Tile	45	SF	Rooms 217, 216, 212, 215, 210, 202, 208 and 203		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12" x 12" Gray Mix Floor Tile Mastic	45	SF	Rooms 217, 216, 212, 215, 210, 202, 208 and 203		Miscellaneous	No	None	0		YES X NO
					3	•	•	•	•	•	•

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Sink Undercoat	15	SF	State Pre-K, 102 - 104, 106, 108, 110, 112, 215, 217		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	2' x 4' Ceiling Panels	9000	SF	2nd Floor Hall, Rooms 210 - 217, Gym Stage area, South Stairwell		Miscellaneous	Yes	None	0		YES X NO
	•	•	•	•		•		•	•		•

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Chalk Board/Poster Board Adhesive	2522	SF	All Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
42	Drywall Ceilings	216	SF	East, West and North Vestibules		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:	g											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Drywall Joint Compound	40	SF	East, West and North Vestibules		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
44	Drywall Joint Tape	40	LF	East, West and North Vestibules		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
2017 - Sprir	ng: No Change												
Comments:													
2017 - Fall:	No Change												
Comments:	<u> </u>												
2018 - Sprir	ng : No Change												
Comments:	<u> </u>												
2018 - Fall:	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	1' X 1' White Pinholed Ceiling Tiles	400	SF	Rooms 101 and 103		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
46	Black & White Terrazzo	3000	SF	1st Floor and Stairwells		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:												
2017 - Sprir Comments:	ng: No Change											
2017 - Fall: Comments:												
2018 - Sprir Comments:	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Brown and White Ceramic Tile and Grout	1296	SF	1st, 2nd Floor Boys and Girls Bathrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

Page 25

		Quantity	Units		Type	Category		Type	Quantity	Units		3 ,
48	Brown & White Ceramic Tile Mastic	1296	SF	1st & 2nd Floor Boys and Girls Bathrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				]							
Comment					]							
2017 - Sp	ring: No Change											
Comment	S:				-							
	II: No Change											
Comment	S:				-							
	ring : No Change											
Comment	s:											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12"x12" Red Floor Tile	520	SF	Auditorium Stage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12"x12" Red Floor Tile Mastic	520	SF	Auditorium Stage		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

0040 Fall Na Ohanna	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12"x12" Yellow Cream Floor Tile	3213	SF	Gym Multi Purpose Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
52	12"x12" Yellow Cream Floor Tile Mastic	3213	SF	Gym Multi Purpose Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" x 12" Off-White Floor Tile	1800	SF	2nd Floor East Corridor, 210-217		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
54	Mastic Associated w/ 12" x 12" Off-White Floor Tile	1800	SF	2nd Floor East Corridor, 210-217		Miscellaneous	No	None	0		YES	X NO
					1							
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	<b>. . . .</b>											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Fittings on Fiberglass Pipe Insulation			Throughout 1st Floor		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Н	Breeching Insulation			Boiler room		TSI					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					-							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				-							
Comments:												
2018 - Spring	: No Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Change				1							
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Duct Expander			1st Floor Above Stage		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 30

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
J	Duct Wrap			Kitchen and Stage and Above Ceiling in the Gym		TSI		None			YES	X NO
2016 - Fall: N	No Change				]							
Comments:					1							
	g: No Change				1							
Comments:												
2017 - Fall: N	No Change				-							
Comments:					-							
2018 - Fall: N	No Change											
Comments:					1							
	g : No Change											
Comments:					1							
L					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Air Handler Duct Wrap - Abated 2006			Kindergarten Rooms 101 and 103 and 133		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
М	Aircell Pipe Insulation			Boiler room		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>				]							
2017 - Fall: N	lo Change				1							
Comments:	<u> </u>				]							
2017 - Spring	g: No Change											
Comments:												
2018 - Spring : No Change												
Comments:												
2018 - Fall: N	lo Change				1							
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Cementitious Pipe Joint Ins. on Aircell Ins. Pipe			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Charles Evans Hughes Elementary School
Date: 12/11/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23901

SCHOOL'S ASBESTOS MANAGEMENT PLAN.