## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

Edward N Hurley Elementary School 23911 4120 School: **Oracle Unit:** Building ID: Address: 3849 W. 69th Pl. Region: 05 Mail Room: Asbestos Surveyor: Delgado, Jesus **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 1/10/2019 Email Address: jmdelgado14@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 9x9cream ft w/beig strks YES 04 200 SF X NO Miscellaneous No None 0 lobby and lite brn w/beige strk 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12x12cream ft w/beig strks and lt brn w/beig strk	8900	SF	room: 110, 101, 104, 106, 108, 212, 200, 202, 204, 206, 208, 210, teachers lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	linoleum	1200	SF	Rooms 100		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
07	mastic 9x9 cream w/biege streaks vft	200	SF	Lobby		Miscellaneous	No	None	0		YES	X NO
2016 - Fal Comments	ll: No Change s:											
2017 - Spr Comments	ring: No Change s:											
2017 - Fal Comments	ll: No Change s:											
2018 - Fal	II: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	mastic 12x12 cream and lt brown w/beige streaks	8900	SF	room: 110, 101, 104, 106, 108, 212, 202, 204, 206, 208, 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

09	mastic under linoleum	1200	SF	room 100		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Fall: N	No Change											
Comments:					]							
2017 - Spring	g: No Change											
Comments:					 							
2018 - Fall: N	No Change											
Comments:					<u> </u>							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:		•	•	

Quantity

3400

Units

SF

Material

Units

Material

Quantity

Material Location

gym, lobby

HA No

10

Material Description

mastic behind 12x12 ceiling

tiles

11	Black baseboards	75	LF	Teacher's Lounge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:	<u> </u>				1							
2017 - Sprin	g: No Change											
Comments:					 							
2017 - Fall: I	No Change											
Comments:					-							
2018 - Fall: I	No Change											
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12	Black baseboard mastic			Teacher's Lounge		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
13	Plaster	135000	SF	Throughout		Surface	Yes	None	0		YES	X NO
2016 - Fal Comments	l: No Change s:											
2017 - Spr Comments	ing: No Change											
	l: No Change											
Comments	•											
					<del></del>							

2018 - Fall: Other

HA No

Comments:Damage observed in second floor girls washroom. Damaged suspect material tested for ACM content. Material determined non-asbestos at localized damage area. results not applicable to remainder of material in building.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	mag block boiler insulation	900	SF	boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

В	preform pipe insulation	2350	LF	Boiler room, tunnel in basement		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change				]						
Comments:											
2017 - Spring	: No Change										
Comments:					 						
2017 - Fall: N	o Change										
Comments:					 						
2018 - Fall: N	o Change				]						
Comments:					-						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB1	baseboard	203211	LF	room 203		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

BBM1	baseboard mastic	2400	LF	All classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	<u> </u>				1							
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	No Change											
Comments:					=							
2018 - Fall: N	No Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Туре

Damage

Quantity

0

None

Damage

Units

Material Location

boiler room, basement

pump room

2016 - Fall: N	o Change		
Comments:		 	
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

125

Material

Quantity

Material

Units

LF

HA No

С

Material Description

aircell joints

YES

X NO

2016 - Fall:	No Chango										
	INO Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
	some open ends identi	fied in tunn	el space.								
	•		- I								
					<u> </u>						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	1	Gadritity	00		.,,,,,	Jacogory		1,700	Guaritity	010	

Type

Material

Category

TSI

TSI

Friable

Yes

Yes

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

160

Material

Quantity

1700

Material

Units

LF

LF

Material Location

Boiler room

Boiler room

HA No

D

Ε

Material Description

cardboard pipe insulation

cardboard joints

Change in Assessment Category

X NO

X NO

YES

YES

Dasement							
2016 - Fall: No Change							
Comments:							
2017 - Fall: No Change							
Comments:							
2017 - Spring: No Change							
Comments:							
2018 - Fall: No Change							
Comments:							
HA No Material Description Material Material Location	Asbestos	Material	Friable	Damage	Damage	Damasa	Change in Assessment Category

Type

Material

TSI

Category

Friable

Yes

Damage

Type

None

Damage

Quantity

0

Damage

Units

TIANO	Material Description	Quantity	Units	Waterial Location	Type	Category	Thable	Type	Quantity	Units	Change in Asses	Sillerit Gategory
FT1	9x9 tan w/ lt. Brwn streaks (checked)	600	SF	offices		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	V				1							
2017 - Fall: N	lo Change				-							

Comments:

2017 - Spring: No Change
Comments:

2018 - Fall: No Change
Comments:

HA No

F

Material Description

preform joints

Material

Units

LF

Material

Quantity

400

Material Location

Boiler room, tunnel in

hasement

Change in Assessment Category

X NO

YES

FT2	9x9 ft - gray w/ brown streaks	90	SF	teachers washroom 2nd floor	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	go									
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	•			•						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT3	9x9 brn w/maroon&cream streak&tan w/cream &blk str	1500	SF	basement hall, cafeteria kitchen, engineers office and bath		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmer	nt Category
FT4	12x12 gray w/brown & red specks	4300	SF	room 101, 103, 105, 107, 201, 205, 207		Miscellaneous	No	None	0		YES	NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT5	12x12 lite tan &cream w/white specks VFT	1300	SF	room 203 and 211		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

FT6	White VFT	500	SF	kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	io onango											
2017 - Fall: N	lo Change											
Comments:												
2017 0					-							
2017 - Spring	յ։ No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
1		Qualitity	Office		1 7 7 0	Cutogory	l	1 7 0 0	Quantity	Ornio	l	

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

FT7	12x12 cream f.t. with beige streaks	5750	SF	teachers lounge, basement hall, cafeteria
0040 = 11 14				
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
		•		_

Material

Quantity

Material

Units

Material Location

corridors, main office,

HA No

Material Description

12x12 cream f.t. with beige

YES

X NO

FTM1	mastic beneath 9x9	500	SF	offices	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N Comments:	o Change									
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM2	mastic beneath 9x9 gray w/brown streaks VFT	90	SF	teachers washroom 2nd floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

FTM3	mastic 9x9 brwn w/marn- crm strks& tan w/crm-black	1500	SF	basement hall, cafeteria kitchen, engineers office and bath		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Changa			•	1	•	•	•	·		
	o Change										
Comments:											
2017 - Spring	: No Change				1						
Comments:											
2017 - Fall: N	o Change				1						
Comments:	•										
2018 - Fall: N	o Change										
Comments:	<u> </u>				1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM4	mastic12x12 gray w/brown- red specks VFT	4300	SF	room: 101, 103, 105, 107, 201, 205, 207		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

FTM5	mastic12x12 Lite tan-cream w/white specks vft	1300	SF	room 203 and 211		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:	-										
2017 - Spring	ı: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					1						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
FTM6	White VFT mastic	500	SF	Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
2017 - Fall: N	o Change											

Comments: 2017 - Spring: No Change Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

2018 - Fall: No Change Comments:

Change in Assessment Category

Damage

Units

FTM7	12x12 cream f.t. with beige streaks mastic	5750	SF	corridors, main office, teachers lounge, basement hall, cafeteria		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	la Changa			·	1						
	lo Change										
Comments:											
2017 - Fall: N	lo Change				1						
Comments:											
					1						
2017 - Spring	: No Change				1						
Comments:					1						
					1						
2018 - Fall: N	lo Change				1						
Comments:	<u> </u>										
					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	aircell pipe insulation	1550	LF	boiler room, basement pump room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Н	boiler gaskets	20	LF	boiler room		TSI	Yes	None	0		YES	X NO
2016 - Fall: No	o Change				1							
Comments:												
2017 - Fall: No	o Change				-							
Comments:												
2017 - Spring:	: No Change											
Comments:					1							
2018 - Fall: No	o Change											
Comments:					-							
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
I	incinerator insulation			boiler room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Page 18

J	canvas wrap duct covering	600	SF	basement, hallway, kitchen	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:	-									
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N	o Change									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	12" x 12" ACT	4150	SF	Lobby, gym, cafeteria		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

L	Fiberglass pipe insulation wrap	300	SF	2nd fl HVAC rm, basement pump room, tunnel in basement		TSI	Yes	None	0	YES	X NO
		•	•	•	· 1	•	•	•	•		
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	•										
2018 - Fall: N	o Change										

Material

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Foil insulation on HVAC duct	580	LF	2nd-story HVAC Room, tunnel and basement		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall: No Change											
Comments:											
2017 - Spring: No Change	)										
Comments:					_						
2017 - Fall: No Change											
Comments:											
2018 - Fall: No Change											
Comments:											
HA No Material Desc	cription	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

660

Material

Quantity

660

Material

Units

LF

LF

Material Location

1st, 2nd floor corridors

1st. 2nd floor corridors

HA No

Ν

О

Material Description

Brown baseboard mastic

Brown baseboard

Change in Assessment Category

X NO

X NO

YES

YES

2016 - Fall:	No Change										
Comments:											
2017 - Sprin	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

TSI

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

Ρ

Q

Material Description

Fiberglass joint coverings

Vibration Collars

Material

Quantity

8

Material

Units

LF

LF

Material Location

2nd story HVAC room

Basement pump room,

Basement tunnel

Change in Assessment Category

X NO

X NO

YES

YES

R	Boiler Jackets (two 1300 each)	2600	SF	Boiler room		TSI	Yes	None	0	YES	X NO
2016 Fall N	la Changa				1						
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	r: No Change										
Comments:											
2017 - Fall: No Change											
Comments:											
2018 - Fall: N	lo Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Boiler header	30	LF	Boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Boiler Jackets (two 1300

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _Edward N Hurley Elementary School
Date: 1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Oracle Unit: 23911 Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.