Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

23921

Oracle Unit:

Friedrich L. Jahn Elementary of the Fine Arts

School:

Address: 3149 N. Wolcott Avenue Region: 01 Mail Room: Asbestos Surveyor: Fuentes, Kenneth X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: kfuentes4@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 3rd Flr. Tchrs Toilet & YES X NO Lounge, Rm 004, 108, 12"x12" White w/ Brown 01 2426 SF Main Off., Tchrs Tlt Miscellaneous No None 0 Streaks VFT Across from 109. Lunchroom 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

4170

Building ID:

02	12"x12" Beige w/ White Streaks VFT	800	SF	Room 301 & Wardrobe	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:	-									
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12"x12" Brown w/ Tan Streaks VFT	120	SF	Room 205 & Library Wardrobe (Under Carpet) Not Observed		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

X NO
_

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Beige w/ Brown Streaks VFT	450	SF	Auditorium Stage and Stage Stairs, Room 003		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Oracle Unit: 23921

06	Battleship Green Linoleum - NOT OBSERVED			Room 107 NOT OBSERVED		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	J											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	-											
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
07	12"x12" Light Green w/ Brown Streaks VFT - NOT	500	SF	Room 001		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

OBSERVED

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material

Quantity

Material

Units

08	9"x9" Red VFT	100	SF	Room 003	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:	o Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	2'x4' White Wormy Ceiling Tile (Tectum)	750	SF	Room 302		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12"x12" White w/ Brown Streaks VFT Mastic	1302	SF	3rd Flr. Tchrs Toilet & Lounge, Rm 004., 108, Main Off., Tchrs Tlt Across from 109, Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Gray w/ Black Streaks VFT Mastic - NOT OBSERVED	420	SF	Principal's Office & Vestibule (under carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	У
14	Battleship Green Linoleum Mastic (Not Observed)	750	SF	Room 107 (Not Observed)		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change]							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Transite Wall Panel	640	SF	Kitchen Storage, Tank Room (Behind Drywall)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

16	2"x18" Border Black VFT	25	SF	Room 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change				-							
Comments:	J											
2017 - Fall: N	No Change				-							
Comments:												
2018 - Fall: N	No Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

17	Streaks VFT - NOT OBSERVED	50	SF	Tile/Wood) NOT OBSERVED
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

Material

Quantity

Material

Units

Material Location

Room 002 (Under

HA No

Material Description

9"x9" Brown w/ Red

YES

X NO

18	9"x9" Green w/ White Streaks VFT	1000	SF	Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26)		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change		<u> </u>	<u> </u>]						
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:	-										
2018 - Fall:	No Change										
Comments:	-										
1					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Beige w/ White Streaks VFT Mastic	800	SF	Room 301 & Wardrobe		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Type	Category		Type	Quantity	Units		
20	9"x9" Green w/ White Streaks VFT Mastic ABATED (2013)			Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26) - NOT OBSERVED ABATED (2013)		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:]							
2017 - Fall:	No Change				-							
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	12"x12" Brown w/Tan Streaks VFT Mastic			Room 205 & Library Wardrobe		Miscellaneous					YES	X NO

Material

Asbestos

Friable

Damage

Damage

HA No

Material Description

ABATED (2013)

Material

Material Location

ABATED (2013)

Damage Change in Assessment Category

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22		9"x9" Beige w/ Brown Streaks VFT Mastic	450	SF	Auditorium Stage and Stage Stairs, Room 003		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	2"x18" Border Black VFT Mastic	25	SF	Room 003		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

24	9"x9" Red VFT Mastic	750	SF	Room 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

25	Streaks VFT Mastic (Under Wood) - NOT OBSERVED	50	SF	Room 002 NOT OBSERVED
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
		•		

HA No

Material Description

9"x9" Brown w/ Red

Material

Quantity

Material

Units

Material Location

Room 002 NOT

YES

X NO

26	12"x12" Light Green w/ Brown Streaks VFT Mastic - NOT OBSERVED	500	SF	Room 002, 001 NOT OBSERVED		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	o Griango										
2017 - Spring	: No Change										
Comments:	. No Orlange										
2018 - Fall: N	o Chango										
Comments:	o Change										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Blue VFT	50	SF	Principals Toilet		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

28	12" x 12" Blue VFT Mastic	50	SF	Principals Toilet	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change	·								
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Asbestos

Type

Material

Material

Category

Category

Friable

Friable

Damage

Damage

Туре

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

29	12" x 12" Peach VFT	1500	SF	Lunchroom	Miscellaneous	No	None	0
	II: No Change							
Comment	s:							
2017 - Fa	II: No Change							
Comment	is:							
2017 - Sp	ring: No Change							
Comment	s:							
2018 - Fa	II: No Change							

Material Location

HA No

HA No

Comments:

Material Description

Material Description

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Change in Assessment Category

Change in Assessment Category

YES

X NO

30	12" x 12" Peach VFT Mastic	1500	SF	Lunchroom		Miscellaneous	No	None	0	YES	X NO
					i						
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	j: No Change										
Comments:	•										
2018 - Fall: N	lo Change										

Type

Material

Category

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12 x 12 inch Light Blue w/White Specks VFT	650	SF	Room 002		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

31A	12 x 12 inch Light Blue w/White Specks VFT Mastic	650	SF	Room 002		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			·							
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:	,										
2018 - Fall: N	lo Change										
Comments:											
					l						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Carpet Mastic	1000	SF	Main Office, Rooms 005, 205		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33	12 x 12 Tan Floor Tile	750	SF	Room 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				-							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12 x 12 Tan Floor Tile Mastic	750	SF	Room 108		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
35	12 x 12 Grey Floor Tile	60	SF	Main Office, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12 x 12 Grey Floor Tile Mastic	60	SF	Main Office, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

07	12 % 12 ********************************		J	Girls Washrooms		····ocoilai iocac			, and the second			
2016 - Fall	: No Change				1							
Comments					-							
2017 - Spri	ing: No Change				-							
Comments					1							
2017 - Fall:	: No Change											
Comments	:]							
2018 - Fall:	: No Change											
Comments	:				-							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment	Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

	Ollis Washiloonis
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Quantity

2500

Units

SF

HA No

37

38

Material Description

12 x 12 White Floor Tile

12 x 12 White Floor Tile

Mastic

Material

Units

SF

Material

Quantity

2500

Material Location

1st and 2nd Floor

1st and 2nd Floor

Girls Washrooms

Corridors, 1st Boys and

Corridors, 1st Boys and

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
39	12 x 12 Yellow Floor Tile	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	NO
2016 - Fall: N	lo Change											

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
40	12 x 12 Floor Tile Mastic	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 20

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (ategory
41	12 x 12 Blue Floor Tile	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X	10
2016 - Fall: N	lo Change				1							-

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12 x 12 Blue Floor Tile Mastic	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
43	12 x 12 Green Floor Tile	250	SF	Teacher's Toilets across Room 109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12 x 12 Green Floor Tile Mastic	250	SF	Teacher's Toilets across Room 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (ategory
45	12 x 12 Light Blue Floor Tile	650	SF	Room 002		Miscellaneous	No	None	0		YES X	10
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12 x 1 2 Light Floor Tile Mastic	650	SF	Room 002		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
47	12 x 12 Royal Blue Floor Tile	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	2017 - Fall: No Change											

Comments:

2017 - Spring: No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12 x 12 Royal Blue Floor Tile Mastic	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
49	12 x 12 Off White Floor Tile	900	SF	Room 001		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ig: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall	No Change				\exists							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12 x 12 Off White Floor Tile Mastic	900	SF	Room 001		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

51	Terrazzo	1800	SF	Room 005, vestibules, 1st Floor Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				7							
Comment												
2017 - Fa	II: No Change											
Comment	S:											
	ring: No Change											
Comment	S:				_							
2018 - Fa	II: No Change											
Comment	S:											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Yes

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

52	Ceramic Tile Grout	1300	SF	and Basement Restroom							
			•	•							
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:	Comments:										
2017 - Fall: N	o Change										
Comments:											
2018 - Fall: No Change											
Comments:											

Quantity

1300

Units

SF

Material

Units

Material

Quantity

Material Location

2nd Floor Restroom (206)

HA No

52

Material Description

Ceramic Tile Grout

Change in Assessment Category

X NO

53	Ceramic Tile Adnesive	1300	SF	and Basement Restroom		Miscellaneous	NO	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>				1							
2017 - Spring	g: No Change											
Comments:					-							
2017 - Fall: N	lo Change				-							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

53

D

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Ceramic Tile Adhesive

Mag Block Breeching ABATED (2016)

Material

Quantity

1300

Material

Units

SF

Material Location

2nd Floor Restroom (206)

Boiler Room ABATED

Change in Assessment Category

X NO

X NO

YES

YES

Е	Aircell Pipe Insulation	150	LF	Passage by Rm. 003, Tank Room, Lunchroom/Kitchen		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change				_						
Comments:											
2017 - Fall: N	lo Change										
Comments:	-										
2018 - Fall: N	lo Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	F	MJP E/F/V on Aircell Pipe Insulation	40	LF	Passage by Rm. 003, Tank Room, Lunchroom/Kitchen		TSI	Yes	None	0		YES	X NO
H	2016 - Fall: No Change												
Į	Comments:												

2017 - Fall: No Change
Comments:

2017 - Spring: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

2018 - Fall: No Change Comments:

G	Mag Block Insulation	40	LF	Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room		TSI	Yes	None	0	YES	X NO
2016 - Fall	: No Change										
Comments											
2017 - Fall	: No Change										
Comments	:										
2017 - Spring: No Change											
Comments	:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	MJP E/F/V on Mag Block Insulation	5	LF	Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

I	Cardboard Pipe Insulation ABATED (2013)	Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets - ABATED (2013)		TSI	None		YES	X NO
2016 - Fall: N	o Change							
Comments:								
2017 - Spring	: No Change							
Comments:								
2017 - Fall: N	lo Change							
Comments:	-							
2018 - Fall: N	o Change							
Comments:	-	7						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	MJP E/F/V on Cardboard Pipe Insulation	7	LF	Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
К	MJP E/F/V on Fiberglass Pipe Insulation	68	LF	Throughout (See Hatching)		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Aircell Duct Insulation	1200	SF	Lunchroom/Kitchen		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	Mag Block Duct Insulation	1070	SF	Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Friedrich L. Jahn Elementary of the Fine Arts
Date: 1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23921

SCHOOL'S ASBESTOS MANAGEMENT PLAN.