Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

School:

23931

Minnie Mars Jamieson Elementary School **Oracle Unit: Building ID:** Address: 5650 N Mozart Street Region: 01 Mail Room: Asbestos Surveyor: Guerra, Jason X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: jguerra26@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 2nd & 3rd Floor Hall -YES 01 SF X NO 9"x9" Red VFT 2100 Miscellaneous No None 0 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

4180

03	Brown Linoleum	500	SF	Room 307 - 1937	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
04	9"x9" Red VFT Mastic	1490	SF	2nd & 3rd Floor Hall- 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change											

Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Comments:

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
06	Brown Linoleum Mastic	500	SF	Room 307 - 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:	<u> </u>				-							
2017 - Fall: I	No Change											
Comments:					_							
2017 - Sprin	g: No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Gray w/ Pink, White, & Black Streaks VFT	2500	SF	1st & 2nd Floor Hall - 1954		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

09	12"x12" Gray w/ Pink, White & Blk Strks VFT Mastic	2500	SF	1st & 2nd Floor Hall - 1954		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			•]						
Comments:	to change				-						
2017 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change				-						
Comments:	J										
2018 - Fall: N	lo Change										
Comments:											
]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11	12"x12" Beige w/ White & Black Streaks VFT	4000	SF	Rooms 112, 114, 116, 216, & 212 - 1954 NOT OBSERVED		Miscellaneous	No		0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
12	12"x12" Gray w/ White Streaks VFT	2400	SF	Rooms 111, 213, & 211 - 1954 NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	¥]							
2017 - Fall: N	No Change											
Comments:					1							
2017 - Spring	g: No Change											
Comments:					 -							
2018 - Fall: N	No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Green w/ White Streaks VFT	1200	SF	Room 215 - 1954		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

Comments:

15	12"x12" Light Brown w/ White & Brown Streaks VFT	2430	SF	Rooms 305, & 1st Floor Hall -1937		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change		<u> </u>]		·				
Comments:	<u> </u>										
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:	•										
2018 - Fall: N	lo Change										
Comments:	-										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	9"x9" Black VFT	1490	SF	2nd & 3rd Floor Halls -1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
17	7	6"x18" Black VFT	400	SF	2nd & 3rd Floor Hall -1937		Miscellaneous	No	None	0		YES	X NO
	16 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Beige w/ White Spots VFT	750	SF	Lunchroom -1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Gray VFTNOT OBSERVED	300	SF	Main Office -1937 (Under HA # 46)		Miscellaneous	No		0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Tan LinoleumNOT OBSERVED	1500	SF	Room 115 -1954, Under Carpet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Beige w/ White & Black Streaks VFT Mastic	4500	SF	Rooms 112, 114, 116, 214, & 212 -1954-		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9"x9" Beige w/ Black Streaks VFT	235	SF	Engineer's Office & Bathroom -1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9"x9" Beige w/ Black Streaks VFT Mastic	235	SF	Engineer's Office & Bathroom -1937		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Gray w/ White Streaks VFT Mastic	800	SF	Room 111, -1954-		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

26	12"x12" Green w/ White Streaks VFT MasticNOT OBSERVED	1200	SF	Room 215 -1954NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
	-	*	•	-	1	•	•	•	•	•	•	
2016 - Fall:	No Change											
Comments												
2017 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
2018 - Fall:	No Change		•									
Comments												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Light Brn w/ White & Brn Strks VFT Mastic	2430	SF	Rooms 305, & 1st Floor Hall -1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

12"x12" Green w/ White

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	9"x9" Black VFT Mastic	1490	SF	2nd & 3rd Floor Halls -1937		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	6"x18" Black VFT Mastic	1490	SF	2nd & 3rd Floor Halls -1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 12

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Beige w/ White Spots VFT Mastic	750	SF	Lunchroom -1937		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	9"x9" Gray VFT Mastic NOT OBSERVED	300	SF	Main Office -1937 (Under New HA# 46)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	itegory
34	Tan Linoleum MasticNOT OBSERVED	800	SF	Room 115 -1954 NOT OBSERVED		Miscellaneous	No	None	0		YES X NO	O
2016 - Fall: N	lo Change				1							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12" x 12" White w/ Beige Spots VFT	5000	SF	Throughout -1999 Modular		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" White w/ Beige Spots VFT Mastic	5000	SF	Throughout - 1999 Modular		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	2' x 2' White w/ Grooves Ceiling Tile	5000	SF	Throughout -1999 Modular		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

										L	
38	12" x 12" Blue VFT	2200	SF	Auditorium -1937		Miscellaneous	No	None	0	YES	X NO
		•	•		1	•	•				
2016 - Fall:	No Change										
Comments											
Commonto											
2017 Falls	No Change										
2017 - Fall.	No Change										
Comments:											
2017 - Spri	ng: No Change										
Comments:											
2018 - Fall:	No Change	•	•								

Material

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9	12" x 12" Blue VFT Mastic	2200	SF	Auditorium -1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12'x12" Light Gray w/ Gray SpecksNOT OBSERVED	800	SF	Room 211 NOT OBSERVED		Miscellaneous	No	None	0		YES X NO
0040 Fall N	- Ohana										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12'x12" Light Gray w/ Gray Specks VFT Mastic	800	SF	NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Light Blue w/ White Specks VFT	800	SF	Basement Teacher's Lounge		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Light Blue w/ White Specks VFT Mastic	800	SF	Basement Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 18

2016 - Fall: N	No Change										
	10 Change										
Comments:											
2017 - Fall: N	No Change										
Comments:	10 Ondrigo										
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
1		Quantity	Units		Type	Category	1	Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

44

45

Comments:

Comments:

Comments:

Comments:

Material Description

Carpet Mastic

Terrazzo

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

2100

500

Material

Units

SF

SF

Material Location

(1954 Bldg).--

Stairs, 1954 Bldg

Rooms 214,113, and 115

Change in Assessment Category

X NO

X NO

YES

YES

46	12"X12" Blue Streaked VFT	800	SF	Main Office, 1937 Bldg	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	g: No Change									
2017 - Fall: N Comments:	lo Change									
2018 - Fall: N Comments:	lo Change									

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46A	12"X12" Blue Streaked VFT Mastic	800	SF	Main Office, 1937 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

Material

Quantity

Material

Units

Material Location

HA No

Material Description

2016 - Fall: I	No Change										
Comments:	<u> </u>										
2017 - Fall: I	No Change										
Comments:					_						
2017 - Sprin	g: No Change										
Comments:					_						
2018 - Fall: I	No Change										
Comments:					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Material

Surface

Category

Miscellaneous

Friable

No

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

0

Material

Quantity

500

Material

Units

SF

SF

Gym

Material Location

Auditorium

HA No

47

48

Material Description

Decorative Plaster

2'X4' Ceiling Tiles

Change in Assessment Category

X NO

X NO

YES

YES

49	Fire Doors	2		Room		Miscellaneous	NO	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Fall: N	lo Change				-							
Comments:					-							
2017 - Spring	g: No Change				-							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Surface

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

49

50

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Textured Ceiling Paint

Fire Doors

Material

Quantity

2

Material

Units

SF

300

Material Location

1999 Mobile Mechanical

Restrooms, 1999 Mobile

Change in Assessment Category

X NO

X NO

YES

YES

51	Vinyl Baseboard Mastic	600	LF	Throughout 1999 Mobile		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Fall	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
52	Terrazzo	12000	SF	2004 Addition, 1st, 2nd, and 3rd Floor Hallways,		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

-

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

Material Description

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Stairwells

Material

Units

Material Location

53	Fire Doors	3		Stairwells, 2004 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Yes

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

30000

Material

Quantity

Material

Units

SF

Material Location

2004 Addition,

Throughout

HA No

54

Material Description

2'X4' Ceiling Tiles

YES

X NO

55	Compound	500	SF	2004 Addition, Columns		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	3:											
	: No Change											
Comments	3:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

Yes

No

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

56	Fire doors	6	EA	projector room
				·
2016 - Fal	I: No Change			
Comments	3:			
2017 - Fal	I: No Change			
Comments	3:			
2017 - Spi	ring: No Change			
Comments	3 :			
2018 - Fal	I: No Change			
Comments	3:			
	-			•

6

Quantity

Units

EΑ

Material

Units

SF

Material

Quantity

500

Material Location

2004 Addition, Columns

Auditorium, balcony,

HA No

55

56

Material Description

Drywall, Tape, and

Fire doors

Change in Assessment Category

X NO

X NO

YES

YES

57	1'x1' Ceiling Tile with Grooves	3000	SF	Auditorium and auditorium balcony		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall:	: No Change										
Comments	:										
2017 - Spri	ng: No Change										
Comments	:										
	: No Change										
Comments	:										
	: No Change										
Comments	:										
					I						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
58	Decorative Plaster trim	1500	SF	Auditorium and Auditorium balcony		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

Material

Quantity

Material

Units

HA No

Material Description

59	PyrobarNOT OBSERVED	900	SF	1954 addition east wall between buildings		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change				_							
Comments:					1							
2017 - Spring	: No Change											
Comments:	<u> </u>											
2018 - Fall: N	o Change				-							
Comments:	J											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

mastic		
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

1500

SF

Material

Quantity

Material

Units

Material Location

room 212 and 216

HA No

60

Material Description

VFT 12"x12" Light gray w/

white and gray streaks with

YES

X NO

61	Drywall System	2400	SF	Gym Ceiling		Miscellaneous	Yes	None	0		YES	X_NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Yes

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

С	Boiler Rope #1NOT OBSERVED	0	LF	Boiler Room -1937							
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	2017 - Spring: No Change										
Comments:											
2017 - Fall: N	o Change		<u>.</u>								
Comments:											
2018 - Fall: N	o Change										
Comments:											

Material

Quantity

Material

Units

Material Location

HA No

Material Description

YES

X NO

		_			0 ,				1	
СС	MJP E/F/V on Aircell Pipe Insulation	40	LF	Unexcavated Area -1954	TSI	Yes	Loc	0	YES	X NO
2016 - Fall	: No Change									
Comments	:									
2017 - Spr	ing: No Change									
Comments	:									
2017 - Fall	: No Change									
Comments	:									
2018 - Fall	: No Change									

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
О	Boiler Rope #2NOT OBSERVED	0	LF	Boiler Room -1937		TSI	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

											1
2016 - Fall:	No Change										
Comments:											
2017 - Fall: No Change											
Comments:											
2017 - Sprir	ng: No Change										
Comments:	<u> </u>										
2018 - Fall:	No Change				_						
Comments:	•										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

TSI

Asbestos

Type

Material

TSI

Category

Friable

Yes

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

325

Material

Quantity

250

Material

Units

LF

LF

Material Location

Unexcavated Area -1954

Unexcavated Area -1954

HA No

DD

ΕE

Material Description

Aircell Pipe Insulation

Cardboard Pipe Insulation

Change in Assessment Category

X NO

X NO

YES

YES

F	Aircell Pipe Insulation	200	LF	Boiler Room -1937	TSI	Yes	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:	o Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FF	Wicking Pipe Wrap on Coils	40	LF	Coil Area -1937		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
GG	MJP E/F/V on Fiberglass Pipe Insulation	60	LF	Unexcavated Area -1954		TSI	Yes	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:				-							
2017 - Spri	ing: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments	:]							
2018 - Fall:	: No Change				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	MJP E/F/V on Cardboard Pipe Insulation	80	LF	Throughout (See Hatching Maps) - 1937		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 32

НН	MJP E/F/V on Cardboard Pipe Insulation	30	LF	Unexcavated Area -1954		TSI	Yes	None	0	YES	X NO
2016 - Fall	I: No Change				1						
Comments											
2017 - Spr	ring: No Change				1						
Comments]						
2017 - Fall	I: No Change				1						
Comments											
2018 - Fall	I: No Change				-						
Comments											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I		MJP E/F/V on Aircell Pipe Insulation	110	LF	Throughout (See Hatching Maps) - 1937		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	Tank Insulation	0	SF	Boiler Room & Store Room -1937		TSI	Yes	None	0		YES X NO
0040 Fall N	- Ohana				1					•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	MJP E/F/V on Fiberglass Pipe Insulation	0	LF	Boiler Room -1937		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments: Elbows abated during domestic water pipe replacement.
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category	
S	Aircell Pipe Insulation	1200	LF	Throughout (See Hatching Maps) - 1937		TSI	Yes	None	0		YES	X NO	
2016 - Fall: No Change Comments:													_

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Т	Cardboard Pipe Insulation	900	LF	Throughout (See Hatching Maps) - 1937		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

W	Aircell Duct Insulation	400	SF	Unexcavated Area -1937		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•]							
2017 - Fall: N	lo Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:					<u> </u>							
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Yes

Damage

Type

None

Damage

Quantity

0

Damage

Units

20

HA No

Ζ

Comments:

Material Description

Boiler Gasket

2016 - Fall: No Change

Material

Quantity

Material

Units

LF

Boiler Room

Material Location

YES

Change in Assessment Category

X NO

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Minnie Mars Jamieson Elementary School
Date: 1/9/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23931

SCHOOL'S ASBESTOS MANAGEMENT PLAN.