Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

	School: Address:	John H Kinzie Elementary School 5625 S. Mobile		Oracle Unit: Region:	24071 04	Building ID: Mail Room:	4330 44
X CHECK	HERE IF	NO CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date:	Oconnell, Thomas 1/11/2019			
			Email Address:	toconnell2@cps.edu			
	Each chil	ld's backpack Notice printed in sc	hool's newsletter	Notice printed in school's	calendar	Other	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	boiler insulation (1956)- ABATED			boiler room		TSI					YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Pre-form pipe insulation (1956)-ABATED			boiler room		TSI					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	paper wrap pipe insulation (1956)-SEE NOTES			1st & 2nd floor janitor's closet		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	aircell pipe insulation (1956)-SEE NOTES			mechanical room, 2nd floor fan room, 1st floor gym		TSI					YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
Commente.	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9x9 tan floor tile (1959)	1610	SF	1st & 2nd floor janitor's closet & room 220		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9x9 tan floor tile mastic (1959)	1610	SF	1st & 2nd floor janitor's closet & room 220		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	hard-coat plaster	25000	SF	throughout building (1956)		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	hard-coat plaster	7000	SF	throughout building (1959)		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	transite wall panel			1st & 2nd floor classrooms		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	wall panel suspected transite			1st & 2nd floor classrooms (1959)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	transite table top	100	SF	room 220 (1959)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
,	18	vibration damper	10	SF	2nd floor fan room		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	vibration damper	10	SF	basement fan room (1959)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	brown carpet mastic	700	SF	rooms 211,208,218		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	green carpet mastic	600	SF	room 124 (1959)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	orange carpet mastic	700	SF	room 206 (1956)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	GREEN carpet mastic	750	SF	room 215 (1959)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	GREEN carpet mastic	14125	SF	rooms:201-205,207- 210,212,214,216		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	brown carpet mastic (1959)	5955	SF	rooms: 117,119,121,123,128,213 ,219,221,223,225		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	baseboard (1956)	70	LF	classroom 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	baseboard mastic	70	LF	classroom 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12x12 off white floor tile (1956)	320	SF	classroom 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12x12 off white floor tile mastic (1956)	320	SF	classroom 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12x12 beige floor tile (1956)	5550	SF	gym lunch room & kitchen corridor		Miscellaneous	No	Loc	12		

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12x12 beige floor tile mastic (1956)	5550	SF	gym lunch room & kitchen corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12x12 beige floor tile (1959)	3250	SF	Room 222		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12x12 tan floor tile (1956)	7720	SF	1st floor teach lunch room, south corridor, room 101, 2nd floor teacher room corridor		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12x12 tan floor tile mastic (1956)	6785	SF	1st floor teach lunch room, south corridor, room 101, 2nd floor teacher room, corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	9x9 brown floor tile (1956)	935	SF	1st & 2nd floor corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	9x9 brown floor tile mastic (1956)	935	SF	1st & 2nd floor corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12x12 brown floor tile (1959)	3250	SF	1st & 2nd floor corridor		Miscellaneous	No	Loc	14		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12x12 brown floor tile mastic (1959)	3250	SF	1st & 2nd floor corridor		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12x12 dark brown floor tile (1956)-SEE NOTES	750	SF	classroom 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12x12 dark brown floor tile mastic (1956)-SEE NOTE	750	SF	classroom 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12x12 dark brown floor tile (1959)-NOT OBSERVED			music room (basement)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12x12 dark brown floor tile mastic (1959)-ABATED			music room (basement)		Miscellaneous					YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	tank insulation (1956)- ABATED			boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12x12 white w/blue specks vft	500	SF	1st and 2nd fl. Elevator lobby		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12x12 white w/blue specks mastic	500	SF	1st & 2nd floor elevator lobby		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	2x4 white ceiling tile	1550	SF	music room (basement)		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Purple Carpet Mastic	650	SF	Rooms 113 and 117		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Grey Multicolored Carpet Mastic	1600	SF	Rooms 102, 131,221,227		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12"x12" Blue w/Specks VFT	800	SF	Rooms 108 and 115		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50A	12"x12" Blue w/Specks VFT Mastic	800	SF	Room 108 and 115		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Blue and Tan Multicolor Carpet Mastic	675	SF	Room 106 and 111		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" x 12" Tan w/ Specks Floor Tile	780	SF	Room 200		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Mastic Associated w/ 12" x 12" Tan w/ Specks Floor Tile	780	SF	Room 200		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	paper wrap pipe insulation (1959)	24	LF	1st floor janitors closet		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change
0
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	aircell pipe insulation (1959)-SEE NOTES ABATED			Gym, room 105, crawlspace, storage room, play room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	boiler door packing (insulation) 1956-ABATED			boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	incinerator insulation (1956) -ABATED			boiler room (door welded shut)		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	fittings on fiberglass insulation	20	FITTING	base, play room, boiler room, crawl space		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	fittings on fiberglass insulation	45	FITTING	base play room, storage room, girls locker room, crawl space		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	fittings on pre-form insulation-ABATED		Fittings	boiler room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
н	fittings on paper wrap insulation-SEE NOTES		Fittings	boiler room, 1st & 2nd floor janitor's closet		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	fittings on aircell insulation- SEE NOTES		Fittings	open crawlspace, boiler mechanic room, 2nd floor fan room, 1st floor gym		TSI					

2016 - Fall: No Change	
Comments:	
2047 Caring No Change	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	fittings on paper wrap insulation	12	FITTING	1st floor janitor's closet		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
к	fittings on aircell insulation- SEE NOTES ABATED		Fittings	boys & girls locker room, play room , storage room, room 105		TSI					YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Black Coating on Sink	750	SF	Room: 102,104,112,114,117,118 , 123,125,127,129,120,131		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	John H Kinzie Elementary School	

Date: 9/3/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

CHECK ONE

A copy of this notice was sent home in each child's backpack	ί.
--	----

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.