Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

	School: Address:	Abraham Lincoln Elementary School 615 W. Kemper Place		Oracle Unit: Region:	24191 02	Building ID: Mail Room:	4480 33
Х СНЕСК Н	ERE IF N	NO CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date:	Serowski, Daniel 1/10/2019			
			Email Address:	dserowski2@cps.edu			

	A copy of the2016/20	17 notice to p	arents and	I staff regarding the a	sbestos manag	ement plan not	ifications w	as distribute	d via:			
	Each child's backpack			orinted in school's ne	Notice printed in school's calendar X Other emailing it to everyon							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
03	Carpet Mastic	1200	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
Comments 2017 - Spi Comments	ring: No Change s: I: No Change											
Comments	I: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" White VFT - NOT OBSERVED	6500	SF	Throughout - 1894 Bldg NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Beige VFT - NOT OBSERVED	250	SF	Engineer's Office, Kitchen Storage - 1894 Bldg NOT OBSERVED		Miscellaneous	No		0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" White VFT Mastic - NOT OBSERVED	50	SF	Throughout - 1894 Bldg (See Hatching Maps) NOT OBSERVED		Miscellaneous	No		0		YES XNO

· · · · · · · · · · · · · · · ·
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Beige VFT Mastic - NOT OBSERVED	250	SF	Engineer's Office, Kitchen Storage 1894 Bldg NOT OBSERVED		Miscellaneous	No		0		YES X NO

	· · · · · ·
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x9" Black VFT - NOT OBSERVED	250	SF	Engineers Office, Kitchen Storage - 1894 Bldg NOT OBSERVED		Miscellaneous	No		0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9"x9" Black VFT Mastic - NOT OBSERVED	250	SF	Engineers Office, Kitchen Storage - 1894 Bldg NOT OBSERVED		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
0	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Off White VFT	4000	SF	1st, 2nd & 3rd Floor Corridors, 303 - 1939 Blda		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Off White VFT Mastic	4000	SF	1st, 2nd & 3rd Floor Corridors, Rm 303 - 1939 Bldg		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Hard Coat Plaster	38000	SF	Throughout - 1939 Bldg		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" White w/ Tan Specks VFT	1900	SF	Basement Corridor, Room 007 (Not Observed) - 1894 Bldg		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" White w/ Tan Specks Mastic	1900	SF	Basement Corridor; (Room 007 NOT OBSERVED)- 1894 Bldg		Miscellaneous	No	None	0		YES X NO

	-
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2010 Caring No Change	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12" x 12" CT w/grooves	5000	SF	Corridors in Bldg 1894		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	16	2x4 Ceiling Tiles with Holes	350	SF	Room 009 Basement (Bldg 1894)		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change								
Comments:								
2017 - Spring: No Change								
Comments:								
2017 - Fall: No Change								
Comments:								
2018 - Spring : No Change								
Comments:								
2018 - Fall: No Change								
Comments:								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Terrazo	8800	SF	Link between bldgs 1894 and 1939 stairwells		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Ceramic Tile Grout	2400	SF	Restrooms Main Office		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Ceramic Tile Adhesive	2400	SF	Restrooms and Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Cream Colored Floor Tile	120	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Cream Colored Floor Tile Mastic	120	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Tan Floor Tile	60	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Tan Floor Tile Mastic	60	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12 x 12 Off White VFT	5400	SF	3rd Floor Corridor, Rm 309, 2nd Floor Corridor, Rm 209, 1st Floor Corridor, Room 012- 1894 Bldn		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12 x 12 Off White VFT Mastic	5400	SF	3rd Floor Corridor, Rm 309, 2nd Floor Corridor, Rm 209, 1st Floor Corridor, Room 012- 1894 Blda		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12 x 12 CT with Grooves	6900	SF	3rd Flr Corridor, 2nd Flr Corridor, 1st Flr Corridor, Walls in Assembly Hall		Miscellaneous	Yes	None	0		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24191 Page 13

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12 x 12 Beige Speckled VFT	2000	SF	1894 Bldg: Supply Room; Rooms 107 & 111		Miscellaneous	No	None	0		

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12 x 12 Beige Speckled Mastic	2000	SF	1894 Bldg: Supply Room; Rooms 107 & 111		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Carpet mastic (Carpet Tile Gray with Stripe Pattern)	1800	SF	Room 108 & 110 (Library)		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Cream w/ Streaks VFT - 1894 Bldg	50	SF	Basement, 1st, 2nd, and 3rd Floor Corridor to the New Bldg		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" Cream w/ Streaks VFT Mastic - 1894 Bldg	50	SF	Basement, 1st, 2nd, and 3rd Floor Corridor to the New Bldg		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	20"X20" Stone Pattern VFT	2200	SF	Rooms 008, 009, and 111A - 1894 Bldg		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:annex construction
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	20"X20" Stone Pattern VFT Mastic	2200	SF	Rooms 008, 009, and 111A - 1894 Bldg		Miscellaneous	No	None	0		

2016 - Fall: Abated	
Comments:annex construction	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	20"X20" Stone Pattern VFT	400	SF	Room 105 - 1939 Bldg		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:annex construction
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	20"X20" Stone Pattern VFT Mastic	400	SF	Room 105 - 1939 Bldg		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated	
Comments:annex construction	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Cardboard Pipe Insulation	235	LF	Pump, Sprinkler & Boiler Rooms, Bsmt Storage Room Office & Toilet, Mech. Rm South of Fan Room - 1894		TSI	Yes	None	0		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
с	Aircell Pipe Insulation	320	LF	Bsmt Boys Toilet, Storage Office Toilet, Mech Rm South Of Fan Rm, Eng Off, Pump & Boiler Rms - 1894		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Mag Block Pipe Insulation	200	LF	Mech Room South of Fan Room, Pump Room, Janitor's closet on 2nd floor - 1894 Bldg		TSI	Yes	None	0		

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	MJP E/F/V on Mag Block Pipe Insulation	8	LF	Mech Room South of Fan Room, Pump Room - 1894 Bldg		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Cardboard Pipe Insulation	33	LF	Pump, Sprinkler & Boiler Rooms, Bsmt Storage Room Office & Toilet, Mech. Rm South of Fan Room - 1894		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	MJP E/F/V on Aircell Pipe Insulation	18	LF	Bsmt Boys Toilet, Storage Office Toilet, Mech Rm South Of Fan Rm, Eng Off, Pump & Boiler Rms - 1894		TSI	Yes	None	0		YES XNO

2010 Falls No Change	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
н	MJP E/F/V on Fiberglass Pipe Insulation	80	SF	Storage Office Toilet, Bsmt Boys & Girls Toilets, Mech Rm S of Fan Rm, Pump and Boiler Rooms - 1894		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HAI	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I		Aircell Duct Insulation	2500	SF	Crawlspace - 1939 Bldg		TSI	Yes	Dist	20		X YES NO

2016 - Fall: Damaged								
Comments:per 3 year survey								
2017 - Spring: No Change								
Comments:								
2017 - Fall: No Change								
Comments:								
2018 - Fall: No Change								
Comments:								
2018 - Spring : No Change								
Comments:								

Oracle Unit: 24191 Page 23

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Aircell Pipe Insulation	3000	LF	1st-3rd Flr Boys & Girls Toilet Chases, 2nd Fl Mech Rm, Tunn., Crwlspce,Bsmt Cor, Fan Rm - 1939 Bldo		TSI	Yes	Dist	20		

2016 - Fall: Damaged
Comments:per 3 year survey
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
к	MJP E/F/V on Aircell Pipe Insulation	450	LF	1st-3rd Flr Boys & Girls Toilet Chases, 2nd Fl Mech Rm, Tunn., Crwlspce,Bsmt Cor, Fan Rm - 1939 Bldg		TSI	Yes	Dist	20		X YES NO

2016 - Fall: Damaged	
Comments:per 3 year survey	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Cardboard Pipe Insulation	2000	LF	Sub-Basement Corridor, Fan Rm, Crawlspace, Tunnel, 1st Fl Janitors Closet - 1939 Bldg		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	MJP E/F/V on Cardboard Pipe Insulation	250	SF	Sub-Basement Corridor, Fan Rm, Crawlspace, Tunnel - 1939 Bldg		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2047 Falls No Change	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Oracle Unit: 24191 Page 26

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Ν	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	Sub-Basement Corridor - 1939 Bldg		TSI	Yes	None	0		

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Abraham Lincoln Elementary School
Date:	1/10/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

CHECK ONE

A copy of this notice was sent home in each child's backpack.

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child



Other. emailing it to everyone

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.