Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Marquette Elementary School 24341 4620 School: **Oracle Unit: Building ID:** 6550 S. Richmond Address: Region: 05 Mail Room: Asbestos Surveyor: Amos, Jerome X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: jamos3@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 9x9 green floor tile -1925 - 1st & 2nd floor YES 02A X NO Miscellaneous Dist checker board pattern corridors 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

2016 - Fall	: No Change				\neg						
Comments											
2017 - Fall	: No Change										
Comments	:										
2017 - Spri	ing: No Change										
Comments	:										
2018 - Fall	: No Change										
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Dist

None

0

Damage

Quantity

Damage

Units

Material Location

1925 - 1st & 2nd floor

1926 - office - public area

corridors

120

HA No

02B

03A

Material Description

9x9 tan & red floor tile -

checker board pattern

12x12 rose floor tile

Material

Quantity

Material

Units

SF

Change in Assessment Category

X NO

X NO

YES

YES

											· I
0040 = "	N. O.				7						
	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprii	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

720

Material

Quantity

400

Material

Units

SF

SF

Material Location

book room

1926 - room 117

1926 - office store room,

HA No

03B

03C

Material Description

12x12 brown floor tile

12x12 yellow floor tile

Change in Assessment Category

X NO

X NO

YES

YES

03D	12x12 green floor tile - checkerboard pattern			1926 - 1st & 2nd floor corridor north wing		Miscellaneous					YES	X NO
2016 - Fal	I: No Change											
Comment												
2017 - Sp	ring: No Change											
Comment	S:											
2017 - Fal	I: No Change											
Comment	S:				_							
2018 - Fal	l: No Change											
Comment	3:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
03E	12x12 tan floor tile -			1926 - 1st & 2nd floor		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

12x12 green floor tile -

checker board pattern

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

1926 - 1st & 2nd floor

corridor north wing

03F	12x12 gray w/brown speckles floor tile	9830	SF	1996 - 1st, 2nd, 3rd floor corridors		Miscellaneous	No	None	0		YES	X NO
0046 Fal	l. Na Obasasa				1							
	l: No Change											
Comments	S:											
2017 - Fal	l: No Change											
Comments	S:											
2017 - Spi	ing: No Change											
Comments	S:											
	-											
2018 - Fal	l: No Change											
Comments	S:											
,					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

			office, classrooms
204C Fall N	o Change		
2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Quantity

41400

Units

SF

HA No

03G

Material Description

12x12 off white w/ specks

floor tile

Material

Units

Material

Quantity

Material Location

1996 - counselor's office,

student lunchroom, main

Change in Assessment Category

X NO

		Quantity	Units		Type	Category		Type	Quantity	Units		
4	12x12 beige w/specks FT	1000	SF	link bldg-faculty center, 1st & 2nd floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Spring Comments:	: No Change											

Material

Friable

Damage

Damage

Asbestos

2017 - Fall: No Change Comments:

Material

Material Location

2018 - Fall: No Change

Material Description

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4A	12x12 beige w/specks FT mastic	1000	SF	Link Bldg-Faculty center, 1st & 2nd floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

09A	9x9 green floor tile mastic			1926 - 1st & 2nd floor coridors		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	No Change											
Comments	<u> </u>											
2018 - Fall:	No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09B	9x9 tan/red floor tile mastic			1926 - 1st & 2nd floor		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

corridor

10A	12x12 rose floor tile mastic			1926 - office - public area		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments					<u> </u>							
2017 - Spri	ng: No Change				_							
Comments	:				-							
2017 - Fall:	No Change											
Comments	:				-							
2018 - Fall:	No Change											
Comments	:											
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
10B	12x12 brown floor tile mastic			1926 - office store room, book room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

10C	12x12 yellow floor tile mastic			1926 - room 117		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:	go											
2017 - Sprir	ng: No Change				-							
Comments:												
2017 - Fall:	No Change				1							
Comments:	-											
2018 - Fall:	No Change				-							
Comments:	Ţ											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
10D	12x12 green floor tile			1926 - 1st & 2nd floor		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

corridor north wing

2016 - Fall:	No Change										
Comments:											
2017 - Sprin	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

9830

HA No

10E

10F

Material Description

12x12 tan floor tile mastic

12x12 gray w/brown

speckles floor tile mastic

Material

Units

SF

Material

Quantity

Material Location

1926 - 1st & 2nd floor

1996 - 1st, 2nd, 3rd floor

corridors

corridor north wing

Change in Assessment Category

X NO

X NO

YES

YES

10G	12x12 off white w/specks floor tile mastic	41400	SF	1996 - counselor's office, student lunchroom, main office, classrooms		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	: No Change										
Comments	S:										
	ing: No Change										
Comments	3:										
	: No Change										
Comments	S:										
2018 - Fal	: No Change										
Comments	S:										
					J						

Type

Asbestos

Type

Material

Category

Material

Category

Miscellaneous

Friable

Friable

No

Damage

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

11A	black baseboard	20	LF	1926 - gym office
2016 - Fall: N Comments:	o Change			
2017 - Spring Comments:	: No Change			
2017 - Fall: N Comments:	o Change			
2018 - Fall: N Comments:	o Change			

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Material Location

1996 - counselor's office,

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

X NO

YES

11B	peach baseboard			1996 - principal's office, conference & counselor's offices, main office		Miscellaneous					YES	X NO
0040 5.11	NI- OL				7							
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
2019 Falls	No Chango				_							
2018 - Fall:	<u> </u>											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

11C	brown baseboard	3000	LF	classrooms						
				·						
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:	, ,									
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: No Change										
Comments:										

3000

HA No

11C

Material Description

brown baseboard

Material

Quantity

Material

Units

LF

Material Location

1996 - throughout

1996 - principal's office,

YES

X NO

12A	black baseboard mastic	20	LF	1926 - gym office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Sprin	g: No Change											
Comments:					-							
2017 - Fall:	No Change											
Comments:					 -							
2018 - Fall:	No Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12B	peach baseboard mastic			1996 - principal's office, conference & counselor's		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

offices, main office

12C	brown baseboard mastic	3000	LF	1996 - throughout classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:					1							
2017 - Sprin	g: No Change											
Comments:	<u> </u>				- -							
2017 - Fall: N	No Change				1							
Comments:	Ţ											
2018 - Fall: N	No Change				1							
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
13	drywall			1926 - room 110		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

13A	drywall	120	SF	1926 gym office bathroom		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
					- 7 F -	22233.)	-	-71				

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

1926 - room 118

Material

Quantity

Material

Units

HA No

14

Material Description

burgandy linoleum

YES

X NO

15	burgandy linoleum mastic			1926 - room 118		Miscellaneous					YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Spr	ing: No Change											
Comments	:											
	: No Change											
Comments	S:				_							
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
16	Rose carpet mastic			1926 - office - behind		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

counter

17	brown carpet mastic			1926 - room 111		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18	blue carpet mastic			1926 - assembly hall		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

19	brown carpet mastic	4700	SF	1996 - principal's office, conference & counselor's offices, library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change			<u> </u>]							
Comments:	io oriarigo											
2017 - Fall: N	lo Change											
Comments:	io oriango											
2017 - Spring	ı: No Change											
Comments:	g. No Change											
2018 - Fall: N	lo Chango											
Comments:	io Change											
					j							
LIANI	Material December	Matadal	I Martanial	I Maria della conden	A -11	I santanini	Leann	D	D	D	Ob	

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	plaster	4900	SF	assembly hall (also called auditorium)		Surface	Yes	None	0		YES X NO
2016 Fall: N	o Chango										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21	12x12 red floor tile	1450	SF	rm 122, 120		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21M	Mastic for HA 21 red floor tile	1450	SF	room 120 & 122		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

22	12x12 red w/gray streaks			copy room & art room on 2nd floor		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	to Onango											
2017 - Spring	g: No Change											
Comments:	g											
2017 - Fall: N	No Change											
Comments:	J											
2018 - Fall: N	No Change											
Comments:	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22M	Mastic for 12 x 12 gray with			2nd floor art/copy room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

red streaks, HA 22

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
23	9x9 light gray floor tile	700	SF	room 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	II: No Change											
Comments	S:											
2017 - Fall	II: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											
2018 - Fall	II: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23M	Mastic for 9" x 9" light gray Floor Tile HA 23	700	SF	room 108		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

24	12x12 off white floor tile	300	SF	1926 gym office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	No Change									
Comments:										
2018 - Fall: N	No Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24M	Mastic for 12" x 12" Off- white floor tile, HA 24	300	SF	gym office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
Comments.		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
25	12x12 gray/tan w/streaks	2100	SF	rm 213, 210, 208		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25M	Mastic for 12" x 12" gray floor tile with streaks, HA 25	2100	SF	rooms 213, 210, 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 23

2016 - Fall	: No Change										
Comments					-						
2017 - Fall:	: No Change										
Comments	:				_						
2017 - Spri	ng: No Change										
Comments	:				-						
2018 - Fall:	: No Change										
Comments	:				-						
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

26M	edging HA 26	500	SF	1st floor corridor
2016 - Fall: N	No Change			
Comments:				
2017 - Spring	g: No Change			
Comments:				
2017 - Fall: N	No Change			
Comments:	-			
2018 - Fall: N	No Change			
Comments:	-			

Quantity

500

Units

SF

Material

Quantity

500

Material

Units

SF

Material Location

1st floor corridor (1926)

1st floor corridor

HA No

26

26M

Material Description

Mastic for 9" x20" black

9x9 black edging

Change in Assessment Category

X NO

X NO

YES

YES

27	2x4 ceiling tile	2350	SF	rooms 139 & 137		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No	o Change]							
Comments:	V											
2017 - Fall: No	o Change											
Comments:												
2017 - Spring:	: No Change											
Comments:					-							
2018 - Fall: No	o Change											
Comments:					<u> </u>							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
28	2x2 ceiling tile			(1996) 1st, 2nd, 3rd fl cxorridors, classrooms		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

and offices

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12x12 white	1200	SF	room 139, 137		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change			<u> </u>							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29M	Mastic for 12" x 12" Bright white foor tile , HA 29	1200	SF	room 137 & 139		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

30	12x12 dark blue w/streaks	200	SF	room 137 & 139	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	: No Change									
2018 - Fall: N Comments:	lo Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30M	dark blue mastic	200	SF	room 137 & 139		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

31	12x12 light blue w/streaks	200	SF	room 137 & 139	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
2017 - Fall: N	lo Change									
2017 - Spring	g: No Change									
Comments: 2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31M	light blue mastic	200	SF	room 137 & 139		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Material Location

Oracle Unit: 24341

32	12x12 green w/streaks	250	SF	room 137 & 139	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32M	green mastic	250	SF	room 137 & 139		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Units

Material

Quantity

Material Location

HA No

Material Description

33	12x12 fluorescent red	250	SF	room 137 & 139	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33M	red mastic	250	SF	room 137 & 139		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

34	12x12 tan w/streaks	100	SF	room 137 & 139	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34M	tan mastic	100	SF	room 137 & 139		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"X12" Beige W/Black Specks Floor Tile	5100	SF	1st and 2nd Floor Corridors, Room 120, 122, 213, 208, 210, Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35M	12"X12" Beige W/Black Specks Floor Tile Mastic	5800	SF	1st and 2nd Corridors, Room 120, 122, 213, 208, 210, Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	12"X12" Blue W/Black Specks Floor Tile	3420	SF	1st and 2nd Floor Corridors and 107A, 107		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change											

Comments:
2017 - Spring: No Change

Comments:

2018 - Fall: No Change Comments:

36M

12" x 12" Blue w/ Black

Specks Floor Tile Mastic

HA No Material Description Material Material Location Asbestos Material Friable Damage Change in Assessment Category Material Damage Damage Quantity Units Type Category Type Quantity Units

Miscellaneous

No

None

0

1st & 2nd Floor Corridor,

107A, 107

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

3420

SF

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
37	12"X12" Gray W/Black Specks Floor Tile	900	SF	1st and 2nd Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	s:											
2017 - Fall	I: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37M	12" x 12" Gray w/ Black Specks Floor Tile Mastic	900	SF	1st & 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
38	2X2 Ceiling Tile	5000	SF	Through the Annex Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:				_							
2017 - Spr	ring: No Change											
Comments	S:											
2018 - Fall	I: No Change				=							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Α	aircell pipe insulation	2000	LF	1926 - pipe chases & air tunnels		TSI	Yes	Loc	2		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

В	airceil fittings	190	LF	tunnels		181	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	g: No Change				-							
Comments:					-							
2017 - Fall: N	lo Change				- - -							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

TSI

TSI

Category

Friable

Yes

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material

Quantity

190

Material

Units

LF

Material Location

1926 - basement

1926 - pipechases & air

HA No

В

D

Material Description

aircell fittings

cardboard fittings

Change in Assessment Category

X NO

X NO

YES

YES

F	mag pipe insulation			1926 - basement		TSI					YES	X NO
2016 - Fall: No Change												
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: No Change												
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
G	mag fittings			1926 - basement		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Н	aircell duct insulation			unexcavated area		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
J	boiler gaskets - material inaccessible			1926 - boiler room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

L	incinerator insulation			inaccessible (incinerator welded shut)		TSI					YES	X NO
2016 - Ea	all: No Change				1							
					-							
Commen	ts:											
2017 - Fa	all: No Change											
Commen	ts.				1							
0011111011					1							
2017 - Sr	oring: No Change											
					1							
Comments:					_							
0040 5-	III. N. O. Charana				4							
	all: No Change											
Commen	ts:											
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
1	2 000	Quantity	Units		Type	Category	1	Type	Quantity	Units	2.13.1.92.117.100000	and a category
					71	5 - 7		71				

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Type

Damage

Quantity

0

None

Damage

Units

HA No

Μ

Comments:

Comments:

Comments:

Comments:

Material Description

aircell duct

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material

Quantity

300

SF

boiler room

Material

Units

Material Location

boiler room - material

YES

X NO

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Marquette Elementary School
Date: 1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 24341

SCHOOL'S ASBESTOS MANAGEMENT PLAN.