## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

24431

**Oracle Unit:** 

Cyrus H McCormick Elementary School

School:

**Building ID:** Address: 2712 S. Sawyer Region: Mail Room: Asbestos Surveyor: Russell, John X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: jrussell29@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12" x 12" Brown Vinyl Floor Rooms 107, 308 & Copy YES 2 A 2400 SF X NO Miscellaneous No None 0 Room 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

4720

2 B	12" x 12" Gray Floor Tile	500	SF	2nd Floor Teacher's Lounge & 3rd Floor Teacher's Washroom		Miscellaneous	No	None	0		YES	X NO
	*	•	·	-	- -	•	•	•	·	<del>-</del>		
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change				1							
	o Oriango				+							
Comments:												
2017 - Spring	: No Change											
Comments:					1							
2018 - Fall: N	o Change				1							
	o onange				4							
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 C	12" x 12" White Floor Tile	800	SF	Room 101		Miscellaneous	No	Loc	10		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

5	Linoleum			Balcony in Auditorium							YES	X NO
2016 - Fall:	No Change				7							
Comments:	· · · · · · · · · · · · · · · · · · ·				= =							
2017 - Fall:	No Change				1							
Comments:	-				]							
2017 - Sprir	ng: No Change				]							
Comments:					-							
2018 - Fall:	No Change											
Comments:					_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
_	011 0111/11 151 711			Basement Kitchen								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

Material Location

Storage Room

Material

Quantity

Material

Units

HA No

7

Material Description

9" x 9" Vinyl Floor Tile

X YES

NO

8 A	12" x 12" Brown Vinyl Floor Tile Mastic	2400	SF	107, 308 & Copy Room	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments:										
2017 - Sprin	g: No Change									
Comments:										
2017 - Fall:	No Change									
Comments:	<u> </u>									
2018 - Fall:	No Change									
Comments:	-									

Asbestos Type Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8 B	12" x 12" Gray Floor Tile Mastic	500	SF	2nd Floor Teacher's Lounge & 3rd Floor Teacher's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

80	Mastic			Room 101		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

9	9" x 9" Vinyl Floor Tile Mastic	Basement Kitchen Storage Room		Miscellaneous	
2016 - Fall: I	Inaccessible		1		
Comments:f	loor is now ceramic				
2017 - Fall: I	No Change				
Comments:					
2017 - Sprin	g: Other		_		
Comments:r	no mastic				
2018 - Fall: I	No Change				

HA No

8 C

Comments:

Material Description

12"x12" White Floor Tile

Material

Quantity

Material

Units

Material Location

Room 101

Change in Assessment Category

X NO

NO

YES

X YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12" x 12" Green Floor Tile			Trailer		Miscellaneous					X YES NO
2016 -	Fall: Abated				]						

2016 - Fall: Abated
Comments:remove during rehab 2014
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:unit rehabed prior to 2014
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12" x 12" Green Floor Tile Mastic			Trailer		Miscellaneous					X YES NO

2016 - Fall: Abated
Comments:rehab 2014
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:unit rehabed prior to 2014
2018 - Fall: No Change
Comments:

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
12	Carpet - REMOVED			Balcony in Auditorium		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments	:											
2017 - Spri	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13	Drywall			Trailer							YES	X NO
2016 - Fall	: No Change											
Comments												

Material

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
14	Roof Flashing - Not AHERA					Miscellaneous					YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
15	Roof Base - Not AHERA					Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 Falls	No Change											
2017 - Fall:	INO Change				1							

Comments:

Comments:

Comments:

2017 - Spring: No Change

2018 - Fall: No Change

16	Drywall			2nd Floor Teacher's Washroom							YES	X NO
2016 - Fall:	No Change											
Comments:					-							
Comments.												
2017 - Fall:	No Change											
Comments:												
					_							
	ng: No Change											
Comments:												
2010 5 11	N. O				_							
2018 - Fall:												
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
17	Spray On Fireproofing			Boiler Room							YES	X NO
''	Topia, on increasing			20								_X_NO
2016 - Fall:	No Chango				7							
					-							
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

18	Carpet Mastic			Room 106 Library							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	V				1							
2017 - Fall: N	lo Change											
Comments:					- -							
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
19	Canvas Wall Covering			Room 106 Library, 103, and 209							YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

20	2' x 4' Lay In Ceiling Panels			Trailer/Kitchen							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>				]							
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21	Blackboards	200	SF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
22	4" White Vinyl Baseboard			Trailer							X YES	NO
2016 - Fall: A												

2016 - Fall: Abated
Comments:rehab 2014
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:unit rehabed prior to 2014
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	4" White Vinyl Baseboard Adhesive			Trailer							X YES NO

2016 - Fall: Abated
Comments:rehab 2014
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:unit rehabed prior to 2014
2018 - Fall: No Change
Comments:

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
24	Brick - Not AHERA			Exterior of Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:												
				T		T.			T.			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
25	Brick Mortar - Not AHERA			Exterior of Building							YES	X NO
2016 - Fall:	No Change											
Comments:												

Material

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

2016 - Fal	: No Change										
Comments	5:										
2017 - Fal	l: No Change										
Comments	S:										
2017 - Spr	ing: No Change										
Comments	S:										
2018 - Fal	: No Change										
Comments											
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
11/4140	Waterial Description			Waterial Education			1 Habie				Change in Assessment Category
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

26

27

Comments:

Comments:

Comments:

Comments:

Material Description

Carpet Mastic

Carpet Mastic

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

650

Material

Units

SF

SF

1000

Material Location

Room 008

Auditorium

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Beige Floor Tile			Mobile Unit 116/117		Miscellaneous					X YES NO
2016 - Fall: A	hated				]						

2016 - Fall: Abated
Comments:rehab 2014
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:unit rehabed prior to 2014
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" Beige Floor Tile Mastic			Mobile Unit 116/117		Miscellaneous					X YES NO

2016 - Fall: Abated
Comments:rehab 2014
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:unit rehabed prior to 2014
2018 - Fall: No Change
Comments:

30	12" x 12" White, Red, and Yellow Floor Tile	3000	SF	Mobile Unit 116/177	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	<u> </u>									
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:	-									
2018 - Fall: N	lo Change									
Comments:	-									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Mastic Associated w/ 12" x 12" White, Red, and Yellow Floor Tile	3000	SF	Mobile Unit 116/117		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	2' x 4' White Textured Ceiling Tile	3000	SF	Mobile Unit 116/117		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	2' x 4' Ceiling Tile w/ Fissures and Holes	200	SF	Main Office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	12" x 12" Beige w/ Brown Floor Tile	100	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	<u>-</u>				1							

2018 - Fall: No Change

Commen	nts:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Mastic Associated w/ 12" x 12" Beige w/ Brown Floor Tile	100	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
А	Aircell Pipe Insulation	50	LF	Engine Room & Basement Corridor		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Hard Joint Compound on Aircell Pipe Insulation	4	LF	Engine Room & Basement Corridor		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Preformed (Mag Block) Pipe Insulation	500	LF	Basement Corridor		TSI	Yes	Loc	10		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Joint Insulation on Mag Block Pipe Insulation	15	LF	Basement Corridor		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	G	Paperwrap Pipe Insulation	200	LF	Basement Corridor, Engine Room		TSI	Yes	Dist	2		YES X NO
1	0040 Fall N	. 01				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Hard Joint Compound on Paperwrap Pipe Insulation	50	LF	Engine Room & Basement Corridor		TSI	Yes	Loc	1		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

I	Duct Covering			Boiler Room							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring												
Comments:re	emoved May 2017				-							
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
К	Feed Water Tank Insulation Jacketing			Boiler Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

L	Boiler Gaskets	80	LF	Boiler Room	Miscellaneous	No	None	0	YES	X NO
2016 - Fal	I: No Change									
Comment										
2017 - Sp	ring: No Change									
Comment	S:									
	I: No Change									
Comment	S:									
2018 - Fal	I: No Change									
Comment	s·									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Incinerator Insulation			Boiler Room		TSI					X YES NO

2016 - Fall: Other	
Comments:removed date unknown	
2017 - Spring: Other	
Comments:removed prior to 2014	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Hard Joint Compound on Fiberglass Pipe Insulation	50	LF	Washrooms		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Cyrus H McCormick Elementary School
Date: <u>1/21/2019</u>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 24431

SCHOOL'S ASBESTOS MANAGEMENT PLAN.