Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Emmett Louis Till Math and Science Academy 24441 4740 School: **Oracle Unit: Building ID:** Address: 6543 S. Champlain Region: 05 Mail Room: Asbestos Surveyor: Bolton, Angela X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: afbolton@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12x12 lt. Beige floor tile 1st & 2nd floor stairwell X YES 002 40 SF NO Miscellaneous No None 0 1895 bldg. landing 2016 - Fall: Abated Comments:12x12 blue tile 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
003	9x9 Tan floor tile	1540	SF	Lunchroom & Playroom, 1895 bldg.		Miscellaneous	No	Dist	45		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
008	12x12 Beige floor tile mastic			1st & 2nd floor stairwell 1895 bldg.		Miscellaneous		None			X YES NO

2016 - Fall: Abated
Comments:replaced
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
009	9x9 tan floor tile mastic	1540	SF	Lunchroom & Playroom, 1895 bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	2019 Caring : No Change
2018 - Fall: No Change	1 0 0
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
010	Brown linoleum mastic	325	SF	3rd floor classroom, 1940 bldg		Miscellaneous	No	None			X YES NO	

2016 - Fall: Other
Comments:wood floor
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
012	12x12 beige floor tile	5790	SF	Corridors throughout hallways, 1895 bldg.		Miscellaneous	No				YES	X NO
2016 - Fall	: No Change											
Comments	:											
2017 - Spri	ing: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2018 - Spri	ing : No Change											
Comments	:											
2018 - Fall	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
013	12x12 beige floor tile mastic	5790	SF	Corridors throughout hallways, 1895 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
014	9x9 Brown floor tile			Corridor throughout 1930, bldg.		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:]							
2017 - Sprii	ng: No Change				1							
Comments:												
2017 - Fall:	No Change				-							
Comments:												
2018 - Sprii	ng : No Change				-							
Comments:												
2018 - Fall:	No Change				1							
Comments:	<u>-</u>											
					J							
			•	_	•		,					

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015	9x9 Brown floor tile mastic			Corridord throughout 1930, bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
016	9x9 black floor tile			1st, 2nd, & 3rd floor corridor, 1930 bldg.		Miscellaneous					X YES NO
2016 - Fal	I: Abated				\neg						
	s:12x12 blue tile										
2017 - Spi	ring: No Change										
Comments	s:										
2017 - Fal	I: No Change										
Comments	s:										
2018 - Spi	ring : No Change										
Comments	s:			<u> </u>							
2018 - Fal	I: No Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
017	9x9 black floor tile mastic			1st, 2nd, & 3rd floor corridor, 1930 bldg.		Miscellaneous					X YES NO		

2016 - Fall: Abated
Comments:replaced
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 6

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
018	hard coat plaster	61450	SF	throughout 1895 bldg.		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	g : No Change											
Comments:]							
2018 - Fall: N	lo Change				_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
019	hard coat plaster	14670	SF	throughout 1930 bldg.		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
020	hard coat plaster	41520	SF	throughout 1940 bldg.		Surface	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments):											
2018 - Spr	ing : No Change											
Comments	S:											
2018 - Fall	: No Change											
Comments												

Material

Damage

Friable

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
023	9x9 brown floor tile			1st & 2nd & 3rd floor corridor, 1940 bldg.		Miscellaneous					X YES NO

2016 - Fall: Abated
Comments:12x12 blue tile
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
024	9x9 brown floor tile mastic			1st & 2nd & 3rd floor corridor, 1940 bldg.		Miscellaneous					X YES	NO
2016 - Fall: A	bated											

2016 - Fall: Abated
Comments:replaced
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
025	9x9 black floor tile			corridors throughout 1940 bldg.		Miscellaneous		None			X YES NO

2016 - Fall: Abated
Comments:12x12 blue tile
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
026	9x9 black floor tile mastic			corridors throughout 1940 bldg.		Miscellaneous		None			X YES NO

Face = 11 - 12 - 12
2016 - Fall: Abated
Comments:replaced
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
026A	12x12 tan floor tile	770	SF	Room 105 (405) installed over existing		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Other
Comments:ood floor
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
027	12x12 dark beige floor tile	10	SF	entrance to room 110 &112, 1895 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Al	2016 - Fall: Abated											
Comments:12	Comments:12x12 blue tile											
2017 - Spring: No Change												
Comments:												
2017 - Fall: No	2017 - Fall: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
028	12x12 dark beige floor tile	10	SF	entrance to room 110 &112, 1895 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:12x12 blue tile
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
029	12x12 yellow floor tile	500	SF	Lunchroom/kitchen, 1895 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Repaired		
Comments:12x12 white tile		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
030	12x12 yellow floor tile mastic	500	SF	Lunchroom/kitchen, 1895 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Repaired
Comments:replaced
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
031	12x12 lt/ grey floor tile	80	SF	corridors throughout 1895 bldg.		Miscellaneous	No	None	0		X YES NO

			ŭ	
2016 - Fall: Ab	oated			
Comments:12:	x12 blue tile			
2017 - Spring:	No Change			
Comments:				
2017 - Fall: No	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: No	o Change			
Comments:				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
032	12x12 lt. grey floor tile mastic	80	SF	throughout corridors, 1895 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:replaced
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
033	12x12 lt. brown floor tile	300	SF	lunchroom, store room & corridors throughout 1895 bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change									•	

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
034	12x12 lt. brown floor tile mastic	300	SF	lunchroom, store room & corridors throughout 1895 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
035	12x12 med. brown floor tile	850	SF	lunchroom, janitors washroom, main office		Miscellaneous	No	Loc	15		YES X NO
2016 - Fall: N	o Change										

0040 Fall No Olassa	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
036	12x12 med. brown floor tile mastic	850	SF	lunchroom, janitors washroom, main office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
037	12x12 brown floor tile	3200	SF	lunchroom, room 210, 1895 bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

	_	
		 <u> </u>
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2010 Chring I No Change		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
037F	McCosh Annex Modular Unit (Fieldhouse)	1200	SF	Throughout		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Deteriorated
Comments:replaced
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
038	12x12 brown floor tile mastic	3200	SF	lunchroom, room 210, 1895 bldg.		Miscellaneous	No	None	0		X YES NO
2016 - Fall: O	thor										

0040 5 11 011	
2016 - Fall: Other	
Comments:wood floor	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
039	12x12 dark brown floor tile	800	SF	lunchroom, 1895 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
040	12x12 dark brown floor tile mastic	800	SF	lunchroom, 1895 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Sprin	g: No Change				=							
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change				=							
Comments:												
2018 - Fall: I	No Change				=							
Comments:	-											
I					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
041	12x12 lt. brown floor tile	780	SF	teachers lunch room, 1930 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
042	12x12 lt. brown floor tile mastic	780	SF	teachers lunch room, 1930 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:					_							
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change				_							
Comments:												
2018 - Sprir	ng : No Change				1							
Comments:]							

Material

Damage

Friable

Damage

ŀ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
(043	12x12 brown floor tile	3630	SF	assembly hall, 1930 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
044	12x12 brown floor tile mastic	3630	SF	assembly hall, 1930 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				-							
Comments:]							
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
045	12x12 black floor tile	3630	SF	assembly hall, 1930 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
046	12x12 black floor tile mastic	3630		assembly hall, 1930 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
	g : No Change				-							
Comments:					-							
2018 - Fall: N	No Change				-							
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
047	12x12 off white floor tile	1050	SF	room 104, 1940 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
048	12x12 off white floor tile mastic	1050	SF	room 104, 1940 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
049	12x12 pink floor tile	520	SF	kindergarten, 1940 bldg.		Miscellaneous	No	None	0		X YES NO	

2016 - Fall: Repaired
Comments:12x12 blue tile
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
050	12x12 pink floor tile mastic	520	SF	kindergarten, 1940 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: R	epaired		
Comments:re	placed		
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
		•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
051	12x12 grey floor tile	300	SF	3rd floor corridor 1940 bldg.		Miscellaneous	No	None	0		X YES NO	

2016 - Fall: Abated
Comments:12x12 blue tle
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
052	12x12 grey floor tile mastic	300	SF	3rd floor corridor 1940 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:replaced
•
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
053	12x12 black floor tile			3rd floor corridor 1940 bldg.		Miscellaneous					X YES NO	

2016 - Fall: Abated
Comments:12x12 blue tile
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 24

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
054	12x12 black floor tile mastic			3rd floor corridor 1940 bldg.		Miscellaneous					X YES	NO
2016 - Fall: Abated Comments:replaced												

2016 - Fall: Abated	
Comments:replaced	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
055	grey carpet mastic			room 207, 1895 bldg.		Miscellaneous					X YES NO

2016 - Fall: Other
Comments:wood floor
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
056	brown carpet mastic	810	SF	room 206, 1895 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				7							
Comments	3:											
2017 - Spr	ring: No Change											
Comments	3:				_							
2017 - Fall	l: No Change											
Comments	3:				_							
2018 - Fall	l: No Change											
Comments	3:			<u> </u>	_							
2018 - Spr	ring : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
057	carpet mastic			kindergarten 1940 bldg.		Miscellaneous					X YES NO

2016 - Fall: Other
Comments:wood floor
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
058	drywall	100	SF	main office, 1895 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change				_							
Comments:												
L					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
059	drywall compound	50	SF	main office, 1895 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
060	baseboard	40	SF	main office, 1895 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change				1							
Comments:	, ,											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
061	baseboard mastic	40	SF	main office, 1895 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
062	acoustical tile	3630	SF	assembly hall, 1930 bldg.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:]							
2018 - Spring	g : No Change				1							
Comments:	, and the second											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
063	acoustical tile mastic	3630	SF	assembly hall, 1930 bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
064	2x4 acoustical tile	1740	SF	main office, rooms 209 & 309, 1895 bldg.		Miscellaneous	Yes	None	0		YES X NO
0040 5 11 11					i						

2016 - Fall: No Change Comments: 2017 - Spring: No Change
Comments:
2017 - Spring: No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2019 Falls No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
065	chalk boards	2110	SF	throughout 1895 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Other
Comments:white board
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
066	chalk boards	900	SF	throughout 1940 bldg.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: O	ther		
Comments:wh	hite board		
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
067	12x12 grey floor tile	1000	SF	1940 bldg - Room 003		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Repaired
Comments:12x12 blue tile
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
068	12x12 white floor tile over wood tile	300	SF	1940 bldg - Room 304A		Miscellaneous	No	None	0		YES	X NO
	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
					4							

2017 - Fall: No Change Comments:

2018 - Spring : No Change

Comments:

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
069	12"x12" Yellow Floor Tile	420	SF	Rooom 106		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
070	12"x12" Yellow Floor Tile Mastic	420	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:]							
2017 - Spring	g: No Change											
Comments:					1							
2017 - Fall: N	No Change											
Comments:					_							
2018 - Spring	g : No Change				<u> </u>							
Comments:												

HA N	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
071		12"x12" Green Floor Tile	420	SF	Room 106		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
072	12"x12" Green Floor Tile Mastic	420	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

2018 - Spring : No Change
Comments:

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
073	Ceramic Floor Tile Grout	600	SF	Girl's and Boy's Washrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
074	Ceramic Floor Tile Adhesive	600	SF	Girl's and Boy's Washrooms		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

204C Folk No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
075	12"x12" White w/Blue Specks Floor tile	30	SF	Engineer's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
076	12"x12" White w/Blue Specks Floor Tile Adhesive	30	SF	Engineer's Washroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
077	Terrazzo	800	SF	Corridors of 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
078	Carpet Adhesive	800	SF	Principal's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change							•				
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:					_							
2018 - Sprii	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
079	12"x12" Blue Mix Floor Tile	17500	SF	1st, 2nd & 3rd Floor Corridors of 1930 and 1940 Buildings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
080	12"x12" Blue Mix Floor Tile Adhesive	17500	SF	1st, 2nd & 3rd Floor Corridors of 1930 and 1940 Buildings		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change						·				·	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	aircell pipe insulation	370	LF	basement & roo 210, 1895 bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	fittings on aircell pipe insulation	37	Fittings	basement & room 210, 1895 bldg.		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	joints on paperwrap pipe insulation	15	Each	basement boiler room, 1895 bldg.		TSI	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	aircell pi[pe insulation	20	LF	basement corridor, 1930 bldg.		TSI	Yes	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	joints on aircell pipe insulation	3	Each	basement corridor - 1930 bldg		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	fittings on fiberglass pipe insulation	265	Each	Basement, room 110, room 210, room 310		TSI	Yes	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
· ·
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	paperwrap pipe insulation	20	Each	basement corridor, 1930 bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	fittings on paperwrap pipe insulation	2	Each	basement corridor, 1930 bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	fittings on fiberglass pipe insulation	4	Each	basement corridor 1930 bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	ategory
N	aircell pipe insulation	220	LF	basement corridor, 1940 bldg.		TSI	Yes	None	0		YES X N	0
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	fittings on aircell pipe insulation	18	Fittings	basement corridor, 1940 bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	paperwrap pipe insulation	180	LF	basement corridor, 1st & 2nd floor washroom pipe chase.		TSI	Yes	None	0		YES X NO
0040 F.II N	2040 Fell No Olesco						•	•	•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	fittings on paperwrap pipe insulation	30	Each	basement corridor, 1st & 2nd floor washroom pipe chase.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
R	fittings on fiberglass pipe insulation	44	Each	fan and engine room, 1940 bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	·-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	boiler gasket	30	LF	boiler room, 1895 bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Т	incinerator insulation			boiler room - removed		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Emmett Louis Till Math and Science Academy
Date: 1/9/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 24441

SCHOOL'S ASBESTOS MANAGEMENT PLAN.