Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

| School: Address: | Donald Morrill Math & Science Elementary Scho 6011 Rockwell | ol | Oracle Unit: Region: | 24571 05 | Building ID: Mail Room: | 4880 43 |
|---------------------|--|--|---|-------------|----------------------------|------------|
| ERE IF N | O CHANGE TO ASBESTOS | Asbestos Surveyor: Survey Date: Email Address: | Collins, Michael 1/10/2019 mdcollins5@cps.edu | | | |

| | A copy of the2016/201 | 7 notice to p | parents and | staff regarding the asl | pestos manag | ement plan noti | fications w | as distribute | d via: | | | |
|------------------------|----------------------------------|----------------------|-------------------|-------------------------|---|----------------------|-------------|----------------|--------------------|-----------------|-----------------|----------------|
| | Each child's backpa | nck | Notice | printed in school's new | Notice printed in school's calendar Other | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | sment Category |
| 02 | 12x12 peach and cream floor tile | | Miscellaneous | No | Dist | 30 | | YES | X NO | | | |
| 2016 - Fall: No Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | - | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2018 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|----------------------|-------------------|---------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 03 | Dark green Linoleum- ABATED | | | Rm 106, old library | | Miscellaneous | | | | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 06 | Decorative Plaster | 5000 | SF | Auditorium | | Surface | Yes | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 7 | Packing material around pipes | 25 | SF | tunnels | | TSI | Yes | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|----------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 10 | Air cell debris | 200 | LF | Unexcavated Tunnel Area | | TSI | Yes | Loc | 1 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 11 | 9x9 brown and tan flr tile mastic | | | 1st,2nd flr corridors | | Miscellaneous | | | | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 12 | 12x12 peach and cream flr tile Mastic | 2400 | SF | 3rd flr corridor | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No |) | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|----------------------|-------------------|---------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 13 | | Linoleum mastic | | | Rm 106- old library | | Miscellaneous | | | | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 14 | 2' x 4' acoustic ceiling tile | 40000 | SF | 1st, 2nd and 3rd fl classrooms and corridors | | Miscellaneous | Yes | None | 0 | | |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 15 | Wall Accents Acoustic Tile | 500 | SF | Auditorium | | Miscellaneous | Yes | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 16 | 12x12 Tan/Cream VFT | 1500 | SF | Rm 111, 106 and 201 | | Miscellaneous | No | Dist | 20 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 17 | 12x12 Tan/cream VFT mastic | 1500 | SF | Rm 101, 106, 201 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 18 | White boiler gasket | 50 | SF | Boiler room (on boiler) | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|----------------------|-------------------|-----------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 19 | Foilwrap over duct insulation | 500 | LF | Boiler room - Boiler duct work | | TSI | Yes | None | 0 | | YES XNO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 20 | Purple carpet mastic | 1500 | SF | Main office, Storage, Rm 107 | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 21 | 12x12 blue on blue floor tile | 1900 | SF | cafeteria lunch room | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 21M | Mastic for HA 21 | 1900 | SF | cafeteria, lunch room | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 22 | 12x12 ft off white w/specks | 320 | SF | kitchen office | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 22M | Mastic for HA 22 | 320 | SF | kitchen office | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 23 | 12x12 ft red w/red streaks | 450 | SF | room 117 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 23M | Mastic for HA 23 | 450 | SF | rm 117 | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 24 | 12x12 ft green w/green specs | 450 | SF | room 116 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 24M | Mastic for HA 24 | 450 | SF | rm 116 | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 25 | 12x12 ft white w/blue and gray | 5050 | SF | room 119, 2nd fl hall, 1st fl hall, rm 220, 216, elevator | | Miscellaneous | No | Dist | 10 | | YES XNO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 25M | Mastic for HA 25 | 5050 | SF | 1st and 2nd floor rooms | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 26 | carpet mastic | 2860 | SF | rm 217 & 219, library | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 27 | baseboard mastic | 980 | SF | rms 116, 117, 119, 2nd floor, kitchen, lunchroom | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 28 | pinhole tile 2x4 ceiling | 2100 | SF | floor room and 1st & 2nd | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 29 | drywall | 12500 | SF | annex, 1st & 2nd floor | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| H | A No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----|------|---------------------------|----------------------|-------------------|----------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 30 | 0 | 2x4 textured ceiling tile | 4000 | SF | annex (S), 1st & 2nd floor | | Miscellaneous | Yes | None | 0 | | YES XNO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| AA | 12"x12" Floor Tile White w/ Tan | 6000 | SF | 1st and 2nd Floor Corridors and Room 103 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| AA1 | 12"x12" Floor Tile White w/ Tan Mastic | 6000 | SF | 1st and 2nd Floor Corridors and Room 103 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| С | Air cell | | | Tunnel | | Miscellaneous | | | | | YES X NO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| I | HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---|-------|-------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| | D | Aircell Pipe Joint Insulation | | | Tunnels | | TSI | | None | | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| E | Cardboard Insulation | 500 | LF | Boiler Room | | TSI | Yes | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| F | Cardboard Joint compound | 40 | SF | Boiler Room, unexcavated tunnel | | TSI | Yes | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FT-1 | 12x12 flr tile, white w/blue pink and yellow fleck | 1900 | SF | Rm 101,214,214B | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.*

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FT-2 | 12x12 flr tile- Dark Brown w/multi colored flecks | 750 | SF | Rm 103 | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FT-3 | 12x12 flr tile, Black w/white flecks | 45 | SF | 1st flr. Hall- Patch | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FT-4 | 9x9 green and cream FT (covered with carpet) | 300 | SF | principals office and storage | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FT-5 | 9x20 black flooring | 1000 | SF | 1st and 2nd fl halls border | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|----------------------|-------------------|--------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FT-6 | 12x12 flr. Tile Cream w/tan | 750 | SF | Rm 111/106 (Not observed), Rm 201 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FT-7 | 9x9 flr. Tile Black and Dark Maroon checked | 300 | SF | Gym office | | Miscellaneous | No | Loc | 15 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FTM-1 | Mastic 12x12 white w/blue, pink, yellow flecks | 1900 | SF | Rm 101,214,214B | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FTM-2 | Mastic 12x12 dark brown w/multicolored flecks | 750 | SF | Rm 103 Main office | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|----------------------|-------------------|--------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FTM-3 | Mastic beneath black 12x12 | 45 | SF | 1st flr Hall patch | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|----------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FTM-4 | Mastic 9x9 green and cream checked (covered) | 300 | SF | Principals office, storage | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FTM-5 | Mastic beneath 9x20 flooring | 1000 | SF | 1st and 2nd hall | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FTM-6 | Mastic 12x12 tan and cream VFT | 1800 | SF | Rm 106,111,201 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| FTM-7 | Mastic beneath 9x9 black and dark maroon VFT | 300 | SF | Gym office | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| G | Mag Block-Boiler | | | Boiler Rm | | Miscellaneous | | | | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|----------------------|-------------------|------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| I | 9x9 brown and tan floor tile | | | 1st, 2nd flr corridors | | TSI | | None | | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| J | cementious mud on valves | 10 | LF | (N) base fan room | | TSI | Yes | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|----------------------|-------------------|------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| к | Aircell Pipe Insulation | 350 | LF | (W) tunnel unexcavated | | TSI | Yes | Dist | 10 | | YES X NO |

| 2016 - Fall: No Change | |
|------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

| School: | Donald Morrill Math & Science Elementary School |
|---------|---|
| Date: | 1/10/2019 |

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

CHECK ONE

| | | A copy of this | s notice was | sent home in | each child's ba | ckpack. |
|--|--|----------------|--------------|--------------|-----------------|---------|
|--|--|----------------|--------------|--------------|-----------------|---------|

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.