## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Ronald Brown Elementary Community Academy 24631 5040 School: **Oracle Unit: Building ID:** Address: 12607 S Union Avenue Region: Mail Room: Asbestos Surveyor: Micou, Alan X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 2'x2' Acoustical Ceiling Tile-Gym Ceiling YES 02 2800 SF X NO Miscellaneous Yes None 0 NOT OBSERVED Not observed in 2013. 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
04A	12x12 white w/blue specks (ABATED)			east service, west corridor		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	j : No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04B	12x12 brown with white specs Floor Tile	1500	SF	Recreation room checker (1/3)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

04C	12x12 crème with brown specs Floor Tile	1500	SF	recreation room, pump room, storage room		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	Vo Change				1						
Comments:	10 Onange				1						
2017 Fall N	Jo Changa										
2017 - Fall: Note:	vo Change										
	g: No Change										
Comments:											
2018 - Fall: I	No Change				-						
Comments:	-										
2018 - Sprin	g : No Change										
Comments:											
					J						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04D	12x12 off white with red and black streaks Floor Tile- ABATED			Rooms 100, 101,103,105 & Teacher's Lounge. Abated		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
04E	12x12 tan with white & brown streaks Floor Tile - ABATED			Rooms 100, 101,103,105 & Teacher's Lounge. Pump Room, Storage Room. Abated		Miscellaneous				YES	X NO
2016 - Fall: No Change											
Comments:	o Griango				-						
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change				_						
Comments:	•										
2018 - Spring	: No Change										
Comments:					_						

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	9x9 tan speckled Floor Tile- ABATED			Room 102. Abated		Miscellaneous					X YES NO

2016 - Fall: Al	2016 - Fall: Abated									
Comments:Ab	Comments:Abated									
2017 - Fall: No Change										
Comments:										
2017 - Spring: No Change										
Comments:										
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05B	9x9 off white w/black & red streaks Floor Tile - ABATED			Room 104. Abated		Miscellaneous		None			X YES NO
2016 - Fall: A	Abated		•						•	•	
Comments:A											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:	-				7						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05C	9x9 tan w/ white and brown streaks Floor Tile -ABATED			Room 104. Abated		Miscellaneous					X YES NO

2016 - Fall: Abated
Comments: Abated
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
08A	Brown Baseboard	60	LF	Recreation Room (1953 Bldg)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08B	Black Baseboard	30	LF	Room 104 (1953)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09A	Brown Baseboard Mastic	60	LF	Recreation Room (1953)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:	<b>-</b>											
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring	g: No Change				]							
Comments:												
2018 - Spring	g : No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09B	Black Baseboard Mastic	30	LF	Room 104 (1953) Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

10	Insulation in Fire Door (1)	1	EA	boiler room	TSI	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	o Onango									
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:	<u> </u>									
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Boiler Gasket -ABATED			boiler room (1953). Abated		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
12	Fire Brick Not Observed	44	SF	Incinerator in Boiler Room. Not Observed		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change			·	]						·	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Incinerator Door (NOT OBSERVED)	5	SF	Incinerator in Boiler Room. Not Observed		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

14	Drywall	300	SF	recreation room wall (1953)		Miscellaneous	Yes	None	0	YES	X NO
					1						
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:	<u> </u>										
2017 - Fall: N	lo Change										
Comments:											
Commonto											
2018 - Spring	g : No Change										
Comments:	,										
Commonto											
2018 - Fall: N	lo Change										
Comments:											
Comments.											
					I						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	12x12 white with white specs tile mastic-ABATED			south service corridor ABATED							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15B	12x12 brown with white specks floor tile mastic	1500	SF	Recreation room checker (1/3)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N Comments:	lo Change										

2016 - Fall: No Change	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15C	12x12 crème with brown specks floor tile mastic - NOT OBSERVED	1500	SF	recreation room, pump room and storage room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

15D	black streaks floor tile mastic - ABATED			& Teacher's Lounge. Abated.		Miscellaneous					YES	X NO
2016 - Fal	: No Change				]							
Comments	S:											
2017 - Fal	: No Change											
Comments	): 				1							
2017 - Spr	ing: No Change											
Comments	<b>:</b>											
2018 - Fal	: No Change											
Comments	S:				-							
	ing : No Change											
Comments	S:				=							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15E	12x12 tan with white & brown streaks floor tile mastic -ABATED			Rooms 100, 101,103,105 & Teacher's Lounge. Pump Rm, Storage Rm. Abated		Miscellaneous					YES	X NO
2016 - Fal	: No Change			·	]							

Material

Category

Asbestos

Type

Friable

Damage

Type

Damage

Quantity

HA No

Comments:

Comments:

Comments:

Comments:

Comments:

2017 - Spring: No Change

2018 - Spring : No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

12x12 off white w/ red &

Material

Units

Material

Quantity

Material Location

Rooms 100, 101,103,105

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
16A	12x12 tan speckled floor tile mastic ABATED			room 102. Abated		Miscellaneous					X YES	NO
2016 - Fall: A	bated				1							
Comments:Al	bated											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16B	9x9 off white w/black & red streaks floor tile mastic ABATED			room 104. Abated		Miscellaneous					X YES NO

2016 - Fall: Abated
Comments: Abated
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

<b> </b>		+		<b>.</b>					
16C	9x9 tan w/ white & brown streaks floor tile mastic ABATED		room 104. Abated		Miscellaneous	None		X YES	NO
				1					
2016 - Fall: A	bated								
Comments:A	bated								
2017 - Spring	g: No Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:									
2018 - Spring	g : No Change								
Comments:									
2018 - Fall: N	lo Change								
Comments:	-								
				<u>-</u>					

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	17	1 X 1 Acoustical Ceiling Tile NOT OBSERVED	5500	SF	Building 1958 - Library, Corridors, Main Office and All Classrooms. Not Observed		Miscellaneous	Yes	None	0		YES X NO
-	2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units	· ·	,
18	Vibration dampner cloth - NOT OBSERVED	6	SF	basement fan room (1958)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change				7							
Comments:	J				]							
2017 - Spring:	: No Change				_							
Comments:												
2017 - Fall: No	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												
					_							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Drywall - NOT OBSERVED	2800	SF	corridor ceilings, boys & girls washrooms (1953)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

21	transite board NOT OBSERVED	400	SF	classrooms 101-106. Not Observed	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	io Onarigo									
2017 - Spring	յ։ No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:	-									
2018 - Spring	: No Change									
Comments:	<b>.</b>									
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	12x12 offwhite w/ black & red streaks floor tile NOT OBSERVED	6600	SF	Main office washroom, computer room, Rms 107,110,112, 113, 114, 115,117. Not Observed		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22B	12x12 tan w/ white & brown streaks floor tile - NOT OBSERVED	6600	SF	Computer Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change		•	•	•	•	•				

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22C	12x12 brown w/ white specks floor tile	1400	SF	Gym; Rm 121(Not Observed)		Miscellaneous	No	None	0		YES X NO

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
22D	12x12 off white crème w/ brown streaks floor tile	1400	SF	Gym; Rm 121(Not Observed)		Miscellaneous	No	None	0		YES	X NO
					1							
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					i							

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	12x12 offwhite w/ black & red streaks floor tile mastic NOT OBSERVED	6600	SF	Main office washroom, computer room, rms 107,110,112- 115,117,119,121. Not Observed.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

2018 - Spring : No Change

Comments:

Material

Material Material Location

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23B	12x12 tan w/ white & brown streaks floor tile mastic NOT OBSERVED	6600	SF	Main office washroom, computer room, rms 107,110,112- 115,117,119,121. Not Observed		Miscellaneous	No	None	0		YES X NO

	•	Quantity	Units		Type	Category		Туре	Quantity	Units		
23C	12x12 brown w/ white specs floor tile mastic	1400	SF	Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											
Comments:					_							
2017 - Spring:	: No Change											
Comments:												
2017 - Fall: No	o Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23D	12x12 off white crème w/ brown streaks floor tile mastic	1400	SF	Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

2018 - Spring : No Change

Comments:

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	9x9 tan w/ black streaks floor tile NOT OBSERVED	330	SF	Kitchen. Not Observed.		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated Comments:Abated  2017 - Fall: No Change Comments:
Comments:Abated  2017 - Fall: No Change  Comments:
2017 - Fall: No Change Comments:
Comments:
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24B	9x9 tile white w/ gray streaks-ABATED					Miscellaneous					X YES NO

2016 - Fall: Abated
Comments: Abated
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	9x9 tan w/ black streaks floor tile mastic NOT OBSERVED	330	SF	Kitchen. Not Observed.		Miscellaneous	No	None	0		X YES NO
	•	•	=	•	·	•	•	•	•	='	•

2016 - Fall: Abated	
Comments: Abated	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25B	9x9 mastic tile white w/ gray streaks-ABATED					Miscellaneous	No				X YES NO

2016 - Fall: Abated
Comments: Abated
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26A	Brown Baseboard NOT OBSERVED	40	LF	Room 116 (1958) Not Observed		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26B	Black Baseboard	135	LF	Main Office, Library (1958) Not Observed.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	Brown Baseboard Mastic NOT OBSERVED	40	LF	Room 116 (1958). Not Observed.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27B	Black Baseboard Mastic	135	LF	Main Office, Library (1958). Not Observed.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Туре	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29 ceilir	stic under 1x1 acoustical ing tile (spline ceiling) T OBSERVED	3000	SF	west corridor, service corridor, rm 100(asst. principals office) (1953). Not Observed.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Blue Carpet Mastic NOT OBSERVED	170	SF	Principal's Office and Main Office. Not Observed.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

31	12"x12" Green Floor Tile	420	SF	MDF Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:	J											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:					_							
	g : No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31A	12"x12" Green Floor Tile Mastic- NOT OBSERVED	420	SF	MDF Room		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

Material

Units

Material

Quantity

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

	'	Quantity	Units		Type	Category		Туре	Quantity	Units	Ü	3 ,
32	12x12 cream w/specks floor tile - NOT OBSERVED	1750	SF	Mobile Unit		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	:											
	: No Change											
Comments	:				_							
2017 - Spri	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32A	12x12 cream w/specks floor tile mastic - NOT OBSERVED	1750	SF	Mobile unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

2018 - Spring : No Change

Comments:

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Cream baseboard - NOT OBSERVED	400	LF	Mobile Unit		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	Mastic cream baseboard - NOT OBSERVED	400	LF	Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 28

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"X12" White w/tan specks floor tile	800	SF	Rooms 119		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"X12" White w/tan specks floor tile mastic	800	SF	Rooms 119		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"X12" White w/blue specks floor tile	15000	SF	1st Floor Corridors & Main Office Area, Rms 116, 117, 118, 119, 120, 121, 109, 110, 111, 112, 113, 114, 115, Janitor's Closet, Work Room, Rms 101, 102, 103, 104, 105, 106, Engineer's Office, main office, Teacher's Lounge, Vault		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"X12" White w/blue floor tile mastic	15000	SF	1st Floor Corridors & Main Office Area, Rms 116, 117, 118, 119, 120, 121, 109, 110, 111, 112, 113, 114, 115, Janitor's Closet, Work Room, Rms 101, 102, 103, 103, 104, 105, 106, Engineer's Office, main office, Teacher's Lounge, Vault		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"X12" Blue w/white specks floor tile	2500	SF	1st Floor Corridors & Main Office Area		Miscellaneous	No	None	0		YES X NO
					1						_

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"X12" Blue w/white specks floor tile mastic	1500	SF	1st Floor Corridors & Main Office Area		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Brown and Tan Ceramic Tile Grout	192	SF	Bldg 1958 - Girls and Boys Toilets. Not Observed.		Miscellaneous	Yes	None	0		YES X NO
	•	•	=	-	•	•	•	•	•	=	•

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Brown and Tan Ceramic Mastic	192	SF	Bldg 1958 - Girls and Boys Toilets. Not Observed.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Light Brown and Tan Ceramic Tile Grout	384	SF	Bldg 1953 - Girls and Boysm Mens and Womens Toilets. Not Observed.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Light Brown and Tan Ceramic Tile Mastic NOT OBSERVED	384	SF	Bldg 1953 - Girls and Boysm Mens and Womens Toilets. Not Observed.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

	·	Quantity	Units		Type	Category		Туре	Quantity	Units	J	,
44	Green Ceramic Tile Grout - NOT OBSERVED	70	SF	1953 Bldg - Entrances		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:					]							
2017 - Spring	: No Change											
Comments:					_							
2017 - Fall: N	o Change				_							
Comments:					_							
2018 - Fall: N	o Change											
Comments:					_							
2018 - Spring	: No Change				_							
Comments:					_							
					_							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Green Ceramic Tile Mastic - NOT OBSERVED	70	SF	1953 Bldg - Entrances		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

**Material Description** 

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Brown Ceramic Tile Grout - NOT OBSERVED	70	SF	1958 Bldg - Entrances		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Brown Ceramic Tile Mastic - NOT OBSERVED	70	SF	1958 Bldg - Entrances		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12 x 12 White Wormed Ceiling Tiles (spline) NOT OBSERVED	4570	SF	Bldg 1953 - Classrooms, Corridor and Offices. Not observed.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12" X 12" blue specked floor tile	1000	SF	Rms 120,118,121, 119, 117, 116, 115, 114, 113, 112, 111, 110, 109; Main Office; Teacher's Lounge; vault; Vestibule Entrances; Rms 101, 102, 103, 104, 105, 106, Office 107; Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 24631

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12" X 12" blue specked floor tile mastic	1000	SF	Rms 120,118,121, 119, 117, 116, 115, 114, 113, 112, 111, 110, 109; Main Office; Teacher's Lounge; Vault; Vestibule Entrances; Rms 101, 102, 103, 104, 105, 106, Office 107; Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	2 X 2 white ceiling tile	2000	SF	Rms 120,118,121, 119, 117, 116, 115, 114, 113, 112, 111, 110, 109; Library Workroom, Gym, Main Office; Teacher's Lounge; Rms 101, 102, 103, 104, 105, 106, Office 107; Engineer's Office, Principal's and Vice Principal's Office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Drywall	4000	SF	East corridor ceilings (1958 bldg); North Corridor Ceilings - 1958 Bdg.; Kitchen; Unisex Toilet; Boys and Girls Toilet - 1958 Bldg; Office 107 Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	White and blue ceramic tile grout	600	SF	Girls toilet, boys toilet, unisex toilet, (1958 bldg); women's staff toilet; boys and girls toilet (1953 bldg); main office toilet; Rm 101-106 toilets; office 107 toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24631

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Multicolor carpet mastic	600	SF	Library, Vice Principal's Office; Principal's Office - all in 1958 Bldg.		Miscellaneous	No	None	0		YES X NO
		•	•	-		•	•	•	•	•	

2016 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Fall: No Change Comments:  2018 - Spring: No Change Comments:		
Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Fall: No Change Comments:  2018 - Spring : No Change		
2017 - Spring: No Change  Comments:  2017 - Fall: No Change  Comments:  2018 - Fall: No Change  Comments:  2018 - Spring : No Change	2016 - Fall: No Change	
Comments:  2017 - Fall: No Change Comments:  2018 - Fall: No Change Comments:  2018 - Spring : No Change	Comments:	
Comments:  2017 - Fall: No Change Comments:  2018 - Fall: No Change Comments:  2018 - Spring : No Change		
2017 - Fall: No Change Comments:  2018 - Fall: No Change Comments:  2018 - Spring : No Change	2017 - Spring: No Change	
Comments:  2018 - Fall: No Change Comments:  2018 - Spring : No Change	Comments:	
Comments:  2018 - Fall: No Change Comments:  2018 - Spring : No Change		
2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Fall: No Change	
Comments: 2018 - Spring : No Change	Comments:	
Comments: 2018 - Spring : No Change		
2018 - Spring : No Change	2018 - Fall: No Change	
	Comments:	
Comments:	2018 - Spring : No Change	
	Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Acoustical Drywall Ceiling System - NOT OBSERVED	1400	SF	Mobile Unit		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Other
Comments:Other
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
56	Drywall - NOT OBSERVED	4000	SF	Mobile Unit		Miscellaneous	No	None	0		X YES	NO
2016 - Fall:	Other											
Comments:	Other											
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	-											
2018 - Sprir	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Pipe Joint Insulation on Fiberglass Insulated Piping ABATED			Boiler Room, Crawl Space (1953). Abated.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

С	Cardboard Pipe Insulation ABATED		Boiler Room, Crawl Space (1953). Abated.		TSI		Loc			YES	X NO
2016 - Fall: I	No Change			]							
	NO Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:	-										
				1							
2018 - Sprin	g : No Change										
Comments:											
				1							
2018 - Fall: I	No Change										
Comments:	<u> </u>			1							
				•							
HA No	Material Description M	Material Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

TSI

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

Damage

Units

D	Pipe Joint Insulation on Cardboard Insulated Piping ABATED	Space (1953). Abated. Not observed. Abated
2016 - Fall: I	No Changa	
	NO Criange	
Comments:		
2017 - Sprin	g: No Change	
Comments:		
2017 - Fall: I	No Change	
Comments:		
2018 - Sprin	g : No Change	
Comments:		
2018 - Fall: I	No Change	
Comments:		

HA No

Material Description

Material

Quantity

Material

Units

Units

Quantity

Material Location

Boiler Room, Crawl

X NO

Change in Assessment Category

E	Aircell Pipe Insulation (ABATED)		Boiler Room, Crawl Space (1953). Not observed		TSI				YES	X NO
			•	1	•	•		•		
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring	r: No Change									
Comments:	-			1						
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	<u> </u>			1						
				1						
2018 - Spring	ı : No Change			1						
Comments:				1						
				1						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Boiler Insulation ABATED			Boiler Room. Abated. Not observed. Abated		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

G	Cardboard Pipe Insulation ABATED	Basement Fan Room, Crawl Space (1958). Abated.		TSI			YES	X NO
			- -					
2016 - Fall: N	lo Change							
Comments:								
2017 - Spring	g: No Change							
Comments:	•							
		1						
2017 - Fall: N	lo Change							
Comments:	-							
			1					
2018 - Spring : No Change								
Comments:								
2018 - Fall: No Change								
Comments:	<u> </u>	1						
			1					
			<b>_</b>					

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Pipe Joint Insulation on Cardboard Insulated Piping ABATED			Basement Fan Room, Crawl Space (1958). Abated.		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

I	Pipe Joint Insulation on Fiberglass Insulated Piping ABATED		Crawl Space (1958). Abated.		TSI				YES	X NO
					•	•		•		
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:				1						
2017 - Spring	: No Change									
Comments:				]						
2018 - Spring : No Change										
Comments:										
2018 - Fall: No Change										
Comments:										
1										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Pipe Joint Insulation on Aircell Insulated Piping (ABATED)			Boiler Room, Crawl Space (1953). Abated.		TSI					YES X NO

HA No

Material Description

Material

Quantity

Material

Units

Material Location

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ronald Brown Elementary Community Academy
Date: <u>1/10/2019</u>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.