## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

2018 - Fall

-	chool: ddress:	Norwood Park Elementary School 5900 N Nina Avenue			Oracle Unit: Region:	24711 01	Building ID: Mail Room:	5120 30
			Asbestos Surveyor:	BALL	EN24			
CHECK HE	RE IF N	O CHANGE TO ASBESTOS	Survey Date:	12/17/	2018			
			Email Address:	ballen	@learncharter.org			

	A copy of the2016/20	017 notice to	parents and	I staff regarding the as	bestos manag	ement plan not	ifications w	as distribut	ed via:			
	Each child's back	back	X Notice	printed in school's new	vsletter	Notice prin	nted in sch	ool's calend	ar Ot	ther		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
01	12"x12" White VFT	9450	SF	Throughout (See Hatching Maps) under existing VFT		Miscellaneous	No	None	0		YES	XNO
2016 - Fal	II: No Change											
Comments	0											
2017 - Fal	II: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											
2018 - Fal	II: No Change											
Comments	s:											
<u> </u>												

Χ

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x12" Brown VFT	400	SF	Rm 108 under the carpet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change Comments:	
Comments.	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" White VFT Mastic	9450	SF	Throughout (See Hatching Maps), under existing VFT		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Brown VFT Mastic	400	SF	Rm 108 under the carpet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	2'x4' Dot Pattern Ceiling Tile	1800	SF	Room 107 Storeroom & Toilet, 109 (Lunchroom)		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Brown Linoleum	200	SF	Room 204A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Brown Linoleum Mastic	200	SF	Room 204A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12'x12" Dark Brown VFT	1250	SF	Room 112 & Kitchen (under existing VFT)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change Comments:	
Comments.	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12'x12" Dark Brown VFT Mastic	1250	SF	Room 112 & Kitchen (under existing VFT)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Brown w/ White Streaks VFT	150	SF	Room 204A (under existing VFT)		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Brown w/ White Streaks VFT Mastic	150	SF	Room 204A (under existing VFT)		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Vanilla VFT	200	SF	Dining Room (Teachers Lounge)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Vanilla VFT Mastic	200	SF	Dining Room (Teachers Lounge)		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Light Gray w/ Black Streaks VFT	700	SF	Rooms 109E and 109W		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Light Gray w/ Black Streaks VFT Mastic	700	SF	Rooms 109E and 109W		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Gray VFT	1900	SF	1st Floor Hallway by East, West, and South Entrances		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Gray VFT Mastic	1900	SF	1st Floor Hallway by East, West, and South Entrances		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Exterior Window Caulk			Throughout							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Interior Window Caulk			Throughout							YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" White w/ Tan Specks VFT	120	SF	East and West Stage Vestibules		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" White w/ Tan Specks VFT Mastic	120	SF	East and West Stage Vestibules		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Light Brown Linoleum	100	SF	Doorways of Rooms 102, 105, 202, 204, 205 (under the carpet), 209		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Light Brown Linoleum Mastic	100	SF	Doorways of Rooms 102, 105, 204, 205 (under the carpet), 209		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Carpet Mastic	2000	SF	Rms 108, 201 & 203; Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" X 12" white with grey specks VFT	5600	SF	1st and 2nd floor corridors, stairwells; 1st and 2nd floor boys and girls toilets entry; 2nd floor elev lobby; Main Office; 1st and 2nd floor Janitor's Closet; Room 107 hall		Miscellaneous	No	None	0		YES XNO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" X 12" white with black and grey specks VFT Mastic	5600	SF	1st and 2nd floor corridors, stairwells; 1st and 2nd floor boys and girls toilets entry; 2nd floor elev lobby; Main Office; 1st and 2nd floor Janitor's Closet; Room 107 hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" X 12" Red VFT	3500	SF	1st and 2nd floor corridors, stairwells; Entrances to Rooms 211, 210, 212, 207, 202, and 111; 2nd floor elev lobby; Room 107 hall		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" X 12" Red VFT Mastic	3500	SF	1st and 2nd floor corridors, stairwells; Entrances to Rooms 211, 210, 212, 207, 202, and 111; 2nd floor elev lobby; Room 107 hall		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" X12" beige-streaked VFT	1700	SF	Room 204A (teacher lounge), Room 112, Room 107 toilets, 1st floor teachers washroom, Kitchen Mngr Office		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" X 12" beige-streaked VFT Mastic	1700	SF	Room 204A (teacher lounge), Room 112, Room 107 toilets, 1st floor teachers washroom, Kitchen Mngr Office		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12" X 12" gray with white- and-black specks VFT	200	SF	Room 112 & kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" X 12" gray with white- and-black specks VFT Mastic	200	SF	Room 112 & kitchen		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
н	MJP E/F/V on Fiberglass Pipe Insulation	115	LF	1st and 2nd Fl Boys and Girls Toilets, and Pipe Chases		TSI	Yes	None	0		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Norwood Pa	ark Elementary School
--------------------	-----------------------

Date: 12/17/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

X A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.