Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

William J Onahan Elementary School 24761 5190 School: **Oracle Unit:** Building ID: Address: 6634 W Raven Street Region: 01 Mail Room: Asbestos Surveyor: Bartsch, Henry X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/14/2018 Email Address: hbartsch@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES Hard Coat Plaster X NO 10 Throughout, 1927 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 24761

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Cardboard Pipe Insulation	660	LF	Toilet Pipe Chases, SW, NW & NE Unexcavated, Aud. Plenum, W. Eng. Rm, Boiler, Pump & E. Fan R, 1927		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9"x9" Tan VFT-ABATED			Room 202 (Teacher's Lunchroom), 1927 - ABATED		Miscellaneous		Loc			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
28	Aircell Duct Insulation	2250	SF	SW, NW, S, & NE Unexcavated Spaces, 1927		TSI	Yes	Dist	800		YES X NO	
2016 - Fall: N	lo Change			<u> </u>]							

0040 Fall No Olassa
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Tank Lagging	800	SF	Pump Room, Store Room South Of Boiler Room, 1927		TSI	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Aircell Pipe Insulation	2000	SF	Throughout and East stairs to stage - 1927		TSI	Yes	Dist	80		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	MJP E/F/V on Aircell Pipe Insulation	250	LF	Throughout, 1927		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

44	12"x12" Cream w/Brown Streaks VFT	2200	SF	1st and 2nd Floor Corridors - 1927	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:	-									

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	9"x9" Tan VFT Mastic - ABATED			Room 202 (Teacher's Lunchroom), 1927 - ABATED		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12"x12" Cream w/Brown Streaks VFT Mastic	2200	SF	1st and 2nd Floor Corridors - 1927		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12"x12" White w/Tan Streaks VFT	1300	SF	3rd Floor Corridor, Room 204, Engineers Office, 1927		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
49	12"x12" White w/Tan Streaks VFT Mastic	1300	SF	3rd Floor Corridor, Room 204, Engineers Office, 1927		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change						•	•	•	•	•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12'x12' Brown w/White & Black Streaks VFT	1300	SF	3rd Floor Corridor, Room 204, Engineers Office, 1927		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

51	12"x12" Brown w/White & Black Streaks VFT Mastic	1300	SF	3rd Floor Corridor, Room 204, Engineers Office, 1927		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	9"x9" Brown VFT - ABATED			Room 209 (Library), (Under Carpet), 1927 - ABATED							YES X NO

HA No

Material Description

Material

Quantity

Material

Units

53	9"x9" Brown VFT Mastic - ABATED	Room 209 (Library) (Under Carpet), 1927 - ABATED				YES	X NO
2016 - Fall: N	lo Change		7				
Comments:	io chango		†				
_							
2017 - Spring	յ։ No Change						
Comments:							
2017 - Fall: N	lo Change						
Comments:							
2018 - Spring	ı : No Change						
Comments:							
2018 - Fall: N	lo Change						
Comments:		·					

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	9"x9" Brown w/Brown & White Streaks VFT	750	SF	Room 108 (Teacher's Restroom)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	9"x9" Brown w/Brown & White Streaks VFT Mastic	750	SF	Room 108 (Teacher's Restroom)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	9"x9" Beige w/Brown & Cream Streaks VFT	4500	SF	Room 101 (Kindergarten) and closet, 1st Floor Corridor, 1927		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

57	9"x9" Beige w/Brown & Cream Streaks VFT Mastic	4500	SF	(Kindergarten), and closet, 1st Floor Corridor, 1927		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	all: No Change										
Commen											
2017 - Sp	oring: No Change										
Commen	ts:										
2017 - Fa	all: No Change										
Commen	ts:										
	oring : No Change										
Commen	ts:										
	all: No Change										
Commen	ts:										
<u> </u>					I						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
58	9"x9" Beige VFT - ABATED			Small hallway NW of room 102 - 1927 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	o Change		*				•		,	•		
0047 0 0	N. Observe											

HA No

Material Description

Material

Units

Material

Quantity

Material Location

59	9"x9" Beige VFT Mastic - ABATED			Hallway NW of 102, 1927 - ABATED		Miscellaneous		None			YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:	· · · · · · · · · · · · · · · · · · ·											
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	2018 - Spring : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
60	9"x9" Gray VFT - ABATED			Room 102, 1927 (ABATED)		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Units

Material

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
61	9"x9" Gray VFT Mastic - ABATED			Room 102, 1927 (ABATED)		Miscellaneous		None			YES	X NO
2016 - Fall: N	No Change	•										
Comments:	•											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:	<u> </u>											
2018 - Fall: N	No Change				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	12"x12" White VFT	600	SF	Main Office & Main Office Store Room, 1927		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
63	12"x12" White VFT Mastic	600	SF	Main Office & Main Office Store Room, 1927		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	MJP E/F/V on Cardboard Pipe Insulation	180	LF	Toilet Pipe Chases, SW, NW & NE Unexcavated, Aud. Plenum, W. Eng. Rm, Boiler, Pump & E. Fan R, 1927		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

66	MJP E/F/V on Fiberglass Pipe Insulation			Throughout 1927		TSI	Yes				YES	X NO
2016 - Fall: I	No Change]							
Comments:	<u> </u>]							
2017 - Sprin	g: No Change				_							
Comments:]							
2017 - Fall: I	No Change											
Comments:					_							
2018 - Sprin	g : No Change				<u> </u>							
Comments:					_							
2018 - Fall: I	No Change				<u> </u>							
Comments:					_							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

67	12"x12" Beige w/ White Specs VFT	1600	SF	Lunch Room, 1995
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

HA No

Material Description

Material

Units

Material

Quantity

Material Location

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12"x12" Beige w/ White Specs VFT Mastic	1600	SF	Lunch Room, 1995		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12"x12" Brown w/ Black Specs VFT	1300	SF	Lunch Room, 1995		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
70	12"x12" Brown w/ Black Specs VFT Mastic	1300	SF	Lunch Room, 1995		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12"x12" Black VFT	250	SF	Lunch Room, 1995		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
72	12"x12" Black VFT Mastic	250	SF	Lunch Room, 1995		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12"x12" Blue VFT	25	SF	Lunch Room, 1995		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

74	12"x12" Blue VFT Mastic	25	SF	Lunchroom, 1995		Miscellaneous	No	None	0	YES	X NO
					1						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Fall: N	o Change										
Comments:	-										
2018 - Spring	: No Change										
Comments:											
	·	•		<u> </u>	5						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Black Rubber Flooring			Food Storage, Serving Area, Prep Area, 1995							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
76	Black Rubber Flooring Mastic			Food Storage, Serving Area, Prep Area, 1995							YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Spring	: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Fall: N	lo Change				=							
Comments:					1							
2018 - Spring	: No Change											
Comments:					=							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	2'x2' White Ceiling Tile			Serving Area, Prep Room, Serving Area Toilet, 1995							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
78	2'x2' Dot White Ceiling Tile			Lunch Room, Lunch Room Office, 1995							YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	-											
2017 - Fall: N	o Change											
Comments:	-											
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Vinyl Baseboard			Lunch Room, 1995							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
80	Vinyl Baseboard Mastic			Lunch Room, 1995							YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:					_							
	g : No Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12"x12" Black VFT	1500	SF	Auditorium and Under Carpet, 1927		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	12"x12" Black VFT Mastic	1500	SF	Auditorium and Under Carpet, 1927		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2010 0 : 11 01
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12"x12" Red VFT	1500	SF	Auditorium and Under Carpet, 1927		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12"x12" Red VFT Mastic	1500	SF	Auditorium and Under Carpet, 1927		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	6"x18" Black VFT	100	SF	Auditorium and Under Carpet, 1927		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

86	6"x18" Black VFT Mastic	100	SF	Auditorium and Under Carpet, 1927		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:	<u> </u>										
2017 - Fall: N	o Change										
Comments:	-										
2018 - Spring	: No Change										
Comments:	-										
2018 - Fall: N	o Change										
Comments:											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Carpet Mastic	1100	SF	Auditorium, 209, Main Office, Principals Office - 1975		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	Terrazzo Floor	3500	SF	Stariwells (Throughout Building 1st to 3rd floors), Auditorium (Stairs to Stage), Auditorium (Balcony Stairwell), 1st Floor vestibules - 1927		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24761

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	12" x 12" Gray Streaked VFT	60	SF	1st, 2nd and 3rd floor hall to new addition building - 1929 Building		Miscellaneous	No	None	0		YES X NO
		· · · · · · · · · · · · · · · · · · ·					•	-			

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	12" x 12" VFT Mastic	60	SF	1st, 2nd and 3rd floor hall to new addition building - 1929 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	12" x 12" Blue Streaked VFT	120	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	
2018 - Fall: No Change	2018 - Spring : No Change
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	12" x 12" Blue Streaked VFT Mastic	120	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	12" x 12" Light Blue Streaked VFT	150	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		Miscellaneous	No	None	0		YES X NO
	•	•	=	-	•	•	•	•	•	=	•

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	12" x 12" VFT Mastic	150	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12" x 12" White with Gray Streaks VFT	460	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•	•	•]	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	12" x 12" VFT Mastic	460	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		Miscellaneous	No	None	0		YES X NO

97	4' x 4' White Ceiling Tile	500	SF	1st, 2nd and 3rd floor hall to new addition building - 1929 Building		Miscellaneous	Yes	None	0		YES	X NO
0040 Fall N	la Obasa				1					•	•	
2016 - Fall: N	No Change											
Comments:												
2017 - Spring: No Change												
Comments:												
					1							
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Spring	g : No Change											
Comments:	<u> </u>											
					1							
					•							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Type

Damage

Quantity

Damage

Units

98	Heat Barrier Paper	30	SF	radiator (bench) cover along exterior wall - Building 1927								
0040 F.II N	I. Ol											
2016 - Fall: N	io Change											
Comments:	Comments:											
2017 - Spring	j: No Change											
Comments:	Comments:											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Room 101 - Inside

1st, 2nd and 3rd floor hall

YES

X NO

99	Decorative Plaster	1500	SF	Assembly Hall		Surface	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Fall: N	lo Change				-							
Comments:					1							
2017 - Spring	: No Change				= 							
Comments:					-							
2018 - Fall: N	lo Change				1							
Comments:					-							
	: No Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:	·	

3000

HA No

100

Material Description

Spray-on Fire Proopfing

Material

Quantity

Material

Units

SF

Material Location

Lunch room and Kitchen -

1995 Builiding

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
101	12"x12" Beige w/ Tan Streaks VFT	400	SF	Room 210		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101A	12"x12" Beige w/ Tan Streaks VFT Mastic	400	SF	Room 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	12" X 12" Off-white streaked VFT	400	SF	Room 210		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102A	12" X 12" Off-white streaked VFT Mastic	400	SF	Room 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William J Onahan Elementary School
Date: 12/15/2018
·
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.