Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

24781

Oracle Unit:

Address: 1040 N. Keeler Avenue Region: 02 Mail Room: Asbestos Surveyor: Acevedo, Andres X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2018 Email Address: aacevedo22@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 1st. 2nd. & 3rd Floor YES X NO Janitor Closets, 2nd Floor MJP on Aircell Pipe 015 15 LF Boys & Girls Toliets, TSI Yes Loc 0 Insulation Crawl Under Auditorium -1918 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Brian Piccolo Elementary Specialty School

School:

Oracle Unit: 24781

5210

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
030	Sink Undercoat (Black)	20	SF	Rooms 214, 314 & 229,1918 Building 225 and 227 Lab - 1965 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	III: No Change				7							
Comment	<u> </u>											
2017 - Sp	oring: No Change				-							
Comment	ts:											
2017 - Fa	III: No Change				-							
Comment	ts:											
2018 - Sp	oring : No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
031	Gray Coating on Sink Basin	4	SF	Kitchen - 1965 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

032	Gray Coating on Sink Basin	100	SF	125 - 1965 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
L					J						

Type

Material

Category

Damage Quantity Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
036	MJP on Fiberglass Pipe Insulation	105	LF	N&S Unexcavated Areas, Kitchen, Base Kitchen Store, Locker Room, Shower Room, Base Stairwell - 1965		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
050	MJP on Fiberglass Pipe Insulation	193	LF	1st, 2nd, & 3rd Floor Boys & Girls Toliet Chases, 201, 202, 203, 204, 205, 206, 101, 102 - 1918 Bldg. Removed 2 ft and 5 ft in Rooms 101 and 202, respectively.		TSI	Yes	None	0		YES X NO

MJP on Cardboard Pipe Insulation 700 LF Service 1. St., 2nd, & 3rd Floor JC's, Auditorium Toliet, Crawl Under Auditorium, Attic - 1918 Bldg. TSI Yes None 0 YES X NO		HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	(051	•	700	LF	JC's, Auditorium Toliet, Crawl Under Auditorium,		TSI	Yes	None	0		

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
052	Air Cell Pipe Insulation	800	LF	1st, 2nd, & 3rd Floor N&S JC's, 2nd Floor Boys & Girls Toliets, Crawl Under Auditorium - 1918 Bldg.		TSI	Yes	None	0		YES X NO

			Additoriani	1310 Diag.
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:	·			

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
054	Cardboard Pipe Insulation	600	LF	1st, 2nd, & 3rd Floor JC's, Auditorium Toliet, Crawl Under Auditorium, Attic - 1918 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fal	I: No Change]							
Comments	•											
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fal	I: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	S:											
2018 - Fal	I: No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
055	Mortar	500	SF	Air Tunnel, Attic, Washrooms - 1918 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
061	12"x12" Dark Brown VFT	950	SF	Room 208 ABATED - 1918 Bldg. 1st Floor Reading Room and Main Office remains.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 7

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmo	ent Category
062	2	12"x12" Dark Brown VFT Mastic	950	SF	Room 208 ABATED - 1918 Bldg. 1st Floor Reading Room and Main Office remains.		Miscellaneous	No	None	0		YES	X NO
201	6 - Fall: N	n Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
063	9"x9" Green VFT	1500	SF	1st Floor Store Room - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units		
064	9"x9" Green VFT Mastic	1500	SF	1st Floor Store Room - 1918 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	g: No Change				1							
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	•]							
2018 - Spring	g : No Change				1							
Comments:	•											
2018 - Fall: N	lo Change				-							

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
065	12"x12" Pink VFT	60000	SF	Throughout - 1965 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
066	12"x12" Pink VFT Mastic	60000	SF	Throughout - 1965 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
067	9"x9" Green & 9"x9" Beige/Brown Checker Board Patterned Floor Tile	0	SF	1st Floor Lunchroom - 1965 Bldg. 2500 SF removed in 2012.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
068	9"x9" Green & 9"x9" Beige/Brown Checker Board Patterned Floor Tile Mastic	0	SF	1st Floor Lunchroom - 1965 Bldg. 2500 SF removed in 2012.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 0 1 11 01
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
069	12"x12" Blue VFT	63000	SF	Throughout - 1965 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
070	12"x12" Blue VFT Mastic	63000	SF	Throughout - 1965 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change				-							
Comments:												
2017 - Fall:	No Change											
Comments:	_											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change				-							
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
071	2'x4' White Ceiling Tile	120000	SF	Throughout - 1965 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
072	2'x4' White Ceiling Tile	5000	SF	Throughout Hallways - 1918 Bldg.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	•											
2017 - Sprin	g: No Change				_							
Comments:	J											
2017 - Fall: N	No Change				1							
Comments:	<u> </u>]							
2018 - Sprin	g : No Change				1							
Comments:	<u> </u>											
2018 - Fall: N	No Change				1							
Comments:	·-···g-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
073	Hard Coat Plaster	100000	SF	Throughout 1918		Surface	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
074	12"x12" White Ceiling Tile	2000	SF	Upper Library, 2000 SF (1918 Bldg.) Removed/replaced but NOT ABATED. Classrooms throughout school were replaced with drop 2' X 4' ceiling tiles EXCEPT Upper Library and Student Dining Area.		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
075	12"x12" White VFT - NOT OBSERVED	2500	SF	1st Floor Store Room, Main Office, Reading Room (#208) - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
076	12"x12" White VFT Mastic - NOT OBSERVED	2500	SF	1st Floor Store Room, Main Office, Reading Room (208) - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
077	12"x12" White w/ Brown Streaks VFT	1500	SF	1st FI: Rm 109 (principals's office), Offices #5, #6, #9, #10 & #11, Assistant Principal's Office Area - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
078	12"x12" White w/ Brown Streaks VFT Mastic	1500	SF	1st Fl: Rm 109, Offices #5, #6, #9, #10 & #11, Assistant Principal's Office Area - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
079	12"x12" Brown w/ White & Black Streaks VFT	630	SF	(Room #204 - Closet Only) & Room #102 (NOT OBSERVED) -1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
080	12"x12" Brown w/ White & Black Streaks VFT Mastic	630	SF	Closet Only (Room 204) and room #102 (NOT OBSERVED) - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24781

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
081	12"x12" Beige w/ Brown Streaks VFT	1600	SF	Rooms 101, 103, 111 - 1918 Bldg. (A total of 1400 SF of tile/mastic were removed from Rooms 112 and 210 in 2012.)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
082	12"x12" Beige w/ Brown Streaks VFT Mastic	1600	SF	Rooms 101, 103, 111 - 1918 Bldg. (A total of 1400 SF of tile/mastic were removed from Rooms 112 and 210 in 2012.)		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
083	12"x12" Brown Grain VFT	750	SF	Room 209 - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
084	12"x12" Brown Grain VFT Mastic	750	SF	Room 209 - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
085	12"x12" Light Brown VFT	1500	SF	Rooms 204 (NOT OBSERVED), 304 & 305 - 1918 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
086	12"x12" Light Brown VFT Mastic	1500	SF	Rooms 204 (NOT OBSERVED), 304 & 305 - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
087	9"x9" White VFT (NOT OBSERVED)	0	SF	Room 314 - 1918 Bldg.		Miscellaneous					YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change				-							
Comments:	<u> </u>				1							
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	•				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
088	9"x9" White VFT Mastic (NOT OBSERVED)	0	SF	Room 314 - 1918 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
089	12"x12" Off White VFT	1500	SF	Rooms 304 & 305 - 1918 Bldg.		Miscellaneous		None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
090	12"x12" Off White VFT Mastic	1500	SF	Rooms 304 & 305 - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
091	12"x12" Off White w/ Beige Streaks VFT	2100	SF	Rooms 203, 205, 301, 303, 308, 309 - 1918 Bldg. (500 SF removed from Rm 202 in 2012.)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
<u> </u>

Oracle Unit: 24781

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
092	12"x12" Off White w/ Beige Streaks VFT Mastic	2100	SF	Rooms 203, 205, 301, 303, 308, 309 - 1918 Bldg. (500 SF removed from Rm 202 in 2012)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
093	12"x12" White w/ Yellow Streaks VFT	800	SF	1st Floor Dean's Office - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

12"x12" White w/ Yellow								
094 Streaks VFT Mastic (NC OBSERVED)	SF	1st Floor Dean's Office - 1918 Bldg.	Miscellaneous	No	None	0	YES	X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
095	12"x12" Peach VFT	900	SF	Room 310 - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 27

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
096	12"x12" Peach VFT Mastic	900	SF	Room 310 - 1918 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
2017 - Spring Comments:	: No Change											
2017 - Fall: N Comments:	o Change											
2018 - Fall: N Comments:	o Change											
2018 - Spring Comments:	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
097	9"x9" White w/ Black Streaks VFT (NOT OBSERVED)	0	SF	Room 205 Wardrobe- 1918 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

098	9"x9" White w/ Black Streaks VFT Mastic (NOT OBSERVED)	0	SF	Room 205 Wardrobe - 1918 Bldg.		Miscellaneous			YES	X NO
2016 - Fall: N	la Changa				1					
	io Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:					1					
2018 - Spring	g : No Change									
Comments:					1					
					1					
					-					

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
099	Gray Fireproofing	60000	SF	Throughout - 1965 Bldg.		Surface		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	9"x9" Spotted Brown VFT (Under New VFT)	1310	SF	Rooms 110, 1st floor storage - 1918 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	9"x9" Spotted Brown VFT Mastic (Under New VFT)	1310	SF	Rooms 110, 1st floor storage - 1918 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 30

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
102	9"x9" Beige VFT	759	SF	1st Floor Store Room and 303 MDF Closet, 3rd Floor Janitors Closet - 1918 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Spring: No Change												
Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	9"x9" Beige VFT Mastic	759	SF	1st Floor Store Room and 303 MDF Closet, 3rd Floor Janitors Closet - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

104	12"x12" Beige VFT	750	SF	Room 102; Storage (Room 104) - 1918 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	to onange											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	J											
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Units

YES

X NO

Damage

Units

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Quantity

750

Units

SF

HA No

105

Material Description

12"x12" Beige VFT Mastic

Material

Quantity

Material

Units

Material Location

Room 102; Storage (Room 104) - 1918 Bldg

106	9"x9" Tan VFT - (REMOVED 2012)			Lunchroom - 1965 bldg. (3000 SF removed in 2012)		Miscellaneous					YES	X NO
2016 - Fall:	No Change	·	•	•	1							
Comments:	140 Change											
2017 - Fall:	No Change											
Comments:	-											
2017 - Sprin	ng: No Change				1							
Comments:												
2018 - Fall:	No Change				1							
Comments:	Ü											
2018 - Sprin	ng : No Change				-							
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Asbestos

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

107	9"x9" Tan VFT Mastic (REMOVED 2012)		(3000 SF removed in 2012)
2016 - Fall: N	No Change		
Comments:			
2017 - Spring	g: No Change		
Comments:			
2017 - Fall: N	No Change		
Comments:			
2018 - Spring	g : No Change		
Comments:			
2018 - Fall: N	No Change		
Comments:			
1	·		·

Quantity

Units

HA No

Material Description

9"x9" Tan VFT Mastic

Material

Quantity

Material

Units

Material Location

Lunchroom - 1965 bldg.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	Terrazo	3000	SF	1st fl corridor and stair, landings - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2010 0 : 11 01
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	Brown Carpet Adhesive	1600	SF	Room 306/3071918 Building:		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
110	Adobe Mosaic Ceramic Tile Grout	2300	SF	1918 Building: 1st, 2nd & 3rd Floor Girl's & Boy's Washrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											

0040 5 11 11 01
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	Adobe Masaic Ceramic Tile Adhesive	2300	SF	1918 Building: 1st, 2nd & 3rd Floor Girl's & Boy's Washrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12"x12" Sand Colored Floor Tile	1090	SF	1918 Building: Room 205		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12"x12" Sand Colored Floor Tile Adhesive	1090	SF	1918 Building: Room 205		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
114	12"x12" Gray Floor Tile	930	SF	1918 Building: Room 202		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	12"x12" Gray Floor Tile Adhesive	930	SF	1918 Building: Room 202		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
116	12"x12" White w/Multi- Specks Floor Tile	1000	SF	1918 Building: Room 110		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	12"x12" White w/Multi- Specks Floor Tile Adhesive	1000	SF	1918 Building: Room 110		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 38

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
118	12"x12" Blue Floor Tile	500	SF	1918 Building: Room 110		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments												
2017 - Spri	ng: No Change				-							
Comments												
2017 - Fall:	No Change											
Comments	•											
2018 - Fall:	No Change											
Comments	<u> </u>											
2018 - Spri	ng : No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	12"x12" Blue Floor Tile Adhesive	500	SF	1918 Building: Room 110		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	Blue Carpet Adhesive	2000	SF	1918 Building: Assembly Hall NOT OBSERVED. Removed/covered in 2012 with 24" X 24" gray slip-free rubber flooring.		Miscellaneous	No	None	0		YES X NO
2016 - Fall	l: No Change]						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 24781

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
121	Red Terrazzo	2850	SF	1965 Addition: 2nd & 3rd Floor Stairways		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	No Change]								
Comments:]								
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	No Change												
Comments:													
2018 - Fall: N	No Change												
Comments:													
2018 - Spring	g : No Change				-								
Comments:	_												
					_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	Mosaic Ceramic Tile Grout	4170	SF	1965 Addition: 1st, 2nd & 3rd Floor Giorl's & Boy's Washrooms		Miscellaneous	No	None	0		YES X NO

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1773	Mosaic Ceramic Tile Adhesive	4170	SF	1965 Addition: 1st, 2nd & 3rd Floor Giorl's & Boy's Washrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	12"x12" White Floor Tile w/Tan Specks	1400	SF	1965 Addition: Room 129 & 122		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
125	12"x12" White Floor Tile w/Tan Specks Adhesuve	1400	SF	1965 Addition: Room 129 & 122		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
126	12"x12" White Fissured Ceiling Tile	4500	SF	1965 Addition: Lunchroom		Miscellaneous	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
127	12"x12" White Fissured Ceiling Tile Adhesive	4500	SF	1965 Addition: Lunchroom		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:					_							
2017 - Spring	: No Change											
Comments:					1							
2017 - Fall: N	o Change				-							
Comments:												
2018 - Fall: N	o Change				1							
Comments:	Ü											
2018 - Spring	: No Change				-							
Comments:	J				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	12" X 12" tan with white streaks, VFT	1960	SF	Vault Main Office (60 SF); Main Office Reception Area (1200 SF); Rm 104 (700 SF). All in 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
129	12" X 12" tan with white streaks, Mastic	1960	SF	Vault Main Office (60 SF); Main Office Reception Area (1200 SF); Rm 104 (700 SF). All in 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 24781

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
130	Transite hood	20	SF	Rm 305 Lab Work Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	_]							
2017 - Sprin	g: No Change				-							
Comments:	.											
2017 - Fall: I	No Change				-							
Comments:												
2018 - Fall: I	No Change				_							
Comments:	<u>-</u>											
2018 - Sprin	g : No Change				1							
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
131	Transite sink & counterop	215	SF	Lab Work Rooms in 303, 305, 306; Biology Lab in Rm 301.		Miscellaneous	No	None	0		YES X NO

HA No

Change in Assessment Category

HA No M	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 1 3 /	12x12 Beige w/ Streaks VFT - 1965 Bldg	9000	SF	Rooms 124, 126, 213, 214, 215, 218, 222, 224, Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
133	12x12 Beige w/Streaks VFT Mastic - 1965 Bldg	9000	SF	Rooms 124, 126, 213, 214, 215, 218, 222, 224, Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	o Elementary Specialty School
Date: 12/21/2018	
the Asbestos Managem	ccordance with Illinois and Federal Asbestos Regulations, that a copy of ent Plan is available at each school during school hours by appointment.
Requests to review the	Asbestos Management Plan must be made at least 24 hours in advance.
The last inspection was	that CPS conducts asbestos inspections of all Schools every three years. completed in 2016. are conducted every six months.
CHECK ONE	
CHECK ONE	
A copy of this notice	ce was sent home in each child's backpack.
A copy of this notice	ce was printed in the school's newsletter and sent home with each child
A copy of this notice	ce was printed in the school's calendar and sent home with each child
Other.	
A COPY OF THIS N	OTICE MUST BE PLACED IN THE
	ESTOS MANAGEMENT PLAN.