Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

James Otis Elementary School 24791 5220 School: **Oracle Unit: Building ID:** Address: 525 N. Armour Street Region: 02 Mail Room: Asbestos Surveyor: Mero, Rafael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: rmero1@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 12"x12" Gray with White 1st, 2nd & 3rd Floor YES 09 SF X NO 2400 Miscellaneous No None 0 Streaks Floor Tile Corridors - 1916 Bldg. 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
10	Multiple Color Linoleum (NOT OBSERVED)	550	SF	Girl's Playroom & Ladies Dressing Room near Girl's Playroom - 1916 Bldg.		Miscellaneous			0		YES	X NO
2016 - Fall:]							
Comments:					<u> </u>							
2017 - Spring: No Change												

Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
12	12"x12" Gray with White Streaks Floor Tile Mastic	2400	SF	1st, 2nd & 3rd Floor Corridors - 1916 Bldg.		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material D	escription	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	Multiple Col Mastic (NOT	or Linoleum OBSERVED)	550	SF	Girl's Playroom & Ladies Dressing Room near Girl's Playroom - 1916 Bldg.		Miscellaneous			0		YES	X NO
2016 -	Fall: No Change					1							

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Green Linoleum	750	SF	Room 205 - 1893 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
15	Green Linoleum Mastic	750	SF	Room 205 - 1893 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
0047 On the s	N. O	-										

Comments:

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

2018 - Spring: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
18	12"x12" Off-White with Speckles Floor Tile	1000	SF	Basement Corridor, 109 - 1893 Bldg.		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
19	12"x12" Off-White with Speckles Floor Tile Mastic	1000	SF	Basement Corridor, 109 - 1893 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	2016 - Fall: No Change Comments:											

2016 - Fall: No Change	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Hard Coat Plaster	20000	SF	Throughout Building - 1893 Bldg.		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	
21	Hard Coat Plaster	15000	SF	Throughout Building - 1916 Bldg.		Surface	No	None	0		YES XN	O
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	MJP E/F/V on Fiberglass Pipe Insulation	150	LF	Boys Basement Toilet		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

26 In the state of	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	26	Ŭ .	3000	SF	Corridors (304, 305) Library, 204 -		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Light Brown with Speckles Floor Tile Mastic	3000	SF	1st, 2nd & 3rd Floor Corridors (304, 305) Library, 204 - 1893 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	·	Quantity	Units		Туре	Category	Туре	Quantity	Units	Ü	
28	12"x12" Gray with White Streaks Floor Tile	20	SF	Room 205 - 1893 Bldg.		Miscellaneous		0		YES	X NO
2016 - Fall: N	o Change]						
Comments:	J										
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Asbestos

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Gray with White Streaks Floor Tile Mastic	20	SF	Room 205 - 1893 Bldg.		Miscellaneous			0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Light Brown with Pink & Dark Streaks Floor Tile	1200	SF	Rooms 204 & 408 - 1893 Bldg.		Miscellaneous	No	Dist	40		YES X NO
2016 - Fall: N	lo Change	•	•			•	•	•	•	•	•

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Light Brown with Pink & Dark Streaks Floor Tile Mastic	1200	SF	Rooms 204 & 408 - 1893 Bldg.		Miscellaneous	No	Dist	40		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	2'x4' White Ceiling Tile	750	SF	Room 404, 407 - 1893 Bldg.		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" Light Beige w/Speckles Floor Tile	1500	SF	Room 105 & Primary Gymnasium (110) - 1893 Bldg.		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Light Beige with Speckles Floor Tile Mastic	1500	SF	Room 105 & Primary Gymnasium (110) - 1893 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Dark Gray with White Streaks Floor Tile	700	SF	Lunchroom 3 - 1916 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

36	12"x12" Dark Gray with White Streaks Floor Tile Mastic	700	SF	Lunchroom 3 - 1916 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	: No Change			<u> </u>	7							
Comments	<u> </u>											
2017 - Spr	ing: No Change				1							
Comments					=							
2017 - Fal	: No Change											
Comments	S:											
2018 - Spr	ing : No Change											
Comments	S:				_							
2018 - Fal	: No Change											
Comments	S:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
37	Burlap/Canvas	20000	SF	2nd & 3rd Floor Corridors, 2nd & 3rd Floor Staircase - 1916		Miscellaneous	No	None	0		YES	X NO

Material

Category

Asbestos

Type

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Floor Staircase - 1916

Change in Assessment Category

	,	Quantity	Units		Туре	Category		Туре	Quantity	Units		,
40	12"x12" Light Brown w/Speckles VFT	1200	SF	Room 213 & Closet - 1916 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

Asbestos

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Light Brown with Speckles Floor Tile Mastic	1200	SF	Room 213 & Closet - 1916 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
42	12"x12" Off-White Floor Tile	1500	SF	Basement Corridor & Girl's Playroom - 1916 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	•	•	•]	•	•		•		•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Off-White Floor Tile Mastic	1500	SF	Basement Corridor & Girl's Playroom - 1916 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	MJP E/F/V on Fiberglass Pipe Insulation	50	LF	Girls Playroom - 1916 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Particle Board	1800	SF	Boiler Room - Field House		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12"x12" Ceiling Tile	750	SF	Room 304 (Library) - 1893 Bldg.		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change	
Comments:	
	-
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53A	12"x12" Ceiling Tile Adhesive	1200	SF	Room 304 (Library) - 1893 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
56	12"x12" Brown with White Streaks Floor Tile	2420	SF	101, Kitchen, Lunch Room Store Room - 1916 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change		•	•]	•	•	•	•	•	•	

<u></u>
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"x12" Brown with White Streaks Floor Tile Mastic	2420	SF	101, Kitchen, Lunch Room Store Room- 1916 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12"x12" Sand Floor Tile	2500	SF	Main Office, Principals Office & Storage, 1st through 4th Floor Faculty Toilet, Room 201, lunchroom 2 - 1916 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24791

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	12"x12" Sand Floor Tile Mastic	2500	SF	Lunchroom 2, Main Office, Principals Office & Storage, 1st through 4th Floor Faculty Toilet, Room 201 - 1916 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Blue Multicolored Carpet Mastic	1400	SF	4th and 3rd, Teachers Lounge and Room 104		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: James Otis Elementary School
Date: 1/8/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 24791

SCHOOL'S ASBESTOS MANAGEMENT PLAN.