## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

24991

**Oracle Unit:** 

**Building ID:** Address: 646 N. Lawndale Avenue Region: 02 Mail Room: Asbestos Surveyor: Mallett, Glenda X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/11/2018 Email Address: gmallett@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Third Floor Teachers 9"x9" Gray VFT (Not YES X NO 01 Lunchroom, 1891 Miscellaneous Observed) Building 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Laura S Ward Elementary School

School:

5680

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x12" Off White VFT	2400	SF	Pre-School (Room 014), Pre-School (Room 410), Engineers Office, Civic Room (Room 12), 1891 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Brown Linoleum	800	SF	Room 111 (Under New Wood Floor), 1936 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

06	Aircell Duct Insulation	600	SF	Basement Corridor, 1915 Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<b>-</b>											
2017 - Spring: No Change												
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Yes

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

Change in Assessment Category

200

SF

HA No

07

Drywall

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Basement Corridor, 1915

Pre-School (Room 014),

1891 Building

YES

X NO

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
08	Vinyl Baseboard	2000	LF	Throughout, 1891 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	l: No Change											
Comments	3:				4							
2017 - Spr	ring: No Change											
Comments	S:											
2015 5 1												
2017 - Fal	I: No Change											
Comments	S:											

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Vinyl Baseboard Mastic	2000	LF	Throughout, 1891 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
10	Brown Linoleum Mastic	400	SF	Auditorium Stage West Vestibule, 1915 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Fire Brick	20	SF	Boiler Room, 1891 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	Boiler Gasket	3	SF	Boiler #2, 1891 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:												
2017 - Spring	g: Other											
	eplaced rubber				1							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Boiler Door Material (Hard)	50	SF	Boiler Room, 1891 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

	I .									
18	Boiler Door Material (Soft)	20	SF	Boiler Room, 1891 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
	o onange									
Comments:										
2017 - Spring	: Other									
Comments:re	placed gasket									
O O I I I I I I I I I I I I I I I I I I	placed gacket									
2047 Fall N	la Changa									
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:	,									
Comments.										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Gray VFT Mastic (Not Observed)			Third Floor Teachers Lunchroom, 1891 Building		Miscellaneous	No	None			YES X NO

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9"x9" Red VFT	1250	SF	Basemnt Teachers Rm - 1936 Building; NOT OBSERVED in Basement Corri., 1st Floor Corri 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 8

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9"x9" Red VFT Mastic	1250	SF	Basement Teacher's Rm -1936 Bldg.; NOT OBSERVED in Basement Corri., 1st Floor Corri 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Brown Linoleum Mastic	800	SF	Room 111 (Under New Wood Floor and HA # 05), 1936 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" White w/ Orange Streaks VFT	500	SF	First Floor Passageway (to 1891 Building), 1936 Building		Miscellaneous	No	None	0		YES X NO
					i						_

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" White w/ Orange Streaks VFT Mastic	500	SF	First Floor Passageway (to 1891 Building), 1936 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments:	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" White w/ Orange Streaks VFT	9550	SF	Kitch. Off., Assembly Hall (Isles Only) and Stage, 1st Flr. Corr., Rms 101- 104, 1915 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" White w/ Orange Streaks VFT Mastic	9650	SF	Kitch. Off., Assembly Hall and Stage, 1st Flr. Corr., Rms 101-104, 1915 Building		Miscellaneous	No	None	0		YES X NO

			Dulluling
2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:	·		·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Off White VFT Mastic	3000	SF	Pre-School (Room 014), Pre-School (Room 410), Engineers Office, Civic Room (Room 12), 1891 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24991

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33	Brown Linoleum	100	SF	Auditorium Stage West Vestibule, 1915 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				]							
Comments												
2017 - Spr	ring: No Change				_							
Comments	3:											
2017 - Fal	l: No Change											
Comments	3:				-							
2018 - Spr	ring : No Change											
Comments	3:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	1'x1' Ceiling Tile	7000	SF	Basement and 1st Floor Corridors, 1936		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	1'x1' Ceiling Tile	3000	SF	Lunch Room, Room 202, 204, 1915		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Tank Insulation	61	SF	Boiler Room, 1891 Building		TSI	Yes	None	0		X YES NO

2016 - Fall: Abated
Comments:old insulation abated and replaced
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Cardboard Pipe Insulation	60	LF	Lunchroom, 1915 Building		TSI	Yes	None	0		YES X NO

		·	·
2016 - Fall: No Cl	hange		
Comments:			
2017 - Spring: No	Change		
Comments:			
2017 - Fall: No Cl	hange		
Comments:			
2018 - Spring : No	o Change		
Comments:			
2018 - Fall: No Cl	hange		
Comments:			
		•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	MJP E/F/V on Cardboard Pipe Insulation	2	LF	Lunchroom, 1915 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	MJP E/F/V on Fiberglass Pipe Insulation	150	EA	Basement Corr., Bsmnt thru 3rd FIr. Boys TIt, Bsmnt Jan. Closet, 2nd & 3rd FIr. Jan. Clst, 1915 Bldg		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Aircell Pipe Insulation	55	LF	Lunchroom and Basement Corridor by Fan Room 1915 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	MJP E/F/V on Aircell Pipe Insulation	8	LF	Lunchroom and Basement Corridor by Fan Room 1915 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	Basement Boys Toilet, Teachers Room, Fan Room, 1936 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
43	1'x1' Ceiling Tile	12000	SF	Throughout 1891		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change								•			
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
1					[							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	9"x9" White VFT (NOT OBSERVED)	1400	SF	Basement Lunchroom, 1915 Building (NOT OBSERVED)		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	9"x9" White VFT Mastic NOT OBSERVED	1400	SF	Basement Lunchroom, 1915 Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Beige VFT	15	SF	Basement Lunchroom, 1915 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

47	12"x12" Beige VFT Mastic	15	SF	Basement Lunchroom, 1915 Building		Miscellaneous	No	None	0	YES	X NO
					i						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:	-										
2018 - Fall: N	o Change										
Comments:	-										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12"x12" Gray VFT (Not Observed)			Auditorium, 1915		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
49	12"x12" Gray VFT Mastic (Not Observed)			Auditorium, 1915							YES	X NO
2016 - Fall: N	o Change				7							
Comments:	Ü											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:					4							
2018 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	o Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	9"x9" Black VFT	1250	SF	Basemnt Teachers Rm - 1936 Building; NOT OBSERVED in Basement Corri., 1st Floor Corri 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	9"x9" Black VFT Mastic	1250	SF	Basemnt Teachers Rm - 1936 Building; NOT OBSERVED in Basement Corri., 1st Floor Corri 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24991

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12"x12" White w/ Beige Streaks VFT	3000	SF	1st and 2nd Floor Corridor, 1891 Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12"x12" White w/ Beige Streaks VFT Mastic	3000	SF	1st and 2nd Floor Corridor, 1891 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12"x12" White w/ Green Streaks VFT	3200	SF	Rm. 205 & Wardrobe, Rm 206, Rm 207/Ward thru Rm 209/Ward., Rm 210/Ward.,2nd Flr.Tchrs Tlt, 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24991

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12"x12" White w/ Green Streaks VFT Mastic	3200	SF	Rm. 205 & Wardrobe, Rm 206, Rm 207/Ward thru Rm 209/Ward., Rm 210/Ward.,2nd Flr.Tchrs Tlt, 1891 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
56	12"x12" White w/ Gray Streaks VFT	6830	SF	Teachers Tlt Nxt to Rm 306,Teacher's Lunchroom, 3rd Floor Corridor, 306 & 307, 307B, 305 & Ward, 309 & Wrd, Rm 310 & Wrd, 1891 Bldg		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
57	12"x12" White w/ Gray Streaks VFT Mastic	6830	SF	Teachers Tlt Nxt to Rm 306, Teacher's Lunchroom, 3rd Floor Corridor, 306 & 307, 307B, 305, 305A & Ward, 309 & Wrd, Rm 310 & Wrd, 1891 Bldg		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

58	9"x9" Gray VFT (Not Observed)	Lunchroom, 1891 Building	Miscellaneous			YES	X NO
0040 Falls	No Observe		٦				
2016 - Fall:							
Comments:							
2217 2							
	ng: No Change						
Comments:							
2017 - Fall:							
Comments:							
	ng : No Change						
Comments:							
2018 - Fall:							
Comments:							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	9"x9" Gray VFT Mastic (Not Observed)			Third Floor Teachers Lunchroom, 1891 Building		Miscellaneous					YES X NO
2016 - Fall: N	lo Change	<u>'</u>									

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
60	12"x12" White w/ Tan Streaks VFT NOT OBSERVED	800	SF	Room 308, 1891 Building		Miscellaneous	No	None	0		YES	X NO
	No Change	•		•		•	•	•	•	•		
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12"x12" White w/ Tan Streaks VFT Mastic NOT OBSERVED	800	SF	Room 308, 1891 Building		Miscellaneous	No	None	0		YES X NO

HA No

2018 - Fall: No Change

Comments:

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
62	12"x12" White w/ Orange Streaks VFT	4800	SF	Room 105-107, Main Office, Prin. Off, 108/Ward, 109/Ward (Health Cent), 110/Ward/Toilet, 1891 Bldg.		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12"x12" White w/ Orange Streaks VFT Mastic	4800	SF	Room 105-107, Main Office, Prin. Off, 108/Ward, 109/Ward (Health Cent), 110/Ward/Toilet, 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
64	12"x12" White w/ Green Streaks VFT	4140	SF	Room 202, 204, 2nd Floor Corridor, 1915 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change		•	•		•		•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12"x12" White w/ Green Streaks VFT Mastic	4140	SF	Room 202, 204, 2nd Floor Corridor, 1915 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
66	12"x12" White w/ Gray Streaks VFT	6000	SF	Room 301 through 304, 3rd Floor Corridor, 3rd Floor Faculty Toilet, 1915 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
2017 - Spring	g. No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12"x12" White w/ Gray Streaks VFT Mastic	6000	SF	Room 301 through 304, 3rd Floor Corridor, 3rd Floor Faculty Toilet, 1915 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
	•	

68	18"x 24" Black Border Tiles	520	SF	Basement and 1st Floor Corridor, 1936 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:	<b>V</b>									
2017 - Fall: N	o Change									
Comments:	<u> </u>									
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:	-									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	18"x24" Black Border Tile Mastic	520	SF	Basement and 1st Floor Corridor, 1936 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
70	Interior Window Caulk	1500	SF	Interior Windows, 1915 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Interior Window Glaze	1500	SF	Interior Windows, 1915 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
74	Transite Panel	24	SF	Outside Lunchroom Doors, 1915 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	•											
2017 - Spring	: No Change				-							
Comments:					1							
2017 - Fall: N	lo Change				=							
Comments:												
2018 - Spring	ı : No Change				=							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					1							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	MJP E/F/V on Fiberglass Pipe Insulation	200	EA	Basement Corr., 1st-3rd Flr. Girls Tlt, 2nd Flr Jan. Clst, Boiler/Tank/Engine Rm, 1915 Bldg		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
76	Exterior Caulk	1000	LF	Exterior Windows, 1891 Building		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				]								
Comments:	•				]								
2017 - Spring	g: No Change				-								
Comments:													
2017 - Fall: N	No Change				-								
Comments:	J												
2018 - Sprine	g : No Change				<u> </u>								
Comments:													
2018 - Fall: N	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Exterior Glaze	1000	LF	Exterior Windows, 1891 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
78	Exterior Caulk	1000	LF	Exterior Windows, 1915 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				Ī							
Comments:												
2017 - Spring	g: No Change											
Comments:					]							
2017 - Fall: N	No Change				-							
Comments:	-				]							
2018 - Spring	g : No Change				1							
Comments:												
2018 - Fall: N	No Change				-							
Comments:	5				]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Exterior Glaze	1000	LF	Exterior Windows, 1915 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
80	Exterior Caulk	1000	LF	Exterior Windows, 1936 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	MJP E/F/V on Mag Block Pipe Insulation	7	LF	Engineers Office, Tank Rm, Basement Corr, Rm 410, Basement Shower Bathroom, 1891 Building		TSI	Yes	None	0		X YES NO

2016 - Fall: Abated
Comments:removed pipe insulation
2017 - Spring: Abated
Comments:engineer office
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Abated
Comments:pipe install abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
82	Drywall Joint Compound	500	SF	Pre-School (014), 1891 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12 x 12 inch Brown w/Yellow Streaks VFT	1800	SF	Assembly Hall (under chairs)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
83 A	12 x 12 inch Brown w/Yellow Streaks VFT Mastic	1800	SF	Assembly Hall (under chairs)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change		•		7	•	•	•	•	•	•	
Comments												
2017 - Spr	ring: No Change				-							
Comments	S:											
2017 - Fal	II: No Change				-							
Comments	S:											
2018 - Spr	ring : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	Blue Linoleum	500	SF	Clinic (1936 Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
84A	Blue Linoleum Mastic	500	SF	Clinic - 1936		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	5											
2018 - Spring	ı : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	2'x4' Lay In Ceiling Panels	500	SF	Clinic		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

		Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86 12" X 12" VFT	blue with streaks	1950	SF	2nd Floor Teacher's Toilet; Lunch Room (Old 10 & 11 Rooms), 302/304 1915 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	12" X 12" blue with streaks, Mastic	1950	SF	2nd Floor Teacher's Toilet; Lunch Room (Old 10 & 11 Rooms), 302/304 1915 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	12" X 12" brown with streaks, VFT	5600	SF	1st, 2nd and 3rd Floor Corridors (all by elevator, 1915 bldg); Assembly Hall; Stage North Vestibule		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24991

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	12" x 12" brown with streaks, Mastic	5600	SF	1st, 2nd and 3rd Floor Corridors (all by elevator, 1915 bldg); Assembly Hall; Stage North Vestibule		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	12" X 12" pink with streaks, VFT	135	SF	2nd and 3rd floor corridors, both by elevator, 1915 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	12" X 12" pink with streaks, mastic	135	SF	2nd and 3rd floor corridors, both by elevator, 1915 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	Carpet mastic	1500	SF	2nd floor library, 1915 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	Fire door	240	SF	3rd floor corridor, 1915 bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	MJP on fiberglass runs	20	LF	3rd floor girls toilet pipe chase, 1891 bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
95	Terrazo	1200	SF	Stair-treads in 1936 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				]							
Comments:	<u> </u>				1							
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:					=							
2018 - Fall: I	No Change											
Comments:					=							
	g : No Change											
Comments:					=							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	12' X 12' gray with multi- color specks, 1936 bldg., VFT	2000	SF	Old rooms 111 and 112 currently clinic		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12' X 12' gray with multi- color specks, 1936 bldg., VFT Mastic	2000	SF	Old rooms 111 and 112 currently clinic		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	Drywall system, 1936 bldg.	4000	SF	Old rooms 111 & 112 (currently clinic)		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
99	2X4 ceiling tile with 2X2 patterns with pinholes, 1936 bldg.	2000	SF	Old 111 & 112 rooms (currently clinic)		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change	•			]	•		•	•	•		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	Vinyl baseboard mastic	1500	SF	Old rooms 111 & 112 (currently clinic)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	12" X 12" tan with streaks, VFT	1100	SF	Kitchen in 1915 bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	12" X 12" tan with streaks, mastic	1100	SF	Kitchen, 1915 bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Gray and Beige Specks Linoleum	1000	SF	Room 308 and Storage Rooms		Miscellaneous	No		0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	Gray and Beige Specks Linoleum Mastic	1000	SF	Room 308 and Storage Rooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
А	Boiler Packing (Boiler #1)	3	SF	Boiler Room, 1891 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cardboard Pipe Insulation	137	LF	Engineers Office, Basement Corridor, Basement Shower Bathroom, 1891 Building		TSI	Yes	None	0		X YES NO

2016 - Fall: Abated
Comments:11/4 pipe insulation removed
2017 - Spring: Abated
Comments:engineer office
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Cardboard Pipe Insulation	16	LF	Engineers Office, Basement Corridor, Basement Shower Bathroom, 1891 Building		TSI	Yes	None	0		X YES NO

2016 - Fall: Abated
Comments:1 1/4 pipe insulation moved
2017 - Spring: Abated
Comments:engineer office pipe insulation
2017 - Fall: No Change
Comments:
2010 5 11 11 21
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Aircell Duct Insulation	1200	SF	Pre-School (Room 014), Pre-School (Room 410), Basement Corridor, 1891 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Mag Block Pipe Insulation	100	LF	Engineers Office, Tank Rm, Basement Corr, Rm 410, Basement Shower Bathroom, 1891 Building		TSI	Yes	None	0		X YES NO

		 <u> </u>
2016 - Fall: Abated		
Comments:1 1/4 pipe insulation rei	moved	
2017 - Fall: No Change		
Comments:		
2017 - Spring: Abated		
Comments:engineer office		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Tank Insulation	150	SF	Tank Room, 1891 Building		TSI	Yes	None	0		X YES NO

2016 - Fall: Abated
Comments:old insulation removed and replaced
·
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Laura S Ward Elementary School
Date: 12/11/2018
·
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.