Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

25011 Portage Park Elementary School 5490 School: **Oracle Unit: Building ID:** 5330 W Berteau Avenue Address: Region: 01 Mail Room: Asbestos Surveyor: Joyce, Kevin **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 12/13/2018 Email Address: kjjoyce@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Plaster Wall & Plaster YES 01 X NO Throughout - 1915 Ceiling 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: Damaged Comments:peeling paint and plaster

Oracle Unit: 25011

02	Brown Coat Plaster	4550	SF	Boiler Room, Air Plenum & Tank Room - 1915		Surface	Yes	None	0	YES	X NO
0040 5 11 1					1						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	-										
2018 - Spring	: No Change										
Comments:	-										
2018 - Fall: N	o Change										
Comments:	<u> </u>										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Green Linoleum - NOT OBSERVED			Library (Building 1915) - NOT OBSERVED							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
05	18"x18" Dark Brown VFT	150	SF	Principal's Office & Toilet, Room 200 - 1915		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Blue Painted Linoleum			Gym Office - 1915							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
07	12"x12" Tan VFT	1520	SF	Room 307A (Tiled Over) -1915		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments	:				<u> </u>							
2017 - Spri	ng: No Change											
Comments	:				-							
	No Change											
Comments	:				-							
2018 - Spri	ng : No Change											
Comments	•				1							
2018 - Fall:	No Change											
Commonto												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x9" Red VFT	730	SF	Principal's Office & Toilet (Under New VFT), Room 200 - 1915		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
10	9"x9" Green VFT	200	SF	Old Engineer's Office (under the carpet) - 1915		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				_							
Comments:]							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Green Linoleum Mastic - NOT OBSERVED			Library - 1915 - NOT OBSERVED							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	18"x18" Dark Brown VFT Mastic (under existing VFT)	150	SF	Principal's Office & Toilet, Room 200 (under existing VFT) - 1915		Miscellaneous	No	None	0		YES X NO
	•	•	=		•	•	•	•	•	•	•

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Blue Painted Linoleum Mastic	300	SF	Gym Office - 1915		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	12"x12" Tan VFT Mastic (Tiled Over)	1520	SF	Room 307A (Tiled Over) - 1915		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Spri	ing: No Change]							
Comments	S:											
2017 - Fall	: No Change											
Comments	S:											
2018 - Spri	ing : No Change											
Comments	s:				_							
2018 - Fall	: No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Red VFT Mastic (under existing VFT)	100	SF	Principal's Office & Toilet, Room 200 (under existing VFT) - 1915		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Green VFT Mastic (under the carpet)	200	SF	Old Engineer's Office - 1915		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Fire Doors	480	SF	Auditorium - 1915		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments:	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	
2018 - Fall: No Change	2018 - Spring : No Change
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Beige VFT	2500	SF	Rooms 110, 111, 112 (1915 Building) (Under HA 68 and 68 A)		Miscellaneous	No	None	0		YES X NO
0040 F.II N	01				1	•	•	•	•	•	-

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Beige VFT Mastic	2500	SF	Rooms 110,111,112 (Building 1915)(Under HA 68 & 68A)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12'x12" Beige w/White Specks VFT Mastic - NOT OBSERVED	150	SF	Rooms (111, 110) - 1915 - NOT OBSERVED		Miscellaneous	No	None			YES X NO
2016 - Fall: N	lo Change	•		•		•	•	•	•	•	•

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Off White w/Tan Specks VFT	500	SF	1st Floor Women's Toilet - 1915		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Off White w/Tan Specks VFT Mastic	500	SF	1st Floor Women's Toilet - 1915		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" White & Grey Speckled VFT	550	SF	Auditorium Stage - 1915		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Other
Comments:painted black
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:floor painted black

		Quantity	Units		Type	Category		Type	Quantity	Units		
25	12"x12" White & Grey Speckled VFT Mastic	550	SF	Auditorium Stage - 1915		Miscellaneous	No	None	0		X YES	NO
2016 - Fall:												
Comments:	painted black											
2017 - Sprin	ig: No Change											
Comments:					-							
2017 - Fall:	•											
Comments:												
2018 - Sprin	ng : No Change				-							

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Beige w/White Specks VFT - NOT OBSERVED			Rooms 110, 111 - 1915 - NOT OBSERVED							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Comments:

2018 - Fall: No Change

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
27	2'x4' Ceiling Tile			Throughout - 1915							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	, 9-											
2017 - Fall: N	lo Change											
Comments:	Ü											
2018 - Spring	g : No Change											
Comments:	,											
2018 - Fall: N	lo Change											
Comments:												
								•				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Interlock Thermo Insulation			Attic - 1915							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Off White VFT (Under HA67 & 67A - existing VFT)	800	SF	Clerk's Office, Main Office & Office Store Room (under existing VFT) - 1915		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Off White VFT Mastic (Under HA67 & 67A - existing VFT)	800	SF	Clerk's Office, Main Office & Office Store Room (under existing VFT) - 1915		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

31	12"x12" Black w/ White Specks VFT - NOT OBSERVED			Room 307A - 1915 - NOT OBSERVED							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	10 0]							
2017 - Spring	g: No Change				1							
Comments:	y. 110 Griango											
2017 - Fall: N	lo Change				_							
Comments:	Ü]							
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	lo Change				_							
Comments:]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Units

Damage

Quantity

Change in Assessment Category

32	12"x12" Black w/ White Specks VFT Mastic - NOT OBSERVED		Room 307A - 1915 - NOT OBSERVED
0040 F.II N	. 01		
2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

HA No

Material Description

Material

Quantity

Material

Units

Material Location

YES

X NO

33	12"x12" Grey w/ Grey Specks VFT - NOT OBSERVED		Room 307A - 1915 - NOT OBSERVED				YES	X NO
2016 - Fall: N	lo Change							
Comments:	io onarigo							
2017 - Spring	յ։ No Change							
Comments:								
0045 5 11 1								
2017 - Fall: N	lo Change							
Comments:								
0040 0 0	NI- Ol-							
	j : No Change							
Comments:								
2018 - Fall: N	lo Change							
Comments:	io Griarigo							

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Grey w/ Grey Specks VFT Mastic - NOT OBSERVED			Room 307A - 1915 - NOT OBSERVED							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Dark Green w/ Specks VFT	1500	SF	Rooms 223, 226, 323 and 326 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Dark Green w/ Specks VFT Mastic	1500	SF	Rooms 223, 226, 323 and 326 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Light Green w/ Specks VFT	3000	SF	West Link, Rooms 223, 226, 323 and 326 - 1999 Addition		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	la Changa	•	•	•	<u> </u>	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" Light Green w/ Specks VFT Mastic	3000	SF	West Link, Rooms 223, 226, 323 and 326 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" Dark Blue w/ Specks VFT	1500	SF	Rooms 222, 225, 322 and 325 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Dark Blue w/ Specks VFT Mastic	1500	SF	Rooms 222, 225, 322 and 325 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Light Blue w/ Specks VFT	3000	SF	Rooms 222, 225, 322 and 325 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Spring: No Change
Comments:
2017 - Spring: No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2019 Falls No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Light Blue w/ Specks VFT Mastic	3000	SF	Rooms 222, 225, 322 and 325 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 20

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Light Brown w/ Specks VFT	1800	SF	Elevator, Rooms 125 including closet, 221 including closet, 224, 321 and 324 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Light Brown w/ Specks VFT Mastic	1800	SF	Elevator, Rooms 125 including closet, 221 including closet, 224, 321 and 324 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Off White w/ Tan Specks VFT	3500	SF	Rooms 125, 221, 224, 324 and 321 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Off White w/ Tan Specks VFT Mastic	3500	SF	Rooms 125, 221, 224, 324 and 321 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
47	Pink Linoleum			1st, 2nd, & 3rd Floor Link's - 1999 Addition							YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Spring	g: No Change											
Comments:	, J]							
2017 - Fall: N	lo Change				1							
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					_							
Fr.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Pink Linoleum Mastic			1st, 2nd, & 3rd Floor Link's - 1999 Addition							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
49	Light Blue Linoleum			Serving Area - 1999 Addition							YES	X NO
2016 - Fall: N	o Change				7							
Comments:	<u> </u>]							
2017 - Spring	: No Change				-							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change				_							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Light Blue Linoleum Mastic			Serving Area - 1999 Addition							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

51	Gray Linoleum			Multi-Purpose Room/Gym - 1999 Addition							YES	X NO
2016 - Fall: N	No Change		•	·	7							
Comments:	10 Change											
Commonto.												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	10 Change											
2018 - Fall: N	No Change											
Comments:	_											
2018 - Spring	g : No Change											
Comments:	g : : : : : : : : : : : : : : : : : : :											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Gray Linoleum Mastic			Multi-Purpose Room/Gym - 1999 Addition							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
53	Vinyl Baseboard			Throughout - 1999 Addition							YES	X NO
2016 - Fall: N	o Change				1							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Vinyl Baseboard Mastic			Throughout - 1999 Addition							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

55	2'x2' White w/Grooves CT			Serving Area, Dishwash and Kitchen Storage/Toilet/Office - 1999 Addition							YES	X NO
2016 Fol	l: No Change				1							
	<u> </u>											
Comments	S:											
					-							
2017 - Fal	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fal	l: No Change											
Comments	S:											
					1							
2018 - Spr	ing : No Change											
Comments												
	-				1							
					4							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

			Addition
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Quantity

Units

HA No

56

Material Description

2'x4' Smooth CT

Material

Units

Material

Quantity

Material Location

Throughout - 1999

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
57	Drywall			Throughout - 1999 Addition							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Drywall Compound			Throughout - 1999 Addition							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

59	Carpet Mastic		Library & Library Office, Assistant Principal's Office, Teacher's Breakroom and Principal's Office - 1999 Addition		
2016 - Fa	all: No Change				
Commen					
2017 - Fa	all: No Change				
Commen					
2017 - Sr	pring: No Change				
Commen					
2018 - Sp	oring : No Change				
Commen	ts:				
2018 - Fa	all: No Change				
Commen					

Material

Units

Material Location

Asbestos

Type

Material

Category

HA No

Material Description

Material

Quantity

Change in Assessment Category

X NO

YES

Damage Type

Friable

Damage Quantity Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
60	Spray-On Insulation			Throughout - 1999 Addition							YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change]							
Comments:					_							
2017 - Spring	: No Change											
Comments:					-							
2018 - Spring	: No Change]							
Comments:					-							
2018 - Fall: N	lo Change]							
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12 x 12 inch Whitew/Black Streaks VFT	750	SF	Room 307A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61 A	12 x 12 inch White w/Black Streaks VFT Mastic	750	SF	Room 307A		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	12 x 12 inch Black w/White Streaks VFT	200	SF	Room 307A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
62 A	12 x 12 inch Black w/White Streaks VFT Mastic	200	SF	Room 307A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
	<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Linoleum	400	SF	Room 307B		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
63 A	Linoleum Mastic	400	SF	Room 307B		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Lining on the Underside of Sink	5	SF	Room 101 Rest Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
65	Drywall, tape & compound	2000	SF	Rooms 314 - 316 and Wall Between Rooms 110 and 111		Miscellaneous	Yes	None	0		YES	X NO
2016 - F	all: No Change											
Commer												
2017 - S	pring: No Change											
Commer	nts:											
2017 - F	all: No Change											
Commer	nts:											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Decorative Plaster	2000	SF	Auditorium (1915		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12"x12" Tan-streaked Floor Tile VFT	500	SF	Principal's Office and Washroom, Old Room 200, Clerk's Office and Closets (1915 Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67A	12"x12" Tan-streaked Floor Tile (MASTIC)	200	SF	Principal's Office and Washroom, Former Room 200, Clerk's Office and Closets (1915 Building)		Miscellaneous	No	None	0		YES X NO

		3/
		·-
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12"x12" Off-White w/tan streaks VFT	2500	SF	Rooms 110, 111 and 112 (1915 Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

68A	12'x12' Off-White w/tan streaks Mastic	2500	SF	Rooms 110, 111 and 112 (1915 Building)		Miscellaneous	No		0		YES	X NO
2016 - Fall:	No Change]							
Comments:	J				-							
2017 - Fall:	No Change]							
Comments:					_							
2017 - Sprin	g: No Change]							
Comments:					_							
2018 - Fall:	No Change]							
Comments:					1							
	g : No Change]							
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

2016 - Fall: N	lo Change		
Comments:			
2017 - Fall: N	lo Change		
Comments:			
2017 - Spring	r: No Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:			
2018 - Spring	ı : No Change		
Comments:			

250

HA No

69

Material Description

12"x12" Off-White w/brown

streaks VFT

Material

Units

SF

Material

Quantity

Material Location

Clerk's Office (1915

Building)

YES

X NO

		Quantity	Units		Type	Category		Туре	Quantity	Units		
69A	12"x12" Off-White w/brown streaks Mastic	250	SF	Clerk's Office (1915 Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	-											

Material

Damage

Damage

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	12'x12' Sky Blue w/white and blue speckles VFT	2000	SF	Main Office, Vault, Hall and Closet (1999 Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

2018 - Spring : No Change

Comments:

Material

Material Location

Damage Change in Assessment Category

70A	12'x12' Sky Blue w/white and blue speckles Mastic	2000	SF	Main Office, Vault, Hall and Closet (1999 Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				7							
Comments												
	-											
2017 - Fal	II: No Change											
Comments	S:											
	ring: No Change											
Comments	S:											
2018 - Fal	II: No Change				-							
Comments												
2019 Sp	ring : No Change				7							
					4							
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
71	Terrazzo	15000	QF.	1st, 2nd and 3rd Floor Corridors , Toilet,		Miscellaneous	No	None	0		YES	X NO

Material

Category

Miscellaneous

Asbestos

Type

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

15000

SF

HA No

71

Material Description

Terrazzo

Material

Quantity

Material

Units

Material Location

Stairwells and Vestibules (1999 Building)

Main Office, Vault, Hall

В	Boiler Packing	300	SF	Boiler Room - 1915		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	2016 - Fall: No Change											
Comments:	<u> </u>											
2017 - Fall: No Change												
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
	g : No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
С	Aircell Pipe Insulation	200	LF	Boiler Room - 1915		TSI	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

D	MJP E/F/V on Aircell Pipe Insulation	15	LF	Principal's Office & toilet and Room 200 (1915)		Miscellaneous	No	None	0	YES	X NO
					1						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring: No Change											
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					•						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	MJP E/F/V on Fiberglass Pipe Insulation	500	LF	Boiler Room, Tank Room, Cold Air Chamber, 1st Floor Women's Washroom (Chase) and West W.A.C 1915		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

F	Mag Block Pipe Insulation	400	LF	Boiler Room and Tank Room - 1915		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring: No Change												
Comments:												
2017 - Fall: N	lo Change											
Comments:					1							
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Type

Damage

Quantity

Damage

Units

	<u> </u>		Room (1915)	
0040 5 11 11	01			
2016 - Fall: No	o Change			
Comments:				
2017 - Spring:	: No Change			
Comments:				
2017 - Fall: No	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: No	o Change			
Comments:		·	 	

54

HA No

G

Material Description

MJP E/F/V on Mag Block Pipe Insulation Material

Units

Material

Quantity

Material Location

Boiler Room, Tank Room, Cold and Warm Air Chambers, South Fan

LF

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Н	Cardboard Pipe Insulation - NOT OBSERVED			2nd Floor Toilet Pipe Chase's, Room 101 Washroom - 1915 - NOT OBSERVED							YES	X NO
2016 - Fall:	No Change				1							
Comments:	<u> </u>											
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	MJP E/F/V on Cardboard Pipe Insulation - NOT OBSERVED			2nd Floor Toilet Pipe Chases, Rm 101 Toilet - 1915 - NOT OBSERVED		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

J	Tank Insulation	202	SF	Boiler Room & Tank Room - 1915		TSI	Yes	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:	<u> </u>				-							
2017 - Fall: No Change												
Comments:												
2017 - Spring: No Change												
Comments:					-							
2018 - Fall: I	No Change											
Comments:					=							
2018 - Spring : No Change												
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
			1				1		+			

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

Damage

Type

Damage

Quantity

0

Damage

Units

Change in Assessment Category

HA No

Κ

Material Description

Boiler Gasket

Material

Quantity

Material

Units

LF

Material Location

Boiler Room - 1915

YES

X NO

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Portage Park Elementary School
Date: 12/14/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 25011