Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

George M Pullman Elementary School 25041 5530 School: **Oracle Unit: Building ID:** Address: 11311 Forrestville Region: Mail Room: Asbestos Surveyor: Madden, Kenya X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Hallways, classrooms, YES 02 2x4 acoustical ceiling tile SF X NO 45500 Miscellaneous Yes None 0 lunchrooms 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

03	12x12 tan w/brown speckled floor tile - ABATED			1st and 2nd floor teachers lounge		Miscellaneous					YES	X NO
2016 - Fall: I	No Change			<u> </u>	- -				•			
	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	-											
			•	_	_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

03A	12x12 off-white w/green specks floor tile - ABATED		Principal's office- washroom
2016 - Fall:	No Change		
Comments:			
2017 - Fall:	No Change		
Comments:			
2017 - Spri	ng: No Change		
Comments:			
2018 - Fall:	No Change		
Comments:		•	
		•	

HA No

Material Description

12x12 tan w/brown

Material

Quantity

Material

Units

Material Location

YES

X NO

2016 - Fall:	No Changa				\neg						
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:	•										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

0

HA No

03B

03C

Material Description

12x12 beige w/white

12x12 blue floor tile - NOT

OBSERVED

streaks floor tile

Material

Quantity

2400

Material

Units

SF

SF

Material Location

Teachers Lounge

Lunchroom 1 and 2, and

3rd flr athletic storage

Change in Assessment Category

X NO

X NO

YES

03D	12x12 dark gray w/white specks floor tile	950	SF	Room 206 & 206 w. room		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change]						
Comments											
	ing: No Change										
Comments	S:				1						
	: No Change				-						
Comments	S:				-						
	: No Change										
Comments	S:				1						
					1						

Type

Asbestos

Type

Material

Category

Material

Category

Miscellaneous

Friable

Friable

No

Damage

Damage

Туре

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

Material Location

Material Location

Kitchen, kitchen storage

03E	12x12 dark gray floor tile	570	SF	Kitchen, kitchen storage room	
2016 - Fall: N	o Change				
Comments:					
2017 - Fall: N Comments:	o Change				
2017 - Spring	: No Change				
Comments:					
2018 - Fall: N	o Change				
Comments:					

Material

Quantity

Material

Quantity

Material

Material

Units

Units

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

X NO

03G	12x12 white w/orange specks floor tile - ABATED			Room 001		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	10 Onlango											
2017 - Sprin	g: No Change				-							
Comments:	g											
2017 - Fall: N	No Change				+							
Comments:	•											
2018 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04	9x9 gray w/white specks floor tile - ABATED			Room 101		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

04A	9X9 TAN/WHITE STREAKS FLOOR TIILE - ABATED			Room 108		Miscellaneous					YES	X NO
2016 - Fall: I	No Change		·	•	1	•	•	•	•	•	•	
	No Change				_							
Comments:					_							
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	J											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

05

Material Description

12x12 tan w/brown specks floor tile mastic - ABATED

Material

Units

Material Quantity

Material Location

2nd flr teachers lounge,

1st flr teachers lounge

Change in Assessment Category

X NO

0046	No Observe				_						
	: No Change										
Comments	:										
2017 - Fall	: No Change										
Comments											
2017 - Spr	ing: No Change										
Comments	:										
2018 - Fall	: No Change										
Comments	:										
,											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

X NO

YES

YES

2016 - Fall: N	lo Change			
Comments:				
2017 - Spring	j: No Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:		•		

2400

Material

Units

SF

Material

Quantity

Material Location

Principal's office-

Lunchroom 1 and 2, and

Teachers Lounge

washroom.

HA No

05A

05B

Material Description

12x12 offwhite w/green

floor tile mastic - ABATED

12x12 beige w/white stripes

floor tile mastic

05C	12x12 blue floor tile mastic - NOT OBSERVED	84	SF	3rd flr athletic storage		Miscellaneous		0	YES	X NO
2016 - Fall: N	No Change]					
Comments:	<u> </u>				- -					
2017 - Spring	g: No Change									
Comments:					1					
2017 - Fall: N	No Change				=					
Comments:					1					
2018 - Fall: N	No Change				_					
Comments:	-				1					

Type

Material

Category

Damage Quantity

Damage

Units

Change in Assessment Category

Page 8

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05D	12x12 dk grey w/white specks floor tile mastic	950	SF	Room 206 & 206 w. room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

05E	12x12 dark gray floor tile mastic	570	SF	Kitchen, kitchen storage room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	ge				= 							
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change				1							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	10.10.13	Quantity	Units		Туре	Category		Туре	Quantity	Units		
05G	12x12 white w/orange specks floor tile mastic - ABATED			Room 001		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

06	9x9 gray white specks floor tile mastic - ABATED			room 101		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	10 Change				-							
2017 - Spring	g: No Change											
Comments:												
0047 F.II N	I. Oleana				_							
2017 - Fall: N	No Change											
Comments:					_							
2018 - Fall: N	No Change				1							
Comments:	Ŭ											
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
06A	9x9 tan w/white streaks floor tile mastic - ABATED			Room 108		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

06H	9x9 gray with white specks floor tile mastic - ABATED			Room 101		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
			+		+		+			†		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

Damage

Units

90

LF

HA No

07

Material Description

Black mopboard

Material

Quantity

Material

Units

Material Location

Lunchrooms 1 and 2

Change in Assessment Category

X NO

											<u> </u>
2016 - Fall: No Ch	ange				7						
Comments:	<u> </u>				=						
2017 - Fall: No Ch	ange										
Comments:					4						
2017 - Spring: No	Change										
Comments:					4						
2018 - Fall: No Ch	ange										
Comments:					4						
					_						
HA No Mate	erial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

Damage

Quantity

0

0

None

Damage

Units

90

Material

Quantity

124

Material

Units

LF

LF

Material Location

Ground flr east exit

Lunch rooms 1 and 2

HA No

07A

80

Material Description

black mopboard mastic

Mopboard brown

Change in Assessment Category

X NO

X NO

YES

2016 - Fall:	No Change										
Comments											
2017 - Fall:	No Change										
Comments	•										
2017 - Spri	ng: No Change										
Comments	•										
2018 - Fall:	No Change										
Comments	•										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

TSI

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

No

Damage

Type

Damage

Quantity

0

0

None

Damage

Units

HA No

08A

10

Comments:

Comments:

Comments:

Comments:

Material Description

brown mopboard mastic

Boiler Gaskets

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

124

10

Material

Units

LF

LF

Material Location

Ground floor east exit

boiler room

Change in Assessment Category

X NO

X NO

YES

	12	Fire Brick	80	SF	Boiler room		Miscellaneous	No	None	0		YES	X NO
	2016 - Fall: No	o Change]							
	Comments:	J											
	2017 - Fall: No	o Change											
	Comments:												
	2017 - Spring:	: No Change											
	Comments:												
	2018 - Fall: No	o Change											
	Comments:												
ı						I							
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
	14	Blue carpet mastic (Not Observed)			Room 102		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Observed)

Material

Quantity

Material

Units

15	Gray carpet mastic	1600	SF	Athletic Storage Room, and Principal's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
					1							
2017 - Spring	: No Change]							
Comments:	-				1							
2018 - Fall: N	o Change											
Comments:	•											
					•							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
-		Quantity	Units		Туре	Category		Туре	Quantity	Units	3	
				1	. 71			.) = -				

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

1500

SF

Material

Quantity

Material

Units

Material Location

Athletic Storage Room,

room 305, 3rd floor

lounge, and athletic

HA No

16

Material Description

12x12 red and white

streaks floor tile

Change in Assessment Category

YES

YES

X NO

17	12x12 red and white streaks floor tile mastic	1500	SF	room 305, 3rd floor lounge, and athletic storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	•	•]	•	•	•	•	•		
Comments:					_							
2017 - Fall:	No Change											
Comments:												
2017 2					4							
2017 - Sprii	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12x12 orange w/ white streaks floor tile	1850	SF	2nd floor lounge, rooms 101 and 108		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

Page 16

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
19	12x12 orange w/ white streaks floor tile mastic	1850	SF	2nd floor lounge, rooms 101 and 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12x12 blue with white streaks floor tile	30	SF	principal's office washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 17

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
21	12x12 blue with white streaks floor tile mastic	30	SF	principal's office washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change		_]							

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12x12 light blue with blue streaks floor tile	1500	SF	Room 001, Room 001 Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

23	12x12 light blue w/blue streaks floor tile mastic	1500	SF	Room 001, Room 001 Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change				_							
Comments:	0											
2017 - Sprin	ng: No Change				1							
Comments:												
2018 - Fall:	No Change				_							
Comments:					1							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

Damage

Quantity

0

None

Damage

Units

	ou out out the		MDF Room
		•	
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

3100

SF

HA No

24

Material Description

12x12 tan with brown

streaks floor tile

Material

Quantity

Material

Units

Material Location

Auditorium, Girls Play

Room, Speech Room, NW Corner-Room, and

YES

X NO

25	12x12 tan with brown streaks floor tile mastic	3100	SF	Play Room, Speech Room, NW Corner- Room, and MDF Room		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change				1						
Comments:					= - -						
2017 - Fall: N	o Change				-						
Comments:					-						
2017 - Spring	: No Change				1						
Comments:											
2018 - Fall: N	o Change				-						
Comments:	-				1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
26	2' X 4' Ceiling Tile	15000	SF	Throughout Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27	Brown Carpet Adhesive - NOT OBSERVED	1025	SF	Room 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:		_										
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Brown Mosaic Ceramic Tile Grout	1000	SF	1st, 2nd and 3rd Floor Girls Washrooms		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

29	Brown Mosaic Ceramic Tile Adhesive	1000	SF	1st, 2nd and 3rd Floor Girls Washrooms		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change				1						
Comments:											
Commonto:					-						
2017 - Fall:	No Change										
Comments:											
0017 0	N O				1						
2017 - Sprir	ng: No Change										
Comments:											
2019 Falls	No Change				-						
2018 - Fall:	No Change										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Hardcoat Plaster - Walls and Ceilings	225000	SF	Throughout School		Surface	Yes	None	0		YES X NO

	1										
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:	Comments:										

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
31	12" X 12" Peach VFT	500	SF	Main office		Miscellaneous	No	None	0		YES	X NO
	II: No Change											
Comments	S:	_										
2017 - Fall	II: No Change											
Comments	s:											
2017 - Spr	ring: No Change											
Comments	s:											
2018 - Fall	II: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Mastic (under 12" X 12" Peach VFT)	500	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Comments:

33	12" X 12" cream with tan streaks floor tile	250	SF	Custodian's Break Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	io Chango											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	•											
2018 - Fall: N	lo Change											
Comments:	•											
					l							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

tile)		
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

250

HA No

34

Material Description

Mastic (under 12" X 12"

cream with tan streaks floor

Material

Quantity

Material

Units

SF

Material Location

Custodian's Break Room

Change in Assessment Category

X NO

35	Red Carpet Mastic	600	SF	Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	io Chango				-							
2017 - Fall: N	lo Change				_							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

250

Material

Units

SF

Material Quantity Material Location

1st Floor Teacher's

Lounge and Toilet

HA No

36

Material Description

Wood-look Laminate

Change in Assessment Category

X NO

А	Air cell duct wrap - ABATED			basement		TSI					YES	X NO
2016 - Fall:	No Change											
Comments:												
					_							
	g: No Change											
Comments:												
0047 F-II	NI- OL	4										
2017 - Fall:	No Change											
Comments:												
2019 Falls	No Changa											
2018 - Fall:	No Change				_							
Comments:												
	T	T	T	T	T	1		1 =	1 =	т	1	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage Quantity	Damage Units	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
В	Air cell pipe lagging - ABATED			Basement, Boiler room, mech room, Room 001, 002, 005, 1st & 2nd floor corridors		TSI					YES	X NO
		1	L	Comucio	- <u> </u>	1	L	l	<u> </u>		1	
2016 - Fall:	2016 - Fall: No Change											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA No

Comments:

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

	71871128										
2016 - Fall: N	No Change										
Comments:	ge				_						
2017 - Fall: I	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
		+							<u> </u>		

TSI

Asbestos

Type

Material

TSI

Category

Friable

Yes

Damage

Type

Damage

Quantity

0

None

Damage

Units

Material

Quantity

Material

Units

LF

basement

Material Location

Basement, boiler room

HA No

С

D

Material Description

Cardboard pipe insulation -

MAG Block Pipe Insulation

Change in Assessment Category

X NO

X NO

YES

E	Aircell hard joints - ABATED			Basement, 1st and 2nd floor		TSI					YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Sprin	g: No Change											
Comments:					-							
2017 - Fall:	No Change				1							
Comments:	<u> </u>											
2018 - Fall:	No Change				-							
Comments:					1							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
F	Fiber glass hard joints -			Basement fan room, corridors on 1st, 2nd and		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

3rd floors

HA No

Material Description

ABATED

Material

Quantity

Material

Units

G	cardboard hard fittings - ABATED			Basement, fan room, boiler room		TSI					YES	X NO
2016 - Fall: N	lo Chango				7							
Comments:	NO Change				-							
Comments.					-							
2017 - Fall: N	lo Change											
Comments:	•											
2017 Carina	n. No Chongo											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: No Change												
Comments:												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
Н	Boiler blanket insulation (NOT OBSERVED)			boiler room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	George M Pullman Elementary School
Date:	1/9/2019
the Asbest	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of os Management Plan is available at each school during school hours by appointment. To review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2016. surveillances are conducted every six months.
CHECK ON	<u>JE</u>
A co	opy of this notice was sent home in each child's backpack.
A co	opy of this notice was printed in the school's newsletter and sent home with each child
A co	opy of this notice was printed in the school's calendar and sent home with each child
Oth	er.
	OF THIS NOTICE MUST BE PLACED IN THE OOL'S ASBESTOS MANAGEMENT PLAN.