## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

William H Ray Elementary School 25071 5560 School: **Oracle Unit: Building ID:** Address: 5631 S. Kimbark Region: Mail Room: Asbestos Surveyor: Collins, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity Throughout 1893 YES 01 Hard Plaster SF 0 X NO 40000 Surface No None Construction 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
02A	12x12 beige w/tan streaks floor tile	1550	SF	basement art room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												

Н	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	)2B	12x12 black floor tile	300	SF	room 306		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
02C	12x12 white floor tile	300	SF	room 306		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02D	12x12 beige streaked floor tile	430	SF	1st, 2nd, 3rd floor corridors (patches)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
02E	12x12 orange floor tile			1st floor corridor - outside boys toilet		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	-											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02F	12x12 tan floor tile	4770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
03A	9x9 black floor tile			main office - principal's office, bathroom, vault		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	<b>.</b>											
2017 - Fall:	No Change				<u> </u>							
Comments:												
2017 - Sprin	g: No Change				_							
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	Ü											
					_							
		•				_	•				•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03B	9x9 white floor tile			main office - principal's office, bathroom & vault		Miscellaneous					YES X NO
					i						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03C	9x9 green floor tile			engineer's toilet		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:	, <u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	1						1	T =	1 -	1 -	61 1 1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	linoleum			basement ladie's room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 6

Quantity Units		Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
08 12x12 floor tile- ABATED	1955 building (demolished)		Miscellaneous					YES	X NO
2016 - Fall: No Change		7							
Comments:		=							
2017 - Spring: No Change		-							
Comments:									
2017 - Fall: No Change		-							
Comments:									
2018 - Spring : No Change		-							
Comments:									
2018 - Fall: No Change		-							
Comments:									
		_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9x9 floor tile- ABATED			1955 building (demolished)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	wallboard	450	SF	basement art room, fire pump room		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	12x12 beige w/tan streaks floor tile mastic	1550	SF	basement - art room		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Other
Comments:Change tile color overlapeed existing tile
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11B	12x12 black floor tile mastic	1000	SF	room 306		Miscellaneous	No	None			YES	X NO
2016 - Fall: N	o Change				]							
Comments:	J				]							
2017 - Spring	: No Change				-							
Comments:												
2017 - Fall: N	o Change				]							
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11C	12x12 white floor tile mastic			room 306		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
11D	12x12 beige streaked floor tile mastic			1st, 2nd, 3rd floor corridors (patches)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11E	12x12 orange floor tile mastic			1st floor corridor - outside boys toilet		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11F	12x12 tan floor tile mastic	4770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102,105,107, engineer'sn office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	9x9 black floor tile mastic (Abated)			main office - principal's office, washroom, vault		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
12B	9x9 white floor tile mastic (Abated)			main office - principal's office, bathroom & vault		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	•											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
					I							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12C	9x9 green floor tile mastic			engineer's toilet		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

13 linoleum mastic basement ladie's room Miscellaneous VES X NO  2016 - Fall: No Change Comments:	
	)
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12x12 floor tile mastic- ABATED			1955 building- (building demolished)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	\ssessr	nent Category
15	9x9 floor tile mastic- ABATED			1955 building- (building demolished)		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:													
2018 - Spring	g : No Change												
Comments:	<u> </u>												
2018 - Fall: N	lo Change												
Comments:	J												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	brown vinyl baseboard	200	LF	basement art room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
17	brown vinyl baseboard mastic	200	LF	basement art room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				]								
Comments:													
2017 - Spring	g: No Change												
Comments:	,												
2017 - Fall: N	No Change												
Comments:	Ü												
2018 - Spring	g : No Change												
Comments:	grand and grand												
2018 - Fall: N	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	drywall compound	200	SF	basement art room		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 15

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assessr	ment Category
19A	12x12 green floor tile	800	SF	Staff lounge - kitchen		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments:	-												
2017 - Sprin	g: No Change				1								
Comments:													
2017 - Fall:	No Change				1								
Comments:	•												
2018 - Fall:	No Change				1								
Comments:	<u> </u>												
2018 - Sprin	g : No Change				-								
Comments:	<u> </u>												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19B	12x12 green floor tile mastic	800	SF	Staff lounge - kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
20	Hard Plaster			Auditorium		Surface					YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	ceiling plaster	10160	SF	throughout basement		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (	ategory
22	12"x12" Light Blue VFT	6700	SF	Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312,		Miscellaneous	No	None	0		YES X	10
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 2 1 11 21	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
Comments.	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Light Blue VFT Mastic	6700	SF	Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312,		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
24	12"x12" Dark Blue VFT	2400	SF	Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,		Miscellaneous	No	None	0		YES	X NO
2016 - Fall Comments	: No Change s:											
2017 - Spri	ing: No Change											

Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Dark Blue VFT Mastic	2400	SF	Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
26	Lab Table Tops	432	SF	Room 309		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	·						•	•			
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Light Green VFT	3200	SF	1st Floor Corridor, Storage Room, Principles Office.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
28	12"x12" Light Green VFT Mastic	3200	SF	1st Floor Corridor, Storage Room, Principles Office.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	•	•	]	•	•	•	•	•	•	
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:					-							
2018 - Fall:	No Change				-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Dark Green VFT	3200	SF	1st Floor Corridor and Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

30	12"x12" Dark Green VFT Mastic	3200	SF	1st Floor Corridor and Office		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change				]						
Comments:											
2017 - Spring: No Change											
Comments:											
2017 - Fall: N	No Change				-						
Comments:	-										
2018 - Fall: N	No Change				_						
Comments:											
2018 - Spring	g : No Change				1						
Comments:											
					J						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	mag block boiler insulation- ABATED			boiler room- material abated and boiler removed in 1994		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
Е	cardboard pipe covering	40	SF	attic - tank		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	cardboard pipe fittings	3	LF	attic - tank		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
G	aircell pipe insulation			original (1893) building air chamber		TSI				YES	X NO
2016 - Fall: Comments:	No Change										
2017 - Sprir	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Sprir	ng : No Change				-						
Comments:											
2018 - Fall:	No Change				-						
Comments:	Ţ				7						

Material

Damage

Friable

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	aircell pipe joints	6	FITTING	basement teachers lounge		TSI	Yes	Loc	1		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
I	preform pipe covering- ABATED			1893 building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	water meter packing	5	FITTING	basement fire pump room, Basement Teacher's Lounge		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
0	cardboard pipe covering- ABATED			1955 addition- (building demolished)		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:					]							
2017 - Spring	: No Change											
Comments:					-							
2018 - Spring	: No Change				]							
Comments:					_							
2018 - Fall: N	o Change											
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	cardboard pipe joint- ABATED			1955 addition- (building demolished)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Q	aircell pipe insulation- ABATED			1955 building addition- (building demolished)		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Fall: N	o Change											
Comments:					 							
2017 - Spring	: No Change											
Comments:					1							
2018 - Fall: N	o Change											
Comments:					1							
2018 - Spring	: No Change											
Comments:					<u> </u>							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	aircell pipe joints- ABATED			1955 addition- (building demolished)		Miscellaneous					YES X NO
2016 Foll	· No Changa										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Cementious Pipe Fittings	10	LF	Girls and Boys bathrooms - pipe chases		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Т	Pipe Insulation	30	LF	Girls and Boys bathrooms - pipe chases		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
U	incinerator brick			boiler room		TSI		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change				_							
Comments:					]							
2018 - Fall: N	lo Change											
Comments:	<u> </u>				]							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
V	Cementitous Pipe Fittings			Engineer's Storage and Fire Pump Room		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
W	Pipe Insulation			Engineer's Storage and Fire Pump Room		TSI		None			YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Х	Material behind metal ceiling and walls			Auditorium Fan Room		Surface		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William H Ray Elementary School
Date:1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25071

SCHOOL'S ASBESTOS MANAGEMENT PLAN.