## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

25291 Franz Peter Schubert Elementary School 5800 School: **Oracle Unit: Building ID:** Address: 2727 N. Long Avenue Region: 02 Mail Room: Asbestos Surveyor: Kraft, Fred **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 1/11/2019 Email Address: fredkraft@sbcglobal.net A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Brown Linoleum NOT 2nd Floor Mens Toilets, YES 01 SF X NO 200 Miscellaneous No None 0 **OBSERVED** 1930 Building 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
02	Brown Linoleum Mastic NOT OBSERVED	200		2nd Floor Mens Toilets, 1930 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change				1							
Comments:												

2018 - Fall: No Change Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12"x12" Beige w/Brown & White Specks VFT	800	SF	Room 301, 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
04	12"x12" Beige w/Brown & White Specks VFT Mastic	800	SF	Room 301, 1930 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change				_							
Comments:												
2017 - Fall:	No Change				=							
Comments:												
2018 - Sprin	ng : No Change				=							
Comments:												
2018 - Fall	No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" White w/White & Gray Specks VFT	4300	SF	Room 216, 218, 220, 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" White w/White & Gray Specks VFT Mastic	4300	SF	Room 216, 218, 220, 1930 Building		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	o Chongo	•								•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" White w/Brown & Light Brown Specks VFT	250	SF	2nd Floor Womens Teachers Toilet, 211 -1930 Bldg		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" White w/Brown & Lt Brown Specks VFT Mastic	250	SF	2nd Floor Womens Teachers Toilet, 211 -1930 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Tan w/White & Black Streaks VFT	1100	SF	Room 206 (not observed), Engineer's Office, -1930 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: Other
Comments:new floor over
2017 - Fall: Repaired
Comments:floor put over
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Tan w/White & Black Streaks VFT Mastic	1100	SF	Room 206 (not observed), Engineer's Office, 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: Other	
Comments:new floor over	
2017 - Fall: Repaired	
Comments:floor put ovrer	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Tan w/Brown & White Specks VFT	420	SF	Room 217 (Carpet), NE Vestibule, 1930 Building		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Tan w/Brown & White Specks VFT Mastic	420	SF	Room 217 (Carpet), NE Vestibule, 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	lo Change		
Comments:			
2017 - Spring	j: Other		
Comments:ru	ıg over floor		
2017 - Fall: N	lo Change		
Comments:			
2018 - Spring	j : No Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:			·
			·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Gray w/White & Gray Specks VFT	2200	SF	1st Floor Lunchroom (NOT OBSERVED); Main Office, Principals Office, Assistant Principals Office - 1930 Building		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Inaccessible	
Comments:new floor	
2017 - Spring: Other	
Comments:new floor over	
2017 - Fall: Repaired	
Comments:floor put over	
2018 - Spring : No Change	
Comments:	
2018 - Fall: Repaired	
Comments:new floor put over old floor	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Gray w/White & Gray Specks VFT Mastic	2200	SF	1st Floor Lunchroom (NOT OBSERVED), Main Office, Principals Office, Assistant Principals Office, 1930 Building		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Inaccessible
Comments:new floor
2017 - Spring: Other
Comments:new floor over
2017 - Fall: Repaired
Comments:floor put over
2018 - Spring : No Change
Comments:
2018 - Fall: Repaired
Comments:new floor put over old floor

Oracle Unit: 25291

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
25	12"x12" Soft Peach w/Sand,White & Brown Specks VFT	4500	SF	Auditorium, 1930 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change		•	•	]	•	•	•	•	•		
Comments	S:											
2017 - Spr	ing: No Change											
Comments	): 											
2017 - Fall	: No Change											
Comments	):											
2018 - Spr	ing · No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Soft Peach w/Sand, Wht & Brn Specks VFT Mastic	4500	SF	Auditorium, 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Gray w/Long Black & Gray Specks VFT	800	SF	103 A, Storage Room Between 103 A & 103 B; 103 B (Carpet) - 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Gray w/Long Black & Gray Specks VFT Mastic	800	SF	103 A, Storage Room Between 103 A & 103 B; 103 B (Carpet) - 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

11/110	Waterial Becomption	Quantity	Units	Waterial Ecoation	Туре	Category	Thabic	Type	Quantity	Units	Onange in 7100000ment Gategor
31	12"x12" Black VFT	150	SF	Toilets on Boiler Room Catwalk, 1930 Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	No Change				7						
Comments:	-										
2017 - Sprin	ng: No Change										
Comments:					_						
2017 - Fall:											
Comments:											
2018 - Sprin	ng : No Change										
Comments:					_						
2018 - Fall:	<u>~</u>										
Comments:					_						
					_						
HA No	Material Description	Material	Material	Material Location	Achestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Categor

Material

Friable

Damage

Damage

Damage

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
32	12"x12" Black VFT Mastic	150	SF	Toilets on Boiler Room Catwalk, 1930 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	ory
33	12"x12" Red VFT	150	SF	Toilets on Boiler Room Catwalk, 1930 Building		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Red VFT Mastic	150	SF	Toilets on Boiler Room Catwalk, 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

38	12" x 12" Gray VFT (Not Observed)	3rd Floor Classrooms, 1930 Building				YES	X NO
			7				
2016 - Fall: N	o Change						
Comments:							
			1				
2017 - Spring	: No Change						
Comments:							
2017 - Fall: N	o Change						
Comments:	-						
2018 - Spring	: No Change						
Comments:							
2018 - Fall: N	o Change						
Comments:	•						
			_				

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12" x 12" Gray VFT Mastic NOT OBSERVED; MOST HARDWOOD FLOORS			3rd Floor Classrooms, 1930 Building							YES X NO

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
40	12" x 12" White w/ Black & Gray Specks VFT	9200	SF	Room 102; 1st - 3rd Floor Corridor; Room 104 (NOT OBSERVED) - 1930 Building		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: Other
Comments:rug over floor
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Repaired
Comments:rug iver floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
41	12" x 12" White w/ Black & Gray Specks VFT Mastic	9200	SF	Room 102; 1st - 3rd Floor Corridor; Room 104 (NOT OBSERVED) - 1930 BuildingToilet, 1930 Building		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 0 1 01
2017 - Spring: Other
Comments:rug over floor
2017 - Fall: No Change
Comments:
2018 - Fall: Repaired
Comments:rug over floor
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
42	12"x 12" Green VFT	3000	SF	1st - 3rd Floor Corridor, 1930 Building		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

43	12"x 12" Green VFT Mastic	3000	SF	1st - 3rd Floor Corridor, 1930 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
	g : No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
44	12" x 12" Gray VFT	12000	SF	Throughout, 1998 Annex		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage Quantity Change in Assessment Category

Material Location

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		0 ,
45	12" x 12" Gray VFT Mastic	12000	SF	Throughout, 1998 Annex		Miscellaneous	No	None	0		YES	X NO
2016 - F	all: No Change				]							
Commer	nts:				_							
2017 - S	pring: No Change				-							
Commer	nts:				]							
2017 - F	all: No Change				1							
Commer	nts:											
2018 - F	all: No Change				1							
Commer												
2018 - S	pring : No Change				1							
Commer					]							
					1							

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Gray Vinyl Baseboard	1500	LF	Throughout, 1998 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
47	Gray Vinyl Baseboard Mastic	1500	LF	Throughout, 1998 Annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				]							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change				-							
Comments:												
2018 - Fall: I	No Change				-							
Comments:	•				]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	2' x 4' White w/ Grooves Ceiling Tile	11000	SF	Throughout, 1998 Annex		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
49	Drywall	50000	SF	Throughout, 1998 Annex		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change				]							
Comments:	<b>.</b>											
2017 - Fall: I	No Change				]							
Comments:												
2017 - Sprin	g: No Change											
Comments:					_							
2018 - Sprin	g : No Change				<u> </u>							
Comments:					_							
2018 - Fall: I	No Change				]							
Comments:					_							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Drywall Joint Compound	50000	SF	Throughout, 1998 Annex		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" White w/ Brown & White Streaks VFT	3600	SF	Throughout, 2000 Mobile Annex		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" x 12" White w/ Brown & White Strks VFT Mastic	3600	SF	Throughout, 2000 Mobile Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 20

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
53	Beige Vinyl Baseboard	600	LF	Throughout, 2000 Mobile Annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	•											
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	•											
					l							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	2' x 2' White w/ Grooves Ceiling Tile	3000	SF	Room 501- 504, 501 Storage Rm- 504 Storage Rm, Sprinkler Room, 2000 Mobile Annex Corridor		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

55	Beige Vinyl Baseboard Mastic	600	LF	Throughout, 2000 Mobile Annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	10 Orlange				-							
0047	I. Ob											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	<u> </u>				1							
2018 - Sprin	g : No Change				-							
Comments:												
2018 - Fall: N	No Change											
Comments:	To Change				1							
Comments.					+							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Surface

No

Dist

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

50

Change in Assessment Category

90000

HA No

56

Material Description

Ceiling Plaster

Material

Units

SF

Material

Quantity

Material Location

Throughout 1930 Building

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
57	Wall Plaster	150000	SF	Throughout 1930 Building		Surface	No	Dist	50		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change				-							
Comments:	<u> </u>											
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Architectural Plaster	5000	SF	Auditorium - 1930 Building		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 23

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
59	Fire Door Insulation	10	EA	Mechanical Areas - 1930 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change				]							
Comments	:											
2017 - Spri	ing: No Change				=							
Comments	:				1							
2017 - Fall	: No Change				=							
Comments	:											
2018 - Fall	: No Change				-							
Comments	:											
2018 - Spri	ing : No Change				=							
Comments	:											
					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Terrazzo Flooring	2500	SF	Hallway Border; Auditorium Stage Stairs (2) - 1930 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 24

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessmen	Category
61	Ceiling Plaster	400	SF	2000 Mobile		Surface	Yes	None	0		YES	X	NO
2016 - Fall: N	lo Change				7								
Comments:	-												
2017 - Spring	g: No Change				1								
Comments:													
2017 - Fall: N	lo Change				-								
Comments:													
2018 - Fall: N	lo Change				-								
Comments:													
2018 - Spring	g : No Change				-								
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Rolled Flooring	2000	SF	2000 Mobile		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
63	Dry Wall	1000	SF	2000 Mobile		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					=							
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	J											
2018 - Spring	g : No Change											
Comments:	, ,											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Ceiling Plaster	250	SF	1998 Annex		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12x12 Off White w/ Green Specks VFT	380	SF	3rd, 2nd &1st Floor Elevator Lobby		Miscellaneous	No	None	0		YES X NO
			•		·		•	•			

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12x12 Off White w/ Green Specks VFT Mastic	380	SF	3rd, 2nd &1st Floor Elevator Lobby		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12x12 Light Blue w/ Black Pin Holes VFT	90	SF	3rd Floor Storage Room- 1930		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12x12 Light Blue w/ Black Pin Holes VFT Mastic	90	SF	3rd Floor Storage Rooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12x12 Green w/ Light Green Specks VFT	800	SF	206		Miscellaneous	No	None	0		YES X NO
					1						_

2016 - Fall: No Change Comments: 2017 - Spring: No Change
Comments:
2017 - Spring: No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2019 Falls No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	12x12 Green w/ Light Green Specks VFT Mastic	800	SF	206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12x12 Tan w/ White Specks VFT	2400	SF	1st Floor Lunchrooms		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
OOAO Oodaa Na Obaaaa
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12x12 Tan w/ White Specks VFT Mastic	2400	SF	1st Floor Lunchrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12x12 White w/ Blue and Red Specks VFT	1200	SF	1st Floor Library		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	12x12 White w/ Blue and Red Specks VFT Mastic	1200	SF	1st Floor Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Carpet Mastic (Dark Gray)	2500	SF	Main Office, Principal's Office, Assistant Principal's Office; Rooms 103B and 217; Auditorium Aisles		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	Interior Window Caulk	7500	LF	Interior Windows		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

99	Exterior Window Caulk	7500	LF	Exterior Windows		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	2017 - Spring: No Change											
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:	J											
2018 - Fall:	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
А	Cardboard Pipe Insulation	1700	LF	Throughout Basement, 1930 Building (See Hatching Maps)		TSI	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Page 33

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Cardboard Pipe Insulation	170	LF	Throughout Basement, 1930 Building (See Hatching Maps)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Aircell Pipe Insulation	3130	LF	Throughout Basement, 1930 Building (See Hatching Maps)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Aircell Pipe Insulation	350	LF	Throughout Basement, 1930 Building (See Hatching Maps)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	MJP E/F/V on Fiberglass Pipe Insulation	200	SF	, 1930 Building		TSI	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Duct Insulation	500	SF	South Unfinished Pipe Crawlspace, 1930 Building		TSI	Yes	None	0		YES X NO
2016 - Fall: No Change					· -					. —	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Boiler Rope (Gasket #1)	2	SF	Boiler Room, 1930 Building		TSI	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Boiler Rope (Gasket #2)	2	LF	Boiler Room, 1930 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
		_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Flue Gasket	15	LF	Boiler Room, 1930 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 37

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Incinerator Insulation	2	SF	Boiler Room, 1930 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

Date: 1/14/2019	
This is to notify you in accordance with Illinois and Federal Asbestos Regulations the Asbestos Management Plan is available at each school during school hours I Requests to review the Asbestos Management Plan must be made at least 24 hours.	by appointment.
Also please be advised that CPS conducts asbestos inspections of all Schools et The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.	very three years.
CHECK ONE	
A copy of this notice was sent home in each child's backpack.	
A copy of this notice was printed in the school's newsletter and sent home with e	ach child
A copy of this notice was printed in the school's calendar and sent home with each	ch child
Other.	
A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.	